

ASS. REC. BY:

REF:

CS/FCI19062885/Uqdbn2

Special Instruction:

Surveyor:

CWS

Markus

ASSIGNMENT (Office)

From (Person):

Henry Kao

of

FCI

Date/Time:

5:10pm @ 15/2/19

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLX 4292D

Insured:

SHA 9506Z

at Workshop m/s:

Zoom Autowerkes

Tel:

94507920

of

130 Bedok Reservoir Rd #08-1339

Policy No:

Claim No:

D19001081MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/2/2019

CA / REV / REP. / REV 24 HRS (DS)

H.O.D. Endorsement:

Date/Time:

1:38pm @ 15/2/19

Person Contacted:

Elin

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	Insp: 15 Kaki Blt Rd 4 #01-53
	SLX 4292D-X
	SHA 9506Z CS/FCI18005310/M1kd3q2
19/2/19 @ 2.19pm	Informed Henry Kao, we are pending estimate from repairer.
26/2/19 @ 12.18pm	revised to Henry Kao by email.

Don: 8/3/2018

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report

Consistent? : Yes or No

G/A / PR Seen.

Consistent? : Yes or No

Est. Repairs:

5 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 20 FEB 2019.

Date/Time, File Pass to?

☐

Preli. Report

1) 26/2/19

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

4x15=60

170+60

50

50+50

79

459



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001081MFSH

Date: 26 February 2019

Our Ref: CS/FCI19002885/Uqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLX 4292D .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 15/02/2019 at the premises of M/s ZOOM AUTOWERKS. and have the following to report:-

Workshop Estimate Amount	: S\$ <u>14,584.64</u> .
Revised Estimate Amount	: S\$ <u>4,250.00 (Lump Sum)</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages
at the rear portion.



Yours faithfully

CHUA KANG SENG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	13-02-2019	Our Ref No. D19001081MFSH
Accident Date	12-02-2019	Claim Type. Third Party
Insured Vehicle	SHA9506Z	Third Party Vehicle. SLX4292D
Survey Location	130 BEDOK RESERVOIR ROAD#08-1339	
Contact Person.	ELIN CAI	
Contact No.	94507920/ 94507920	Fax No. 0
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ZOOM AUTOWERKS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Date of Accident

: 01/02/19 Accident Time: 5.10pm (24-HR-Format)

Accident Place

: Along PIE toward Tuen

Vehicle No. (Car Plate No.)

: GX 8232K Make/Model: Toyota Dyna

Insurance Company

: EQ Policy No: DMCPH218-006560

Owner or Company Name / IC No.

: Flexi Flex Pte Ltd / 201114152K

Owner or Company Contact No.

: Owner's Hp Company Tel

DRIVER'S Name / IC No.

: Ponnusamy Vinothraja / 66788304M

DRIVER'S Date Of Birth

: 20/7/1990 DRIVER'S License Pass Date 16/7/2014

Relationship of Owner & Driver

: Spouse \ Parents \ Children \ Sibling \ Employee \ Others:

DRIVER'S Address

: 23 Nanyang Road BIKB #02-03A

DRIVER'S Contact No. / Alt No.

: 1) 6841 5995 2) 5628588

DRIVER'S Occupation

: 8308 3953
: INDOOR \ OUTDOOR (e.g. working inside or outside office)

Email Address

:

Weather & Road Surface

: CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET

Reporting Type

: Reporting Only \ Claim Other Party \ Claim Own Insurance

Number of Passengers (Including Driver): 1 Driver

Was there any video Captured by car camera: YES \ NO

Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose

Any Injury (If YES, Pls state): NO

Other Party Driver's Particular (if any)

Vehicle No:

GBD3434S (China)

Vehicle No:

SKX1602A

Vehicle Make/Model:

Vehicle Make/Model:

Name Driver:

Name Driver:

IC No. Driver/Contact:

IC No. Driver/Contact:

* NEW - Passenger's name & gender:

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 26 February 2019 12:18 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Henry Kao Cai Jie'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001081MFSH/1
Attachments: CSFCI19002885Uqd3.pdf

Dear Henry,

Enclosed herewith preliminary advice of SLX 4292D.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 19 February 2019 2:19 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001081MFSH/1

Dear Henry,

Please be informed that we have inspected the vehicle SLX 4292D on 15/02/2019.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 15 February 2019 1:41 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001081MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 19 February 2019 2:19 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Henry Kao Cai Jie'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001081MFSH/1

Dear Henry,

Please be informed that we have inspected the vehicle SLX 4292D on 15/02/2019.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 15 February 2019 1:41 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001081MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 14 February 2019 5:10 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19001081MFSH/1

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Kia Cerato Forte 1.6A SX (New 5-yr COE) at \$27,800



Best Condition, Low Depre at
\$5,560 /yr, Almost New Tyres
And Battery, Call Now!
Speedo Motoring StarAd

Aut
An Inspiration

click here to view
our **PRISTINE**
at

Browse by Category

Sort by Date Posted

13 vehicles

Odyssey

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
Search Selection	Odyssey		Any	Any	2016	Any	Any	
		Honda Odyssey 2.4A EXV-S Sunroof	\$108,800	\$11,740 /yr	24-Oct-2016	2,356 cc	65,000 km	
Addition Self Fix Tailgate, Under Warranty, 100% Loan Approval,Very Well Maintained, Fully Serviced By Kah Motor High Spec Unit With Spacious And Luxurious Drive For The Whole Family.								
Posted: 18-Feb-2019 Tags: 2016 Honda Odyssey, 2016 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda								
		Honda Odyssey 2.4A EXV-S Navi Res Sunroof	\$103,800	\$12,560 /yr	21-Jan-2016	2,356 cc	-	
Low Interest Rate From 1.99%, In House Loan Available, Well Maintained MPV That Is As Good As Brand New And Smell Like Brand New (Kah Motor) Maintained With On-going Warranty! 1 Owner! ST...								
Dickson Automobile								
Posted: 18-Feb-2019 Tags: 2016 Honda Odyssey, 2016 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda								
		Honda Odyssey 2.4A EXV-S	\$105,800	\$12,940 /yr	06-Jan-2016	2,356 cc	54,691 km	
Highest Specs Model With Build In Navigation And All Round Parking Cameras, In Original Condition, Guaranteed Accident-Free! Fully Ac And Maintained With 5 Years Warranty From Kah Motors! ...								
Car Search								
Posted: 16-Feb-2019 Tags: 2016 Honda Odyssey, 2016 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda								
		Honda Odyssey 2.4A EXV-S	\$109,800	\$12,110 /yr	08-Sep-2016	2,356 cc	47,300 km	
Monthly At \$1,790 For 84 Months Full Loan Available! Non-smoker Car! 1 Owner, Well Maintained Condition. 100% Accident-Free! Most Size 7 Seater In The Market. Call Me Now Before It's Sold...								
Viking Motor Pte Ltd								
Posted: 16-Feb-2019 Tags: 2016 Honda Odyssey, 2016 honda odyssey, Honda Odyssey, honda odyssey, Honda, Odyssey, odyssey, Used Honda								
		Air Filter						
Product Code: RB3AF. Fits Honda Odyssey RB3 2009 onwards.								
More info about this product								

Compare

1a Odyssey 2.4A EXV-S
oof

\$105,000**\$11,910 /yr****07-Jul-2016****2,356 cc****70,000 km**

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Foreign Identification Number
Owner ID:	8605W
Vehicle Details	
Vehicle No.:	SLX4292D
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Feb 2019
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EXV-S CVT SR
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	K24W72011310
Chassis No.:	JHMRC1890GC202942
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$30,530.00
Original Registration Date:	01 Apr 2016
First Registration Date:	01 Apr 2016
Transfer Count:	1
Actual ARF Paid:	\$34,742.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Mar 2026
PARF Rebate Amount:	\$26,056.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,604.00
COE Rebate Amount:	\$33,796.00
Total Rebate Amount:	\$59,852.00

The information contained herein is correct as at 25 Feb 2019

OK



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

not Allowed

h/c

15/2/19

h/s @ 4250/1

5 day.

take place After repair

15 February 2019

REG NO.: SLX 4292 D
MAKE/MODEL: HONDA ODYSSEY

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Rear windscreen moulding	\$ Rec 109.80 ✓
1	Rear tailgate	Body \$ 1,952.50 ✓
2	Rear tailgate dampers	\$ 11 253.00 X
1	Rear tailgate inner trim board	\$ 299.60 ✓
2	Rear tailgate lamps	\$ 11 1,078.20 X
1	Rear tailgate inner lock	twi \$ 205.70 ✓
1	Rear tailgate weather strip	\$ Twi 115.10 ✓
2	Rear taillamps	\$ 1,462.40 ✓
1	Rear end panel	\$ 637.50 ✓
1	Rear end panel inner garnish	\$ Twi 246.40 ✓
1	Rear bumper	\$ 1,557.20 ✓
1	Rear bumper beam	\$ 92.10 X
2	Rear bumper brackets	\$ 111.20 X
1	Rear bumper reinforcement	\$ 197.20 X
2	Rear bumper side retainers	rel \$ 97.20 ✓
2	Rear bumper reflectors	\$ 127.60 X
1	Rear floor board	\$ 210.00 X
1	Rear floor panel	\$ 1,260.50 X
1	Rear exhaust silencer	\$ 1,251.60 X
2	Rear exhaust mountings	\$ 97.20 X
1	Rear fender air gate	\$ 32.60 X
2	Rear fender inner trim garnishes	\$ 911.20 X
		\$ 12,305.80
Less 20%		\$ 2,461.16
		\$ 9,844.64

P-3992.1
202
P-3193.68
S.N-330.00
Calor-1800.00
2323.68
4288

c/f:

\$

9,844.64

SPECIAL NETT ITEMS

1	Rear windscreen sealant	\$	mer	80.00	40
1	Rear bumper clip (1 set)	\$	mer	50.00	40
1	Rear reverse sensor (1 set)	\$	shub	480.00	250
		\$		610.00	

S/N**LABOUR CHARGES**

1	To remove, replaced damaged lamps and check up rear wiring.	\$		80.00	30
2	To remove and refit inner garnishes.	\$		150.00	80
3	To remove and refit rear reverse sensor.	\$		150.00	50
4	To transfer rear tailgate mechanism and wiring assembly.	\$		120.00	60
5	To remove and refit rear windscreen glass.	\$		180.00	120
6	To remove, refit and replace exhaust silencer and mountings.	\$	17	150.00	80
7	To apply undercoating.	\$		200.00	60
8	Panel beating.	\$		1,600.00	600
9	To re-spray painting on the affected areas.	\$		1,500.00	800
		\$		4,130.00	

GRAND TOTAL :**\$****14,584.64**

LKK Auto Consultants hence notify

- Not necessary to return for spray painting
- To remove damaged part(s) during resurvey
- Photographs are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No financial deduction(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repaker

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19002885/Uqd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 26-02-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 9506Z	Veh. Inspected	SLX 4292D
Policy No.		Coverage (\$)	0.00
Claim No.	D19001081MFSH	Excess (\$)	0.00
Assign From	HENRY KAO	Assign Date	15/02/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA ODYSSEY (A)	c.c	2356
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JHMRC1890GC202942	Colour	RED
Odometer	27369	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	DUNLOP	6 mm
L/H Front Tyre	215/55 R17	DUNLOP	6 mm
R/H Rear Tyre	215/55 R17	DUNLOP	6 mm
L/H Rear Tyre	215/55 R17	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	12/02/2019	Inspection Date	15/02/2019
Survey held at	15 KAKI BKT RD 4#01-53		
Repairer	ZOOM AUTOWERKS PTE LTD		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 4292D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR WINDSCREEN MOULDING	NECESSARY	109.80	109.80
1	REAR TAILGATE	BADLY DENTED	1,952.50	1,070.80
2	REAR TAILGATE DAMPERS	NOT NECESSARY	253.00	-
1	REAR TAILGATE INNER TRIM BOARD	DEFORMED / CRACKED	299.60	299.60
2	REAR TAILGATE LAMPS	NOT NECESSARY	1,078.20	-
1	REAR TAILGATE INNER LOCK	TWISTED / SHORTED	205.70	205.70
1	REAR TAILGATE WEATHER STRIP	TWISTED	115.10	115.10
2	REAR TAILLAMPS	CRACKED	1,462.40	961.20
1	REAR END PANEL	DENTED	637.50	460.80
1	REAR END PANEL INNER GARNISH	TWISTED	246.40	103.60
1	REAR BUMPER	DENTED / DEFORMED	1,557.20	568.30
1	REAR BUMPER BEAM	NO SUCH PARTS	92.10	-
2	REAR BUMPER BRACKETS	NO SUCH PARTS	111.20	-
1	REAR BUMPER REINFORCEMENT	NO SUCH PARTS	197.20	-
2	REAR BUMPER SIDE RETAINERS	NECESSARY / BENT	97.20	97.20
2	REAR BUMPER REFLECTORS	NOT NECESSARY	127.60	-
1	REAR FLOOR BOARD	NOT NECESSARY	210.00	-
1	REAR FLOOR PANEL	NOT NECESSARY	1,260.50	-
1	REAR EXHAUST SILENCER	NOT NECESSARY	1,251.60	-
2	REAR EXHAUST MOUNTINGS	NOT NECESSARY	97.20	-
1	REAR FENDER AIR GATE	NOT NECESSARY	32.60	-
2	REAR FENDER INNER TRIM GARNISHES	NOT NECESSARY	911.20	-
	LESS 20% DISCOUNT		-2,461.16	-798.42
			9,844.64	3,193.68
SPECIAL NETT ITEMS				
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	50.00	40.00

Report Ref No. CS/FCI19002885/Uqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR REVERSE SENSOR (SN)	SHORTED	480.00	250.00
			610.00	330.00
	LABOUR			
	TO REMOVE, REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING.		80.00	30.00
	TO REMOVE AND REFIT INNER GARNISHES.		150.00	80.00
	TO REMOVE AND REFIT REAR REVERSE SENSOR.		150.00	50.00
	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY.		120.00	60.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.		180.00	120.00
	TO REMOVE, REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS.	NOT NECESSARY	150.00	-
	TO APPLY UNDERCOATING.		200.00	60.00
	PANEL BEATING.		1,600.00	600.00
	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS.		1,500.00	800.00
			4,130.00	1,800.00
	GRAND TOTAL		14,584.64	5,323.68
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,250.00

Report Ref No. CS/FCI19002885/Uqd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.