

ESTIMATE FOR SDS78D

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

Ms Chia Cheow Hua

Blk 1 Amber Gardens #10-02 Singapore 439957

64400878

WIP No

Reg No/Reg Date Date In/Mileage

Chassis No

Engine No Make/Model

Colour/Trim

Vehicle & Document Information

30873 SDS78D

/ 02/09/2011

WDD2120472A448668

27186030235618

MB/E 250 CGI SEDAN (W212)

027 775 Iridium sil/ 042 201 Black

Account No	Terms	Date/Time Printed	CSE	Operator	· · · · · · · · · · · · · · · · · · ·					
VCV31535	CRDVCH	14/02/2019/ 14:35	AQ	305 / Alan	Quek Ai Lun					
		Description of Good	s / Services			Qty	Unit Price	Disc%	Amount	
DRIVE IN DATE IN	ÆXCESS DATE SURVE	::VPA/P1976298 // 13 :14-02-2019 // TBA	-02-2019				X 1			
BY/AUTHR A BPILAB	IZED ON	•					i	0.10	380	0.00
	RY TO CHEC	CK CONTROL UNITS & RES	SET MEMORY	ТО	and the same of th					/
	SETTINGS.	NETT			~ [15	3		Mes/ 61	0 00
S BPNSUB Supply 1	PC REG. P	LATE WITH HOUSING.NET	ГТ		(N - N)	()ご	Carrie Carrier		1 11 9 0	0.00
	ORDER NO:			- (i)		1				
S BPNSUB				AU(II)					7.2 95	0.00
		1PC FRONT RIGHT TYRE	& IPC REAR	MMMM	land.				6	,72
RIGHT TY BPILAB	KE	And the second s	(~~\\)	/////					540	0.00
	& CONDUCT	WHEEL ALIGNMENT NETT					~	\7	1920 248 120	1
A BPILAB							(D)	wh).	1920 248	0.00
	INSTALL F	RONT SUSPENSION & WHI	EEL/BASE				-1		1,2	^ ^
A BPILAB	ADI AMD LITT	THE COOLS AN HIGHWANT NI	TT						120	0.00
CHECK HE A BPILAB	ADLAMP WII	TH FOCUS ADJUSTMENT.N	E 1 1						1440 1920 1200 150	0.00
	REPLACE F	RONT BUMPER & REMOVE	FRONT SUPP	ORT					/	
	PONENTS &									
A BPIRES									150	0.00
	FRONT BUMP	PER & FRONT BONNET								
S BPNTOW	TOUTHO ED	ROM MARINE PARADE RD	TO DISC							
	NG DOLLEY	TOM MAKINE PAKADE ND	IO FESC							
WO: 1603	00									
M LH/F HEA	DIAMP CF	4/				1.00	1105.12		110	-
M RH ['] /F HEA	DLAMP 🕜	en /				1.00	1105.12			15.12
M RADIATOR		cpr/				1.00 1.00	1183.82	00.00		33.82 6.47
II KADIATOK		RACKET BRO								

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383



ESTIMATE FOR SDS78D

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

Ms Chia Cheow Hua

Blk 1 Amber Gardens #10-02 Singapore 439957

64400878

WIP No

Reg No/Reg Date

Date In/Mileage

Chassis No

Engine No

Make/Model

Colour/Trim

Vehicle & Document Information

30873

SDS78D / 02/09/2011

WDD2120472A448668

27186030235618

MB/E 250 CGI SEDAN (W212)

027 775 Iridium sil/ 042 201 Black

Account No	Terms	Date/Time Printed	CSE	Operator					
WCV31535	CRDVCH	14/02/2019/ 14:35	AQ	305 / Alan	Quek Ai Lu	n			
		Description of God	ods / Services			Qty	Unit Price	Disc%	Amount
M BONNET ST						1.00	101.50		101.5
M BONNET SE						1.00		00.00	21.2
M FRT BUMPI					27 A Domi	1.00	1469.24		1469.2
M LH/F BUMF	PER GARNIS	H/W				1.00	85.83		85.8
M RH/F BUMF	PER GARNIS	SC COD DUMPED 444				1.00	*	00.00	85.8
M CT/F BASI	IC MOUNTIN	IG FOR BUMPER		4.1		1.00	74.92	00.00	74.9 70.5
,		_		jul	· · ·	1.00	State of the state		70.5
	ACT ABSORB	IG FOR BUMPER T	Γ,	th Junian	LS (M)	1.00	70.54 110.24	00.00	110.2
	CING SENSO		1 +	th looks d	7.7	4.00	355.42		1421.6
		R SEAL & 7		1,6	1/1/	4.00		00.00	28.7
M LICENSE F	PLATE BASE	TOA /	wh :	A DOWN		1.00	184.82		184.8
	TOM GRILLE		\sim	10 mills		1.00		00.00	71.5
FRT CROSS		B1/	The state of the s	イルバン	h-"	1.00	546.09		546.0
	SUPPORT ME	MBER 7	~ / / / /	212 ha a.	T115	1.00	155.54		155.5
		MBER CLAMP	Y \\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	2/05/14 (0)	210	1.00		00.00	42.0
	WHEEL C			lli		1.00	609.02		609.0
	WHEEL C		ע או	1 4 6 66	1	1.00	609.02		609.0
	CK-ABSORBE		Ro	m by M	UP (1.00	856.01	00.00	856.0
M FRT TORSI		7	1/2	7 1		1.00	479.05	00.00	479.0
M RH/F TORS	SION BAR R					1.00	109.57	00.00	109.5
M RH/F STEE	ERING KNUC	KLE	I	xcess:51 Zeveri	50	1.00	1261.19	00.00	1261.1
M RH/F WHEE	EL HUB 🔼		ŧ	7 ((1)		1.00	747.27		747.2
M RH/F LOWE				· .		1.00	502.50		502.5
M RH/F BALL	_ JOINT 🏅			loulle		1.00	143.81		143.8
M RH/F TRUS	ST ARM 🏅	7	'	cere i		1.00	517.64		517.6
M RH/F TRUS	ST ARM BUS	HING .				1.00	111.45		111.4
M STEERING	ASSEMBLY	7.				1.00	8012.26	00.00	8012.2
			Cycle & Carriag	Quek e Industries Pie L	kd				
		DID:	6771 4377 HP: 9	t Repair Center 186 5112 Fax: 6	372 1272				
			lmail: alan.quek@						
Confirmed &	accepted by							N I - 44	20 700 64
						30/ 6 3		Nett	29,789.6
						7% GS	sion 29	789.65	2085.2
									04.074.0
		company stamp					Total P	ayable	31,874.9

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

> Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg

LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: