

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG19002895/JEA3Q2

**Date:** 24/04/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800043689

**Claimant**  
**Vehicle No :** SHB774U **Insured Vehicle No :** SJP8992G

Date of Loss: 11/02/2019 Nature of Claim: TP Claim No: 2812226837SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHB774U</b>	Engine No:	2ZR1459206
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Chassis No:	JTDKN36U805753218
Reg. Date:	02/12/2014 (Man. Year: 2014)	Odometer:	457066 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	875.48	760.83	114.65	13.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	956.00	420.00	536.00	56.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>1,831.48</b>	<b>1,180.83</b>	<b>650.65</b>	<b>35.53</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,100.00</b>		
<b>Nett Amount (\$\$)</b>	<b>1,831.48</b>	<b>1,100.00</b>	<b>731.48</b>	<b>39.94</b>
<b>+ Loss of Use (4.0 x S\$50.00/day) (\$\$)</b>		200.00		
<b>+ Car Rental (4.0 x S\$104.86/day) (\$\$)</b>		419.44		
<b>+ Doc/Search Fee (\$\$)</b>		7.00		
<b>Nett Liability (\$\$)</b>		<b>1,726.44</b>		

### INSPECTION

Date of Assignment: 13/02/2019

Date Inspected: 13/02/2019 Inspected At:

SMRT Automotive Services Pte Ltd  
(Woodlands)  
60 Woodlands Industrial Park E4  
Singapore 757705

Estimated Period of Repair: 2.0 days

**Adjuster:** ONG HWEE JIE**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER REAR (DISC 25%)	Deformed	458.60 F	*343.95 F
2	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
3	1		*ADVERTISEMENT STICKER (SN)	Necessary	296.88 F	*296.88 F
F=Franchise part.						
<b>Total Parts (\$\$)</b>					<b>875.48</b>	<b>760.83</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING & BODY WORK	New	338.00	200.00
2	SPRAY PAINT	New	378.00	200.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
4	TO WASH AND VACUUM	New	60.00	0.00
5	TO REPLACE SUNDRY PARTS	New	100.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>956.00</b>	<b>420.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >