

INS. CASE OWNER:

RA

CC 4, Asm 1900 2964, Jaka352

LKK: 99030
IDAC:

Surveyor:

OHJ

DOI:

ASSIGNMENT


18/1/19

Date / Time:

18/1/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : SHP 681H

Claim No. : S 9 M 01 D S F 6 x

Name of Insured : TIC SVS PLC

Policy No. :

Insured Tel No. : HP: 5,000-00

Make / Model : Vans Ave 2

Excess Sec II : SS D.O.A : 13/1/19

Place of Accident :

Is driver the owner? (YES NO) Nature of Accident :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

If NO, Driver Name / Age :

Insured Liability : % Final ? Yes / No

Driver Tel No. :

(V/L: YES / NO)

GBO 720/c



INRS: WSP: smpt.m
Tel:
Liability:
RMKS:



INRS: WSP:
Tel:
Liability:
RMKS:



INRS: WSP:
Tel:
Liability:
RMKS:



INRS: WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE / PIC
11/3	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
05/04/19	After call ltr to OI:	05/04/19 - JIC
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice	<input checked="" type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/>
	Medical Bill:	<input checked="" type="checkbox"/>
	PIR:	<input checked="" type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input checked="" type="checkbox"/>
	Post-Repair Photos:	<input checked="" type="checkbox"/>
	Others:	<input type="checkbox"/>
PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost: LGS	SS \$9250.00 (7 days) Reduction: \$10,678.36 % 54	Confirm by: Steve / Steve
FINAL SETTLEMENT	Date/Time: 18/1/19	Confirm with: ESTHER
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No. :	Email <input type="checkbox"/> Call <input type="checkbox"/>
Repair Cost: (w/GST)	SS \$9297.50	
Loss of Rental (LOR):	SS \$642.00 (10 days) x \$64.20 (w/GST)	
Loss of Use (LOU):	SS - (\$ x - days)	
Loss of Income (LOI):	SS - (\$ x days)	
LOR only <input checked="" type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]	
GIA/LTA Search	SS -	
Medical:	SS -	
Disbursement:	SS - (e.g. Tow/ Independent)	
Legal Cost	SS -	
Total:	SS 10,539.50	Global Sum SS: 10,530.00
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	SS 10,530.00	Name 1: SMRT Automotive Services Pte Ltd.
Payee 2: (Strike if N.A.)	SS	Name 2:
Payee 3: (Strike if N.A.)	SS	Name 3:

COPY SENT

✓ GIA

REFERENCE NUMBER	
DATE / TIME	ACTIONS / REMARKS
18/12	- settle @ GTS \$10,530.00, DV send (pending DV in).
	- DV in, File pass MK to close.

Hwee Jie

REF: AXA

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop n/s: _____
 of _____
 Insured _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 7 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GBD720K Yr Regn: 21 May 2014
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota DYNA c.c 2982
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 244392 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTFAT35Y80K203D46
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / STRim / STD A/Rim or _____
 Tyre Size: F: 195R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or OHTSU
 Front _____ Rear _____
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. 13/2/19 D.O.I. 18/2/19
 Survey held at Carz Auto
 Des. of Damages: Frnt Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MU - \$38000
	PV - \$18991
	NV - \$19009
	HS \$9250 - (Red = \$10,678.36 / 54%)
	* 7 repair days + 1 Sunday + 2 PRS = 10 days + 1 Sat = 11 days.

Date/Time. File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time. File Returns to? _____
 2) _____

Days Of Repair: _____
 Resurvey No. of Trip: _____
 Survey Fee: _____
 Transportation: _____
) \$ + PS. SI
) Phues
) Other:

Report Format : _____
 Lump Sum / I.B.I: (\$ _____)

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

TOTAL _____

Cecilia




SMRT Automotive Services Pte Ltd
50 Woodlands Industrial Park E4
Singapore 757705
Tel: 65 6362 3422
Fax: 65 6368 7420

SMRT Vehicle Repair Estimate

Group : Buses / Taxis / Private Car
 Reg. No. : GBD 720 K
 Make / Model : TOYOTA DYNA
 Chassis No : JTFAT35Y80K203046
 Name of Driver : UNIFIED OFFSHORE ENGINEERING PTE LTD
 Date/Time of Accident : 13/02/2019 / 07:50AM
 Surveyer is Required ? YES / NO
 If Yes, VICOM / LKK / AIS / Others MSIG : _____
 Vehicle is Towed Back ? YES / NO Date / Time : _____
 Accident reporting date : 13/02/2019 07:50
 Type of Accident : Skid / Head-Rear / Head-On / Side Swipe / Others
 Special Instruction to ARC, if any :
TP CLAIM AXA

Ref. No. _____
 Reg. Date : 21/05/2014
 Mileage _____
 Rental/Replacement Vehicle : Yes / No



Signed : _____ Date : _____

Accident Repair Job Card No : _____ Date Prepared : _____
 Summary of Repair Estimates Repair Completed : _____

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	\$ <u>1,300.00</u>	\$ _____
Total Spray Painting Charges :	\$ <u>1,000.00</u>	\$ _____
Total Material Charges :	\$ <u>16,398.36</u>	\$ _____
Other Charges :	\$ <u>1,230.00</u>	\$ _____
TOTAL :	\$ <u>19,928.36</u>	\$ _____

Lump Sum Repair, if any : _____
 No. of Repair Days : [10] days [_____] days

Signature : Prepared by: _____ Adjusted by: _____

QN No. _____ Invoice No. _____
 Signed : _____ Date : _____

Part 4 - Spare Parts / Material Usage

To be completed by Service Advisor, ARC							
Part Number	Parts Description	Qty	Cost Price (\$)	less 25%	Final Price (\$)	Repair (R) Replace (/)	Not given (X) Repair (R) Replace (/)
	FRONT BUMPER DEF	1	\$ 786.20	25%	\$ 589.65	/	
	FRONT BUMPER BRACKET DD	2	\$ 510.80	25%	\$ 383.10	/	
	FRONT RADIATOR GRILLE DEF	1	\$ 582.70	25%	\$ 437.03	/	
	FRONT RADIATOR GRILLE LOGO NEL	1	\$ 95.80	25%	\$ 71.85	/	
	FRONT CABIN PANEL DD	1	\$ 1,420.20	25%	\$ 1,065.15	/	
	FRONT WIPER PANEL NN Repair	1	\$ 459.10	25%	\$ 344.33	X	
	FRONT CABIN PANEL PROTECTOR NN NN	1	\$ 235.80	25%	\$ 176.85	X	
NN	FRONT WIPER PANEL SIDE BRACKET LH CRA	1	\$ 125.10	25%	\$ 93.83	/	
	FRONT CORNER PANEL LH MIS	1	\$ 285.20	25%	\$ 213.90	/	
	FRONT CORNER PANEL BRACKET LH CRA	1	\$ 158.60	25%	\$ 118.95	/	
	FRONT CORNER PANEL PROTECTOR LH CRA	1	\$ 155.40	25%	\$ 116.55	/	
	FRONT HEADLAMP LH CRA	1	\$ 975.90	25%	\$ 731.93	/	
	FRONT HEADLAMP SIDE BRACKET NN	1	\$ 155.20	25%	\$ 116.40	X	
	FRONT DOOR LH BUC	1	\$ 1,608.20	25%	\$ 1,206.15	/	
	FRONT DOOR TRIM BOARD LH NN NN	1	\$ 585.10	25%	\$ 438.83	X	
	FRONT DOOR HINGE LH NN	2	\$ 220.40	25%	\$ 165.30	X	
	FRONT DOOR LOWER SEAL LH Custom	1	\$ 189.90	25%	\$ 142.43	X	
	FRONT DOOR TRIM BOARD SWITCH LH NN	1	\$ 309.70	25%	\$ 232.28	X	
	FRONT DOOR WEATHERSTRIP LH NN	1	\$ 415.10	25%	\$ 311.33	X	
	FRONT DOOR INNER LOCK LH Slotted	1	\$ 375.10	25%	\$ 281.33	/	
	FRONT DOOR CENTER LOCK MOTOR LH SVC	1	\$ 189.60	25%	\$ 142.20	X	
	FRONT DOOR GLASS LH NN	1	\$ 725.10	25%	\$ 543.83	X	
CUT	FRONT DOOR GLASS OUTER MOULDING LH	1	\$ 125.70	25%	\$ 94.28	/	
	FRONT DOOR SIDE COVER LH NN	1	\$ 108.20	25%	\$ 81.15	X	
	FRONT DOOR GLASS RUN RUBBER LH NN	1	\$ 202.60	25%	\$ 151.95	X	
NN	FRONT DOOR GLASS REGULATOR GEAR LH	1	\$ 375.90	25%	\$ 281.93	X	
NN	FRONT DOOR GLASS REGULATOR MOTOR LH	1	\$ 553.20	25%	\$ 414.90	X	
	FRONT DOOR STEP PANEL LH NN NN	1	\$ 455.10	25%	\$ 341.33	X	
	FRONT DOOR STEP PANEL GARNISH LH SCR	1	\$ 408.60	25%	\$ 306.45	/	
	FRONT SIDE MIRROR GLASS LH NN	1	\$ 685.70	25%	\$ 514.28	X	
	FRONT SIDE MIRROR ROUND LH NN	1	\$ 407.10	25%	\$ 305.33	X	
	FRONT SIDE MIRROR BRACKET LH CRA	1	\$ 550.30	25%	\$ 412.73	/	
	FRONT SIDE MIRROR GLASS SMALL LH NN	1	\$ 245.10	25%	\$ 183.83	X	
	FRONT SIDE MIRROR BRACKET TOP COVER LH MIS	1	\$ 95.20	25%	\$ 71.40	/	
	FRONT WINDSCREEN GLASS RUBBER EUT	1	\$ 305.20	25%	\$ 228.90	/	
	FRONT A/C FAN ASSY CRA	1	\$ 1,323.50	25%	\$ 992.63	/	
	FRONT A/C CONDENSER BT	1	\$ 1,407.10	25%	\$ 1,055.33	/	
	FRONT A/C CONDENSER BRACKET NN	3	\$ 917.10	25%	\$ 687.83	X	
	FRONT A/C CONDENSER LIQUID PIPE BT	2	\$ 990.40	25%	\$ 742.80	/	
NN	FRONT A/C BLOWER MOTOR WITH HOUSING	1	\$ 1,890.95	25%	\$ 1,418.21	X	

Special Nett Items	Parts Description	Qty	Cost Price (\$)	Discount	Final Price (\$)	Repair (R)	Not given (X)
						Replace (/)	Repair (R)
	FRONT BUMPER CLIP <i>NEC</i>	8	\$ 40.00	-	\$ 30 40.00	/	
	FRONT RADIATOR GRILLE CLIP	10	\$ 50.00	-	\$ 50.00	X	
	FRONT WIPER PANEL CLIP <i>NEC</i>	10	\$ 50.00	-	\$ 30 50.00	/	
	FRONT DOOR LTA STICKER LH <i>NEC</i>	1	\$ 50.00	-	\$ 50.00	/	
TOTAL MATERIALS			\$ 21,801.15	-	\$ 16,398.36		

P-9466-37

Surveyor Remark:

*Have Joe - LKK
12/2/19
L/S #days
7
[Signature]*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Part 1 - Labour Works

Job Scope	Quotation from ARC	
To renew damaged parts, replace and realign hydraulic, and aligned all parts	\$	1,300.00
Total Labour Cost	\$	1,300.00 59800

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	
To respray affected areas	\$	1,000.00
Spray Painting	\$	1,000.00 800

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC			
To tuffcoat affect areas	\$	250.00	100	N/C
To renew front/ windscreen glass	\$	150.00	120	N/C
To remove /refit aircon condenser, pipings, vacuum and recharge aircon gas	\$	150.00	80	N/C
To remove/refit dashboard	\$	350.00	X	N/N
To remove and refit interior upholstery	\$	150.00	X	N/N
To remover /refit wiring check	\$	60.00	30	N/C
To remove/replace door mechanism (LH)	\$	120.00	50	N/C
Total Other Costs	\$	1,230.00		


N-380

P- 9466.37
 N- 380
 L- 1700
 11,546.37
 L/S - 9237.09
 = 9250

SMRT Vehicle Repair Estimate

Group : <u>Buses / Taxis / Private Car</u> Reg. No. : <u>GBD 720 K</u> Make / Model : <u>TOYOTA DYNA</u> Chassis No : <u>JTFAT35Y80K203046</u> Name of Driver : <u>UNIFIED OFFSHORE ENGINEERING PTE LTD</u> Date/Time of Accident : <u>13/02/2019 / 07:50AM</u> Surveyor is Required ? <u>YES / NO</u> If Yes, VICOM / LKK / AIS / Others MSIG : _____ Vehicle is Towed Back ? <u>YES / NO</u> Date / Time : _____ Accident reporting date : <u>13/02/2019 07:50</u> Type of Accident : <u>Skid / Head-Rear / Head-On / Side Swipe / Others</u> Special Instruction to ARC, if any : <u>TP CLAIM AXA</u>	Ref. No. : _____ Reg. Date : <u>21/05/2014</u> Mileage : _____ Rental/Replacement Vehicle : _____ Yes / No
--	---

The damages on the vehicle are as indicated in the following diagram :



Signed : _____ Date : _____

Accident Repair Job Card No : _____ Summary of Repair Estimates	Date Prepared : _____ Repair Completed : _____	Adjusted by Surveyor, if applicable \$ _____ \$ _____ \$ _____ \$ _____ \$ _____
Quotation from ARC		
Total Labour Charges : \$ _____ Total Spray Painting Charges : \$ _____ Total Material Charges : \$ _____ Other Charges : \$ _____ TOTAL : \$ _____	1,300.00 1,000.00 16,398.36 1,230.00 19,928.36	
Lump Sum Repair, if any : _____ No. of Repair Days : [10] days Signature : Prepared by: _____		_____ [] days Adjusted by: _____

QN No. _____ Invoice No. _____
 Signed : _____ Date : _____

Part 4 - Spare Parts / Material Usage

To be completed by Service Advisor, ARC

Part Number	Parts Description	Qty	Cost Price (\$)	less 25%	Final Price (\$)	Repair (R) Replace (/)	Not given (X) Repair (R) Replace (/)
	FRONT BUMPER DEF	1	\$ 786.20	25%	\$ 589.65	/	
	FRONT BUMPER BRACKET DD	2	\$ 510.80	25%	\$ 383.10	/	
	FRONT RADIATOR GRILLE DEF	1	\$ 582.70	25%	\$ 437.03	/	
	FRONT RADIATOR GRILLE LOGO NEL	1	\$ 95.80	25%	\$ 71.85	/	
	FRONT CABIN PANEL DD	1	\$ 1,420.20	25%	\$ 1,065.15	/	
	FRONT WIPER PANEL MM Repair	1	\$ 459.10	25%	\$ 344.33	X	
	FRONT CABIN PANEL PROTECTOR CRA NN	1	\$ 235.80	25%	\$ 176.85	X	
CRA DM	FRONT WIPER PANEL SIDE BRACKET LH CRA	1	\$ 125.10	25%	\$ 93.83	/	
	FRONT CORNER PANEL LH MIS	1	\$ 285.20	25%	\$ 213.90	/	
	FRONT CORNER PANEL BRACKET LH CRA	1	\$ 158.60	25%	\$ 118.95	/	
	FRONT CORNER PANEL PROTECTOR LH CRA	1	\$ 155.40	25%	\$ 116.55	/	
	FRONT HEADLAMP LH CRA	1	\$ 975.90	25%	\$ 731.93	/	
	FRONT HEADLAMP SIDE BRACKET NN	1	\$ 155.20	25%	\$ 116.40	X	
	FRONT DOOR LH BUC	1	\$ 1,808.20	25%	\$ 1,206.15	/	
	FRONT DOOR TRIM BOARD LH MM NN	1	\$ 585.10	25%	\$ 438.83	X	
	FRONT DOOR HINGE LH NN	2	\$ 220.40	25%	\$ 165.30	X	
	FRONT DOOR LOWER SEAL LH CUT MM	1	\$ 189.90	25%	\$ 142.43	X	
	FRONT DOOR TRIM BOARD SWITCH LH NN	1	\$ 309.70	25%	\$ 232.28	X	
	FRONT DOOR WEATHERSTRIP LH NN	1	\$ 415.10	25%	\$ 311.33	X	
	FRONT DOOR INNER LOCK LH sluted	1	\$ 375.10	25%	\$ 281.33	/	
	FRONT DOOR CENTER LOCK MOTOR LH SUC	1	\$ 189.60	25%	\$ 142.20	X	
	FRONT DOOR GLASS LH NN	1	\$ 725.10	25%	\$ 543.83	X	
CUT	FRONT DOOR GLASS OUTER MOULDING LH	1	\$ 125.70	25%	\$ 94.28	/	
	FRONT DOOR SIDE COVER LH NN	1	\$ 108.20	25%	\$ 81.15	X	
	FRONT DOOR GLASS RUN RUBBER LH NN	1	\$ 202.60	25%	\$ 151.95	X	
NN	FRONT DOOR GLASS REGULATOR GEAR LH	1	\$ 375.90	25%	\$ 281.93	X	
NN	FRONT DOOR GLASS REGULATOR MOTOR LH	1	\$ 553.20	25%	\$ 414.90	X	
	FRONT DOOR STEP PANEL LH SCR NN	1	\$ 455.10	25%	\$ 341.33	X	
	FRONT DOOR STEP PANEL GARNISH LH SCR	1	\$ 408.60	25%	\$ 306.45	/	
	FRONT SIDE MIRROR GLASS LH NN	1	\$ 685.70	25%	\$ 514.28	X	
	FRONT SIDE MIRROR ROUND LH NN	1	\$ 407.10	25%	\$ 305.33	X	
	FRONT SIDE MIRROR BRACKET LH CRA	1	\$ 550.30	25%	\$ 412.73	/	
	FRONT SIDE MIRROR GLASS SMALL LH NN	1	\$ 245.10	25%	\$ 183.83	X	
	FRONT SIDE MIRROR BRACKET TOP COVER LH MIS	1	\$ 95.20	25%	\$ 71.40	/	
	FRONT WINDSCREEN GLASS RUBBER BUT	1	\$ 305.20	25%	\$ 228.90	/	
	FRONT A/C FAN ASSY CRA	1	\$ 1,323.50	25%	\$ 992.63	/	
	FRONT A/C CONDENSER BT	1	\$ 1,407.10	25%	\$ 1,055.33	/	
	FRONT A/C CONDENSER BRACKET NN	3	\$ 917.10	25%	\$ 687.83	X	
	FRONT A/C CONDENSER LIQUID PIPE BT	2	\$ 990.40	25%	\$ 742.80	/	
NN	FRONT A/C BLOWER MOTOR WITH HOUSING	1	\$ 1,890.95	25%	\$ 1,418.21	X	

Special Nett Items	Parts Description	Qty	Cost Price (\$)	Discount	Final Price (\$)	Repair (R)	Not given (X)
						Replace (/)	Repair (R)
	FRONT BUMPER CLIP <i>NEC</i>	8	\$ 40.00	-	\$ 30 40.00	/	
	FRONT RADIATOR GRILLE CLIP <i>NH</i>	10	\$ 50.00	-	\$ 50.00	X	
	FRONT WIPER PANEL CLIP <i>NEC</i>	10	\$ 50.00	-	\$ 30 50.00	/	
	FRONT DOOR LTA STICKER LH <i>NEC</i>	1	\$ 50.00	-	\$ 50.00	/	
TOTAL MATERIALS			\$ 21,801.15	-	\$ 16,398.36		

Surveyor Remark:

*Have Job - LKK
18/2/19
L/S 5 days
[Signature]*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Part 1 - Labour Works

Job Scope	Quotation from ARC	
To renew damaged parts, replace and realign hydraulic, and aligned all parts	\$ 1,300.00	
Total Labour Cost	\$ 1,300.00	\$9800

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	
To respray affected areas	\$ 1,000.00	
Spray Painting	\$ 1,000.00	\$800

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	
To tuffcoat affect areas	\$ 250.00	\$100
To renew front/ windscreen glass	\$ 150.00	\$120
To remove /refit aircon condensor, pipings, vacuum and recharge aircon gas	\$ 150.00	\$80
To remove/refit dashboard	\$ 350.00	*? X
To remove and refit interior upholstery	\$ 150.00	! X
To remover /refit wiring check	\$ 60.00	30
To remove/replace door mechanism (LH)	\$ 120.00	50
Total Other Costs	\$ 1,230.00	

19928.464

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2502D
Vehicle Details	
Vehicle No.:	GBD720K
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA DYNA 150 MANUAL
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	1KD2400542
Chassis No.:	JTFAT35Y80K203046
Maximum Power Output:	-
Open Market Value:	\$27,856.00
Original Registration Date:	21 May 2014
First Registration Date:	21 May 2014
Transfer Count:	3
Actual ARF Paid:	\$1,393.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	20 May 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$36,301.00
COE Rebate Amount:	\$18,991.00
Total Rebate Amount:	\$18,991.00

The information contained herein is correct as at 26 Feb 2019

OK

CHEAPEST CAR INSURANCE RENEWAL



Choice of \$0 excess



Option of any workshop

GET A CHEAPER QUOTE NOW

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

New 5 Years Coe Renewal Honda Fit 1.3A



2.38% P.A Low Interest @ Gv Finance. \$0 Admin Fees. \$1500 Downpayment Monthly \$468 GV Credit Pte Ltd StarAd



CERTIFIED PRE-OWN MERCEDES-BENZ

[View our cars](#)

Browse by Category Sort by Date Posted 40 results/

12 vehicles

dyna

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Stat
Search Selection dyna		Any	Any	2014	Any	Any	Any	Av
	Toyota Dyna 150 Fuel Type: Diesel 10 Feet Reliable Truck In Town. Well Maintained. Excellent Reliability. Act Now To Grab This Excellent Vehicle. Call Our Friendly Sales Representatives Now To Arrange For A Viewing And For A Consultat...	\$39,800	\$7,490 /yr	19-Jun-2014	2,982 cc	-	Truck	Av
Posted: 31-Jan-2019 Tags: 2014 Toyota Dyna, 2014 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota								
	Toyota Dyna 150 Fuel Type: Diesel 1 Owner, Extremely Good Condition. Low Mileage. Many Units Available. Comes With Full Canopy. High Loan Welcome. High Trade In Value. Buy One Instead Of Renting! Optional Accesories (Box, Chequered Pl...	\$41,800	\$7,590 /yr	29-Aug-2014	2,982 cc	-	Truck	Av
Car (S) Pte Ltd Posted: 25-Feb-2019 Tags: 2014 Toyota Dyna, 2014 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota								
	Toyota Dyna 150 Fuel Type: Diesel Comes With A New Paintwork, Repairs Done Up, Flexible And Fast High Loan Financing Available Easily, High Trade-In Value For Existing Vehicle! Genuine Pricing, No Hidden Fees! Call Any Of Our Friendly...	\$41,000	\$7,430 /yr	02-Sep-2014	2,982 cc	-	Truck	Av
Posted: 09-Feb-2019 Tags: 2014 Toyota Dyna, 2014 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota								
	BMW 3 Series 320i Efficient Dynamics Latest Model! Full Agent Serviced Unit! Low Mileage! High Loan/Trade In.	\$85,800	\$12,480 /yr	30-Sep-2014	1,598 cc	80,000 km	Luxury	Av
Posted: 23-Feb-2019 Tags: 2014 BMW 320i, 2014 bmw 320i, BMW 320i, bmw 320i, BMW, 320i, Used BMW								
	Range Rover debuts limited edition Velar The SVAutobiography Dynamic Edition builds on the Velar's elegant simplicity with heightened levels of luxury and comfort. Read this article							
	BMW 3 Series 320i Efficient Dynamics Cheapest In The Market, AP RACING 6/4 BRAKES, M-Sport, M3 Rims, BC Coils. M3 Fully Kitted Grey With Black Leather Interior, Full PML Serviced Records, Well Maintained By Previous Owner. PML Warranty Till 5...	\$88,800	\$13,010 /yr	30-Sep-2014	1,598 cc	84,915 km	Luxury	Av
Posted: 22-Feb-2019 Tags: 2014 BMW 320i, 2014 bmw 320i, BMW 320i, bmw 320i, BMW, 320i, Used BMW								
	BMW 3 Series 320i Efficient Dynamics Most Efficient Low Genuine Mileage. Sporty Design With Super Fuel Efficiency. Showroom Condition. Genuine Deal. Us Now For More Details. Consignment Unit!	\$81,800	\$11,760 /yr	30-Sep-2014	1,598 cc	-	Luxury	Av
Posted: 28-Jan-2019 Tags: 2014 BMW 320i, 2014 bmw 320i, BMW 320i, bmw 320i, BMW, 320i, Used BMW								

SATISFACTION FORM

I, Unified Offshore Engineering Pte Ltd, hereby acknowledge having received from SMRT Automotive Services Pte Ltd my vehicle bearing registration number G800 720K, which has been repaired to my satisfaction and acceptance. And I agree that the payment of the account for such repairs to SMRT Automotive Services Pte Ltd. shall be in full discharge of all claims under policy number 5103140062 in respect of the damage caused in the accident which occurred on 13/2/19.



Signature, NRIC No. & Date



Co. Stamp (If applicable)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 16/12/2019

Survey Details:

Date of loss	13-Feb-19
Date of appointment	18-Feb-19
Date of survey	18-Feb-19
Location of survey	SMRT, WL

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	GBD720K
Make and Model	TOYOTA DYNA 150 MANUAL - 2982cc
Date of registration	21-May-14
Parf Rebate	
Market Value	\$ 38,000.00
Parf Rebate	\$ 19,077.00
Nett Loss	\$ 18,923.00

Repair details:

Initial Estimate	19,928.36
------------------	-----------

Proposed/Revised repair cost:

Parts	\$ 9,466.37
Check items (estimate)	\$ -
Labour	\$ 2,080.00
Total	\$ 11,546.37
Lump Sum(if applicable)	\$ 9,250.00

Number of days for repair	7 days
---------------------------	---------------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

07 RECOMMENDED REPAIR DAYS + 1 SUNDAY + 1 SAT + 2PRS = 11
DAYS

Mandate:

Liability(TP)		100%	
Proposed repair cost	\$	9,897.50	W/GST
Loss of use	\$	-	
Loss of rental (W/GST)	\$	1,177.00	11 days x \$107.00
Loss of income	\$	-	
LTA search fees	\$	-	
Others		-	
Proposed Total		11,074.50	

 <MANDATE IA> - S9M01DSF {ACCIDENT INVOLVING SHF 681H & GBD 720K ON 13/02/2019}

Type

 Question

Message

LIABILITY: 100% (OI MAKING U TURN ON 1ST LANE WHEN TPV AT 2ND LANE ON OI'S RIGHT) - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$11,074.50 (CLAIMING LOR). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL

[Reply](#)



Re:<MANDATE IA> - S9M01DSF {ACCIDENT INVOLVING SHF 681H & GBD 720K ON 13/02/2019}

Type

🔔 Question

Message

Hi, pls proceed as per mandate. TY.

Reply



SMRT AUTOMOTIVE SERVICES PTE LTD
60 Woodlands Industrial Park E4
Singapore 757705
Tel : 65 6482 3888
Fax : 65 6368 7421
www.smrt.com.sg

AXA INSURANCE SINGAPORE PTE LTD
AXA Tower
8 Shenton Way
#27-01/02
Singapore 068811

MOTOR CLAIMS DEPT

Our Ref.: GBD720K WL/FEB2019/010
Your Ref.: SHF681H

Dear Sirs / Madam,

ACCIDENT INVOLVING GBD720K AND SHF681H ON 13 FEBRUARY 2019

LETTER OF CLAIM

We claim on behalf of WOON QIU JIE owner of the vehicle No.: SHF681H. Your driver's negligent driving has caused the above accident. As a result, my client has suffered the following losses:-


1. Cost of Repair	:	\$ 9,897.50 with GST
2. Loss of Use for ____ days @ S\$ ____ /day	:	-
3. Loss of Rental for 13 days @ S\$ 110 /day	:	\$ 1,530.10 with GST
4. Loss of Income for ____ days @ S\$ ____ /day	:	-
5. Police Report/ SAS Report/ LTA Search Fee	:	-
6. Survey Fee	:	-
Total Claims :		\$ 11,427.60

We enclose the following documents:

- | | |
|--|---|
| <input type="checkbox"/> Repair Invoice | <input checked="" type="checkbox"/> Letter of Authorisation |
| <input type="checkbox"/> Survey Report | <input type="checkbox"/> LTA Search result |
| <input type="checkbox"/> Photographs _____ pcs | <input type="checkbox"/> Others : |
| <input type="checkbox"/> Investigation results | 1. <u>Satisfaction Form</u> |
| <input checked="" type="checkbox"/> Proof of Loss of Use/Rental/Income | 2. _____ |
| <input type="checkbox"/> Police / SAS report of _____ | 3. _____ |

We look forward to your confirmation to settle our claims within 15 days from the date of this letter. Payment by cheque shall be crossed and made payable to SMRT AUTOMOTIVE SERVICES PTE LTD for amount of \$11,427.60.

Yours sincerely,
SMRT AUTOMOTIVE SERVICES PTE LTD



For Manager,
Claims Department

FR-AS-CLM-02 REV 1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19002964/Jga3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 27-12-2019



ATTN: RICHARD ANG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHF 681H	Veh. Inspected	GBD 720K
Policy No.	VPX/P1680520	Coverage (\$)	0.00
Claim No.	S9M01DSF	Excess (\$)	0.00
Assign From	RICHARD ANG	Assign Date	18/02/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTFAT35Y80K203046	Colour	WHITE
Odometer	244392	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	OHTSU	7 mm
L/H Front Tyre	195 R15	OHTSU	7 mm
R/H Rear Tyre	195 R15	OHTSU	7 mm
L/H Rear Tyre	195 R15	OHTSU	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/02/2019	Inspection Date	18/02/2019
Survey held at	CARZ AUTO - 1 KAKI BUKIT AVE 6 #02-26 S'POR 417883		
Repairer	SMRT AUTOMOTIVE SERVICES PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 720K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER (CONSISTENT)	DEFORMED	589.65	589.65
2	FRONT BUMPER BRACKET (CONSISTENT)	DENTED	383.10	383.10
1	FRONT RADIATOR GRILLE (CONSISTENT)	DEFORMED	437.03	437.03
1	FRONT RADIATOR GRILLE LOGO (CONSISTENT)	NECESSARY	71.85	71.85
1	FRONT CABIN PANEL (CONSISTENT)	DENTED	1,065.15	1,065.15
1	FRONT WIRE PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	344.33	-
1	FRONT CABIN PANEL PROTECTOR (CONSISTENT)	NOT NECESSARY	176.85	-
1	FRONT WIRE PANEL SIDE BRACKET LH (CONSISTENT)	CRACKED	93.83	93.83
1	FRONT CORNER PANEL LH (CONSISTENT)	MISSING	213.90	213.90
1	FRONT CORNER PANEL BRACKET LH (CONSISTENT)	CRACKED	118.95	118.95
1	FRONT CORNER PANEL PROTECTOR LH (CONSISTENT)	CRACKED	116.55	116.55
1	FRONT HEADLAMP LH (CONSISTENT)	CRACKED	731.93	731.93
1	FRONT HEADLAMP SIDE BRACKET (CONSISTENT)	NOT NECESSARY	116.40	-
1	FRONT DOOR LH (CONSISTENT)	BUCKLED	1,206.15	1,206.15
1	FRONT DOOR TRIM BOARD LH (CONSISTENT)	NOT NECESSARY	438.83	-
2	FRONT DOOR HINGE LH (CONSISTENT)	NOT NECESSARY	165.30	-
1	FRONT DOOR LOWER SEAL LH (CONSISTENT)	CUT	142.43	142.43
1	FRONT DOOR TRIM BOARD SWITCH LH (CONSISTENT)	NOT NECESSARY	232.28	-
1	FRONT DOOR WEATHERSTRIP LH (CONSISTENT)	NOT NECESSARY	311.33	-
1	FRONT DOOR INNER LOCK LH (CONSISTENT)	SHORTED	281.33	281.33
1	FRONT DOOR CENTER LOCK MOTOR LH (CONSISTENT)	SERVICEABLE	142.20	-
1	FRONT DOOR GLASS LH (CONSISTENT)	NOT NECESSARY	543.83	-
1	FRONT DOOR GLASS OUTER MOULDING LH (CONSISTENT)	CUT	94.28	94.28
1	FRONT DOOR SIDE COVER LH (CONSISTENT)	NOT NECESSARY	81.15	-
1	FRONT DOOR GLASS RUN RUBBER LH (CONSISTENT)	NOT NECESSARY	151.95	-
1	FRONT DOOR GLASS REGULATOR GEAR LH (CONSISTENT)	NOT NECESSARY	281.93	-
1	FRONT DOOR GLASS REGULATOR MOTOR LH (CONSISTENT)	NOT NECESSARY	414.90	-
1	FRONT DOOR STEP PANEL LH (CONSISTENT)	NOT NECESSARY	341.33	-

Report Ref No. CC4/ASM19002964/Jga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT DOOR STEP PANEL GARNISH LH (CONSISTENT)	SCRATCHED	306.45	306.45
1	FRONT SIDE MIRROR GLASS LH (CONSISTENT)	NOT NECESSARY	514.28	-
1	FRONT SIDE MIRROR ROUND LH (CONSISTENT)	NOT NECESSARY	305.33	-
1	FRONT SIDE MIRROR BRACKET LH (CONSISTENT)	CRACKED	412.73	412.73
1	FRONT SIDE MIRROR GLASS SMALL LH (CONSISTENT)	NOT NECESSARY	183.83	-
1	FRONT SIDE MIRROR BRACKET TOP COVER LH (CONSISTENT)	MISSING	71.40	71.40
1	FRONT WINDSCREEN GLASS RUBBER (CONSISTENT)	CUT	228.90	228.90
1	FRONT A/C FAN ASSY (CONSISTENT)	CRACKED	992.63	992.63
1	FRONT A/C CONDENSER (CONSISTENT)	BENT	1,055.33	1,055.33
3	FRONT A/C CONDENSER BRACKET (CONSISTENT)	NOT NECESSARY	687.83	-
2	FRONT A/C CONDENSER LIQUID PIPE (CONSISTENT)	BENT	742.80	742.80
1	FRONT A/C BLOWER MOTOR WITH HOUSING (CONSISTENT)	NOT NECESSARY	1,418.21	-
			16,208.46	9,356.37
<u>SPECIAL NETT ITEMS</u>				
8	FRONT BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	40.00	30.00
10	FRONT RADIATOR GRILLE CLIP (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
10	FRONT WIPER PANEL CLIP (SN) (CONSISTENT)	NECESSARY	50.00	30.00
1	FRONT DOOR LTA STICKER LH (SN) (CONSISTENT)	NECESSARY	50.00	50.00
			190.00	110.00
<u>LABOUR</u>				
TO RENEW DAMAGED PARTS, REPLACE AND REALIGN HYDRAULIC, AND ALIGNED ALL PARTS. INCLUSIVE OF THE REPAIR OF FRONT WIRE PANEL.			1,300.00	900.00
TO RESPRAY AFFECTED AREAS.			1,000.00	800.00
TO TUFF COAT AFFECT AREAS.			250.00	100.00
TO RENEW FRONT / WINDSCREEN GLASS.			150.00	120.00
TO REMOVE / REFIT AIRCON CONDENSOR, PIPINGS, VACUUM AND RECHARGE AIRCON GAS.			150.00	80.00
TO REMOVE / REFIT DASHBOARD.			350.00	-
TO REMOVE AND REFIT INTERIOR UPHOLSTERY.			150.00	-
TO REMOVE / REFIT WIRING CHECK.			60.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE / REPLACE DOOR MECHANISM (LH)		120.00	50.00
			3,530.00	2,080.00
	GRAND TOTAL		19,928.46	11,546.37
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,250.00

Report Ref No. CC4/ASM19002964/Jga3s2

ONG HWEE JIE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.