

REPAIR ESTIMATE*

AXA

VEHICLE NO : SHC 8518K

DATE 16/2/2019 11:47

MAKE :

MODEL : HYUNDAI i40

LS

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>X 1/2</i>			\$ 544.50
	Front Bumper Bracket (LH) <i>X 1/2</i>			\$ 24.60
	Headlamp (LH) <i>X 1/2</i>			\$ 1,388.00
	Front Fender (LH) <i>- 1/2</i>			\$ 566.30
	Front Fender Shield (LH) <i>X 1/2</i>			\$ 175.90
	SUB TOTAL			\$ 2,699.30
	LESS 20%			\$ 539.86
	DISCOUNTED TOTAL			\$ 2,159.44
	Labour Charge			
	Panel Beating			\$ 500.00 ²⁰⁰
	Spray Painting Charge			\$ 500.00 ⁴⁰⁰
	Wiring			\$ 30.00 ^{X 4}
	Tuff Kote			\$ 50.00 ²⁰
	TOTAL LABOUR			\$ 1,080.00
	ESTIMATE TOTAL			\$ 3,239.44
<p><i>Kalvin LK</i></p> <p><i>18/2/19 noon</i></p> <p><i>2 hrs</i></p> <p><i>L/S</i></p> <p><i>After Repair p/s</i></p> <p>Larry Ng</p> <div style="border: 1px solid black; padding: 5px;"> <p>LKK Auto Consultants hereby notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> </div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				