

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19002983/T1DS3Q2

Date: 03/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994421

Claimant

Vehicle No : XE1667J

Insured Vehicle No : SMG941T

Date of Loss: 06/02/2019

Nature of Claim: TP

Claim No: 6040168151SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XE1667J

Make & Model: SCANIA P360CB6X4MHZ, 12.7 D (M)

Engine No: 6923059

Reg. Date: 27/04/2016 (Man. Year: 2016)

Chassis No: YS2P6X40005413755

Colour: Blue

Odometer: 88081 km

Engine Capacity: 12742 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes

Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 315/80 R22.5

Rear Tyre Size: 315/80 R22.5 (D)

Front Left Side: West Lake 8 mm

Rear Left Side: West Lake 8/8 mm

Front Right Side: West Lake 8 mm

Rear Right Side: West Lake 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,100.00	13,950.00	9,150.00	39.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,400.00	2,050.00	2,350.00	53.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,500.00	16,000.00	11,500.00	41.82
Approved Total (Overridden) (S\$)		12,800.00		
Nett Amount (S\$)	27,500.00	12,800.00	14,700.00	53.45
+ Loss of Use (8.0 x S\$150.00/day) (S\$)		1,200.00		
+ Doc/Search Fee (S\$)		58.00		
Nett Liability (S\$)		14,058.00		
Global Sum Settlement (S\$)		14,020.00		

INSPECTION

Date of Assignment: 15/02/2019

Date Inspected: 19/02/2019 Inspected At:

Ryder Auto Pte Ltd (HQ)
2 Kaki Bukit Ave 2, #02-19 AutoHub
@ Kaki Bukit
Singapore 417921

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FUEL TANK (ALUMINIUM)	Dented	9,090.00 F	*6,000.00 F
2	2		*FUEL TANK BRACKET (LOWER)	Bent	1,200.00 F	*700.00 F
3	2		*FUEL TANK BRACKET (UPPER)	Bent	900.00 F	*500.00 F
4	2		*FUEL TANK STAND BRACKET (LOWER)	Bent	900.00 F	*500.00 F
5	1		*ANTI-TANK (FRONT)	Dented	3,110.00 F	*1,700.00 F
6	1		*REAR N/S GUARD (LTA APPROVED)	Bent	3,200.00 F	*1,800.00 F
7	1		*REAR N/S GUARD BRACKET (3 PCS)	Bent	2,400.00 F	*1,400.00 F
8	2		*REAR N/S GUARD BRACKET (UPPER)	Bent	300.00 F	*200.00 F
9	1		*REAR N/S GUARD BLOCK BRACKET	Bent	1,800.00 F	*1,000.00 F
10	1		*SET REAR N/S GUARD YELLOW /BLACK STICKER	Necessary	200.00 F	*150.00 F

F=Franchise part.

Total Parts (S\$) 23,100.00 13,950.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIT N/S GUARD	New	2,800.00	1,350.00
2	TO REMOVE AND REFIT FUEL TANK INCLUDING BLEEDING	New	900.00	400.00
3	TO REMOVE AND REFIT AIR-TANK INCLUDING CHECKING LEAKAGE	New	700.00	300.00
Gross Labour Cost (\$\$)			4,400.00	2,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >