



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 2171R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (CONSISTENT)	DEFORMED	836.00	836.00
2	FRONT BUMPER SIDE HOLDER @\$55.00 (CONSISTENT)	O/S DAMAGED	110.00	55.00
1	FRONT BUMPER RH SIDE LOWER GARNISH (CONSISTENT)	CRACKED	242.00	242.00
1	FRONT BUMPER CENTRE GRILLE (CONSISTENT)	NOT NECESSARY	385.00	-
1	FRONT BUMPER SPONGE (CONSISTENT)	CRACKED	49.50	49.50
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	473.00	-
1	SET FRONT BUMPER CLIPS (CONSISTENT)	NECESSARY	60.00	30.00
1	FRONT RH FENDER (CONSISTENT)	DENTED	467.50	467.50
1	FRONT RH FENDER INNER SHIELD (CONSISTENT)	NOT NECESSARY	126.50	-
1	SET FRONT RH FENDER INNER SHIELD CLIPS (CONSISTENT)	NOT NECESSARY	60.00	-
1	FRONT RH HEAD LAMP (CONSISTENT)	CUT	506.00	506.00
1	FRONT RH HEAD LAMP LOWER BRACKET (CONSISTENT)	NOT NECESSARY	44.00	-
1	FRONT RH SHOCK ABSORBER (CONSISTENT)	BENT	286.00	286.00
1	FRONT RH LOWER ARM (CONSISTENT)	BENT	308.00	308.00
1	FRONT RH KNUCKLE ARM (CONSISTENT)	BENT	528.00	528.00
1	FRONT RH KNUCKLE ARM BEARING (CONSISTENT)	NECESSARY	440.00	440.00
1	FRONT RH DRIVEH SHAFT (CONSISTENT)	NOT NECESSARY	1,980.00	-
1	FRONT GRILLE (CONSISTENT)	NOT NECESSARY	341.00	-
1	FRONT WIPER TANK (CONSISTENT)	DEFORMED	121.00	121.00
1	FRONT ENGINE LOWER COVER (CONSISTENT)	CRACKED	220.00	220.00
1	STEERING RACK (CONSISTENT)	NOT NECESSARY	4,356.00	-
1	FRONT RH LINKAGE (CONSISTENT)	NOT NECESSARY	88.00	-
1	FRONT CROSSMEMBER (CONSISTENT)	NOT NECESSARY	1,045.00	-
	LESS 10% DISCOUNT		-	-408.90
			13,072.50	3,680.10
<u>SPECIAL NETT ITEMS</u>				
1	FRONT RH SPORT RIM (SN) (CONSISTENT)	CUT	880.00	450.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT RH TYRE (SN) (CONSISTENT)	NOT NECESSARY	480.00	-
			1,360.00	450.00
	LABOUR			
	TO CHECK WHEEL ALIGNMENT.		100.00	80.00
	REMOVE & REINSTALL FRONT SUSPENSION .		500.00	220.00
	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT.		1,600.00	500.00
	RESPRAY PAINTING.		1,200.00	500.00
			3,400.00	1,300.00
GRAND TOTAL			17,832.50	5,430.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,300.00

Report Ref No. CC4/ASM19002992/Aga3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.