

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: GX2245M190215

Estimate**Customer**

Name: China Taiping Insurance (Singapore) Pte Ltd

Date: 16-02-19

Address Motor Claims Department

Vehicle No: GX2245M

3 Anson Road #16-00

Model/Make: Toyota Hiace

Springleaf Tower

Singapore 079909

Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tailgate <i>Body</i>	\$ 1,472.50	
2	Tailgate "Toyota Logo" Motif <i>neu</i>	\$ 70.50	
3	Tailgate "70 KM/H" Sticker <i>neu</i>	\$ 15.00	SN 105.N
4	Tailgate Inner Lock <i>DD/JM</i>	\$ 359.00	
5	Tailgate Weatherstrip <i>TO.N</i>	\$ 387.90	
6	Tailgate Windscreen Moulding <i>ns</i>	\$ 219.00	X
7	Tailgate Windscreen Sealant <i>neu</i>	\$ 50.00	SN 405.N
8	Tailgate Number Plate & Base <i>11</i>	\$ 48.00	SN X
9	Bumper <i>DD</i>	\$ 496.50	
10	Bumper Clips 1 set <i>neu</i>	\$ 65.00	
11	Bumper Side Holder 02 pcs (@S\$69.10) <i>Bent</i>	\$ 138.20	
12	Bumper Lower Bracket 04 pcs (@S\$103.00) <i>Bent</i>	\$ 412.00	
13	Bumper Reverse Sensor <i>Shofid</i>	\$ 220.00	SN 2005.N
14	Tail Lamps 02 pcs (@ S\$365.10) <i>neu</i>	\$ 730.20	
15	End Panel Outer <i>Body</i>	\$ 566.10	
16	End Panel Inner <i>neu</i>	\$ 936.20	X
17	End Panel Top Plate <i>DD</i>	\$ 166.50	
18	End Panel Sealant <i>11</i>	\$ 50.00	SN X
	To check all wiring & electrical component for proper function	\$ 50.00	30
	Remove & reinstall Windscreen Glass to facilitate repairs & perform water test	\$ 120.00	1
	Remove and refix rear tailgate components & wiper mechanism	\$ 80.00	60
	Remove and replace rear exhaust pipe system to facilitate repairs	\$ 80.00	11X
	Remove and refix rear Bumper distance sensor	\$ 90.00	50
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 880.00	600
	To putty & spray painting & including touch up paint on accident affected	\$ 800.00	600
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 80.00	60

Total Parts & Labour of estimate for damaged vehicle

S 8,582.60

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7-4864.4
25%
3648.30
5418.30
4334.

not Authorized
2/5 \$4300
500.