

ASS. REC. BY:

REF:

CS/INC19003030/Dgd302

Special Instruction:

Survivor

ASSIGNMENT (Office)From (Person): Daniel Koh of INC Date/Time: 18/2/2019

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SHD 6752H Insured: SMP 6915Kat Workshop m/s Chunni Tel: 65425119of BLK 10 AMC #03-19Policy No: _____ Claim No: MT-1032145-002

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 15/2/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT

Date/Time	Action/Instruction () Estimate
	<u>SHD 6752H-X</u>
	<u>SMP 6915K-X</u>

REF:

ASSIGNMENT

COB April 2024

2016 April

From _____ Date _____

Estimated Cost _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV _____

To inspect Vehicle No. _____

at Workshop n/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: **SHD 6752H** Vt Regn _____

Type: M/Car / M/Cycle / Bus / Van / Lorry / Truck / Prime Mover /

Truck / Trailer or _____

Make: **Mercedes Benz E220** S.S. **2143**

Colour: **white** A/C: Insured / Std / NI / NA

Sp Reading: **240451** T/Radio: Insured / Std / NI / NA

Eng/No: **65192433266109**

C/No: **WDD 2120012 B318830**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____


Modi: Nil S/Rim / STD A/Rim or _____

Tyre Size: F: **225/55 R16**

R: **11**

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: **25.20** days Res: Yes or NoLum Sum: **20** % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **Westlake**

Front	Rear
R/Bal. 5 mm	R/Bal. 5 mm
L/Bal. 5 mm	L/Bal. 5 mm
D.O.A. 15/02/2019	D.O.A. 18/02/2019
Survey held at churni AMK	04/19 PM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front y Rev N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

HTUC SMF 6915K

SV 120,299

LTA 57,999

HL 62,300/-

RECEIVED 11 APR 2019

11/04/19 Jman 4/5 55,000/- at 25 dgs 8th (Red \$ 56879.09, 51%)

Date/Time, File Pass to? ☐ : Preli. Report1) 11/4 **thru** ☐ : Final Report

Date/Time, File Return to? _____

Days Of Repair: **25**Resurvey No. of Trip: **2**Survey Fee: **290**

Transportation

1) 3 + RS 50

1) Photos

1) Effect

1) _____

TOTAL

Report Format: **TP**Lump Sum / L.B.1: (\$ **55000**)Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech Invs (\$)☐ Weekend (\$)**290**

Catherine Chong (LKK Auto)

From: Daniel Koh <daniel.koh@income.com.sg>
Sent: Monday, 18 February, 2019 10:00 AM
To: 'assignments@lkkauto.com'
Cc: Teng Ken Leong; Thio Tse Kiat
Subject: FW: TP CASES FARMED OUT TO LKK ON 18/2/2019

Dear Veron / Nivitha

Please assist to survey the vehicle as per Mr Teng's instruction :-

S/NO	THIRD PARTY	OUR INSURED	WORKSHOP / CONTACT	DOA / REF / OFFICER	TIMING
1	PC1746U	FBF1868Y	LEXBUILD INTERNATIONAL / Shirley Lim 96158280	14-2-2019 / MT-1032347-001 / Azhari	14:00-16:00
2	PC6401G	SHC6307R	SC AUTO INDUSTRIES / Hamimah 65719958	6-2-2019 / MT-1031536-002 / Serene Lim	10:00-12:00
3	SHD6752H	SMF6915K	SOON HOCK MOTOR / 65425119	15-2-2019 / MT-1032145-002 / Wo Jessie	

Please contact workshops.

Please ack.

Thank You

MCD019021286 / ComfortDelGro Engineering Pte Ltd - Layan
 ENTRY DATE & TIME: 15/02/2019 14:32
 SUBMITTED BY: Catherine Por Moy Juan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	15/02/2019 14:32
Date Of Accident	15/02/2019 08:05
Exact Location Of Accident	BUKIT TIMAH RD TWDS UPP B.TIMAH
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHD6752H
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	MERC
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	
Driver	
Name of Driver	NG SENG BOON
NRIC No	S7011049J
Date Of Birth	05/04/1970
Occupation	OUTDOOR
Date Of Driving Pass	06/07/1990
Driving Experience	28 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90056666
Fax Number	
Contact Number	
EEmail Address	SENGBOON2000@YAHOO.COM

Address	670C #13-632 EDGEFIELD PLAINS
Postcode	823670
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (Including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMF6915K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LU YIJIA
NRIC/Passport Number	G1030787U
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRT
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHD2333K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	JAMES CHAN
NRIC/Passport Number	S1447234G
Contact Number	81826000
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	REAR
No. Of Passenger (Including Driver)	

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) Involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)

Date & Time: 15.02.2019@1200HRS

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: June

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 15.02.2019 @ 0805HRS I was travelling along Bukit timah Rd twds Upper Bukit Timah Rd with no passenger onboard.

As I was waiting for the veh(C) SHD 2333K slow down and stopped and I followed too. Suddenly Veh(B) SMF 6915K hit onto my vehicle rear portion and caused my vehicle to surge forward and hit veh(C) SHD 2333K

As the accident took place too fast I could not take evasive action to prevent the accident.

I have company video and photos at scene to support my claims .

No injury in this accident .

Veh(B) SMF 6915K MS Lu Yi Jia G 1030787U

Veh(C) SHD 2333K MR James Chan S 1447234G

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 15.02.2019@1200HRS

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: June

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHD 6752H

DATE : 15.02.2019

MAKE :

TEL : 6542 5119

MODEL : MERCEDES

FAX : 6542 6039

NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Bumper Assy, Frt Bnc			\$ 1,890.50	✓
	Bumper Reinforcement, Frt Dented			\$ 1,158.00	✓
	Bumper Bracket, Frt/LH/RH NW	\$	95.00	\$ 190.00	X
	Bumper Absorber, Frt/LH/RH 2 Bt	\$	295.00	\$ 590.00	2✓
	Bumper Frame, Frt/Centre Broken			\$ 389.00	✓
	Bumper Sponge, Frt/Centre broken			\$ 285.00	✓
	Bumper Grille, Frt/Centre broken/deformed			\$ 290.50	✓
	Bumper Inner Clip, Frt NW			\$ 22.00	X
	License Plate Trim Cover, Frt Distorted			\$ 155.00	✓
	Headlamp (LH/RH) mostly broken	\$	3,957.00	\$ 7,914.00	✓
	Head Lamp Bracket (LH/RH) 2 Bt	\$	300.00	\$ 600.00	2✓
	Radiator Top Panel, Frt 2 Bt			\$ 330.50	2✓
	Head Lamp Panel (LH/RH) 2 Bt	\$	480.00	\$ 960.00	2✓
	Radiator Grille broken			\$ 1,220.00	✓
	Radiator Grille Star Logo broken			\$ 170.00	✓
	Radiator Grille Adjuster Bracket broken broken			\$ 685.70	✓
	Bonnet Assy Dented			\$ 2,850.60	✓
	Bonnet Mercedes Star Logo chipped/broken			\$ 112.00	✓
	Bonnet Hinge (LH/RH) NW	\$	285.50	\$ 571.00	X
	Bonnet Hinge Sensor (LH/RH) 2 NW	\$	485.50	\$ 971.00	X
	Bonnet Stopper Spring (LH/RH) N/S Bt O/S NW	\$	385.00	\$ 770.00	✓
	Bonnet Lock Sensor (LH/RH) 2 Dam	\$	285.50	\$ 571.00	2✓
	Bonnet Shock Absorber NW			\$ 295.40	X
	Bonnet Insulator NW			\$ 235.40	X
	Bonnet Centre Lock NW			\$ 95.00	X
	Bonnet Lock, Top Bt			\$ 94.00	✓
	Bonnet Lock Lower 2 Bt			\$ 92.00	2✓
	Bonnet Lock Brace Panel Bt			\$ 64.80	✓
	Bonnet Air Inlet Grille NW broken			\$ 269.25	✓
	Radiator Assy 2 Bt/punctured			\$ 1,345.00	2✓
	Radiator Fan Blower Assy 2 chipped			\$ 1,385.40	2✓
	Radiator Shroud 2 mostly broken			\$ 1,225.60	2✓
	Radiator Air Baffle, Top NW			\$ 80.00	X
	Radiator Air Baffle, Lower NW			\$ 125.90	X
	Radiator Overflow Hose NW			\$ 186.40	X
	Radiator Dowel Pin -2 pcs NW	\$	14.00	\$ 28.00	✓
	Radiator Mounting Lower NW			\$ 8.00	X
	Radiator Mounting Top-2 pcs NW NW	\$	19.00	\$ 38.00	✓
	Radiator Hose, Top NW			\$ 75.00	X
	Radiator Hose Lower NW			\$ 95.00	X
	Aircon Condenser 2 Bt/punctured			\$ 1,235.80	2✓
	Turbo Charger Air Cooler 2 Bt			\$ 1,053.80	2✓
	Turbo Charger Cooler Hose, RH NW			\$ 313.60	X
	Turbo Charger Cooler Hose, LH NW			\$ 75.45	X
	Turbo Charger Cooler Hose, Top NW			\$ 92.50	X

SHD 6752H

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Gearbox Cooler punctured			\$ 1,800.00	✓
	Safety Belt, Frt/LH/RH not Done		\$ 1,650.00	\$ 3,300.00	* ✓
	Head Rest Assy (LH/RH) activation		\$ 1,850.00	\$ 3,700.00	350/- SW
			32488.45		
	SUB TOTAL			\$ 40,005.10	
	LESS 10%		29239.60	\$ 4,000.51	
	DISCOUNTED TOTAL			\$ 36,004.59	
	Number Plate, Frt (Merc Taxi) broken		400.00	\$ 50.00	Nett ✓
	Labour Charge				
	Panel Beating			\$ 1,000.00	800/-
	Spray Painting Charge			\$ 600.00	500/-
	Wiring Charge			\$ 50.00	30/-
	Towing Charges			\$ 50.00	NH
	Tuff Kote		1750.00	\$ 50.00	40/-
	Remove/Refix Aircon & Refill Gas			\$ 150.00	80/-
	Re-programme Air Bag & Safety Belt System			\$ 550.00	1200/-
	Re-set and Diagnosis			\$ 550.00	300/-
	TOTAL LABOUR			\$ 3,000.00	
	Boot Lid Bnc			\$ 2,470.00	✓
	Boot Lid Lamp (LH/RH) broken/distorted	\$	655.00	\$ 1,310.00	✓
	Boot Lid Rubber deformed			\$ 170.00	✓
	Boot Lid Hinge Cover (LH/RH) not done	\$	490.40	\$ 980.80	2 X
	Boot Lid Hinge (LH/RH) not done	\$	580.50	\$ 1,161.00	✓
	Boot Lid Moulding CRACK			\$ 110.00	✓
	Boot Lid Outer Handle mostly deformed			\$ 87.40	✓
	Boot Lid Lock not done / broken			\$ 275.00	✓
	Boot Lid Lock Lower Catch not done			\$ 35.00	✓
	Boot Lid Lock Sticker NH			\$ 17.00	X
	Boot Lid 'E220' Emblem LHC			\$ 54.30	✓
	Boot Lid Star Logo LHC			\$ 45.00	✓
	Boot Lid Bluetec NH			\$ 90.00	✓
	Boot Lid 'CDI' Emblem LHC			\$ 54.30	✓
	Third Brake Light NH			\$ 290.90	X
	Boot Lid Inner Garnish crumpled			\$ 124.80	✓
	License Plate Trim Cover NH			\$ 96.70	X
	Rear Bumper deformed / broken			\$ 1,510.00	✓
	Rear Bumper Reinforcement Deformed			\$ 1,150.00	✓
	Rear Bumper Bracket Lower (LH/RH) not done	\$	135.00	\$ 270.00	✓
	Rear Bumper Bracket Top (LH/RH) not done broken NIS NH	\$	125.00	\$ 250.00	2 LH
	Rear Bumper Retainer Mounting (LH/RH) NIS broken O/S NH	\$	115.00	\$ 230.00	✓
	Rear Bumper Towing Cover NH			\$ 175.00	X
	Rear Bumper Lower Cover deformed			\$ 325.00	✓

SHD 6752H

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear No. Plate <i>st</i>			\$ 56.20	Nett ✓
	Rear Bumper Sensor <i>D-m</i>			\$ 388.00	Nett 220/-
	Rear Fender Top Garnish Rivet (LH) 7pcs <i>huc</i>		\$ 9.00	\$ 63.00	Nett ✓
	Rear Windscreen Sealant <i>huc</i>			\$ 180.00	Nett ✓
	Rear Door Comfort Limo Cab Logo <i>huc</i>			\$ 60.00	Nett ✓
			579.20		
				\$ 747.20	
	Labour Charge				
	Panel Beating			\$ 2,400.00	1400/-
	Spray Painting Charge			\$ 1,800.00	1200/-
	Wiring Charge			\$ 100.00	30/-
	Tuff Kote			\$ 150.00	40/-
	Rear Chassis Alignment Charges			\$ 400.00	150/-
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	80/-
	Remove/Refix Rear Windscreen Glass (sealant)			\$ 120.00	80/-
	Remove/Refix Reverse Sensor			\$ 120.00	40/-
	Remove/Refix Undercarriage (RR)			\$ 200.00	40/-
	Remove/Refix Fuel Tank			\$ 150.00	40/-
	Remove/Refix Exhaust Pipe			\$ 150.00	60/-
	Rear Wheel Alignment			\$ 120.00	40/-
	Re-set Rear ABS System			\$ 200.00	40/-
			3080.00		
	TOTAL LABOUR			\$ 6,060.00	
	ESTIMATE TOTAL			\$ 94,169.25	
	18/02/2019 @ 1630hrs				
	W/A Antm				
	2/sum 28 25				
	18 days				
	myan				
	LKK Auto				
			62866.09		
		Supp	11565.72		
			74431.81		
			L/s 55 000/-		
				111879.09	
	LKK Auto Consultants hence notify the Repairer of the following:				
	• To resurvey before/after spray painting				
	• To display damaged part(s) during resurvey				
	• Parts prices are subject to confirmation				
	• Third party survey is on a "Without Prejudice" basis				
	• No illegal modification(s) is allowed				
	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company				
	Acknowledged by Repairer				
	Signature:				
	Date:				
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

111879.09

1/1 Sh. May

DATE : 19.02.2019

TEL : 6542 5119

FAX : 6542 6039

[illegible]

2kk Ando



Check
Part prices

11565.72

~~\$ 12,850.80~~

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHD 6752H (Supplementary)

DATE : 12.03.2019



MAKE :

TEL : 6542 5119

MODEL : MERCEDES

FAX : 6542 6039

1/1 Ah me

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Brake Master Pump Assy Dem HC			\$ 1,638.00
	Brake Booster Dem HC			\$ 2,238.00
	Aircon Compressor Dem HC			\$ 2,950.80
	SUB TOTAL			\$ 6,826.80
	LESS 10%			\$ 682.68
	DISCOUNTED TOTAL			\$ 6,144.12
	 Ryan LKK And 			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref : CS/INC19003030/Dqd3e2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date : 12-04-2019

189556

ATTN: WO JESSIE

Code : INC



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMF 6915K	Veh. Inspected	SHD 6752H
Policy No.		Coverage (\$)	0.00
Claim No.	MT-1032145-002	Excess (\$)	0.00
Assign From	DANIEL KOH	Assign Date	18/02/2019

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ E220	c.c	2143
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WDD2120012B318830	Colour	WHITE
Odometer	240451	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R16	WEST LAKE	5 mm
L/H Front Tyre	225/55 R16	WEST LAKE	5 mm
R/H Rear Tyre	225/55 R16	WEST LAKE	5 mm
L/H Rear Tyre	225/55 R16	WEST LAKE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR N/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	15/02/2019	Inspection Date	18/02/2019
Survey held at	CHUNNI MOTOR REPAIRS PTE LTD BLK 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTOPOINT #03-19 SINGAPORE 568047		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	25 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 6

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6752H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER ASSY, FRT	BUCKLED	1,890.50	1,890.50
1	BUMPER REINFORCEMENT, FRT	DENTED	1,158.00	1,158.00
2	BUMPER BRACKET, FRT / LH / RH @\$95.00	NOT NECESSARY	190.00	-
2	BUMPER ABSORBER, FRT / LH / RH @\$295.00	BENT	590.00	590.00
1	BUMPER FRAME, FRT / CENTRE	BROKEN	389.00	389.00
1	BUMPER SPONGE, FRT / CENTRE	BROKEN	285.00	285.00
1	BUMPER GRILLE, FRT / CENTRE	BROKEN / DEFORMED	290.50	290.50
1	BUMPER INNER CLIP, FRT	NOT NECESSARY	22.00	-
1	LICENSE PLATE TRIM COVER, FRT	DISTORTED	155.00	155.00
2	HEADLAMP (LH/RH) @\$3957.00	MTG BROKEN	7,914.00	7,914.00
2	HEAD LAMP BRACKET (LH/RH) @\$300.00	BENT	600.00	600.00
1	RADIATOR TOP PANEL, FRT	BENT	330.50	330.50
2	HEAD LAMP PANEL (LH/RH) @\$480.00	BENT	960.00	960.00
1	RADIATOR GRILLE	BROKEN	1,220.00	1,220.00
1	RADIATOR GRILLE STAR LOGO	BROKEN	170.00	170.00
1	RADIATOR GRILLE ADJUSTER BRACKET	BROKEN	685.70	685.70
1	BONNET ASSY	DENTED	2,850.60	2,850.60
1	BONNET MERCEDES STAR LOGO	DISLodge / BROKEN	112.00	112.00
2	BONNET HINGE (LH/RH) @\$285.50	NOT NECESSARY	571.00	-
2	BONNET HINGE SENSOR (LH/RH) @\$485.50	NOT NECESSARY	971.00	-
2	BONNET STOPPER SPRING (LH/RH) @\$385.00	N/S BENT / O/S NOT NECESSARY	770.00	385.00
2	BONNET LOCK SENSOR (LH/RH) @\$285.50	DAMAGED	571.00	571.00
1	BONNET SHOCK ABSORBER	NOT NECESSARY	295.40	-
1	BONNET INSULATOR	NOT NECESSARY	235.40	-
1	BONNET CENTRE LOCK	NOT NECESSARY	95.00	-
1	BONNET LOCK, TOP	BENT	94.00	94.00
1	BONNET LOCK LOWER	BENT	92.00	92.00
1	BONNET LOCK BRACE PANEL	BENT	64.80	64.80
1	BONNET AIR INLET GRILLE	BROKEN	269.25	269.25
1	RADIATOR ASSY	BENT / PUNCTURE	1,345.00	1,345.00
1	RADIATOR FAN BLOWER ASSY	DISTORTED	1,385.40	1,385.40
1	RADIATOR SHROUD	MTG BROKEN	1,225.60	1,225.60

Report Ref No. CS/INC19003030/Dqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR AIR BAFFLE, TOP	NOT NECESSARY	80.00	-
1	RADIATOR AIR BAFFLE, LOWER	NOT NECESSARY	125.90	-
1	RADIATOR OVERFLOW HOSE	NOT NECESSARY	186.40	-
2	RADIATOR DOWEL PIN @\$14.00	NECESSARY	28.00	28.00
1	RADIATOR MOUNTING LOWER	NOT NECESSARY	8.00	-
2	RADIATOR MOUNTING TOP @\$19.00	NECESSARY	38.00	38.00
1	RADIATOR HOSE, TOP	NOT NECESSARY	75.00	-
1	RADIATOR HOSE LOWER	NOT NECESSARY	95.00	-
1	AIRCON CONDENSER	BENT / PUNCTURE	1,235.80	1,235.80
1	TURBOR CHARGER AIR COOLER	BENT	1,053.80	1,053.80
1	TURBOR CHARGER COOLER HOSE, RH	NOT NECESSARY	313.60	-
1	TURBOR CHARGER COOLER HOSE, LH	NOT NECESSARY	75.45	-
1	TURBOR CHARGER COOLER HOSE, TOP	NOT NECESSARY	92.50	-
1	GEARBOX COOLER	PUNCTURE	1,800.00	1,800.00
2	SAFETY BELT, FRT / LH / RH @\$1650.00	DAMAGED	3,300.00	3,300.00
1	BOOT LID	BUCKLED	2,470.00	2,470.00
2	BOOT LID LAMP (LH/RH) @\$655.00	BROKEN / DISLODGE	1,310.00	1,310.00
1	BOOT LID RUBBER	DEFORMED	170.00	170.00
2	BOOT LID HINGE COVER (LH/RH) @\$490.40	NOT NECESSARY	980.80	-
2	BOOT LID HINGE (LH/RH) @\$580.50	BENT	1,161.00	1,161.00
1	BOOT LID MOULDING	CRACKED	110.00	110.00
1	BOOT LID OUTER HANDLE	MTG DEFORMED	87.40	87.40
1	BOOT LID LOCK	BENT / BROKEN	275.00	275.00
1	BOOT LID LOCK LOWER CATCH	BENT	35.00	35.00
1	BOOT LID LOCK STICKER	NOT NECESSARY	17.00	-
1	BOOT LID 'E220' EMBLEM	NECESSARY	54.30	54.30
1	BOOT LID STAR LOGO	NECESSARY	45.00	45.00
1	BOOT LID BLUETEC	NECESSARY	90.00	90.00
1	BOOT LID 'CDI' EMBLEM	NECESSARY	54.30	54.30
1	THIRD BRAKE LIGHT	NOT NECESSARY	290.90	-
1	BOOT LID INNER GARNISH	CRUMPLED	124.80	124.80
1	LICENSE PLATE TRIM COVER	NOT NECESSARY	96.70	-
1	REAR BUMPER	DENTED / BROKEN	1,510.00	1,510.00
1	REAR BUMPER REINFORCEMENT	DENTED	1,150.00	1,150.00
2	REAR BUMPER BRACKET LOWER (LH/RH) @\$135.00	DAMAGED	270.00	270.00

Report Ref No. CS/INC19003030/Dqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR BUMPER BRACKET TOP (LH/RH) @\$125.00	N/S BROKEN / O/S NOT NECESSARY	250.00	125.00
2	REAR BUMPER RETAINER MOUNTING (LH/RH) @\$115.00	N/S BROKEN / O/S NOT NECESSARY	230.00	115.00
1	REAR BUMPER TOWING COVER	NOT NECESSARY	175.00	-
1	REAR BUMPER LOWER COVER	DEFORMED	325.00	325.00
1	TAILLAMP QUARTER PANEL OUTER (LH)	BUCKLED	388.00	388.00
2	TAILLAMP (LH/RH) @\$1280.00	BROKEN / CRACKED	2,560.00	2,560.00
1	REAR PANEL END	BUCKLED	1,380.00	1,380.00
1	REAR PANEL INNER GARNISH	BROKEN	240.00	240.00
10	REAR PANEL INNER GARNISH CLIP	NECESSARY	40.00	40.00
1	SPARE TYRE PANEL	NOT NECESSARY	1,280.00	-
1	SPARE TYRE	NOT NECESSARY	310.00	-
1	SPARE WHEEL LOWER GARNISH	NOT NECESSARY	361.20	-
1	SPARE WHEEL TOP COVER	NOT NECESSARY	95.00	-
1	SPARE TYRE PANEL CUSHION COVER	NOT NECESSARY	365.00	-
1	SPARE TYRE JACK COVER	NOT NECESSARY	65.00	-
1	REAR FIBER TOOL BOX	NOT NECESSARY	650.00	-
1	BLUETEE SPARE TANK	DENTED	2,580.00	2,580.00
1	REAR SUB CHASSIS MEMBER (LH)	BUCKLED	950.00	950.00
1	REAR EXHAUST PIPE INSULATOR	BENT	46.00	46.00
1	REAR EXHAUST SILENCER	BENT	1,890.00	1,890.00
1	REAR EXHAUST '8' SHAPE RING	NOT NECESSARY	16.00	-
1	REAR EXHAUST MOUNTING	NOT NECESSARY	21.85	-
1	REAR FENDER (LH)	BUCKLED	2,980.50	2,980.50
1	REAR FENDER INNER PANEL (LH)	DENTED	1,950.80	1,950.80
1	REAR FENDER SPLASH SHIELD (LH)	NOT NECESSARY	195.00	-
1	REAR FENDER INNER GARNISH (LH)	NOT NECESSARY	980.60	-
1	REAR FENDER AIR DUCT (LH)	NOT NECESSARY	490.50	-
1	REAR FENDER TOP GARNISH (LH)	DEFORMED	26.00	26.00
1	REAR WINDSCREEN GLASS C/W MOULDING	SHATTERED	1,845.00	1,845.00
1	REAR SPEAKER PANEL	DENTED	1,250.00	1,250.00
1	REAR SPEAKER PANEL CUSHION COVER	NOT NECESSARY	320.00	-
2	REAR SAFETY BELT (LH/RH) @\$1650.00	ACTIVATED	8,250.00	3,300.00
1	REAR TYRE (LH)	NOT NECESSARY	480.00	-
1	REAR TYRE RIM (LH)	NOT NECESSARY	1,250.00	-

Report Ref No. CS/INC19003030/Dqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WHEEL HUB BEARING	NOT NECESSARY	561.80	-
1	REAR SHOCK ABSORBER (LH)	NOT NECESSARY	532.00	-
1	REAR SHOCK ABSORBER MOUNTING (LH)	NOT NECESSARY	235.00	-
1	REAR WHEEL DRIVE SHAFT	NOT NECESSARY	2,500.00	-
1	REAR CONTROL ARM LONG (LH)	NOT NECESSARY	939.50	-
1	REAR CONTROL ARM LOWER (LH)	NOT NECESSARY	859.50	-
1	REAR KNUCKLE ASSY (LH)	NOT NECESSARY	1,700.00	-
1	CONTROL ARM RR / THRUST ROD	NOT NECESSARY	858.50	-
1	CONTROL ARM RR/ THRUST ARM	NOT NECESSARY	950.00	-
1	FENDER, FRT / LH (ADDITIONAL)	BENT / DENTED	996.80	996.80
1	BOOT LID INNER LOWER GARNISH (ADDITIONAL)	MTG CRACKED	388.00	388.00
1	REAR BUMPER CENTRE SUPPORT BRACKET (ADDITIONAL)	BROKEN	850.00	850.00
1	REAR FENDER (RH) (ADDITIONAL)	DENTED	2,980.50	2,980.50
2	REAR FENDER TRIMBOARD (LH/RH) @\$850.00 (ADDITIONAL)	DEFORMED	1,700.00	1,700.00
1	TURBO CHARGE AIR COOLER AIR BUBBLE (ADDITIONAL)	BROKEN	385.00	385.00
2	HEAD LAMP PANEL "S" BRACKET (LH/RH) @\$128.00 (ADDITIONAL)	BENT	256.00	256.00
2	HEAD LAMP PANEL "L" BRACKET (LH/RH) @\$128.00 (ADDITIONAL)	BENT	256.00	256.00
1	RADIATOR SPARE TANK BY-PASS HOSE (ADDITIONAL)	BENT	368.00	368.00
1	ACCELERATION SENSOR (ADDITIONAL)	BROKEN	1,690.00	1,690.00
1	REAR CROSSMEMBER (ADDITIONAL)	DISTORTED	2,980.50	2,980.50
1	BRAKE MASTER PUMP ASSY (DAMAGED) (ADDITIONAL)	NOT CONSISTENT WITH THE IMPACT	1,638.00	-
1	BRAKE BOOSTER (DAMAGED) (ADDITIONAL)	NOT CONSISTENT WITH THE IMPACT	2,238.00	-
1	AIRCON COMPRESSOR (DAMAGED) (ADDITIONAL)	NOT CONSISTENT WITH THE IMPACT	2,950.80	-
	LESS 10% DISCOUNT		-10,965.77	-7,624.74
			98,691.88	68,622.61
2	HEAD REST ASSY (LH/RH) @\$1850.00 (SN)	ACTIVATED	3,700.00	350.00
	LESS 10% DISCOUNT		-370.00	-
			3,330.00	350.00

Report Ref No. CS/INC19003030/Dqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	NUMBER PLATE, FRT (MERC TAXI) (SN)	BROKEN	50.00	50.00
1	REAR NO. PLATE (SN)	BENT	56.20	56.20
1	REAR BUMPER SENSOR (SN)	DAMAGED	388.00	220.00
7	REAR FENDER TOP GARNISH RIVET (LH) @\$9.00 (SN)	NECESSARY	63.00	63.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	180.00	180.00
1	REAR DOOR COMFORT LIMO CAB LOGO (SN)	NECESSARY	60.00	60.00
			797.20	629.20
	<u>LABOUR</u>			
	PANEL BEATING.		3,400.00	2,200.00
	SPRAY PAINTING CHARGE.		2,400.00	1,700.00
	WIRING CHARGE.		150.00	60.00
	TOWING CHARGES.	NOT NECESSARY	50.00	-
	TUFF KOTE.		50.00	40.00
	REMOVE / REFIX AIRCON & REFILL GAS.		150.00	80.00
	RE-PROGRAME AIR BAG & SAFETY BELT SYSTEM. }		550.00	300.00
	RE-SET AND DIAGNOSIS. }		550.00	-
	TUFF KOTE.		150.00	40.00
	REAR CHASSIS ALIGNMENT CHARGES.		400.00	150.00
	REMOVE / REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE / REFIX REAR WINDSCREEN GLASS (SEALANT).		120.00	80.00
	REMOVE / REFIX REVERSE SENSOR.		120.00	40.00
	REMOVE / REFIX UNDERCARRIAGE (RR).	NOT NECESSARY	200.00	-
	REMOVE / REFIX FUEL TANK.	NOT NECESSARY	150.00	-
	REMOVE / REFIX EXHAUST PIPE.		150.00	60.00
	REAR WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	RE-SET REAR ABS SYSTEM.	NOT NECESSARY	200.00	-
			-	-
			-	-
			-	-
			-	-
			-	-
			9,060.00	4,830.00
	GRAND TOTAL		111,879.08	74,431.81

Report Ref No. CS/INC19003030/Dqd3e2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			55,000.00
---	--	--	-----------

Report Ref No. CS/INC19003030/Dqd3e2

ANG BRYAN TANI

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.