

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHD3009R

DATE: 18. Feb. 2019

MAKE : HYUNDAI

MODEL : i40

DOA: 15. Feb. 2019

AXA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Front Bumper Cover <i>X Rep 1</i>			\$1,052.20
1	Front Bumper Side Bracket – LH ?			\$24.60
1	Front Bumper Top Bracket – LH ?			\$22.40
10	Front Bumper Clips X		\$2.20	\$22.00
1	Front Fender – LH <i>X Rep 2</i>			\$566.30
1	Front Wheel Cover – LH			\$107.10
SUB TOTAL				\$1,794.60
LESS 20%				\$358.92
DISCOUNTED TOTAL				\$1,435.68
				\$-
Labour Charge				
1	Panel Beating			<i>200</i> <del>\$500.00</del>
1	Spray Painting Charge			<i>400</i> <del>\$500.00</del>
1	Tuff Kote			X <del>\$50.00</del>
1	Wiring Charge			X <del>\$50.00</del>
TOTAL LABOUR				\$1,100.00
ESTIMATE TOTAL				\$2,535.68
<p><i>Ka Lin, 1/1/19</i></p> <p><i>19/2/19 to 20/2</i></p> <p><i>20 Days</i></p> <p><i>PIP</i></p> <p><i>After Repair</i></p>				
<p>KKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>To resurvey before/after spray painting</li> <li>To display damaged part(s) during resurvey</li> <li>Parts price are subject to confirmation</li> <li>Third party survey is on a "Without Prejudice" basis</li> <li>No illegal modification is allowed</li> <li>Supplementary items must have approval and is subject to final approval by the insurance company</li> </ul> <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p>				
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

Larry Ng