

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 9244L

DATE 16/2/2019 9:56

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>Rebored</i>			\$ 553.00
	Rear Bumper Reinforcement <i>✓</i>			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH) <i>2/1 X sun part Bar</i>		80.30	\$ 160.60
	Rear Bumper Clip 10 pcs <i>✓</i>			\$ 22.00
	Rear Bumper Bracket <i>X sun</i>		35.60	\$ 71.20
	Rear Bumper Sponge <i>✓ torn</i>			\$ 103.50
	Rear Bumper Under Cover <i>X sun</i>			\$ 228.00
	SUB TOTAL			\$ 1,566.70
	LESS 20%			\$ 313.34
	DISCOUNTED TOTAL			\$ 1,253.36
	Rear Bumper Rubber Mat <i>✓</i>			\$ 50.00 Nett
	Rear Bumper Advertisement Logo <i>✓</i>			\$ 50.00 Nett
	Rear Fender Advertisement Logo (LH/RH) <i>✓</i>		100.00	\$ 200.00 Nett
	Rear Bumper Reverse Sensor <i>✓ shot</i>			\$ 135.70 Nett
				\$ 435.70
	Labour Charge			
	Panel Beating			\$ 350.00 <i>200</i>
	Spray Painting Charge			\$ 250.00 <i>200</i>
	Wiring Charge			\$ 30.00 <i>X 10</i>
	Remove/Refix Reverse Sensor			\$ 80.00 <i>30</i>
	TOTAL LABOUR			\$ 710.00
	ESTIMATE TOTAL			\$ 2,399.06
<p><i>1 car bumper</i></p> <p><i>18/2/19 1050h</i></p> <p><i>2 Pass</i></p> <p><i>RIP</i></p> <p><i>Before Paint & Gl.</i></p>				
<div> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> </div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

EQ