

Page

REF:

89080

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: **SLT 1353C**
at Workshop m/s: **Accord Auto**
of: **Bulker Interad**
Insured: **LPC**
Policy No.: _____
Claims No.: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: **102K**
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SLT 1353C** Yr Regn: **2017 OUT**
Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: **Honda Odyssey 2-4** C.C. **2356**
Colour: **WHITE** A/C: _____ Insured / Std / NI / NA
Sp. Reading: **043623** T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: **JHMR 18904C 203920**
Gen. Cond: Good / ☒ Fair / Poor / Burnt
Steering: ☒ Order / Jammed / Leaked / Burnt or
Brake: ☒ Order / Jammed / Leaked / Burnt or
Modi: Nil / ☒ S/Rim / STD A/Rim or
Tyre Size: F: **215/55R17**
R: _____

BS / ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front		Rear	
R/Bal. 6	mm	R/Bal. 6	mm
L/Bal. 6	mm	L/Bal. 6	mm
D.O.A. 12/02/19		D.O.I. 19/02/19	
Survey held at	Accord Auto		

Des. of Damages: ☒ Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Insp (\$)
☐ Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)