

2/5/2002

ASS. REC. BY:

REF: CS/MSG19003092/RHd3m Special Instruction:Survivor: Regul ASSIGNMENT (Office)From (Person): Monica chung of MSG Date/Time: 15/2/19 @ 3:47pm

Estimated Cost: Bill to:

OD FTP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SKR 4790B Insured: GBF 4788Dat Workshop m/s: Premium Tel: 6474 3323of 281 Alexandra RoadPolicy No: 29035476MCF Claim No: S85104

Sum Insured: Excess:

Make of Veh: D.O.A. 13/02/2019
(Client's Record)CA / REV / REP. / REV 24 HRS ^{lup}Date/Time: 4:20pm 15/2/19 Person Contacted: Keefung H.O.D. Endorsement: Vehicle IN/OUT

Date/Time	Action/Instruction (→) Estimate
	GBF 4788 D-
	SKR 4790B-X
202-	Revised via menmen preli advise.
	Part by part \$6730.60 (Red: 5645.45%)
	6703.60 5102.4 43%

Rasul

REF: MS16

7074F

ASSIGNMENT

From: Date: 18/2/2019

Estimated Cost

OD: ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKR 4790B

at Work shop n/s: Premium

at: 281 Alexandra Road

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh: 11am @ owner waiting

(Policy Condition) Kee Sieng

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SKR 4990B

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Sumen Forester 20 XT

Colour: white

Sp. Reading: 075623

Eng/No:

C/No: JF15JHk8866039749

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ morder / Jammed / Leaked / Burnt or

Brake: ☒ morder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continuum

Front: R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 13/02/19

Survey held at Premium

Des. of Damages: ☒ Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 1-9 MAR 2019

Date/Time, File Pass to? ☐ Preli. Report

19/3/2019 ☒ Final Report

Date/Time, File Return to?

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation

Photos

Others

Report Format: TP

Lump Sum / L.B. 6730.60

6703.60

200

10

210

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 20 Feb 2019

Preliminary Advice

Insured Vehicle No	: GBF4788D	Accident Date	: 13/02/2019
TP Vehicle No	: SKR4790B	Assignment Date	: 15/02/2019
Make	: SUBARU FORESTER	Est. Duration of Repair	: 5.00
Date of Inspection	: 18/02/2019		
Inspection At	: PREMIUM AUTOCARE CENTRE (ALEXANDRA) 281 ALEXANDRA ROAD SINGAPORE 159938		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,806.00
Revised Amount	:S\$	6,030.00
Check Items (Estimated)	:S\$	3,798.00
Total	:S\$	9,828.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(x) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Feb 2019		15 Feb 2019 15:47 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	D2D Express Pte Ltd, Co. Reg. No.: 201132017D		
Main Claimant:	WONG MING JIE, ID: S8117074F		
Vehicle Reg. No.:	SKR4790B	Date of Loss:	13/02/2019 18:00 - :59 [48 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 585104	Policy/Cover Note No.:	29035476MKF (Comprehensive) Coverage: 10/11/2017 - 31/12/2019
Vehicle Reg. No. (Insured):	GBF4788D	Policy No. (Claimant):	
		Excess:	
Repairer:	Premium Autocare Centre (Alexandra) 281 Alexandra Road, 159938 Alexandra - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 16/02/2019]		
Adj Asg. Remarks:	Survey appt 18/02/19, 11am. Owner waiting. on WP. Please contact us ASAP if you cannot attend this assignment. Liability (Non-reporting) Kindly arrange survey on 18/2/2019 11am and contact kee Siang @ 6474 3323		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAuto)

From: Claims PAC <claims@premiumautocare.com.sg>
Sent: Friday, 15 March 2019 6:30 PM
To: Rasul (LKKAuto)
Cc: claims@premiumautocare.com.sg
Subject: RE: FINAL REVISION SKR 4790 B survey on 18/2/2019 - TP MSIG
Attachments: SKR 4790 B - REVISED EST.pdf

Dear Rasul,

Revised estimate attached for your reference

Kindly confirm repair cost S\$6,703.60 @ 5 days of repairs.

Your early closure is well appreciate.

Best Regards,

Kee Siang
Claims Advisor
Premium Autocare Centre
24 Benoi Sector, Singapore 629857
p. +65 6474 3323 f. +65 6264 6786
e. claims@premiumautocare.com.sg w. www.premiumautocare.com.sg



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

Premium Autocare Centre

24 Benoi Sector, Singapore 629857

Tel : 6474 3323 Fax : 6264 6786

Email: Nora.khai@premiumautocare.com.sg / claims@premiumautocare.com.sg

Telefax

Estimate : Accident Repairs
Workshop : 24 Benoi Sector
Contact No : 6474 3323
Fax No : 6264 6786
Reference : PAC/TP/0010/2019/KS
Date : 14-Feb-19

Vehicle NOT in workshop. Kindly arrange for survey.

Your insured vehicle no : GBF 4788 D

NTUC Income Insurance Co - Claims Department

73 BRAS BASAH ROAD,

#05-01 NTUC TRADE UNION HOUSE,

SINGAPORE 189556

Attn: Motor Claims Dept

Tel: Fax 6338 1504

Owner's Name : Mr Wong MingJie
Address : Blk 336 Pasir Panjang Road
#04-05
Singapore 118668
Telephone : (HP)+65 96251185
Type of Claim : Third Party Claim
Policy No. : 2100402483-04
Vehicle No : **SKR 4790 B**
Model Code : Subaru Forester 2.0 XT AWD
Model / Year : Feb-15
Engine No : FA20J937414
Chassis No : JF1SJGK85EG039749
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Allan Wu
Accident Date : 13-Feb-19
Place of Accident : ALONG COMMONWEALTH AVE WEST

Premium Autocare Centre

24 Benoi Sector, Singapore 629857

Tel : 6474 3323 Fax : 6264 6786

Telefax

Estimated Labour Charges for Accident Vehicle SKR 4790 B

S/n	Nature of Jobs	Estimated Charges	remarks
1	To remove and transfer front wire harness for headlights, fog lamps horns and outside temperature sensor.	S/N \$ 150.00	
2	To remove and transfer aircon condenser, radiator, additional radiator, electrical fans and control unit. To carry out vacuum / regas and to pressurise cooling system.	S/N \$ 600.00	
3	To dismantle and renew front bumper, bonnet and both headlight. Renew lock carrier and align to position. Reorganise front crash management components. Reinstall all parts removed.	\$ 2,450.00	200 875
4	To respray front bumper and bonnet.	\$ 1,050.00	700
5	To carry out diagnostic check.	S/N \$ 150.00	
TOTAL LABOUR CHARGES		: \$ 4,400.00	

Premium Autocare Centre

24 Benoi Sector, Singapore 629857

Tel : 6474 3323 Fax : 6264 6786

Telefax

Material List for Accident Vehicle Regn No. SKR 4790 B

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>DE-</i>	\$ 480.00	✓✓
2	FRONT BUMPER GRILLE LOWER <i>CRA -</i>	\$ 300.00	✓✓
3	RADIATOR GRILLE <i>CRA X800</i>	\$ 135.00	
4	FRONT HEADLIGHT NOZZLE LH / RH <i>X800</i> <i>sun</i>	2 \$ 168.00	
5	FRONT HEADLIGHT NOZZLE COVER LH / RH <i>LH X / RH - mr2</i>	2 \$ 106.00	✓ 53
6	FRONT BUMPER REINFORCEMENT BEAM <i>? PA</i>	\$ 285.00	✓✓ 285
7	FRONT BUMPER SPONGE <i>? X800</i>	\$ 113.00	
8	BONNET <i>PA -</i>	\$ 958.00	✓ 958
9	BONNET CHROME TRIM <i>CRA -</i>	\$ 135.00	✓ 135
10	FRONT SUPPORT PANEL <i>? X800</i>	\$ 420.00	
11	FRONT AIR INTAKE DUCT <i>? X800</i>	\$ 53.00	
12	HEADLIGHT LH / RH <i>RH - CRA / LH - ? X800</i>	2 \$ 2,750.00	1375
13	HEADLIGHT CONTROL UNIT LH / RH <i>? X800</i>	2 TBC	
14	FRONT SUPPORT PANEL COVER <i>? CRA -</i>	\$ 38.00	✓ 38
15	RADIATOR <i>? X800</i>	\$ 570.00	
16	CONDENSOR <i>? X800</i>	\$ 660.00	
17	FRONT NO PLATE WITH HOLDER <i>PA</i>	S/N \$ 35.00	✓ 35
18	SUNDRIES <i>? X800</i>	\$ 200.00	
TOTAL SPARE PARTS CHARGES		:	\$ 7,406.00
TOTAL LABOUR CHARGES		:	\$ 4,400.00
GRAND TOTAL		:	\$ 11,806.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Autocare Centre

24 Benoi Sector, Singapore 629857

Tel : 6474 3323 Fax : 6264 6786

Telefax

[Handwritten signature]
20/2/19

Name

: Rasm - Hp 90010068

Surveyed Date

: 18/02/19 @ 1145

Authorised Date

:

Excess Cost

:

5 days

Liability

:

Remarks

:

Resurvey before paint

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6474 3323 for appointment.

Yours faithfully,

Premium Autocare Centre

Allan Wu

Body Shop Manager

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--

Premium Autocare Centre

24 Benoi Sector, Singapore 629857

Tel : 6474 3323 Fax : 6264 6786

Email: Nora.khai@premiumautocare.com.sg / claims@premiumautocare.com.sg

Telefax

Estimate : Accident Repairs
Workshop : 24 Benoi Sector
Contact No : 6474 3323
Fax No : 6264 6786
Reference : PAC/TP/0010/2019/KS
Date : 14-Feb-19

Vehicle NOT in workshop. Kindly arrange for survey.

Your insured vehicle no : GBF 4788 D

MSIG Insurance (Singapore) Pte Ltd

No 4 Shenton Way
#23-01 SGX Centre 2
Singapore 068896

Attn: Motor Claims Dept

Tel: 6827 27692 - Fax: 6225 7402

Hi, Rasul »

5 Working Days

Owner's Name : Mr Wong MingJie
Address : Blk 336 Pasir Panjang Road
#04-05
Singapore 118668
Telephone : (HP)+65 96251185
Type of Claim : Third Party Claim
Policy No. : 2100402483-04
Vehicle No : **SKR 4790 B**
Model Code : Subaru Forestor 2.0 XT AWD
Model / Year : Feb-15
Engine No : FA20J937414
Chassis No : JF1SJGK85EG039749
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Allan Wu
Accident Date : 13-Feb-19
Place of Accident : ALONG COMMONWEALTH AVE WEST

Premium Autocare Centre

24 Benoi Sector, Singapore 629857

Tel : 6474 3323 Fax : 6264 6786

Telefax

Estimated Labour Charges for Accident Vehicle SKR 4790 B

S/n	Nature of Jobs		Estimated Charges		Remarks
1	To remove and transfer front wire harness for headlights, fog lamps horns and outside temperature sensor.	S/N	\$ 150.00	\$	150.00
2	To remove and transfer aircon condenser, radiator, additional radiator, electrical fans and control unit. To carry out vacuum / regas and to pressurise cooling system.	S/N	\$ 600.00	\$	600.00
3	To dismantle and renew front bumper, bonnet and both headlight. Renew lock carrier and align to position. Reorganise front crash management components. Reinstall all parts removed.		\$ 2,450.00	\$	875.00
4	To respray front bumper and bonnet.		\$ 1,050.00	\$	700.00
5	To carry out diagnostic check.	S/N	\$ 150.00	\$	150.00
TOTAL LABOUR CHARGES		:	\$ 4,400.00	\$	2,475.00

Premium Autocare Centre

24 Benoi Sector, Singapore 629857
Tel : 6474 3323 Fax : 6264 6786

Telefax

Material List for Accident Vehicle Regn No. SKR 4790 B

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 480.00	\$ 480.00
2	FRONT BUMPER GRILLE LOWER	\$ 300.00	\$ 300.00
3	RADIATOR GRILLE	\$ 135.00	
4	FRONT HEADLIGHT NOZZLE LH / RH	2 \$ 168.00	
5	FRONT HEADLIGHT NOZZLE COVER LH / RH	2 \$ 106.00	\$ 53.00
6	FRONT BUMPER REINFORCEMENT BEAM	\$ 285.00	\$ 285.00
7	FRONT BUMPER SPONGE	\$ 113.00	
8	BONNET	\$ 958.00	\$ 958.00
9	BONNET CHROME TRIM	\$ 135.00	\$ 135.00
10	FRONT SUPPORT PANEL	\$ 420.00	
11	FRONT AIR INTAKE DUCT	\$ 53.00	
12	HEADLIGHT LH / RH	2 \$ 2,750.00	\$ 1,375.00
13	HEADLIGHT CONTROL UNIT LH / RH	2 TBC	TBC
14	FRONT SUPPORT PANEL COVER	\$ 38.00	\$ 38.00
15	RADIATOR	\$ 570.00	
16	CONDENSOR	\$ 660.00	
17	FRONT NO PLATE WITH HOLDER	S/N \$ 35.00	\$ 35.00
18	SUNDRIES	\$ 200.00	
	SUPPLEMENTARY		\$ 569.60
	TOTAL SPARE PARTS CHARGES	: \$ 7,406.00	\$ 4,228.60
	TOTAL LABOUR CHARGES	: \$ 4,400.00	\$ 2,475.00
	GRAND TOTAL	: \$ 11,806.00	\$ 6,703.60

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Autocare Centre

24 Benoi Sector, Singapore 629857

Tel : 6474 3323 Fax : 6264 6786

Email: Nora.khai@premiumautocare.com.sg / claims@premiumautocare.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

MSIG Insurance (Singapore) Pte Ltd No 4 Shenton Way #23-01 SGX Centre 2 Singapore 068896 Attn: Motor Claims Dept Tel: Fax:		Estimate No. PA/TP/0010/2019/KS Date 26-Feb-19 Service Advisor Chang Pages 1 Regn No SKR 4790 B Model No SUBARU FORESTER	
Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	To repair and respray front support panel.	\$ 800.00	\$ 350.00
<u>Parts</u>			
1	HEADLIGHT MOUNTING - RH	\$ 120.00	\$ 120.00
2	FRONT BUMPER CLIPS	\$ 100.00	\$ 99.60
Grand Total		\$ 1,020.00	\$ 569.60

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Autocare Centre

24 Benoi Sector, Singapore 629857

Tel : 6474 3323 Fax : 6264 6786

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6474 3323 for appointment.

Yours faithfully,
Premium Autocare Centre

Allan Wu
Body Shop Manager

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19003092/R1TD3N2

Date: 20/03/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29035476MKF
Claimant Vehicle No :	SKR4790B	Insured Vehicle No :	GBF4788D
Date of Loss:	13/02/2019	Nature of Claim:	TP
		Claim No:	585104

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKR4790B	Engine No:	FA20J937414
Make & Model:	SUBARU FORESTER, 2.0 XT AWD CVT (A)	Chassis No:	JF1SJGK85EG039749
Reg. Date:	11/02/2015 (Man. Year: 2014)	Odometer:	75623 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,625.60	3,878.60	3,747.00	49.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,200.00	2,825.00	2,375.00	45.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	12,825.60	6,703.60	6,122.00	47.73
+ GST 7.00/7.00% (\$\$)	897.79	469.25	428.54	47.73
Nett Amount (\$\$)	13,723.39	7,172.85	6,550.54	47.73

INSPECTION

Date of Assignment:	15/02/2019	
Date Inspected:	18/02/2019	Inspected At: Premium Autocare Centre (Alexandra) 281 Alexandra Road Singapore 159938
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Mar 2019)
Parts:	M1-SUV	SUBARU FORESTER 2.0 XT AWD CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKR4790B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	480.00 FS	*480.00 FS
2	1		*FRONT BUMPER GRILLE LOWER	Cracked	300.00 FS	*300.00 FS
3	1		*RADIATOR GRILLE	Serviceable	135.00 FS	*- FS
4	2		*FRONT HEADLIGHT NOZZLE LH/RH	Serviceable	168.00 FS	*- FS
5	1		*FRONT HEADLIGHT NOZZLE COVER LH/RH	O/s Missing/N/s Serviceable	106.00 FS	*53.00 FS
6	1		*FRONT BUMPER REINFORCEMENT BEAM	Bent	285.00 FS	*285.00 FS
7	1		*FRONT BUMPER SPONGE	Serviceable	113.00 FS	*- FS
8	1		*BONNET	Bent	958.00 FS	*958.00 FS
9	1		*BONNET CHROME TRIM	Cracked	135.00 FS	*135.00 FS
10	1		*FRONT SUPPORT PANEL	Serviceable	420.00 FS	*- FS
11	1		*FRONT AIR INTAKE DUCT	Serviceable	53.00 FS	*- FS
12	1		*HEADLIGHT LH/RH	O/s Cracked/N/s Serviceable	2,750.00 FS	*1,375.00 FS
13	2		*HEADLIGHT CONTROL UNIT LH/RH (NPA)	Not Necessary	0.00 FS	*- FS
14	1		*FRONT SUPPORT PANEL COVER	Cracked	38.00 FS	*38.00 FS
15	1		*RADIATOR	Serviceable	570.00 FS	*- FS
16	1		*CONDENSOR	Serviceable	660.00 FS	*- FS
17	1		*FRONT NO PLATE WITH HOLDER	Cracked	35.00 FS	*35.00 FS
18	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS
19	1		*HEADLIGHT MOUNTING-RH	Cracked	120.00 FS	*120.00 FS
20	1		*FRONT BUMPER CLIPS	Necessary	99.60 FS	*99.60 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 7,625.60 3,878.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,FOGLAMPS,HORNS AND OUTSIDE TEMPERATURE SENSOR	New	150.00	150.00
2	TO REMOVE AND TRANSFER AIRCON CONDENSER,RADIATOR,ADDITIONAL RADIATOR,ELECTRICAL FANS AND CONTROL UNIT.TO CARRY OUT VACUUM/REGAS AND TO PRESSURISE COOLING SYSTEM	New	600.00	600.00
3	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET AND BOTH HEADLIGHT.RENEW LOCK CARRIER AND ALIGN TO POSITION.REORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,450.00	875.00
4	TO RESPRAY FRONT BUMPER AND BONNET	New	1,050.00	700.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	150.00	150.00
6	TO REPAIR AND RESPRAY FRONT SUPPORT PANEL	New	800.00	350.00
Gross Labour Cost (S\$)			5,200.00	2,825.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >