rom (Person): C	non shu N	ai agnal or				Detc/T	ime;	9/2/1	90
Estimated Cost; OD/FP WS/	TP RES / OD E	PS I FVA I I	MW / MW	Bill to:		••			
To Inspect Vehic	le No:	GBB	5177 (	5	Ins	sured:	Sku	1970	91A
at Workshop m/s		New	Harle	TOCK		Tel-	674	790	41
of		1 leaglei B	ikt A	ve 6 #	01-43	3			
Policy No:_D	and teen	1700000	ŚŚ	Claim N	lo:	CMID	1900	0933	3
Sum Insured:				Exces					
Make of Veh: (Client's Record)						D.O.A	161	02/	2010
CA / REV / R	EP. / REV 24	HRS				H.O.I	). Endorsen	nent:	
Date/Time: 3.5	spmo 19/2/	Person	Contacted	Suk	(yi	Vchicle(	nolai	Г	
Date/Time /	ction/Instructio	n ( )	Estima	te			-		
	1BB 51770	-×	14						
	3KU 9791	A-X							
2012/10/	721hv0	vailant	140	menu	010	newdo	101	estin	note

# ...CLAIM SUBFOLDER...(New Assignment)

LAIM SUBF	OLDER TRA	CKING							
Case 1	Votified	Est Submitted	Adj Assigned	Adj Rpt	Adj Sub	mitted	Ins Auth'ed	Status	
Main	16 Feb 2019		19 Feb 2019 10:44 Assign					grand manner	ssignment   Case
М	ain	Re	ference		Claim Details		Docume	nts	Show All
CLAIM SUB	FOLDER DE	TAILS		- Harrison City Communication	CONTRACTOR STATE	[Create	ed by insurer]	and the second state	Section Assessment Control
Insured:	ETHOZ GE	ROUP LTD, Co. F	keg. No.: 19810	4531H					
Main Claimant:	KIAN TIO	NG EGGS SUPPL	IER TRADING,	Co. Reg. No	o.: 53090127K				
Vehicle Reg. No.:	GBB517	7G			Date of Loss:	16/02/2	019 11:00 - :59		
Claim Type:	Policy/Cover Note No.: D19MTRENT000060 (Third Party Only)					у)			
Vehicle Reg. No. (Insured):	SKU9791	A			Policy No. (Claimant):				
					Excess:	1			
Repairer:	New Hock	Teck Motor Pte	Ltd (HQ) 1 Kak	ki Bukit Ave 6	, Blk C #01-43	Autobay@	Kaki Bukit, 4178	83 Kaki Buk	cit - Tel: 6747 9241
Handling Insurer:	Sompo In	surance Singapo	ore Pte. Ltd. (H	IQ) - Tel: 646	1 6555 [Han	dled by C	HAN SHU HUI A	<b>GNES -</b> 63	29 5327]
Adjuster:	LKK Auto	<b>Consultants Pte</b>	Ltd (HQ) - Tel:	6256-3561 .	[Final Rpt	due 28/	02/2019]		
Driver/Custo dian (Insured):		YUE (), NRIC: G	3839667L, Tel	: +65915621	82		28		
ASSOCIATE	D MAIL RE	CEIVED						View All	Compose Case Mai
There are no	mail for this	case.							
ALL ASSOC	CIATED TAS	ks⊟				View A	II Search Tasks	Create N	New Task   Complete
Due Date No results,	Priority	Type Task	Group Subj	ject Hand	ller Assign	ed By	Completed O	n Cre	eated On Done

## **View Sent Message**

This mail is associated with :

\*GBB5177G (CMTD1900933) [SKU9791A]

TP KIAN TIONG EGGS SUPPLIER TRADING Feb 16 2019 11:00AM [ETHOZ GROUP LTD] New Hock Teck Motor Pte Ltd

View Recipients | Print Message | Delete Message | Forward Resend

LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on 22/02/2019 17:31 PM. From

agnes.chan@sompo.com.sg

GBB5177G (CMTD1900933) [SKU9791A] Subject

Please be informed that we have inspected the vehicle GBB 5177G on 19/02/2019 We are pending estimate from repairer.

Best Regards, Denise Tay | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

#### **DOCUMENTS SUMMARY**

There are no documents.



**New Cars** 

**Used Cars** 

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



## **ANNOUNCING Carway**

as sgCarMart Premium Dealer for the 2<sup>nd</sup> Consecutive Year



SEARCH Toyota Dyna

Price Range

▼ Depreciation ▼ 2009

▼ Vehicle Type

Y 3 Search

#### ▶ Used Car Comparison

--- Comparing 4 Vehicles ---

Toyota Dyna 150 (New 5-yr COE)

Toyota Dyna 150 (Nev







Clear All Add all to Shortlist

Back to search result

Back to search result	· HERDERSCHEINE STEINER STEINE	THE VERY CONTRACTOR OF THE PARTY OF THE PART		
CAR DETAILS			<b>加州的社会</b>	
Price	\$33,800	\$30,800	\$31,800	\$31,800
Instalment	N.A.	N.A.	N.A.	N.A.
Registration Date	05-Mar-2009	26-Mar-2009	25-May-2009	25-May-2009
Manufactured	2009	2009	2009	2009
Mileage			168,257 km	
Transmission	Manual	Manual	Manual	Manual
Engine Cap	2,982 ℃	2,982 cc	2,982 cc	2,982 cc
Road Tax		•	•	
Power				
Curb Weight	1,760 kg	1,660 kg	1,660 kg	1,660 kg
Features		Delivering A Class Leading Payload, The Toyota Dyna Also Comes With Excellent Fuel Efficiency And A Spacious Cabin To Fulfil Your Business Needs.	Top Choice For All Successful Business,	One Of The Most Lorry In The Mark And Also A Power Business.
Accessories	New Paintwork, New Leather Seat,	Sturdy Exterior, Comfortable Interior, Impressive Performance, Superior Safety. They Are Fitted To The Rear Axle With Dual Tires.	¥	Full Rear Checker
Description	Owner! Drive By Owner Only, Silent Powerful 1KD Euro 4 Turbo Engline, Suitable For Start Up Business And Parts Had Been Replace Or Change! Call Fast, New 5 Years COE To Go Along, Additional To Go Along With Either Canopy Or Box Includsive	With The Powerful 3.0 Lieter 80 KW/109 PS Common Rail Diesel Engine And Enormous Load Capacity They Are Almost No Limits Set. It Has Comfortable Interior And Exterior And Equipped With All Best Technologies That Requires For A Truck, 100% Loan And High Trade In Available, 10 Years Optional At \$48800 Now! Wait No More! Call Us For Appointment Now To Meet This Delivery Beast!	Good To Go For Another 5 Years. No Repairs Needed. Easy Approval For Loan. Price Negotiable. Kindly Call Our Friendly Sale Consultant Now.	Well Maintained! Very Good Condit Whole Vehicle Is Serviced Regular! In Welcomed! Cai Appointment To V For Your Business
COE		(A)		
OMV	\$24,243	\$24,243	\$24,970	\$24,970
ARF	\$1,213	\$1,213	\$1,249	\$1,249
Depreciation	\$6,760 /yr	\$6,160 /yr	\$6,360 /yr	\$6,360 /yr
No. of Owners	2	1	2	2
Type of Vehicle	Truck	Truck	Truck	Truck
Category	COE Car	COE Car, Premium Ad Car	COE Car	COE Car
Availability	Available	Available	Available	Available
Remarks	A CONTROL OF THE CONT	98000-1728TTD-164	And the second s	and the second s



Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



# **ANNOUNCING Autotrust Traders Pte Ltd**

as sgCarMart Premium Dealer for the 3rd Consecutive Year





Post an Advertisement Sell it yourself Advertise it at just \$58 until it's SOLD! New 5 Years Coe Renewal Toyota Wish 1.8A

2.68% P.A Low Interest®GV
Finance. 2 Years Warranty.
\$3800 Down Monthly From \$73







Toyota Dyna 150 (COE till

One Owner, Very Well Kept Vehicle, No Repair Needed, Loan Available.

\$52,800 \$5,280 /yr

04-Mar-2009

2,982 cc

Truck

Available

Fuel Type:

Toyota Dyna Box Height 6.5ft With 2 Sliding Doors! Brand New Paintwork And Upholstery! Renew 10 Years COE. Can Loan Up 84 Months! Door Step Viewing Possible! High Loan, Low Interest! Kindly Call Our F...

ABWIN (1994) Pie Ltd

Fuel Type: Diesel



## > Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID: Vehicle Details	0127K
Vehicle No.:	GBB5177G
Vehicle to be Exported:	Yes
Intended Deregistration Date:	07 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 MANUAL 3SEATER
Primary Colour:	Silver
Manufacturing Year	2009
Engine No.:	1KD1923657
Chassis No.:	JTFAT35Y20K200532
Maximum Power Output:	**************************************
Open Market Value:	\$24,970.00
Original Registration Date:	18 May 2009
First Registration Date:	18 May 2009
Transfer Count:	1
Actual ARF Paid:	\$1,249.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	
PARF Rebate Amount:	\$0.00
Intended COF Rebate Details	
COE Expiry Date:	31 Mar 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$13,378.00
COE Rebate Amount:	\$127.00
Total Rebate Amount:	\$127.00
Message	

vehicle.

The information contained herein is correct as at 07 Mar 2019

#### > Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Business

Owner ID:

0127K

Vehicle Details

Vehicle No.:

GBB5177G

Vehicle to be Exported:

No

Intended Deregistration Date:

16 Feb 2019

Vehicle Make:

TOYOTA

Vehicle Model:

DYNA 150 MANUAL 3SEATER

Primary Colour:

Silver

Manufacturing Year:

2009

Engine No.:

1KD1923657

Chassis No.:

JTFAT35Y20K200532

Maximum Power Output:

Open Market Value:

\$24,970.00

Original Registration Date:

18 May 2009

First Registration Date:

18 May 2009

Transfer Count:

Actual ARF Paid:

\$1,249.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

\$0.00

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

17 May 2019

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

QP Paid:

\$6.610.00

COE Rebate Amount:

\$167.00

Total Rebate Amount:

\$167.00

The information contained herein is correct as at 16 Feb 2019

OK

MSIAE19022719 / SME Motor Pto Lite - Kaki Bukit ENTRY DATE & TIME 18/02/2019 17 08 SUBMITTED BY: Chia Pei Ying

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

13/06 6013 1UL IV. J.

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

AC	:CI	DEN	I SI	ATE	MENI

Date Of Report

18/02/2019 17:08

Date Of Accident

16/02/2019 11:30

Exact Location Of Accident

CTE BEFORE BRADDELL RD EXIT 10

Country/State of Loss

SINGAPORE

#### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number

GBB5177G

Insured/Policyholder

Name Of Registered Owner

KIAN TIONG EGGS SUPPLIER TRADING

Co Reg No

53090127K

Email Address

NOEMAIL

Mobile Phone No

Alternative Phone No

OFFICE-97543833

Vehicle Particulars

Manufacturer

TOYOTA

Model

DYNA

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No. Please state action to be taken

THIRD PARTY

Vehicle Category

COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

5097351913-01

Cover Note Number

Driver

Name of Driver

LIU FUBO

NRIC No

G2030825M

Date Of Birth

29/07/1984

Occupation

OUTDOOR

Date Of Driving Pass

07/05/2018

Driving Experience

0 YEAR AND 9 MONTH

Gender

MALE

Mobile Number

(LOCAL) +65-97821877

Fax Number

Contact Number

NOEMAIL

EMail Address

Page 1 of 16

Address

Postcode

Was driver an employee of the Insured's Company YES

If No. Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

COLLISION - CHANGE/CROSS LANE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

involved in the accident

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

2

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

#### Circumstances of Accident

I WAS DRIVING STRAIGHT ALONG CTE BEFORE BRADDELL RD EXIT 10 AT 4TH LANE OF 5 LANES. SUDDENLY, VEHICLE B FROM THIRD LANE DROVE WITH FAST SPEED AND ENCROACHED INTO MY LANE DUE TO HE WANT TO CHANGE TO FIFTH LANE (BRADDELL ROAD EXIT). I JAMMED BRAKE TRY TO AVOID IT BUT UNFORTUNATELY, UNABLE TO AVOID AND CAUSE THE ACCIDENT HAPPENED. DUE TO THE STRONG IMPACT, ALL EGGS INSIDE MY LORRY IS BROKEN, BOTH OF US ALIGHTED, VEHICLE B ADMITTED HIS FAULT AND APOLOGISED TO ME.

#### Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

NO

Was there any audio recorded?

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SKU9791A

Vehicle Make/Model/Colour

VEHICLE B

Details Of Properties Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

171 V 101 101 101 101 11 170

MICOSYCOS

## **DETAILS OF INJURED PERSON 1**

Name

LIU FUBO

Approximate Age

Injuries Sustain

Injured person in which vehicle?

GBB5177G

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1 Please report correctly the details of the accident to speed up the claims process
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrecresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  Interested parties.
- By the lodgment of this report to the insurers, you nereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disciosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detaction, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

建忠蛋行贸易 KIAN TIONG EGGS SUPPLIER TRADING

Blk 213 Yishun St 21 #07-175 Singapore 760213

Po**Hip: \$754 S\$33**ura Date & Time:


Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name: NBIC/FIN No.:

25820 Seed/University

NEW HOCK TECK

SKETCH PLAN

12/02 FOIS INE INFOR LWV



I was driving straight along (12 before bradden Rd ext 10 at 4th lane	
of 5 lanes. Suddenly, yeth "B" from 3rd lane drove with very flust speed and	
encroached into my lane due his warm to change to 5th lane (Brouddell R	d &11 10)
avoid and caused the accident happened.	
Due to the strong impact, all eggs inside my long is broken.  Both of us anighted veh "8" admitted his fault and apologised with me	波

DECLARATION

I/We declare the foregoing particulars are true in every respect.

蛋行贸易 KIAN TIONG EGGS SUPPLIER TRADING
Blk 213 Yishun St 21 #07-175 Singapore 760213
H/p: 9764 3833
Policyholder's Signature
Date & Time:

Driver's Signature (If driver is not the policyholder) Date & Time

19 p 12.55pm

Reporting Centre Personnel's Signature Name: NRIC/FIN No.



















# 新福德車廠私人有限公司

# NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883 Email: admin@nhtmotor.com

Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

16/02/2019

Blk 1 Kaki Bukit Ave 6

# 01-43

7P. Soupo

JTFAT35 Y20 K200532

Singapore 417883

Accident date: 16/02/2019

Estimated repair cost for vehicle no: GBB5177G TOYOTA DYNA 150 3.0 M '09

CHASSIS: ITEAT35Y20K200532

S/n	Qty	Items	U/price	Amount
1	1	Front Windscreen Shattered.		\$1,271.85
2	1	Front Windscreen Rubber New		\$371.80
3	1	Front Windscreen Erp Sticker		\$20.00
4	1	Front Wiper Panel Deuted		\$381.10
5	1	Front Wiper Panel Lower Cover Could.		\$132.25
6	2	Front Wiper Panel Lower Side Lit Missing	\$131.90	\$263.80
7	2	Front Wiper Nozzle	\$43.00	\$86.00 -
8	1	Front Wiper Arm Link 100 Nec		\$139.60
9	1	Front Panel Distorled		\$974.45
10	1	Front Panel Dyna Logo		\$85.00
11	2	Front Side Panel LH Buderd.	\$182.25	\$364.50
12	2	Front Side Panel Top Cover Repus		\$132.10
13	4	Front Side Panel Top Cover Clips	\$6.50	\$26.00
14	1	Front L/H Side Mirror		\$561.60
15	1	Front L/H Side Mirror Bracket		\$781.80
16	1	Front L/H Side Mirror Bracket Cover		\$787.40
17	1	Front L/H Side Mirror Cover		\$171.40
18	1	Front L/H Side Mirror Cover (small)		\$132.25
19	1	Front Grille Smashed		\$371.40
20	5	Front Grille Clips	\$6.50	\$32.50
21	2	Front Head Lamp Cruck	\$781.90	\$1,563.80
22	2	Front Head Lamp Lower Rubber Ht Mec	\$132.10	\$264.20
23	1	Front Bumper Distard.		\$474.25
24	1	Front Bumper Number Plate Creded		\$50.00
25	1	Front Bumper Reinforcement		\$291.25
26	1	Front Bumper Centre Chassis Member >>> 4	~	\$674.45
27	1		leed.	\$1,800.90
28	1	Front Air-Con Coolant Coil Section Pipe		\$398.90
29	1	Front Air-Con Coolant Coil Discharge Pipe		\$386.60

30	1	Front Air-Con Air Duct & Blower Assy Revended		\$978.10
31	1	Front Floor Panel		\$3,500.00 *
32	1	Front Dashboard chulced		\$972.45
33	1	Front Console Box ZNF		\$388.60
34	2	Front Seat Cushion	\$950.00	\$1,900.00 +
35	1	Front Air-Con Blower Coolant Coil Assy Pepeated.		\$561.60
36	1	Front Air-Con Heater Blower Assy		\$1,217.85
37	1	Front Centre Member Shaft Assy		\$781.45
38	1	Front Centre Member Mounting		\$232.10
39	2	Front Centre Member Mounting Bracket	\$241.10	\$482.20
40	1	Front Steering Box		\$3,598.50
41	1	Front Brake Master Pump		\$1,052.00
42	1	Front Brake Bracket		\$174.40
43	1	Front Clutch Cable		\$191.60
44	1	Front Radiator Dended		\$981.85
45	1	Front Radiator Fan Crucked		\$245.70
46	1	Front Radiator Fan Cowling 2		\$281.75
47	1	Front Radiator Fan Clutch		\$377.40
48	1	Front L/H Door Bucked		\$1,549.10
49	2	Front L/H Door Hinge New	\$132.10	\$264.20
50	1	Front L/H Door Company Sticker New		\$30.00
51	1	Front L/H Door Inner Lock Jamed		\$277.75
52	1	Front L/H Door Inner Rubber M4 ~		\$234.10
53	1	Front L/H Door Inner Lower Rubber		\$271.85
54	1	Front L/H Door Inner Trim Board		\$741.90
55	1	Front L/H Door Inner Gear Motor Assy		\$581.90
56	1			\$631.35
57	1	Front L/H Step Panel Garnish 'xlam		\$318.35
58	1	Front L/H Arch Panel		\$271.75
59	1	Front L/H Arch Panel Garnish Men		\$281.90
60	1	Front R/H Door Briefed	ć122.10	\$1,549.10
61	2	Front R/H Door Hinge Not ~	\$132.10	\$264.20
62	1	Front R/H Door Company Sticker		\$30.00
63	1	Front R/H Door Inner Lock		\$277.75
64	1	Front R/H Door Inner Rubber   ~		\$234.10
65	1	Front R/H Door Inner Lower Rubber H ~		\$271.85 +
66	1	Front R/H Door Inner Trim Board New		\$741.90
67	1	Front R/H Door Pillar Outer		\$631.35
8	1	Air Con Fon Assy (Side) Brilly 955  Air Con Fon Assy (Side) 498	Subtotal :-	\$40,363.10
69	1	Air Con Fan Assy (Side ) 498		19077-15
70	1	Front LH DOX 6/433 Shutlerec 650-10		
7 (	1	Front LH Poor 6143 Outer moulding 200 33.90		14307-86
72	1	Glove Box cauled 395		
73	1	Air Tank Deved 19380.		
74	(	Wiper Motor Dend 258		

## Labour charges

\$120.00
\$50.00
& send vehicle for \$480.00 <sup>200</sup>
s380.00 220°
\$380.00 220. air duct blower \$750.00 300.
teering pump, \$480.00 200
otor, trim board, \$180.00 &
\$3,500.00 8.50
\$3,500.00 \$50.00 \$200.00 30 \$150.00 60
\$200.00 60
\$3,000.00 1800 nce notify ng:
Daiotino
Subtotal:- \$11,490.00
Total:- \$51,853.10 Insurance Company  Total:- \$51,853.10
toled: 20077.86
4/s: 16k.
16 Days.
tants her te follow after spray parts; dun son a 'Wir pon's is allowed to con a 'Wir pon's is allowed to contact the contact t

## LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No:

D19MTRENT000060

Engine No:

Chassis No:

Odometer:

CS/SMO19003094/ATD3N2

1KD1923657

492387 km

JTFAT35Y20K200532

Date:

03/04/2019

REFERENCE

Handling Insurer: Claimant Sompo Insurance Singapore Pte.

GBB5177G

Policy No: No:

Insured Vehicle

SKU9791A

Vehicle No: Date of Loss:

16/02/2019

Nature of Claim:

TP

Claim

CMTD1900933

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

GBB5177G

Make & Model:

TOYOTA DYNA 1.5T, 3.0 (A)

18/05/2009 (Man. Year: 2009)

Reg. Date: Colour:

Grey 2982 cc

**Engine Capacity:** Market Value/New Car

N/A

Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes Engine Modification:

Yes Footbrake (Serviceable): No Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

195 R15C Michelin 6 mm Rear Tyre Size: Rear Left Side:

155 R12C Journey 6 mm

Front Left Side: Front Right Side:

Michelin 6 mm

Rear Right Side:

Journey 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's 14,968.87	Difference 28,518.03	Diff % 65.58
Parts Miscellaneous Items	43,486.90 0.00	0.00	0.00	00.00
Labour	11,490.00	5,770.00	5,720.00	49.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00		
Calculated Gross Total (S\$)	54,976.90	20,738.87	34,238.03	62.28
Approved Total (Overridden) (S\$)		16,000.00		
(S\$)	54,976.90	16,000.00	38,976.90	70.90
+ GST 7.00/7.00% (S\$)	3,848.38	1,120.00	2,728.38	70.90
Nett Amount (S\$)	58,825.28	17,120.00	41,705.28	70.90

INSPECTION

Date of Assignment:

19/02/2019

Date Inspected:

19/02/2019 Inspected At:

New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Blk C #01-43

Autobay@Kaki Bukit Singapore 417883

Estimated Period of Repair:

16.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 03 Apr 2019)

Parts: TOYOTA DYNA 1.5T 3.0 (A) (Model not available in database) N/A

(Price-denominated Standard List) Labour: Repairer's Print Code: (Unsubmitted, no print-code for GBB5177G)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page Validity:

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

Roc	omn	one	hat	Parts
	CHILL	HEIR	160	Falls

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT WINDSCREEN	Shattered	1,271.85 F	*1,271.85 FL
2	1	*FRONT WINDSCREEN RUBBER	Necessary	371.80 F	*371.80 FL
3	1	*FRONT WINDSCREEN ERP STICKER	Necessary	20.00 F	*20.00 FL
4	1	*FRONT WIPER PANEL	Dented	381.10 F	*381.10 FL
5	1	*FRONT WIPER PANEL LOWER COVER	Cracked	132.25 F	*132.25 FL
6	1	*FRONT WIPER PANEL LOWER SIDE	N/S Missing	263.80 F	*131.90 FL
7	2	*FRONT WIPER NOZZLE	Cracked	86.00 F	*86.00 FL
8	1	*FRONT WIPER ARM LINK	Not Necessary	139.60 F	*-FL
9	1	*FRONT PANEL	Distorted	974.45 F	*974.45 FL
10	1	*FRONT PANEL DYNA LOGO	Necessary	85.00 F	*85.00 FL
11	1	*FRONT SIDE PANEL	N/S Buckled	364.50 F	*182.25 FL
12	2	*FRONT SIDE PANEL TOP COVER	Repair	132.10 F	*- FL
13	4	*FRONT SIDE PANEL TOP COVER CLIPS	Not Necessary		*-FL
14	1	*FRONT L/H SIDE MIRROR	Not Necessary		*- FL
15	1	*FRONT L/H SIDE MIRROR BRACKET	Not Necessary	781.80 F	*- FL
16	1	*FRONT L/H SIDE MIRROR BRACKET COVER	Not Necessary		*- FL
17	1	*FRONT L/H SIDE MIRROR COVER	Not Necessary	171.40 F	*-FL
18	1	*FRONT L/H SIDE MIRROR COVER (SMALL)	Not Necessary	132.25 F	*- FL
19	1	*FRONT GRILLE	Smashed	371.40 F	*371.40 FL
20	5	*FRONT GRILLE CLIPS	Necessary	32.50 F	*32.50 FL
21	2	*FRONT HEAD LAMP	Cracked	1,563.80 F	*1,241.60 FL
22	2	*FRONT HEAD LAMP LOWER RUBBER	Not Necessary	264.20 F	*-FL
23	1	*FRONT BUMPER	Distorted	474.25 F	*474.25 FL
24	1	*FRONT BUMPER NUMBER PLATE	Cracked	50.00 F	*30.00 FL
25	1	*FRONT BUMPER REINFORCEMENT	Bent	291.25 F	*291.25 FL
26	1	*FRONT BUMPER CENTRE CHASSIS MEMBER	Not Necessary	674.45 F	*- FL
27	1	*FRONT AIR-CON COOLANT COIL & BLOWER ASSY	Cracked	1,800.90 F	*1,098.00 FL
28	1	*FRONT AIR-CON COOLANT COIL SECTION PIPE	Not Necessary	398.90 F	*- FL
29	1	*FRONT AIR-CON COOLANT COIL DISCHARGE PIPE	Not Necessary	386.60 F	*- FL
30	1	*FRONT AIR-CON AIR DUCT & BLOWER ASSY	Repeated	978.10 F	*- FL
31	1	*FRONT FLOOR PANEL	Repair	3,500.00 F	*- FL
32	1	*FRONT DASHBOARD	Cracked	972.45 F	*972.45 FL
33	1	*FRONT CONSOLE BOX	Not Necessary	388.60 F	*- FL
34	2	*FRONT SEAT CUSHION	Not Necessary	1,900.00 F	*- FL
35	1	*FRONT AIR-CON BLOWER COOLANT COIL ASSY	Repeated	561.60 F	*- FL
36	1	*FRONT AIR-CON HEATER BLOWER ASSY	Cracked	1,217.85 F	*1,217.85 FL
37	1	*FRONT CENTRE MEMBER SHAFT ASSY	Bent	781.45 F	*781.45 FL
38	1	*FRONT CENTRE MEMBER MOUNTING	Damaged	232.10 F	*232.10 FL
39	2	*FRONT CENTRE MEMBER MOUNTING BRACKET	Bent	482.20 F	*482.20 FL
40	1	*FRONT STEERING BOX	Not Necessary	3,598.50 F	*- FL
41	1	*FRONT BRAKE MASTER PUMP	Not Necessary	1,052.00 F	*- FL
42	1	*FRONT BRAKE BRACKET	Not Necessary	174.40 F	*- FL
43	1	*FRONT CLUTCH CABLE	Not Necessary	191.60 F	*- FL
44	1	*FRONT RADIATOR	Dented	981.85 F	*981.85 FL

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
45	1	*FRONT RADIATOR FAN	Cracked	245.70 F	*182.00 FL
46	1	*FRONT RADIATOR FAN COWLING	Not Necessary	281.75 F	*- FL
47	1	*FRONT RADIATOR FAN CLUTCH	Not Necessary	377.40 F	*- FL
48	1	*FRONT L/H DOOR	Buckled	1,549.10 F	*1,549.10 FL
49	2	*FRONT L/H DOOR HINGE	Not Necessary	264.20 F	0F *30.00FL 5F *277.75FL 0F *-FL
50	1	*FRONT L/H DOOR COMPANY STICKER	Necessary	30.00 F	
51	1	*FRONT L/H DOOR INNER LOCK	Jammed	277.75 F	
52	1	*FRONT L/H DOOR INNER RUBBER	Not Necessary	234.10 F	
53	1	*FRONT L/H DOOR INNER LOWER RUBBER	Not Necessary		
54	1	*FRONT L/H DOOR INNER TRIM BOARD	Deformed	741.90 F	*741.90 FL
55	1	*FRONT L/H DOOR INNER GEAR MOTOR ASSY	Not Necessary	581.90 F	*- FL
56	1	*FRONT L/H DOOR PILLAR OUTER	Buckled	631.35 F	*631.35 FL
57	1	*FRONT L/H STEP PANEL GARNISH	Not Necessary	318.35 F	*- FL
58	1	*FRONT L/H ARCH PANEL	Repair	271.75 F	*- FL
59	1	*FRONT L/H ARCH PANEL GARNISH	Not Necessary	281.90 F	*- FL
60	1	*FRONT R/H DOOR	Buckled	1,549.10 F	*1,549.10 FL
61	2	*FRONT R/H DOOR HINGE	Not Necessary	264.20 F	*- FL
62	1	*FRONT R/H DOOR COMPANY STICKER	Necessary	30.00 F	*30.00 FL
63	1	*FRONT R/H DOOR INNER LOCK	Not Necessary	277.75 F	*- FL
64	1	*FRONT R/H DOOR INNER RUBBER	Not Necessary		
65	1	*FRONT R/H DOOR INNER LOWER RUBBER	Not Necessary	271.85 F	
66	1	*FRONT R/H DOOR INNER TRIM BOARD	Not Necessary	741.90 F	*- FL
67	1	*FRONT R/H DOOR PILLAR OUTER	Repair 631.35 F		*-FL
68	1	*AIR CON FAN ASSY (SIDE)	Distorted	498.00 F	*498.00 FL
69	1	*FRONT LH DOOR GLASS	Shattered	650.10 F	*650.10 FL
70	1	*FRONT LH DOOR GLASS OUTER MOULDING	Deformed	133.90 F	*133.90 FL
71	1	*GLOVE BOX	Cracked	395.00 F	*395.00 FL
72	1	*AIR TANK	Dented	193.80 F	*193.80 FL
73	1	*WIPER MOTOR	Damaged	298.00 F	*298.00 FL
74	1	*AIR CON CONDENSER (SIDE)	Distorted	955.00 F	*955.00 FL
F=Fra	nchise	part. L=ListItemDisc.			
			Sub Total (S\$)	43,486.90	19,958.50
		- List Item Discount on L Items			4,989.63
			Total Parts (S\$)	COLOR D'ESSONS	14 069 97

Total Parts (S\$) 43,486.90 14,968.87

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

		<ul> <li>Intersection and accommodate</li> </ul>
Recomme	nded	ahour
Decomme	IIUCU	Laboui

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items		1805200000	
1	TO REMOVE & REFIT FRONT WINDSCREEN	New	120.00	120.00
2	GUM	New	50.00	50.00
3	TO REMOVE & REFIT SEAT CUSHION , PLYWOOD & SEND VEHICLE FOR CLEANING SERVICE	New	480.00	200.00
4	TO REMOVE & REFIT DASHBOARD & CONSOLE BOX	New	380.00	220.00
5	TO REMOVE & REFIT AIR-CON COOLANT COIL & AIR DUCT BLOWER PIPE ,RADIATOR,FAN MOTOR & TOP UP GAS	New	750.00	300.00
6	TO REMOVE & REFIT BRAKE MASTER PUMP, STEERING PUMP, STEERING BOX AND BRACKET	New	480.00	200.00
7	TO REMOVE & REFIT FRONT L/H DOOR GEAR MOTOR ,TRIM BOARD,GLASS ,LOCK & RUBBER	New	180.00	80.00
8	TO REPAIR FRONT CHASSIS FRAME	New	3,500.00	850.00
9	TO CHECK WIRING	New	200.00	30.00
10	TOWING FEE	New	150.00	60.00
11	TUFF KOTE	New	200.00	60.00
12	PANEL BEATING	New	3,000.00	1,800.00
13	SPRAY PAINTING	New	2,000.00	1,800.00
	Gross Labou	Gross Labour Cost (S\$)		5,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >