

Torque 5 Pte Ltd (Co.Reg.No:201313221G)

No. 8 Kaki Bukit Ave 4,, #01-50

Singapore 415875

Tel: 64524457 Fax: 64524584 Email: sam.chang@torque5.com

INSURER: FWD Singapore Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	SLD 5018 D
Policy No:	PNPV2018-00006213	Date of Loss:	17/02/2019
Vehicle Reg. No.:	SLD5018D	Driveable?	
Driver Age/Info:	47 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ZACCHAEUS SIEW YONG PAU	Contact No:	+6598796781
Driver:	ZACCHAEUS SIEW YONG PAU		

Make/Model:	TOYOTA AXIO, 1.5 (A)	Vehicle Reg. Date:	20/06/2016
Vehicle Colour:	BLACK		
Engine No:	2NR8568349	Chassis No:	NRE1610014379
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	5

Description of Accident/Loss	REFER TO ATTACHMENT
------------------------------	---------------------

Remarks:	VEHICLE CURRENTLY IN WORKSHOP.. KINDLY MAKE NECESSARY ARRANGEMENT..
----------	---

Present Location:	TORQUE 5 PTE LTD (KAKI BUKIT)
-------------------	-------------------------------

COST OF CLAIMS

	Amount
Parts	1,020.00
Miscellaneous Items	85.00
Labour	1,330.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,435.00
+ GST 7.00% (S\$)	170.45
Nett Amount (S\$)	2,605.45

This claim is handled by: STEPHANIE TEO WAN TING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Feb 2019)

Parts: 143 TOYOTA AXIO 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLD5018D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET / Bue	0.00	0.00	*220.00 F
2	1		*RADIATOR GRILLE / BR	0.00	0.00	*160.00 F
3	1		*FRONT BUMPER / BR	0.00	0.00	*180.00 F
4	2		*FRONT BUMPER RETAINER (LH+RH) / ce	0.00	0.00	*50.00 F
5	1		*FRONT BUMPER LOWER GRILLE / BR	0.00	0.00	*110.00 F
6	1		*HEAD LAMP (RH) / CRA	0.00	0.00	*300.00 F

F=Franchise part.

Total Parts (S\$) **1,020.00**

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRONT BUMPER CLIP SET / dec	45.00
2	1	FRONT NUMBER PLATE & CASING / CAA	40.00
Sub Total (\$\$)			85.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO CHECK WIRING & LIGHTING SYSTEM & FOCUS HEAD LAMP	New 30	40.00
2	TO PERFORM ANTI-RUST, UNDERCOATING ON AFFECTED AREAS	New 30	30.00
3	TO REPAIR, REPLACE & REALIGN DAMAGED AREAS	New 600	660.00
4	TO SPRAY PAINTING ON AFFECTED AREAS	New 500	600.00
Gross Labour Cost (\$\$)			1,330.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

4 Days.

part by part

before paint photos.

Gmo Qiy

20/2/19.

Not Authorised.

Excess \$500

