

7/20/2011  
7833, REV. 1/07

REP es/smo19003098/ U fd3 <sup>n2</sup> Special Instructions

SALVAGE

ASSIGNMENT (Office)

From (Person)

Gnsh Paulang

of

SMO

Date/Time

19/2/19 @ 3:59pm

Estimated Cost

Bill to

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No

XE 3790Y

Insured

XD 6272L

at Workshop n/s

Think one auto

Tel

928 8488

of

No. 18 Defn Ave 2

Policy No

DIEMTHCVE002311

Claim No

CMTD1900967

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A

18/2/19

CA / REV / REP. / REV 24 HRS

lup

20/2/19

H.O.D. Endorsement

Date/Time

5:23pm @ 19/2/19

Person Contacted

Koen

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

XE 3790Y - X

XD 6272L - X

27/2-

Revised via menmen preli advise.

REF: SMO

## ASSIGNMENT

Event: Date: 20/2/19

Estimated Cost:

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: XE 3790X

at Work/Shop no: Think one

of No 18 Defn Ave 2

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt. Consistent?: Yes or No

GIA: PR Seen: 2 Consistent?: Yes or No

Est. Repairs: 2 days Res: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP: / 24 HRS (up)

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: XE 3790X Page: 12 17

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Crane / Mower /

Truck / Trailer or

Make: UD Trucks 10837

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 26245 T/Radio: Insured / Std / NI / NA

Eng/No:

C/Ho: JNCMIFIASJU026857

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: M / S/Rim / STD A/Rim or

Tyre Size: F: 11 R 22.5

R:

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6/6 mm

L/Bal: 6 mm L/Bal: 6/6 mm

D.O.A. 18/2/19 D.O.I. 20/2/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Lt & Rt w/ screen cracked!  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27/2/19 confirmed 4/5 # 2000 with Karen. (Red: 2843420, 9307)  
(Red:)

RECEIVED 28 FEB 2019

Date/Time: File Pass to?

28/2/Typist

Date/Time: File Return to?



: Preli. Report



Final Report

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. fees (\$)



Weekend (\$)

Survey Fee:

Transportation

S + P + S

1. Hacks

1. Other

1. ...

Total:

450  
10

460

Report Format:

Lump Sum / LB 1:15

Tp  
20007-

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Feb 2019		19 Feb 2019 15:59 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	CA TRANSPORTATION & WAREHOUSING PTE LTD, Co. Reg. No.: 199200740D		
Main Claimant:	THINK ONE LEASING PTE LTD, Co. Reg. No.: 201115609M		
Vehicle Reg. No.:	XE3790Y	Date of Loss:	18/02/2019 15:00 - :59
Claim Type:	TP / CMTD1900967	Policy/Cover Note No.:	D18MTHCVE002311 (Comprehensive)
Vehicle Reg. No. (Insured):	XD6272L	Policy No. (Claimant):	
		Excess:	
Repairer:	Think One Autocare Pte Ltd (HQ) No. 18 Defu Avenue 2, 539522 Ubi - Tel: 68443300		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 28/02/2019]		
Adj Asg. Remarks:	WS: KAREN 6844 3300 HP: 9128 8488 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT		

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sampo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: GNOH PAU LOONG

Date: 22 Feb 2019

**Preliminary Advice**

Insured Vehicle No	: XD6272L	Accident Date	: 18/02/2019
TP Vehicle No	: XE3790Y	Assignment Date	: 19/02/2019
Make	: UD TRUCKS GKB85ELDHNT	Est. Duration of Repair	: 0.00
Date of Inspection	: 20/02/2019		
Inspection At	: THINK ONE AUTOCARE PTE LTD (HQ) NO. 18 DEFU AVENUE 2 SINGAPORE 539522		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident. front windscreen cracked

Repairer's Estimate (Gross)	:S\$	10,332.00
Revised Amount	:S\$	1,202.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,202.00
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : Survey on WP

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 5609M

**Vehicle Details**

Vehicle No.: XE3790Y

Vehicle to be Exported: No

Intended Deregistration Date: 20 Feb 2019

Vehicle Make: UD TRUCKS

Vehicle Model: GKB5ELDHNT ESCOT V

Primary Colour: White

Manufacturing Year: 2017

Engine No.: GH11746657

Chassis No.: JNCM1F1A5JU026851

Maximum Power Output: -

Open Market Value: \$76,122.00

Original Registration Date: 13 Dec 2017

First Registration Date: 13 Dec 2017

Transfer Count: 1

Actual ARF Paid: \$3,807.00

**Intended PARF Rebate Details**

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

**Intended COE Rebate Details**

COE Expiry Date: 12 Dec 2027

COE Category: C - Goods Vehicle &amp; Bus

COE Period(Years): 10

QP Paid: \$42,000.00

COE Rebate Amount: \$38,372.00

**Total Rebate Amount: \$38,372.00**

The information contained herein is correct as at 20 Feb 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	18/02/2019 16:52
Date Of Accident	18/02/2019 15:30
Exact Location Of Accident	GREENWICH DRIVE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	XE3790Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	THINK ONE LEASING PTE LTD
Co Reg No	201115609M
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96788288
Alternative Phone No	OFFICE-65553300

### Vehicle Particulars

Manufacturer	UD TRUCKS
Model	GKB5ELDHNT ESCOT V
Exact Purpose for which vehicle was being used at time of accident	PERSONAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	GOODS VEHICLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5070244660-03
Cover Note Number	

### Driver

Name of Driver	IDRIS BIN MUHAMMAD
NRIC No	S6834298H
Date Of Birth	30/09/1968
Occupation	OUTDOOR
Date Of Driving Pass	30/03/1999
Driving Experience	19 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96502369
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	APT BLK 208 PASIR RIS STREET 21 #04-346
Postcode	510208
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON THE 18.02.2019 AT ABOUT 13:30HR. I PARK MY VEHICLE XE3790Y ALONG THE STATED LOCATION ROADSIDE. A 40 FOOTER CONTAINER PASSBY MY VEHICLE FORGET TO CLOSE THE CONTAINER DOOR AND HIT ON MY RIGHT SIDE MIRROR AND CAUSES THE WINDSCREEN TO CRACK.


#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD6272L
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	GOODS VEHICLE
Name of Driver	CHEW SING CHER
NRIC/Passport Number	S1062846F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN



A-XE3790Y

B-XD6272L

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on the 18.02.2019 at about 13:36hr I park my vehicle XE3790Y along the stated location Roadside. A 40-footer container pass by my vehicle forget to close the container door and hit on my Right Side mirror and causes the windscreen to crack.

DECLARATION

I/We declare that the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Think One Autocare Pte Ltd  
18 Defu Lane Avenue 2  
Singapore 539522

Tel: 6644 3300 Fax: 6842 4888

Reporting Centre Personnel's Signature

Name:  
NRIC/FIN No.:



Think One Autocare Pte Ltd  
No.18 Defu Avenue 2  
Singapore 539522  
Tel: 6844 3300 Fax: 6842 4988

XE3790Y UD Trucks

L/S \$ 2000

Not attached  
to the photo of the car  
20/2/19 2 day  
P/2P

No	Qty	Parts Description	Estimated Parts Price
1	1	Front bumper assy (inner)	17 \$ 1,670.00 X
2	1	Front bumper assy (outer)	17 \$ 1,478.00 X
3	1	Front bumper top protector	17 \$ 258.00 X
4	1	Front bumper reinforcement	17 \$ 392.00 X
5	1	Front bumper reinforcement right side bracket	17 \$ 125.00 X
6	1	Front towing hock	17 \$ 186.00 X
7	1	Front towing hock plate	17 \$ 66.00 X
8	1	Front bumper right bracket	17 \$ 65.00 X
9	3	Front bumper right side stay	17 \$ 129.00 X
10	1	Front torsion bar	17 \$ 824.00 X
11	1	Front torsion bar bracket	17 \$ 232.00 X
12	2	Front torsion bar mounting	17 \$ 364.00 X
13	1	Front torsion bar right side absorber	17 \$ 435.00 X
14	1	Front grille assy	17 \$ 552.00 X
15	2	Front grille cover	17 \$ 195.00 X
16	1	Front panel assy	17 \$ 1,780.00 X
17	1	Front panel lock assy	17 \$ 185.00 X
18	1	Front panel lock catch	17 \$ 135.00 X
19	1	Front panel UD emblem	17 \$ 128.00 X
20	1	Front right corner panel	17 \$ 632.00 X
21	3	Front wiper blade	17 \$ 206.00 X
22	1	Front wiper tank	17 \$ 315.00 X
23	1	Front wiper motor	17 \$ 495.00 X
24	1	Front view mirror o/s (big & small)	316 \$ 780.00 ✓
25	1	Front right headlamp	17 \$ 1,480.00 X
26	1	Front right headlamp bracket	17 \$ 220.00 X
27	1	Front right headlamp holder	17 \$ 65.00 X
28	1	Front right signal lamp	17 \$ 155.00 X
			\$ 13,547.00
Less 10%			\$ 1,354.70
			\$ 12,192.30
<u>Special Nett Items</u>			
1	16	Front bumper clips	17 \$ 80.00 X
2	8	Front grille clips	17 \$ 50.00 X
3	1set	Front panel company sticker	17 \$ 650.00 X
4	1	Front no plate	17 \$ 80.00 X
			\$ 860.00
<b>Total Parts</b>			<b>\$ 13,052.30</b>

P-2280  
17  
2052  
2111

**Think One Autocare Pte Ltd**  
**No.18 Defu Avenue 2**  
**Singapore 539522**  
**Tel: 6844 3300 Fax: 6842 4988**

**XE3790Y UD Trucks**

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front right affected area and replace front right damaged parts.	\$ 3,000.00 300
2	To putty and spray painting front right affected portion.	11 \$ 3,000.00 X
3	To apply anti rust proofing to front right affected area.	11 \$ 200.00 X
4	To check wiring and focus front headlamp.	11 \$ 50.00 X
		<u>\$ 6,250.00</u>

**Total parts : \$ 13,052.30**

**Total labour : \$ 6,250.00**

**Total repair cost : \$ 19,302.30**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To describe damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Think One Autocare Pte Ltd  
No.18 Defu Avenue 2  
Singapore 539522  
Tel: 6844 3300 Fax: 6842 4988

**XE3790Y UD Trucks**

			Estimated Parts Price
No	Qty	Parts Description	
<u>Supplementary Items</u>			
1	1	Front windscreen glass	one \$ 11,000.00 ✓
2	1	Front windscreen glass moulding	8u \$ 480.00 ✗
			\$ 11,480.00
Less 10%			\$ 1,148.00
			<u>\$ 10,332.00</u>
<b>Total Parts</b>			<b>\$ 10,332.00</b>

Think One Autocare Pte Ltd  
No.18 Defu Avenue 2  
Singapore 539522  
Tel: 6844 3300 Fax: 6842 4988

**XE3790Y UD Trucks**

No	Description	Labour Charges
1	To remove and install front windscreen glass assy.	\$ 800.00
		<u>\$ 800.00</u>

200

Total parts : \$ 10,332.00  
Total labour : \$ 800.00  
Total repair cost : \$ 11,132.00

## LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19003098/UTD3N2

Date: 01/03/2019

## REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTHCVE002311
Claimant Vehicle No :	XE3790Y	Insured Vehicle No :	XD6272L
Date of Loss:	18/02/2019	Nature of Claim:	TP
		Claim No:	CMTD1900967

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	XE3790Y	Engine No:	GH11746657
Make & Model:	UD TRUCKS GKB85ELDHNT, 10.8 D (M)	Chassis No:	JNCM1F1A5JU026851
Reg. Date:	13/12/2017 (Man. Year: 2017)	Odometer:	26245 km
Colour:	White		
Engine Capacity:	10837 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	11R22.5	Rear Tyre Size:	11R22.5 (D)
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6/6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6/6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	23,384.30	2,052.00	21,332.30	91.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,050.00	500.00	6,550.00	92.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>30,434.30</b>	<b>2,552.00</b>	<b>27,882.30</b>	<b>91.61</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,000.00</b>		
<b>(\$\$)</b>	<b>30,434.30</b>	<b>2,000.00</b>	<b>28,434.30</b>	<b>93.43</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>2,130.40</b>	<b>140.00</b>	<b>1,990.40</b>	<b>93.43</b>
<b>Nett Amount (\$\$)</b>	<b>32,564.70</b>	<b>2,140.00</b>	<b>30,424.70</b>	<b>93.43</b>

## INSPECTION

Date of Assignment:	19/02/2019		
Date Inspected:	20/02/2019	Inspected At:	Think One Autocare Pte Ltd (HQ) No. 18 Defu Avenue 2 Singapore 539522
Estimated Period of Repair:	2.0 days		

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 01 Mar 2019)	
<b>Parts:</b>	N/A	UD TRUCKS GKB85ELDHNT 10.8 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for XE3790Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER ASSY (INNER)	Not Necessary	1,670.00 FL	*- FL
2	1		*FRONT BUMPER ASSY (OUTER)	Not Necessary	1,478.00 FL	*- FL
3	1		*FRONT BUMPER TOP PROTECTOR	Not Necessary	258.00 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	392.00 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT RIGHT SIDE BRACKET	Not Necessary	125.00 FL	*- FL
6	1		*FRONT TOWING HOCK	Not Necessary	186.00 FL	*- FL
7	1		*FRONT TOWING HOCK PLATE	Not Necessary	66.00 FL	*- FL
8	1		*FRONT BUMPER RIGHT BRACKET	Not Necessary	65.00 FL	*- FL
9	3		*FRONT BUMPER RIGHT SIDE STAY	Not Necessary	129.00 FL	*- FL
10	1		*FRONT TORSION BAR	Not Necessary	824.00 FL	*- FL
11	1		*FRONT TORSION BAR BRACKET	Not Necessary	232.00 FL	*- FL
12	2		*FRONT TORSION BAR MOUNTING	Not Necessary	364.00 FL	*- FL
13	1		*FRONT TORSION BAR RIGHT SIDE ABSORBER	Not Necessary	435.00 FL	*- FL
14	1		*FRONT GRILLE ASSY	Not Necessary	552.00 FL	*- FL
15	2		*FRONT GRILLE COVER	Not Necessary	195.00 FL	*- FL
16	1		*FRONT PANEL ASSY	Not Necessary	1,780.00 FL	*- FL
17	1		*FRONT PANEL LOCK ASSY	Not Necessary	185.00 FL	*- FL
18	1		*FRONT PANEL LOCK CATCH	Not Necessary	135.00 FL	*- FL
19	1		*FRONT PANEL UD EMBLEM	Not Necessary	128.00 FL	*- FL
20	1		*FRONT RIGHT CORNER PANEL	Not Necessary	632.00 FL	*- FL
21	3		*FRONT WIPER BLADE	Not Necessary	206.00 FL	*- FL
22	1		*FRONT WIPER TANK	Not Necessary	315.00 FL	*- FL
23	1		*FRONT WIPER MOTOR	Not Necessary	495.00 FL	*- FL
24	1		*FRONT VIEW MIRROR O/S (BIG & SMALL)	Broken	780.00 FL	*780.00 FL
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
25	1		*FRONT RIGHT HEADLAMP	Not Necessary	1,480.00 FL	*- FL
26	1		*FRONT RIGHT HEADLAMP BRACKET	Not Necessary	220.00 FL	*- FL
27	1		*FRONT RIGHT HEADLAMP HOLDER	Not Necessary	65.00 FL	*- FL
28	1		*FRONT RIGHT SIGNAL LAMP	Not Necessary	155.00 FL	*- FL
29	16		*FRONT BUMPER CLIPS	Not Necessary	80.00 FS	*- FS
30	8		*FRONT GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
31	1		*SET FRONT PANEL COMPANY STICKER	Not Necessary	650.00 FS	*- FS
32	1		*FRONT NO PLATE	Not Necessary	80.00 FS	*- FS
33	1		*FRONT WINDSCREEN GLASS	Cracked	11,000.00 FL	*1,500.00 FL
34	1		*FRONT WINDSCREEN GLASS MOULDING	Serviceable	480.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>25,887.00</b>	<b>2,280.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>2,502.70</b>	<b>228.00</b>
<b>Total Parts (\$\$)</b>	<b>23,384.30</b>	<b>2,052.00</b>

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN FRONT RIGHT AFFECTED AREA AND REPLACE FRONT RIGHT DAMAGED PARTS	New	3,000.00	300.00
2	TO PUTTY AND SPRAY PAINTING FRONT RIGHT AFFECTED PORTION	New	3,000.00	0.00
3	TO APPLY ANTI RUST PROOFING TO FRONT RIGHT AFFECTED AREA	New	200.00	0.00
4	TO CHECK WIRING AND FOCUS FRONT HEADLAMP	New	50.00	0.00
5	TO REMOVE AND INSTALL FRONT WINDSCREEN GLASS ASSY	New	800.00	200.00
Gross Labour Cost (\$\$)			7,050.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >