



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving 1 2015 MITSUBISHI FUSO FM65FM2RDEB (YP275T)

Date of Loss 21 January 2019

Time of Loss 11.30

Loss Description YP275T (INSD) C/W YP2962E (TP GREAT EASTERN)

Comment

Workshop Details

Total Rebate Amount 3581

Nett Loss Amount \$82,419.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (OD)

Days of work completion * 20



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# YP275T

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

23/11/2015



Mileage

165706

Age of Vehicle

3

CATEGORY

POLICY
INFORMATION

ASSESSMENT INFORMATION

Manufacturing
Year

2015

2015

Make

MITSUBISHI

MITSUBISHI

Model

FUSO
FM65FM2RDEB

FUSO FM65FM2RDEB

Driver Details

CATEGORY

FNOL INFORMATION

POST SURVEY
INFORMATION

Driver Name

MARUTHAMUTHU
GAVASKAR

Date of Birth

3 June 1985

dd/mm/yyyy



Age

34

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		
Type of Paint		
Chassis No	FM65FMA20094	FM65FMA20094
Engine No	6M60207266	6M60207266
Engine Capacity		7545
Sum Insured	0	0
Market Value	0	86000

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	4	
Driver License #		
License Type		
License Issue Date	1 January 2015	dd/mm/yyyy 
License Expiration Date		dd/mm/yyyy 
Address	NIL, Singapore	
Address type	Personal Correspondence	

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Male	
Marital status	Unknown	
Identification #	G6330107N	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

20/02/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

1000

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Fair ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

11R22.5

Front left side

FIREMAX8mm

Front right side

FIREMAX8mm

Rear Tyre Size

11R22.5(D)

Rear left side

FIREMAX8/8mm

Rear right side

FIREMAX8/8mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add

Approve

Deny

Submit All

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
		0	1		FRT BUMPER (WCP) (10%)	Bent	0	1430	No					1430	Reviewing	
		0	1		FRT BUMPER SIDE (RH) (WCP) (10%)	Missing	0	198	No					198	Reviewing	
		0	1		FRT BUMPER FOGLAMP (RH) (WCP) (10%)	Cracked	0	880	No					880	Reviewing	
		0	1		FRT HEADLAMP (RH) (WCP) (10%)	Broken	0	770	No					770	Reviewing	
		0	1		FRT HEADLAMP HOLDER (RH)	Serviceable	0	0	No					0	Deny	
		0	1		FRT DOOR (RH) (WCP) (10%)	Bent	0	3520	No					3520	Reviewing	
		0	1		FRT DOOR HINGE (TOP)	Serviceable	0	0	No					0	Deny	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
		0	1		FRT DOOR HINGE (BOTTOM)	Serviceable	0	0	No					0	Deny	
		0	1		FRT DOOR LAMP (RH) (WCP) (10%)	Broken	0	82.5	No					82.5	Reviewing	
		0	1		FRT DOOR WHEEL ARCH GARNISH (RH) (WCP) (10%)	Cracked	0	825	No					825	Reviewing	
		0	1		FRT DOOR ROCKER GARNISH	Serviceable	0	0	No					0	Deny	
		0	1		FRT DOOR RUN CHANNEL	Serviceable	0	0	No					0	Deny	
		0	1		FRT DOOR MUDGUARD PROTECTOR (WCP) (10%)	Missing	0	82.5	No					82.5	Reviewing	
		0	1		FRT STEP PANEL (RH) (WCP) (10%)	Broken	0	275	No					275	Reviewing	
		0	1		FRT STEP ALLOY (TOP) (WCP) (10%)	Broken	0	264	No					264	Reviewing	
		0	1		FRT STEP ALLOY (LOWER) (WCP) (10%)	Broken	0	264	No					264	Reviewing	
		0	1		FRT STEP ALLOY HOLDER (LOWER) (WCP) (10%)	Bent	0	440	No					440	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
		0	1		FRT STEP ALLOY BRACKET (LOWER) (WCP) (10%)	Bent	0	198	No					198	Reviewing	
		0	1		FRT STEP PANEL REFLECTOR (WCP) (10%)	Missing	0	93.5	No					93.5	Reviewing	
		0	1		FRT SIDE MIRROR ARM (WCP) (10%)	Bent	0	302.5	No					302.5	Reviewing	
		0	1		FRT SIDE MIRROR BRACKET (WCP) (10%)	Damaged	0	44	No					44	Reviewing	
		0	1		FRT CORNER PANEL (RH)	Repair	0	0	No					0	Deny	
		0	1		FRT SIDE MIRROR (RH)	Serviceable	0	0	No					0	Deny	

Labour

AddApproveDenySubmit All

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
		0		TO KNOCK, WELD, REMOVE & FIX ABOVE PARTS	0	800	0	0	Reviewing		
		0		TO PUTTY & RESPRAY PAINTING ON AFFECTED AREA	0	800	0	0	Reviewing		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

ESTIMATED
AMOUNTADJUSTED
AMOUNT

COMMENT

REMOVE



0

DAYS OF
REPAIR : 7
DAYS

Reviewing

0



0

FRT
DOOR
'BLUETEC'
LOGO

Reviewing

10

NECESSARY





SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount		\$0.00		Adjusted Claim Amount			\$10,279.00	
CATEGORY		ESTIMATE		ADJUSTED				
Spare Parts		\$0.00		\$9,669.00				
Labour		\$0.00		\$1,600.00				
Miscellaneous		\$0.00		\$10.00				
Excess				-\$1,000.00				

Submit for Review



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

ESTIMATED
AMOUNTADJUSTED
AMOUNT

COMMENT

REMOVE



0

FINAL
LUMP
SUM

Reviewing

3600





SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim
Amount

\$0.00

Adjusted Claim Amount

\$2,600.00

CATEGORY

ESTIMATE

ADJUSTED

Miscellaneous

\$0.00

\$3,600.00

Excess

-\$1,000.00

Submit for Review