Siang Motor

Blk 8 Kaki Bukit Ave 4 Premier @ Kaki Bukit Gate 1 #01-10 S415875

Mobile: 8686 2266 Prepare by : Adrian

Email: siangmotor.sg@gmail.com

Estimate

Vehicle No SFN905U

Make

Volvo 560

Spare Parts & Accessories

| S/NO | Desciption | Remark | Unit Price | QTY | Total |
|------|-----------------------------|---------|-------------|-----|------------|
| / 1 | Rear Bumper / CL W/XM | Damaged | \$2,247.00 | 1 | \$2,247.00 |
| 2 | | Damaged | \$149.40 | 2 | \$298.80 |
| /3 | Rear Bumper Reinforcement X | Damaged | \$588.50 | 1 | \$588.50 |
| 4 | Rear Bumper Carrier 🗶 | Damaged | \$331.70 | 2 | \$663.40 |
| 5 | Rear Bumper Sensor X | Damaged | \$306.10 | 2 | \$612.20 |
| 1 6 | Rear Bumper Tow Cover / M:S | Damaged | \$112.35 | 1 | \$112.35 |
| 17 | Rear Tail Lamp RH | Damaged | \$529.65 | 1 | \$529.65 |
| 8 | Rear Tail Lamp Carrier RH X | Damaged | \$181.90 | 1 | \$181.90 |
| 9 | Rear Boot Emblem X | Damaged | \$235.40 | 1 | \$235.40 |
| | | .0017 | Total S/P C | nst | \$5 469 20 |

1991.3

Labour

| 1 Labour, tools and material to dismantle and replace necessary parts | L/S | \$700.00 \$750.00 |
|---|-----|----------------------|
| 2 Labour, tools and material to spray paint to all the affected parts | L/S | \$750.00 |
| 3 Labour, tools and material to remove, check and replace all necessary | | |
| taillamp & wiring parts to facilitate the repair. | L/S | \$150.00 |
| 4 Labour, tools and material to replace rear sensor | L/S | \$180.00 |
| 5 Labour, machine and others to diagnoise and reset system | L/S | \$150.00 |

Total Labour Cost

We undertake to carry out the repiar job base on lump sum of And we required 4 working days to complete the job.

SGD \$5920.00/-

2302.17

30/2/19.

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- · Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: