

Steve - Test

22/03/2002

ASS. REC. BY: REF: 033 / LPC 18021885 / R1sd3-1 Special Instruction: _____
Surveyor: Rasul ASSIGNMENT (Office)
From (Person): Ong Li Li of LPC Date/Time: 05/12/018 851am
Estimated Cost: _____ Bill to: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS
To Inspect Vehicle No: ABE 6905A Insured: YN 6171E
at Workshop m/s: TJ Car Care Tel: 4757 5155
of Slk 1010 Bukit Merah Lane 3 #01-115
Policy No: _____ Claim No: 18/18/18/VCOO/021178
Sum Insured: _____ Excess: _____
Make of Veh: _____ D.O.A. 03-12-2018
(Client's Record)
CA / REV / REP. / REV 24 HRS WP
Date/Time: 05/12/018 940am Person Contacted: Mr. Lim Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	ABE 6905A - NBA / LPC 18021730 / Y
	YN 6171E - NBA / LPC 18021680 / Y
11/04/19	Submit HS \$ 8,050/- @ 9 days (\$ 4,750/- Red - 38%)

- Part.
- ERV

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Friday, 15 February 2019 4:03 PM
To: MT_Claim_SG; assignments@lkkauto.com; Admin-D (LKKAuto)
Subject: RE: 2nd PRS - Our Ref: 18/18/18/VC00/021178 and our ref: GBE6905A/GT/sy/cl [External General]
Attachments: 21178 TP SURVEY REPORT.pdf

Lonpac External - General

Dear Nivitha/Catherine


Attached is the TP survey report.

Please let us have your surveyor's review/report.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: ONG LI LI
Sent: Wednesday, 5 December, 2018 8:51 AM
To: 'Accident@kscgp.com'; MT_Claim_SG; assignments@lkkauto.com; 'Admin-D (LKKAuto)'
Cc: motor@kscgp.com
Subject: RE: 2nd PRS - Our Ref: 18/18/18/VC00/021178 and our ref: GBE6905A/GT/sy/cl

Without Prejudice
Save as to Costs

Dear Calshie

We are not agreeable to your proposed list of surveyors and we shall appoint LKK Auto Consultants Pte Ltd to conduct the PRS.

Dear Catherine/Nivitha

Please refer to the attached and make the necessary arrangement.

Regards,

Ong Li Li


Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

Signature **PRS** *Farah*

REF: **LPC**

ASSIGNMENT

From: _____ Date: **05/12/18**
 Estimated Cost: _____
 OD / **TP** / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **G0E 6905A**
 at Workshop m/s: **TJ Car Care**
 of: **Bik 1010 Bukit Merah Lnc 3 #01-115**
 Insured: _____
 Policy No.: _____
 Claims No.: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: **G0E 6905A** Yr Regn: **03 Mar / 2016**
 Type: M.Car / M.Cycle / Bus / **Van** / Lorry / Taxi / Prime Mover /

Truck / Trailer or
 Make: **Fiat Doblo** C.C. **1518**
 Colour: **White** A/C: Insured / Std / NI / NA
 Sp. Reading: **72059** T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: **ZFA 263000UB46392**

Gen. Cond: Good / **Fair** / Poor / Burnt
 Steering: **Order** / Jammed / Leaked / Burnt or
 Brake: **Order** / Jammed / Leaked / Burnt or
 Mod: **Nil** / S/Rim / STD A/Rim or

Tyre Size F: **205/60R16**
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / **YOKO** or

Front		Rear
R/Bal. 6 mm		R/Bal. 6 mm
L/Bal. 6 mm		L/Bal. 6 mm

D.O.A. **03/12/18** D.O.I. **03/12/18 @ 0322pm**

Survey held at **TJ CAR CARE**

Des. of Damages **Front** / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Submit PRS report.

Date/Time, File Pass to? ☐ : Preli. Report
06/12/18 ☐ : Final Report
 1) **Typist**
 Date/Time, File Return to?

Days Of Repair: **/**
 Resurvey No. of Trip: **/**

Survey Fee:
 Transportation
 S + RS: \$

Photos
 Others

TOTAL

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Invs (\$)
☐ Weekend (\$)

Report Format: **PRS**
 Lump Sum / I.B.I: (\$)

450
450

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0651D
Vehicle Details	
Vehicle No.:	GBE6905A
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Apr 2019
Vehicle Make:	FIAT
Vehicle Model:	DOBLO CARGO MAXI 1.6 MT/ 6MT GLAZE
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	198A30007494202
Chassis No.:	ZFA26300006B46392
Maximum Power Output:	-
Open Market Value:	\$18,511.00
Original Registration Date:	03 Mar 2016
First Registration Date:	03 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$926.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	02 Mar 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$37,412.00
COE Rebate Amount:	\$25,763.00
Total Rebate Amount:	\$25,763.00

The information contained herein is correct as at 11 Apr 2019

OK

D.O.A. 3/12/2018
Bal: 7yrs 3mths

M.V. \$46,000
Rebate \$25,763
repair limit \$20,237.



Fiat Doblo Cargo Maxi 1.6A

Fuel Type: Diesel

Think One Automobile & Trading

Posted: 08-Mar-2019 Tags: 2016 Fiat Doblo, 2016 fiat dobro, Fiat Doblo, fiat dobro, Fiat, Doblo, dobro, Used Fiat

-

N.A

22-Mar-2016

1,598 cc

-

Van

SOLD



Fiat Doblo Cargo Maxi 1.6A

Fuel Type: Diesel

Selling On Behalf Of Direct Owner To Private Buyer By SgCarConsign.

Posted: 28-Feb-2019 Tags: 2016 Fiat Doblo, 2016 fiat dobro, Fiat Doblo, fiat dobro, Fiat, Doblo, dobro, Used Fiat

-

N.A

17-Oct-2016

1,598 cc

-

Van

SOLD



Fiat Doblo Cargo Maxi 1.6M

Fuel Type: Diesel

1 Owner Only. Still Under Agent Warranty & 4 Free Servicing Left. Regular Servicing Done With Agent Since Day 1. Excellent Condition, Best Buy! Daily Less Than \$18. Hurry! Don't Miss This Great Deal!

ABWIN Bus Pte Ltd

Posted: 28-Feb-2019 Tags: 2016 Fiat Doblo, 2016 fiat dobro, Fiat Doblo, fiat dobro, Fiat, Doblo, dobro, Used Fiat

-

N.A

28-Mar-2016

1,598 cc

-

Van

SOLD

PREMIUM AD



Sell direct to buyers at your price!

Get your car sold at a higher price and let our recommended consignment agents negotiate on your behalf without personally entertaining sales calls. List your car with one of our agents today.

Find out more!



Fiat Doblo Cargo Maxi 1.6A

Fuel Type: Diesel

Scheduled Servicing Intervals At 20,000Km (Up To 160,000Km) Or 5 Years (Whichever Comes First). Regularly Serviced By GoldBell. Road Tax Until May 2019. Newly Replaced 4 Tyres. High Loans/ Trade In Av...

Prem Roy Motoring

Posted: 27-Feb-2019 Tags: 2016 Fiat Doblo, 2016 fiat dobro, Fiat Doblo, fiat dobro, Fiat, Doblo, dobro, Used Fiat

\$46,888

\$6,610 /yr

16-May-2016

1,598 cc

91,000 km

Van

Available

PREMIUM AD



Fiat Doblo Cargo Maxi 1.6A

Fuel Type: Diesel

1 Ownership, 100%b Accident Free, Still Under Agent Warranty 3 Year Or 100Km Whichever Come First, Buy With Peace Of Mind, Very Affordable For Just Started To Do Business, Very Low Depreciation Per Da...

Posted: 25-Feb-2019 Tags: 2016 Fiat Doblo, 2016 fiat dobro, Fiat Doblo, fiat dobro, Fiat, Doblo, dobro, Used Fiat

\$56,900

\$7,880 /yr

28-Jun-2016

1,598 cc

42,297 km

Van

Available



Fiat Doblo Cargo Maxi 1.6M

Fuel Type: Diesel

1 Owner, Still Under Agent Warranty 3 Years Or 100K Km Whichever Come First. Buy With Peace Of Mind, Low Depreciation, Cheaper Than Renting A Van, Please Call For Viewing.

Posted: 18-Feb-2019 Tags: 2016 Fiat Doblo, 2016 fiat dobro, Fiat Doblo, fiat dobro, Fiat, Doblo, dobro, Used Fiat

-

N.A

28-Mar-2016

1,598 cc

-

Van

SOLD



Fiat Doblo Cargo Maxi 1.6A

Fuel Type: Diesel

Near New Condition, Ready To Drive Away Anytime! No Repairs Required! With 2 Digit Number Plate And Aluminium Chequered Plate Deck! Call Us Now!

Yes Motoring

Posted: 26-Jan-2019 Tags: 2016 Fiat Doblo, 2016 fiat dobro, Fiat Doblo, fiat dobro, Fiat, Doblo, dobro, Used Fiat

-

N.A

20-May-2016

1,598 cc

-

Van

SOLD

PREMIUM AD

Save this search criteria, to get email alerts whenever a match is found.

Make: Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Fiat Doblo, Fiat Doblo Singapore, used Fiat Doblo Singapore, used Fiat Doblo, used vehicles Singapore or even buy used Fiat Doblo Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2019 sgCarMart. All rights reserved.

Compare

ST Appraisal Services

Insurance Loss Adjusters & Licensed Appraisers

Insurance Claim Investigator

Business Address: 60 Arab Street Singapore 199757

Tel: 66523352 / 98586761; Fax: 62970270

Mailing Address : 161 Alexandra Post Office Singapore 911506

Date : 11th Jan 2019

Our Ref : TP / TJCC GBE6905A/ 12.03/18

Your Ref :

M/s Goldbell Car Rental Pte Ltd
10 Raeburn Park
#02-01
Singapore 088702

DAMAGED VEHICLE (GBE 6905 A) INSPECTION REPORT (WITHOUT PREJUDICE)

Detailed accounts of our inspection are as follows:-

(A) Reference

Name of Claimant	: M/s Goldbell Car Rental Pte Ltd	Date of Request	: 5 th Dec 2018
		Referred By	: Person in charge
Policy No.	: Please Advice	Date of Inspection	: 5 th Dec 2018
Claim No.	: Please Advice	Date of Re-inspection	:
Accident Date	: 3 rd Dec 2018	Sum Insured	: NA
Repairer	: TJ Car Care Services	Excess Amount	: NA
	Blk 1010 Bukit Merah Lane 3	3 rd Party Vehicle	: Please Advice
	#01-115 Singapore 159724	3 rd Party Insurer	: Please Advice

(B) Particulars of Vehicle


Registration No	: GBE 6905 A	Mileage	: 72059 Km
Make & Model	: FIAT DOBLO MAXI 1.6 MT	Engine No	: 198A30007494202
Date of Registration	: 3 rd Mar 2016	Chassis No.	: ZFA26300006B46392
Colour	: White	Engine Capacity.	: 1,598 cc

(C) Pre-Accident Condition (Static Test Only)

Steering	: Serviceable	Paint Work	: Good
Foot-brake	: Serviceable	Modification	: NIL
Hand-brake	: Serviceable	General Condition	: Good

(D) Tyre Condition

	Tread Depth	Make	Size
Front Left	60 %	YOKOHAMA	205/60 R16
Front Right	60 %	YOKOHAMA	205/60 R16
Rear Left	60 %	YOKOHAMA	205/60 R16
Rear Right	60 %	YOKOHAMA	205/60 R16

(E) Point of Impact**(F) General Description of Damages**

The impact of the collision has damaged/affected the rear LH door, rear RH door, rear bumper, front bumper and etc.

Please refer to the Annex for a detailed account of the damages and photographs taken.

(G) Recommendation

We have inspected thoroughly the actual damages found on the vehicle, before we arrived at our recommendation as to whether the parts needed replacement or repairs.

Our adjusted cost of lump sum repair is **\$13,000.00** and an estimated **10** days is required to repair the vehicle. Please refer to the Annex for a detailed account of the cost estimates.

(H) Remarks

We have not authorised the repairs. However for information, under normal circumstances, the repairs should not exceed **10** days.

This inspection was conducted on a "without prejudice" basis.

We are pleased to advice that the inspection work was carried out accordingly, and hereby submit our Appraisal Report, which includes evidence photographs.

ST Appraisal Services



T T RAJAN
MVI, ITC (Mechanical), NTC (Motor Vehicle)
ASIET, MSAAA, Assessor/Appraiser
AD041-2007532D

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS FOR VEHICLE NO: GBE 6905 A

Adjustment of Spare Parts Costs for Repairs

Item	Qty	Vehicle parts description	Condition / Remark	Estimated by workshop	Disc. (%)	Adjusted cost
1	1	LH door panel	dented	1472.00	10	1324.80 /
2	1	LH door badge - MAXI	necessary	95.70	10	86.13 /
3	1	LH door badge - DOBLO	necessary	67.30	10	60.57 /
4	1	LH door weatherstripe	damaged	286.00	10	257.40 X NN
5	2	LH door number plate lamp @ \$72.30	damaged	144.60	10	130.14 X NN
6	1	LH door outer handle	damaged	115.00 182.30	10	164.07 / Δ
7	1	LH door lower hinge	distorted	97.20	10	87.48 /
8	1	LH door upper hinge	re-use	97.20	100	0.00 X
9	1	LH door inner board	damaged	186.00	10	167.40 X NN
10	1	LH door wiper motor	malfunction	379.60	10	341.64 X NN
11	1	LH door wiper arm	damaged	186.30	10	167.67 X NN
12	1	LH door glass	shattered	754.30	10	678.87 450/
13	1	LH door lower lock	distorted	158.20	10	142.38 X NN ✓ Δ
14	1	LH door glass	shattered	754.30	10	678.87 X Ppt.
15	1	RH door panel	dented	1146.30	10	1031.67 /
16	1	RH door glass	shattered	546.20	10	491.58 350/
17	1	RH door outer garnish	detached	132.50	10	119.25 /
18	1	RH door badge - PROFESIONAL	necessary	71.20	10	64.08 /
19	1	RH door badge - MULTIJET	necessary	52.10	10	46.89 /
20	1	RH door label	necessary	38.50	10	34.65 /
21	1	RH door weatherstripe	damaged	202.50	10	182.25 X NN
22	1	RH door upper hinge	serviceable	97.20	100	0.00 X
23	1	RH door lower hinge	distorted	97.20	10	87.48 /
24	1	RH door inner board	folded	142.00	10	127.80 X NN
25	1	RH door lower lock	distorted	158.20	10	142.38 X ✓ Δ
26	1	RH door upper lock	malfunction	151.30	10	136.17 X NN
27	1	Rear door frame moulding	cut/damaged	386.30	10	347.67 /
28	1	Taillamp @ \$384.20	cracked	768.40	10	691.56 384.20/
29	1	Rear bumper	cut/damaged	468.50	10	421.65 /
30	1	Rear bumper reinforcement	dented	314.00	10	282.60 /
31	2	Rear bumper side holder	detached	205.20	10	184.68 /
32	2	Rear bumper reflector	damaged	195.60	10	176.04 X ✓ Δ CR6
33	1	Rear end member	dented	429.30	10	386.37 /
34	1	Rear end garnish	damaged	268.20	10	241.38 X NN ✓ Δ CR6
35	1	Exhaust end pipe	dented	746.50	10	671.85 X HHR
36	1	Exhaust mounting	necessary	72.00	10	64.80 X NN ✓ Δ
37	1	Front bumper	cut/damaged	622.00	10	559.80 /
38	2	Front bumper side holder	necessary	136.00	10	122.40 /
39	1	Front bumper lower garnish	damaged	211.00	10	189.90 /
40	1	Front bumper foam	damaged	86.00	10	77.40 /
41	1	Front bumper reinforcement	serviceable	658.20	100	0.00 X
42	1	Front bumper inner air guide	folded	142.55	10	128.30 X NN ✓ Δ

ST Appraisal Services

Annex

43	1	Front bumper tow hook cover	serviceable	76.30	100	0.00 X
44	1	Front grille	serviceable	225.00	100	0.00 X
45	1	Front grille emblem	serviceable	76.30	100	0.00 X
Special nett items						
1	1	Rear bumper sensor	damaged	280.00		260.00 / 200
2	1	Rear door sticker - 70 km/h	necessary	18.00		15.00 /
3	1	Rear door sticker - 6 pax	necessary	15.00		12.00 /
4	2	Rear windscreen sealant	necessary	150.00		140.00 / 80
5	1	Rear number plate	serviceable	50.00		0.00 X
6	1	Front number plate	damaged	50.00		45.00 / 25 PDD
				14346.55	11770.02	412

Adjustment of Labour Costs for Repairs

To remove/replace/reshape damaged and affected parts and panels. To realign replacement parts (rear section)	1800.00	1620.00	900 / 800
To remove/replace/reshape damaged and affected parts and panels. To realign replacement parts (front section)	540.00	360.00	200 /
Supply paint materials and expandable items. To respray rear door, rear member and other necessary parts.	1500.00	1350.00	900 /
To remove/refit interior fittings to facilitate repair.	250.00	180.00	50 /
To remove/replace two door glass. Carry out water leak test.	250.00	180.00	50 / +70
Install rear bumper sensor and check for proper functions.	80.00	60.00	30 /
To carry out anti rust treatment on the affected panels.	160.00	140.00	30 / +60
To provide towing service.	60.00	60.00	X
Total labour	4640.00	3950.00	2220

Adjustment Parts and Labour Costs of Repairs

	Estimated by workshop	Adjusted cost
TOTAL PARTS COSTS	14346.55	11770.02
TOTAL LABOUR COSTS	4640.00	3950.00
TOTAL REPAIR COSTS	18986.55	15720.02

ADJUSTED REPAIR COST

13000.00

9420.34
 4/5 - 7536.27
 = 7550

9 days

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/12/2018 17:42
Date Of Accident	03/12/2018 10:30
Exact Location Of Accident	ALEXANDRA RD BESIDE 438 ALEXANDRA POINT BUILDING
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE6905A
Insured/Policyholder	
Name Of Registered Owner	GOLDBELL CAR RENTAL PTE LTD
Co Reg No	200710651D
Email Address	HOCKLEE2000@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-94366632
Alternative Phone No	OFFICE-94366632

Vehicle Particulars

Manufacturer	FIAT
Model	DOBLO
Exact Purpose for which vehicle was being used at time of accident	WORKING PURPOSES
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD18V00032/VCZ/R03
Cover Note Number	

Driver

Name of Driver	LEE LEONG HOCK
NRIC No	S8582082F
Date Of Birth	06/12/1985
Occupation	OUTDOOR
Date Of Driving Pass	13/08/2008
Driving Experience	10 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94366632
Fax Number	
Contact Number	OTHERS-94366632
EEmail Address	HOCKLEE2000@HOTMAIL.COM

Address	BLK 932B HOUGANG AVENUE 9 #04-100
Postcode	532932
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN AND POLICE REPORT T/20181203/7013

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN6171E
Vehicle Make/Model/Colour	ISUZU
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	AZHAGESAN ARULVEL
NRIC/Passport Number	G6640684P
Contact Number	98613524
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SGX1181U

Vehicle Make/Model/Colour

MERCEDES BENZ BLACK

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

MAK YOKE YING

NRIC/Passport Number

S1366914G

Contact Number

Address

36 JAMBOL PLACE

Postcode

119363

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

DETAILS OF INJURED PERSON 1

Name

LEE LEONG HOCK

Approximate Age

Injuries Sustain

SERIOUS INJURY

Injured person in which vehicle?

GBE6905A

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CS3/LPC18021885/R1sd3e2-1	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 11-04-2019	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 6171E	Veh. Inspected	GBE 6905A	
Policy No.		Coverage (\$)	0.00	
Claim No.	18/18/18/VC00/021178	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	05/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	FIAT DOBLO	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	ZFA26300006B46392	Colour	WHITE	
Odometer	72059	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	YOKOHAMA	6 mm	
L/H Front Tyre	205/60 R16	YOKOHAMA	6 mm	
R/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/12/2018	Inspection Date	05/12/2018	
Survey held at	TJ CAR CARE SERVICES BLK 1010, BUKIT MERAH LANE 3 #01-115 SINGAPORE 159724			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 6905A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	LH DOOR PANEL	DENTED	1,472.00	1,472.00
1	LH DOOR BADGE - MAXI	NECESSARY	95.70	95.70
1	LH DOOR BADGE - DOBLO	NECESSARY	67.30	67.30
1	LH DOOR WEATHERSTRIPE	NOT NECESSARY	286.00	-
2	LH DOOR NUMBER PLATE LAMP @\$72.30	NOT NECESSARY	144.60	-
1	LH DOOR OUTER HANDLE	DAMAGED	182.30	115.20
1	LH DOOR LOWER HINGE	DISTORTED	97.20	97.20
1	LH DOOR UPPER HINGE	REUSE	97.20	-
1	LH DOOR INNER BOARD	NOT NECESSARY	186.00	-
1	LH DOOR WIPER MOTOR	NOT NECESSARY	379.60	-
1	LH DOOR WIPER ARM	NOT NECESSARY	186.30	-
1	LH DOOR GLASS	SHATTERED	754.30	450.00
1	LH DOOR LOWER LOCK	DISTORTED	158.20	158.20
4	LH DOOR GLASS	REPEATED	754.30	-
1	RH DOOR PANEL	DENTED	1,146.30	1,146.30
1	RH DOOR GLASS	SHATTERED	546.20	350.00
1	RH DOOR OUTER GARNISH	DETACHED	132.50	132.50
1	RH DOOR BADGE - PROFESIONAL	NECESSARY	71.20	71.20
1	RH DOOR BADGE - MULTIJET	NECESSARY	52.10	52.10
1	RH DOOR LABEL	NECESSARY	38.50	38.50
1	RH DOOR WEATHERSTRIPE	NOT NECESSARY	202.50	-
1	RH DOOR UPPER HINGE	SERVICEABLE	97.20	-
1	RH DOOR LOWER HINGE	DISTORTED	97.20	97.20
1	RH DOOR INNER BOARD	NOT NECESSARY	142.00	-
1	RH DOOR LOWER LOCK	DISTORTED	158.20	158.20
1	RH DOOR UPPER LOCK	NOT NECESSARY	151.30	-
1	REAR DOOR FRAME MOULDING	CUT / DAMAGED	386.30	386.30
2	TAILLAMP @\$384.20	CRACKED-1PC ONLY	768.40	384.20
1	REAR BUMPER	CUT / DAMAGED	468.50	468.50
1	REAR BUMPER REINFORCEMENT	DENTED	314.00	314.00

Report Ref No. CS3/LPC18021885/R1sd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR BUMPER SIDE HOLDER	DETACHED	205.20	205.20
2	REAR BUMPER REFLECTOR	DAMAGED / CRACKED	195.60	195.60
1	REAR END MEMBER	DENTED	429.30	429.30
1	REAR END GARNISH	DAMAGED / CRACKED	268.20	268.20
1	EXHAUST END PIPE	TO REPAIR SEE LABOUR	746.50	-
1	EXHAUST MOUNTING	NECESSARY / DISTORTED	72.00	72.00
1	FRONT BUMPER	CUT / DAMAGED	622.00	622.00
2	FRONT BUMPER SIDE HOLDER	NECESSARY	136.00	136.00
1	FRONT BUMPER LOWER GARNISH	DAMAGED	211.00	211.00
1	FRONT BUMPER FOAM	DAMAGED	86.00	86.00
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	658.20	-
1	FRONT BUMPER INNER AIR GUIDE	FOLDED	142.55	142.55
1	FRONT BUMPER TOW HOOK COVER	SERVICEABLE	76.30	-
1	FRONT GRILLE	SERVICEABLE	225.00	-
1	FRONT GRILLE EMBLEM	SERVICEABLE	76.30	-
	LESS 10% DISCOUNT		-	-842.25
			13,783.55	7,580.20
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER SENSOR (SN)	DAMAGED	280.00	200.00
1	REAR DOOR STICKER - 70 KM/H (SN)	NECESSARY	18.00	15.00
1	REAR DOOR STICKER - 6PAX (SN)	NECESSARY	15.00	12.00
2	REAR WINDSCREEN SEALANT (SN)	NECESSARY	150.00	80.00
1	REAR NUMBER PLATE (SN)	SERVICEABLE	50.00	-
1	FRONT NUMBER PLATE (SN)	DAMAGED / DENTED	50.00	25.00
			563.00	332.00
	<u>LABOUR</u>			
	TO REMOVE / REPLACE / RESHAPE DAMAGED AND AFFECTED PARTS AND PANELS. TO REALIGN REPLACEMENT PARTS (REAR SECTION). INCLUSIVE OF THE REPAIR OF EXHAUST END PIPE.		1,800.00	800.00

Report Ref No. CS3/LPC18021885/R1sd3e2-1

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE / REPLACE / RESHAPE DAMAGED AND AFFECTED PARTS AND PANELS. TO REALIGN REPLACEMENT PARTS. (FRONT SECTION)		540.00	200.00
	SUPPLY PAINT MATERIALS AND EXPANDABLE ITEMS. TO RESPRAY REAR DOOR, REAR MEMBER AND OTHER NECESSARY PARTS.		1,500.00	900.00
	TO REMOVE / REFIT INTERIOR FITTINGS TO FACILITATE REPAIR.		250.00	50.00
	TO REMOVE / REPLACE TWO DOOR GLASS. CARRY OUT WATER LEAK TEST.		250.00	120.00
	INSTALL REAR BUMPER SENSOR AND CHECK FOR PROPER FUNCTIONS.		80.00	30.00
	TO CARRY OUT ANTI RUST TREATMENT ON THE AFFECTED PANELS.		160.00	90.00
	TO PROVIDE TOWING SERVICES.		60.00	-
			4,640.00	2,190.00
GRAND TOTAL			18,986.55	10,102.20

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,050.00
---	--	--	--	-----------------

Report Ref No. CS3/LPC18021885/R1sd3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.