

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19003138/DKA3N2

Date: 20/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900011845
Claimant
Vehicle No : SKK7766P **Insured Vehicle No :** SMH252T
Date of Loss: 02/02/2019 **Nature of Claim:** TP **Claim No:** 5554768953SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKK7766P**
 Make & Model: HONDA FIT, 1.3 G (A) Engine No: L13A4008682
 Reg. Date: 18/01/2008 (Man. Year: 2007) Chassis No: GE61007352
 Colour: Grey Odometer: 180687 km
 Engine Capacity: 1339 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15
 Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm
 Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,475.76	1,715.80	3,759.96	68.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,510.00	1,120.00	3,390.00	75.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,985.76	2,835.80	7,149.96	71.60
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	9,985.76	2,000.00	7,985.76	79.97
+ GST 7.00/7.00% (S\$)	699.00	140.00	559.00	79.97
Nett Amount (S\$)	10,684.76	2,140.00	8,544.76	79.97
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
(S\$)		2,840.00		
Liabe Amount (50.00%) (S\$)		1,420.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		1,427.49		
Global Sum Settlement (S\$)		1,420.00		

INSPECTION

Date of Assignment: 18/02/2019

Date Inspected: 20/02/2020 Inspected At:

Teamwork Garage Pte Ltd (HQ)
 53 Ubi Ave 1 #01-24, Paya Ubi

Industrial Park
Singapore 408934

Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*END PANEL	Not Necessary	565.90 FL	*- FL
2	1		*END PANEL TOP GARNISH	Not Necessary	107.80 FL	*- FL
3	1		*REAR TAILLAMP	O/S Cracked / N/SNot Necessary	414.50 FL	*207.25 FL
4	2		*REAR FENDER INNER TRIM	Not Necessary	589.00 FL	*- FL
5	1		*TAILGATE	Repair	908.00 FL	*- FL
6	1		*TAILGATE WEATHERSTRIP	Not Necessary	92.30 FL	*- FL
7	1		*TAILGATE LOCK	Not Necessary	186.20 FL	*- FL
8	1		*TAILGATE LOCK STRIKER	Not Necessary	28.00 FL	*- FL
9	1		*TAILGATE INNER TRIM	Not Necessary	151.00 FL	*- FL
10	1		*TAILGATE GLASS MOLDING	Not Necessary	86.00 FL	*- FL
11	1		*SPARE TYRE TOP BOARD	Not Necessary	291.00 FL	*- FL
12	1		*SET REAR REVERSE SENSOR	Damaged	400.00 FS	*220.00 FS
13	1		*SET REAR BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
14	1		*REAR BUMPER (AFTER MARKET)	Distorted	1,200.00 FS	*800.00 FS
15	1		*REAR BUMPER UNDER GARNISH (AFTER MARKET)	Distorted	800.00 FS	*500.00 FS
16	1		*JOINT SEALANT	Not Necessary	150.00 FS	*- FS
17	1		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **6,159.70** **1,757.25**
- List Item Discount on L Items 20.00/20.00% (\$\$) **683.94** **41.45**

Total Parts (\$\$) **5,475.76** **1,715.80**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	60.00	30.00
2	REMOVE AND REFIT REAR LINING,TRIM AND GARNISH	New	200.00	0.00
3	REMOVE AND STRAIGHTEN REAR EXHAUST	New	150.00	0.00
4	REMOVE AND REFIT REAR WINDSCREEN	New	150.00	0.00
5	TRANSFER PARTS ,ATTACHMENT FROM OLD TAILGATE TO NEW	New	200.00	0.00
6	PANEL BEATING ON AFFECTED AREAS	New	1,400.00	300.00
7	SPRAY PAINTING ON AFFECTED AREAS	New	1,400.00	300.00
8	REMOVE AND RENEW WRAPPING ON AFFECTED AREAS	New	800.00	450.00
9	REMOVE AND RENEW REAR REVERSE SENSOR	New	150.00	40.00
Gross Labour Cost (S\$)			4,510.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >