



SLE9204B

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : LONPAC

OWN INSURER : AIG

CLAIM TYPE : TP

Date of Accident : 19/2/2019

Vehicle Reg. No. : SLE9204B

Vehicle Reg. Date: 5-Aug-2016

Make / Model : T. COROLLA AXIO 1.5 HB

Engine No. : 1NZR404381

Chassis No. : NKE1657134291

COST OF CLAIMS

Parts Cost / List Items : \$ 4,482.00

Plus/Less 25% \$ 1,120.50

Total Cost / List : \$ 3,361.50

Special Nett Items : \$ 250.00

Total Parts Amount : \$ 3,611.50

Total Labour Amount : \$ 2,200.00

Gross Total : \$ 5,811.50

GST % : 7% \$ 406.81

Nett Amount : \$ 6,218.31

Surveyor Name and Company :

Rasul - LKK

Date of survey : 21/02/19 @ 0900

Part by Part / Lump Sum : 3 days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email : rasul@lkkauto.com

Fax No : _____

HP No : 900068

This claim is handled by : MINOKO

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLE9204B**

Vehicle Reg. Date: **5/8/2016**

Make / Model : **T. COROLLA AXIO 1.5 HB**

Engine No. : **1NZR404381**

Chassis No. : **NKE1657134291**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Rear bumper	<i>scr /</i>	\$ 1,486.00		
2	1	Rear bumper reflector RH	<i>X</i>	\$ 185.00		
3	1	Rear bumper retainer RH	<i>X</i>	\$ 172.00		
4	1set	Rear bumper clip - set	<i>sc /</i>	\$ 64.00		
5	1	Taillamp RH	<i>blo /</i>	\$ 1,200.00		
6	1set	Taillamp clip - set	<i>sc /</i>	\$ 30.00		
7	1	Taillamp lower bracket RH	<i>?</i>	\$ 330.00		
8	1	Rear fender RH	<i>repair</i>	\$ 835.00		
9	1	Rear fender inner shield RH	<i>X</i>	\$ 90.00		
10	1set	Rear fender inner shield clips	<i>X</i>	\$ 90.00		
11	1	Rear rim cover RH	<i>X inconsistent</i>		\$ 250.00	
12	0	0				
13	0	0				
14	0	0				
15	0	0				
16	0	0				
17	0	0				
18	0	0				
19	0	0				
20	0	0				
21	0	0				
22	0	0				
23	0	0				
24	0	0				
25	0	0				
26	0	0				
27	0	0				
28	0	0				
29	0	0				
30	0	0				
31	0	0				
32	0	0				
33	0	0				
34	0	0				
35	0	0				
36	0	0				
37	0	0				
38	0	0				
39	0	0				
40	0	0				

6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

No	MECHANICAL / ELECTRICAL / PANEL / PAINT LABOUR	AMOUNT	ADJUSTED AMOUNT
1	To straighten and panel beating accident area. Rear Portion.	\$ 1,000.00	300
2	To putty, respray painting and polish affected areas. Rear Portion.	\$ 1,000.00	400
3	To remove and replace reverse sensor.	\$ 100.00	60
4	To check and rectify wiring after disconnect and reconnect.	\$ 100.00	30
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before <u>after</u> spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____			