

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19003142/EDA3Q2

Date: 16/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SMC1818G **Insured Vehicle No :** SLW4092U

Date of Loss: 25/01/2019 **Nature of Claim:** TP **Claim No:** 0435841998SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC1818G		
Make & Model:	TOYOTA ALPHARD, 2.5 (A)	Engine No:	2ARJ090171
Reg. Date:	20/07/2018 (Man. Year: 2018)	Chassis No:	JTNGF3DH008016114
Colour:	Black	Odometer:	20329 km
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Toyo 7 mm	Rear Left Side:	Toyo 7 mm
Front Right Side:	Toyo 7 mm	Rear Right Side:	Toyo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,305.27	2,149.79	3,155.48	59.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,960.00	1,130.00	1,830.00	61.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,265.27	3,279.79	4,985.48	60.32
+ GST 7.00/7.00% (S\$)	578.57	229.59	348.98	60.32
Nett Amount (S\$)	8,843.84	3,509.38	5,334.46	60.32
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 18/02/2019

Date Inspected: 26/03/2019 Inspected At:

Teamwork Garage Pte Ltd (HQ)
53 Ubi Ave 1 #01-24, Paya Ubi
Industrial Park
Singapore 408934

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	609.90 FL	*609.90 FL
2	1		*END PANEL -OUTER	Repair	728.30 FL	*- FL
3	1		*END PANEL -INNER	Not Necessary	594.20 FL	*- FL
4	1		*REAR TAILLAMP PANEL	Not Necessary	364.80 FL	*- FL
5	1		*REAR BUMPER RETAINER (2 PCS)	Necessary	70.40 FL	*70.39 FL
6	2		*REAR BUMPER BRACKET	Not Necessary	90.80 FL	*- FL
7	1		*END PANEL TOP GARNISH	Not Necessary	173.10 FL	*- FL
8	1		*REAR TAILLAMP	Not Necessary	519.30 FL	*- FL
9	1		*REAR PDC SENSOR WIRE	Not Necessary	445.68 FL	*- FL
10	1		*REAR BUMPER SIDE COVER RH	Not Necessary	601.45 FL	*- FL
11	1		*SET REAR BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
12	1		*SET REAR REVERSE SENSOR	Not Necessary	400.00 FS	*- FS
13	1		*TAILGATE	Dented	2,100.00 FL	*1,957.00 FL
14	1		*WINDSCREEN MOULDING	Necessary	189.10 FL	*189.10 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,927.03	2,856.39
- List Item Discount on L Items 25.00/25.00% (\$)	1,621.76	706.60
Total Parts (\$)	5,305.27	2,149.79

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK REAR WIRING AND LIGHTING	New	60.00	30.00
2	REMOVE AND REFIT REAR LINING ,TRIM AND GARNISH	New	200.00	50.00
3	REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	30.00
4	PANEL BEATING ON AFFECTED AREAS	New	1,200.00	400.00
5	SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	500.00
6	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	20.00
7	REMOVE AND REFIT REAR WINDSCREEN	New	200.00	100.00
Gross Labour Cost (\$\$)			2,960.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >