

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19003175/UEA3Q2

**Date:** 23/06/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800134950

**Claimant**  
**Vehicle No :** FBM8244T **Insured Vehicle No :** SLJ6021E

Date of Loss: 09/01/2019 Nature of Claim: TP Claim No: 8553042929SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>FBM8244T</b>		
Make & Model:	YAMAHA GDR155A (AEROX), 155cc	Engine No:	G3J8E0035445
Reg. Date:	12/04/2018 (Man. Year: 2018)	Chassis No:	MH3SG4640JJ031074
Colour:	Red/Black	Odometer:	21580 km
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	120/70-14	Rear Tyre Size:	140/70-14
Front Left Side:	Timsun 7 mm	Rear Left Side:	Timsun 7 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,138.50	3,043.00	1,095.50	26.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	670.00	300.00	370.00	55.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>4,808.50</b>	<b>3,343.00</b>	<b>1,465.50</b>	<b>30.48</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	336.60	234.01	102.59	30.48
<b>Nett Amount (\$\$)</b>	<b>5,145.10</b>	<b>3,577.01</b>	<b>1,568.09</b>	<b>30.48</b>
<b>+ Loss of Use (4.0 x S\$20.00/day) (\$\$)</b>		80.00		
<b>+ Medical Costs (\$\$)</b>		162.41		
<b>+ Doc/Search Fee (\$\$)</b>		7.45		
<b>Nett Liability (\$\$)</b>		<b>3,826.87</b>		

### INSPECTION

Date of Assignment: 14/02/2019

Date Inspected: 20/02/2019 Inspected At:

Looi's Motor Enterprise Pte. Ltd. (HQ)  
No 55 Kaki Bukit Place, Eunos  
Techpark  
Singapore 416230

Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLIGHT	Cracked	160.00 FL	*160.00 FL
2	1		*SADDLE COMP	Torn	280.00 FL	*280.00 FL
3	1		*SET MIRROR	Cut	65.00 FL	*65.00 FL
4	1		*MASTER PUMP RH COVER LID	Cut	30.00 FL	*30.00 FL
5	1		*BRAKE LEVER	Cut	25.00 FL	*25.00 FL
6	1		*MUDGUARD	Cut	120.00 FL	*120.00 FL
7	1		*EXHAUST COVER	Scratched	80.00 FL	*80.00 FL
8	1		*MAINSTAND	Repair	240.00 FL	*- FL
9	1		*COWLING	Cracked	350.00 FL	*350.00 FL
10	1		*SIGNAL REAR RH	Cracked	60.00 FL	*60.00 FL
11	1		*COVER SIDE REAR RH	Cut	260.00 FL	*260.00 FL
12	1		*COVER SIDE REAR LH	Cracked	260.00 FL	*260.00 FL
13	1		*COVER CENTRE REAR	Cut	140.00 FL	*140.00 FL
14	1		*COVER CENTRE MID RH	Cut	280.00 FL	*280.00 FL
15	1		*COVER CENTRE MID LH	Cut	280.00 FL	*280.00 FL
16	1		*COWLING COVER CENTRE	Not Necessary	180.00 FL	*- FL
17	1		*INNER COVER HEADLIGHT	Cracked	160.00 FL	*160.00 FL
18	1		*INNER COVER RH	Not Necessary	150.00 FL	*- FL
19	1		*INNER COVER LH	Not Necessary	150.00 FL	*- FL
20	1		*FLOOR BOARD RH	Cut / Deformed	210.00 FL	*210.00 FL
21	1		*COVER FLOOR BOARD RH	Deformed / Twisted	260.00 FL	*260.00 FL
22	1		*RUBBER FLOOR BOARD RH	Necessary	120.00 FL	*120.00 FL
23	1		*RADIATOR COVER	Cut	130.00 FL	*130.00 FL
24	1		*COVER LID	Not Necessary	140.00 FL	*- FL
25	1		*COVER PILLION FOOTREST LH	Not Necessary	180.00 FL	*- FL
26	1		*EMBLEM YAMAHA	Necessary	30.00 FL	*30.00 FL
27	2		*EMBLEM 3D LOGO	Necessary	70.00 FL	*70.00 FL
28	1		*COVER LID DAMPER	Not Necessary	35.00 FL	*- FL
29	1		*HELMET	Repair	120.00 FL	*- FL
30	1		*NUMBER PLATE	Bent	30.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>4,595.00</b>	<b>3,380.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	456.50	337.00
<b>Total Parts (S\$)</b>	<b>4,138.50</b>	<b>3,043.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	ALIGNMENT WHEEL	New	350.00	0.00
2	LABOUR	New	320.00	300.00
<b>Gross Labour Cost (\$)</b>			<b>670.00</b>	<b>300.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >