Page 1 of 5 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19003177/JQD3E2

Date: 19/03/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 29076927 Claimant Vehicle SLU3644U

Insured Vehicle No: GBC6777M No:

ΤP Date of Loss: 16/02/2019 Nature of Claim: Claim No: 585361

DESCRIPTION & IDENTIFICATION OF VEHICLE

SLU3644U Reg No:

Make & Model: KIA CERATO FORTE, 1.6 SX (A) Engine No: G4FCAH305081

Reg. Date: 18/03/2011 (Man. Year: 2010) Chassis No: KNAFW411MB5379781

Colour: Odometer: 141314 km White

Engine Capacity: 1591 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

215/45 R17 Front Tyre Size: 215/45 R17 Rear Tyre Size: Front Left Side: Rear Left Side: Dunlop 6 mm Dunlop 6 mm Rear Right Side: Front Right Side: Dunlop 6 mm Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,038.12	2,580.00	6,458.12	71.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,030.00	1,900.00	1,130.00	37.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,068.12	4,480.00	7,588.12	62.88
Approved Total (Overridden) (S\$)		3,350.00		
(S\$)	12,068.12	3,350.00	8,718.12	72.24
+ GST 7.00/7.00% (S\$)	844.77	234.50	610.27	72.24
Nett Amount (S\$)	12,912.89	3,584.50	9,328.39	72.24

INSPECTION

Date of Assignment: 20/02/2019

Date Inspected: 21/02/2019 Inspected At: Carz Auto Services Pte Ltd - Woodlands

(HQ)

NO 61. WOODLANDS INDUSTRIAL PARK E9, #04-04 E9 PREMIUM

SINGAPORE 757047

Singapore 757047

Estimated Period of Repair: 4.0 days Adjuster Report Page 2 of 5

Adjuster: ONG HWEE JIE Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Mar 2019)

Parts: 143 KIA CERATO FORTE 1.6 SX (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLU3644U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER RH	Repair	1,100.90 FL	*- FL
2	1		*REAR FENDER MUDFLAP RH	Not Necessary	55.80 FL	*- FL
3	1		*REAR FENDER INNER TRIM RH	Not Necessary	273.90 FL	*- FL
4	1		*REAR RIM RH	Scratched	695.30 FL	*695.30 FL
5	1		*REAR WHEEL BEARING WITH HUB RH	Damaged	330.70 FL	*330.70 FL
6	1		*REAR DOOR RH	Buckled	924.80 FL	*924.80 FL
7	1		*REAR DOOR WEATHERSTRIP RH	Deformed	155.00 FL	*155.00 FL
8	1		*REAR DOOR INNER TRIM BOARD RH	Not Necessary	622.40 FL	*- FL
9	1		*REAR DOOR GLASS OUTER MOULDING RH	Necessary	65.20 FL	*65.20 FL
10	2		*REAR DOOR HINGE RH	Bent	70.60 FL	*70.60 FL
11	1		*REAR DOOR CHECK PIN RH	Not Necessary	35.60 FL	*- FL
12	2		*REAR DOOR STICKER FRAME RH	Necessary	70.80 FL	*70.80 FL
13	1		*REAR DOOR INNER HANDLE RH	Cracked	40.60 FL	*40.60 FL
14	1		*REAR DOOR INNER LOCK RH	Jammed	300.90 FL	*300.90 FL
15	1		*REAR DOOR INNER POWER WINDOW SWITCH RH	Serviceable	85.90 FL	*- FL
16	1		*REAR DOOR INNER RUBBER SEAL RH	Deformed	125.30 FL	*125.30 FL
17	1		*REAR DOOR INNER TRIM BOARD MOULDING RH	Not Necessary	50.50 FL	*- FL
18	1		*REAR DOOR OUTER HANDLE RH	Serviceable	55.60 FL	*-FL
19	1		*REAR DOOR OUTER HANDLE COVER RH	Not Necessary	25.00 FL	*- FL
20	1		*REAR DOOR WINDOW REGULATOR ASSY RH	Serviceable	445.00 FL	*-FL
21	1		*REAR DOOR WINDOW REGULATOR MOTOR RH	Serviceable	380.00 FL	*- FL
22	1		*REAR SHOCK ABSORBER RH	Not Necessary	752.80 FL	*-FL
23	1		*FRONT DOOR RH	Repair	752.80 FL	*- FL
24	2		*FRONT DOOR STICKER FRAME RH	Necessary	70.80 FL	*70.80 FL
25	1		*FRONT DOOR INNER TRIM BOARD RH	Not Necessary	778.40 FL	*- FL
26	1		*FRONT DOOR GLASS OUTER MOULDING RH	Not Necessary	65.20 FL	*-FL
27	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	155.00 FL	*- FL
28	1		*FRONT DOOR INNER LOCK RH	Not Necessary	220.50 FL	*-FL
29	1		*FRONT DOOR INNER HANDLE RH	Not Necessary	45.80 FL	*-FL
30	1		*FRONT DOOR OUTER HANDLE RH	Not Necessary	335.70 FL	*-FL
31	10		*REAR FENDER INNER TRIM CLIP	Not Necessary	40.00 FS	*-FS
32	1		*REAR TYRE RH	Not Necessary	250.00 FS	*-FS
33	10		*REAR DOOR INNER TRIM CLIP	Not Necessary	40.00 FS	*-FS
34	10		*REAR DOOR WEATHERSTRIP CLIP	Necessary	40.00 FS	*15.00 FS
35	10		*FRONT DOOR WEATHERSTRIP CLIP	Not Necessary	40.00 FS	*- FS
36	1		*SIDE SKIRT RH	Repair	450.00 FS	*-FS
			Nation B:			

F=Franchise part. S=SpcNett. L=ListItemDisc.

 Sub Total (S\$)
 9,946.80
 2,865.00

 - List Item Discount on L Items 10.00/10.00% (S\$)
 908.68
 285.00

Candition

Danairaria

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 5

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
			Total Parts (S\$)	9,038.12	2,580.00
Report was unsubmitted during this print-out.					

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount			
Lab	Labour Items						
1	TO RENEW DAMAGED PARTS, REPLACED AND REALIGNED HYDRAULIC, ALIGNED ALL PARTS	New	800.00	600.00			
2	TO RESPRAY AFFECTED AREAS	New	1,200.00	900.00			
3	TO REMOVE & REFIX REAR WINDSCREEN	New	120.00	0.00			
4	TO TUFFCOAT AFFECTED AREA	New	250.00	100.00			
5	TO REMOVE / REFIT INTERIOR UPHOLSTERY	New	80.00	60.00			
6	TO REMOVE / REPLACE REAR UNDERCARRIAGE	New	250.00	120.00			
7	TO REMOVE / REFIT / ADJUST BRAKE FOUR WHEELS	New	100.00	0.00			
8	TO REMOVE / REPLACE DOOR MECHANISM	New	150.00	60.00			
9	TO CONDUCT 4 WHEELS ALIGNMENT	New	80.00	60.00			
	Gross Labour Cost (S\$)		3,030.00	1,900.00			
	Report was unsubmitted during	this print-out.					

< END OF ESTIMATES >