



Case Details

Case Reference Number : TAX/02/19/2087
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHC4317A

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-5776-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AXA Insurance Singapore Pte Ltd
 Accident Date and Time : 16/02/2019 03:15 AM
 Vehicle Age(In Months) : 62

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			DOOR FRT/RH	1	894.40	894.40	25.00	670.80	Replace	1	0	Repair ▾	
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace ▾	NEC
One Time Key In	Main			DOOR LOCK FRT/RH	1	575.80	575.80	25.00	431.85	Replace	0	0	Not Give ▾	
One Time Key In	Main			MIRROR LAMP RH	1	65.30	65.30	10.00	58.77	Replace	0	0	Not Give ▾	
One Time Key In	Main			COVER, OUTER MIRROR, RH	1	107.40	107.40	25.00	80.55	Replace	0	0	Not Give ▾	
One Time Key In	Main			MOULDING BODY, RH	1	673.60	673.60	25.00	505.20	Replace	1	0	Repair ▾	
One Time Key In	Main			DOOR RR/RH	1	954.50	954.50	25.00	715.88	Replace	1	0	Repair ▾	
One Time Key In	Main			HINGE LOWER RHR, DOOR	1	52.00	52.00	25.00	39.00	Replace	0	0	Not Give ▾	
One Time Key In	Main			HINGE UPPER RHR, DOOR	1	81.70	81.70	25.00	61.28	Replace	0	0	Not Give ▾	
One Time Key In	Main			CHECK ASSY, RR DOOR,	1	150.30	150.30	25.00	112.73	Replace	0	0	Not Give ▾	

Total Spare Part Cost 6,427.75

Surveyor Total 202.05

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 5,142.20

Final Sur Total 161.64

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			DOOR LOCK RR/RH	1	709.30	709.30	25.00	531.97	Replace	0	0	Not Give ▾	
One Time Key In	Main			DOOR LOCK STRIKER	1	40.50	40.50	25.00	30.38	Replace	0	0	Not Give ▾	
One Time Key In	Main			DOOR OUTER HANDLE RR/RH	1	69.80	69.80	25.00	52.35	Replace	0	0	Check ▾	
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	1	0	Repair ▾	
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	25.00	5.85	Replace	1	5.85	Replace ▾	NEC
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	25.00	16.20	Replace	1	16.20	Replace ▾	NEC
One Time Key In	Main			QUARTER GLASS RR/RH	1	846.50	846.50	25.00	634.88	Replace	0	0	Not Give ▾	
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give ▾	
One Time Key In	Main			FENDER LINER RR/RH	1	141.30	141.30	25.00	105.98	Replace	0	0	Check ▾	
One Time Key In	Main			WHEEL, DISC	1	1,490.20	1,490.20	25.00	1,117.65	Replace	1	0	Repair ▾	
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	0	Repair ▾	
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	0	0	Check ▾	
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Check ▾	
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace ▾	NEC
Total Spare Part Cost									6,427.75		Surveyor Total		202.05	
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)		20	
Final Spare Part Cost									5,142.20		Final Sur Total		161.64	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			1,014.00	900.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	1,014.00	900	
Total:			1,014.00	900.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT DOOR RH	378.00	200	
2	Main	TO RESPRAY VIEW MIRROR	180.00	0	
3	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	100	
4	Main	TO RESPRAY RH REAR DOOR	378.00	200	
5	Main	TO RESPRAY RIM	180.00	50	
6	Main	TO RESPRAY REAR FENDER RH	378.00	200	
7	Main	TO RESPRAY REAR BUMPER	378.00	200	
Total:			2,052.00	950.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30	
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
4	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30	
5	Main	TO TRANSFER DOOR MECHANISM	120.00	0	
6	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0	
7	Main	TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0	
8	Main	TO REMOVE / REFIT SEAT	120.00	0	
9	Main	TO REPLACE SUNDRY PARTS	100.00	0	
10	Main	TO WASH AND VACUUM	60.00	0	
Total:			1,065.00	80.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	5,142.20	161.64
Total Labour Cost	1,014.00	900.00
Total Spray Painting	2,052.00	950.00
Other	1,065.00	80.00
Overall Total	9,273.20	2,091.64
Lump Sum Repair Option	☐	☒
Lump Sum Total	9,250.00	2,100.00
Surveyor Approved Amount		2,100.00
No of Repair Days*	7	5
Remarks	-	L/S REPAIR, PHOTO AFTER PAINT.
Surveyor Name		Hwee jie
Signature		
Survey Date	20/02/2019	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: