



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1053A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	RADIATOR TOP COVER (CONSISTENT)	NOT NECESSARY	56.00	-
1	FRONT BUMPER (CONSISTENT)	CRACKED	531.00	531.00
1	FRONT BUMPER EMBLEM (CONSISTENT)	NECESSARY	44.00	44.00
1	FRONT BUMPER STRIP (CONSISTENT)	NOT NECESSARY	40.00	-
1	BONNET (CONSISTENT)	DAMAGED	979.00	979.00
1	BONNET GRILLE (CONSISTENT)	DAMAGED	386.00	386.00
	LESS 10% DISCOUNT		-203.60	-194.00
			1,832.40	1,746.00
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	48.00	48.00
1	SUNDRY (CONSISTENT) (SN)	NECESSARY	50.00	20.00
			98.00	68.00
	<u>LABOUR</u>			
	TO CHECK WIRING HEADLAMP WIRING.	NOT NECESSARY	80.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT ,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF THE SAME.		650.00	300.00
	TO PUTTY & SPRAY PAINTING ON FRONT BUMPER ,BONNET,BONNET GRILLE.		600.00	540.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		80.00	30.00
			1,410.00	870.00
	GRAND TOTAL		3,340.40	2,684.00
	RECOMMENDED COST OF REPAIRS			2,684.00

Report Ref No. CC4/ASM19003196/K1gs3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.