

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7555P**AAD1902-136***Not Authorized
Proposed 611 Smp @ 45001*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHB 7555P

KL1LA69RJBB093910

CHEVROLET

EPICA 2.0

16.2.2019

EQ

20/4/2012

PART**LIST**

1	1	Rear Bumper	\$	<i>BT/CM</i> 1,202.00 ✓
2	1	Rear Bumper Beam	\$	<i>BT</i> 239.94 ✓
3	1	Rear Bumper Centre Absorber	\$	<i>CM</i> 260.00 ✓
4	1	Rear Bumper Side Retainer RH	\$	<i>CM</i> 68.76 ✓
5	1	Rear Bumper Side Retainer LH	\$	<i>Sm</i> 68.76 X
6	1	Rear Bumper Reflectors RH	\$	<i>BT</i> 119.74 ✓
7	1	Rear Bumper Reflectors LH	\$	<i>Sm</i> 119.74 X
8	1	Rear Bumper Tow Hook Cover	\$	<i>Sm</i> 93.00 X
9	1	Rear End Panel Outer	\$	<i>BT</i> 623.76 ✓
10	1	Rear End Panel Inner Trim	\$	<i>Sm</i> 263.84 X
11	1	Rear Luggage Floor Panel	\$	<i>BT</i> 2,911.70 X
12	1	Rear Luggage Floor Panel Insulator	\$	<i>Sm</i> 1,991.70 X
13	1	Rear Luggage Floor Panel Trim Board	\$	<i>Sm</i> 2,011.60 X
14	1	Bootlid	\$	<i>BT</i> 973.00 ✓
15	1	Bootlid inner trim board	\$	<i>Sm</i> 400.00 X
16	1	Bootlid Weatherstrip	\$	<i>Sm</i> 344.28 X
17	1	Bootlid Lock - Top	\$	<i>BT</i> 466.56 X
18	1	Bootlid 'CHEVROLET' Badge	\$	<i>BT</i> 120.62 ✓
19	1	Bootlid Logo	\$	<i>BT</i> 138.84 ✓
20	1	Bootlid 'EPICA LT' Badge	\$	<i>BT</i> 119.84 ✓
21	1	Bootlid Reflector Centre	\$	<i>Sm</i> 217.97 X
22	1	Bootlid Reflector RH	\$	<i>Sm</i> 128.40 X
23	1	Bootlid Reflector LH	\$	<i>Sm</i> 128.40 X
24	1	Rear Tail Lamp RH	\$	<i>CM</i> 479.30 ✓
25	1	Rear Tail Lamp LH	\$	<i>Sm</i> 479.30 X
26	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	<i>BT</i> 1,110.00 X
27	1	Rear Fender <i>RH</i>	\$	<i>BT</i> 1,145.00 ✓
28	1	Rear Fender Inner Trim <i>RH</i>	\$	<i>CM</i> 418.44 ✓
29	1	Rear Windscreen Inner Sponge Seal	\$	<i>Sm</i> 80.00 X

Trans-cab Auto Services Pte Ltd

AAD1902-136

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7555P

TOTAL	\$	16,724.49
10%	\$	1,672.45
	\$	15,052.04

Specical Nett

1	1Set	Bootlid inner trim board Clip	\$	<i>nn</i>	40.00	X
2	1Set	Rear Bumper Parking Sensor	\$	<i>shiat</i>	300.00	✓
3	1Set	Rear Bumper Fastener Clip	\$	<i>nn</i>	44.00	✓
4	1Set	Rear Fender Inner Trim Clip <i>PH</i>	\$	<i>nn</i>	30.00	✓
5	1Set	Rear Bumper End Dust Cover Clip	\$	<i>nn</i>	30.00	X
6	1	Rear Exhaust Mounting	\$	<i>nn</i>	300.00	X
7	2	Rear Windscreen Sealant	\$	<i>nn</i>	80.00	<i>80.00</i>
8	1	Rear Windscreen Inner Sponge Seal	\$	<i>nn</i>	100.00	<i>30.00</i>

TOTAL	\$	924.00
--------------	-----------	---------------

TOTAL PARTS	\$	15,976.04
--------------------	-----------	------------------

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 4,500.00 *1200*

Putty And Spray Painting Of The Affected Portion.

\$ 4,500.00 *800*

To reinstall rear bumper parking sensor.

\$ 170.00 *60*

To transfer of end panel fittings and conduct
water seepage test.

\$ *nn* 170.00 X

To transfer of boot fittings and conduct water
seepage test.

\$ 170.00 *60*

To remove and refit interior fittings, trimings,
garnish, fittings and other, to enable repair.

\$ 380.00 *100*

To check steering geometry and computer wheel
alignment

\$ *nn* 220.00 X

Trans-cab Auto Services Pte Ltd**AAD1902-136**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7555P

To Remove And Refit Rear W/Screen Glass To
Facilitate Bodywork Repair.

\$ 170.00 *1201*

To transfer of Rear Bumper fittings and conduct
water seepage test.

\$ *~* 170.00 *X*

\$ **10,450.00**

TOTAL \$ 26,426.04

Repair Days (LUMP SUM)~~15 DAYS~~*9 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: