

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
45	1		*ERP STICKER <i>me ✓</i>	0	0.00	*26.00 FS)
46	1		*FRT WINDSCREEN PILLAR LH <i>BT ✓</i>	0.00	0.00	*170.00 F/
47	1		*FRT WINDSCREEN PILLAR INNER TRIM LH <i>DE ✓</i>	0.00	0.00	*120.00 F/
48	1		*FRT ROOF TOP PANEL <i>BT ✓</i>	0.00	0.00	*380.00 F/
49	1		*FRT CABIN ROOF LINING <i>DE ✓</i>	0.00	0.00	*280.00 F/
50	1		*FRT DOOR PILLAR @ FRT LH <i>BT ✓</i>	0.00	0.00	*170.00 F/
51	1		*FRT DOOR INNER MOULDING LH <i>DE ✓</i>	0.00	0.00	*70.00 F/
52	1		*FRT ROCKER PANEL LH <i>BT ✓</i>	0.00	0.00	*240.00 F/
53	1		*FRT ROCKER PANEL SEAL LH <i>me ✓</i>	0.00	0.00	*50.00 F/
54	1		*FRT SCUFF PLATE LH <i>DE ✓</i>	0.00	0.00	*150.00 F/
55	1		*FRT STEP PANEL LH <i>ERA ✓</i>	0.00	0.00	*150.00 F/
56	1		*FRT STEP GARNISH LH <i>CRA ✓</i>	0.00	0.00	*95.00 F/
57	2		*FRT DOOR <i>me ✓</i>	0.00	0.00	*1,100.00 F/
58	2		*FRT DOOR HINGE <i>BT ✓</i>	0.00	0.00	*70.00 F/
59	1		*FRT DOOR CHECKER <i>? xsvl</i>	0.00	0.00	*65.00 FX
60	1		*FRT DOOR GLASS RUN CHANNEL <i>BT ✓</i>	0.00	0.00	*70.00 F/
61	1		*FRT DOOR GLASS WINDOW GUIDE <i>? xsvl</i>	0.00	0.00	*70.00 FX
62	1		*FRT DOOR GLASS LH <i>BT ✓</i>	0.00	0.00	*180.00 F/
63	1		*FRT DOOR GLASS OUTER MOULDING LH <i>me ✓</i>	0.00	0.00	*55.00 F/
64	1		*FRT DOOR GLASS INNER MOULDING LH <i>me ✓</i>	0.00	0.00	*70.00 F/
65	1		*FRT DOOR FRAME OUTER COVER @ FRONT <i>me ✓</i>	0.00	0.00	*35.00 F/
66	1		*FRT DOOR SEAL @ FRONT <i>me ✓</i>	0.00	0.00	*70.00 F/
67	1		*FRT DOOR WEATHERSTRIPE <i>me ✓</i>	0.00	0.00	*75.00 F/
68	1		LH *FRT DOOR LOWER SEAL <i>me ✓</i>	0.00	0.00	*35.00 F/
69	1		LH *FRT DOOR OUTER HANDLE LH <i>? xsvl</i>	0.00	0.00	*55.00 FX
70	1		*FRT DOOR INNER HANDLE LH <i>? xsvl</i>	0.00	0.00	*35.00 FX
71	1		*FRT DOOR WINDOW SWITCH <i>CRA ✓</i>	0.00	0.00	*120.00 F/
72	1		*FRT DOOR SPEAKER LH <i>? xsvl</i>	0	0.00	*80.00 FSX
73	2		*FRT DOOR INNER TRIM BOARD LH <i>DE ✓</i>	0.00	0.00	*560.00 F/
74	1		*FRT DOOR ARM REST LH <i>? xsvl</i>	0.00	0.00	*120.00 FX
75	1		*FRT DOOR LOCK LH <i>BT ✓</i>	0.00	0.00	*120.00 F/
76	1		*FRT DOOR GLASS REGULATOR LH <i>BT (photo) xsvl</i>	0.00	0.00	*75.00 FX
77	1		*FRT DOOR GLASS REGULATOR MOTOR LH <i>? xsvl</i>	0.00	0.00	*180.00 FX
78	2		*FRT DOOR ROC STICKER <i>me ✓</i>	0	0.00	*40.00 FS)
79	1		*FRT DOOR PILLAR @ REAR <i>BT ✓</i>	0.00	0.00	*170.00 F/
80	1		*FRT WIPER TANK <i>? xsvl</i>	0.00	0.00	*55.00 FX
81	1		*FRT CABIN RR VIEW MIRROR <i>? xsvl</i>	0.00	0.00	*55.00 FX
82	1		*FRT DASHBOARD <i>DE ✓</i>	0.00	0.00	*380.00 F/
83	1		*FRT DASHBOARD SUPPORT BEAM <i>BT (photo) xsvl</i>	0.00	0.00	*280.00 F/
84	1		*BRAKE BOOSTER <i>? xsvl</i>	0.00	0.00	*450.00 FX
85	1		*BRAKE MASTER PUMP <i>? xsvl</i>	0.00	0.00	*150.00 FY
86	1		*BRAKE FLUID TANK <i>? xsvl</i>	0.00	0.00	*55.00 FX
87	1		*BRAKE FLUID <i>me ✓</i>	0	0.00	*20.00 FS)
88	1		*SPEEDOMETER <i>CRA (photo) xsvl</i>	0.00	0.00	*550.00 FX
89	1		*SPEEDOMETER OUTER TRIM <i>CRA ✓</i>	0.00	0.00	*150.00 F/
90	1		*STEERING COLUMN UPPER COVER <i>? xsvl</i>	0.00	0.00	*150.00 FX
91	1		*BRAKE PEDAL ASSY <i>? xsvl</i>	0.00	0.00	*150.00 FX
92	1		*CLUTCH PEDAL ASSY <i>? xsvl</i>	0.00	0.00	*150.00 FX
93	1		*RADIO <i>? xsvl</i>	0	0.00	*220.00 FS*
94	1		*RADIO OUTER TRIM <i>CRA ✓</i>	0.00	0.00	*120.00 F/
95	1		*AIRCON CONTROL SWITCH ASSY <i>? xsvl</i>	0.00	0.00	*120.00 FX
96	1		*GEAR SHIFT CONSOLE BOX <i>CRA ✓</i>	0.00	0.00	*150.00 F/
97	1		*GLOVE BOX FRONT LH <i>? xsvl</i>	0.00	0.00	*150.00 FX
98	1		*AIR CON BLOWER ASSY <i>CRA ✓</i>	0.00	0.00	*550.00 F/
99	1		*AIR CON BLOWER OUTER COVER <i>(photo) ✓</i>	0.00	0.00	*185.00 F/
100	1		*AIR CON HEATER COOLING COIL ASSY <i>BT ✓</i>	0.00	0.00	*1,700.00 F/
101	1		*FRT DASHBOARD CENTRE LOWER COVER <i>? xsvl</i>	0.00	0.00	*190.00 FX

2/21/2019

Repairer Estimates

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
102	1		*SPEED DEVICE ? xslc	0	0.00	*180.00 FS X
103	1		*AIRBAG @STEERING Act	0.00	0.00	*550.00 F ✓
104	1		*AIRBAG CLOCK SPRING Act -	0.00	0.00	*240.00 F ✓
105	1		*AIRBAG CONTROL UNIT Act -	0.00	0.00	*450.00 F ✓
106	2		*FRT SEAT BELT Act -	0.00	0.00	*560.00 F ✓
107	1		*RADIATOR ? xslc	0.00	0.00	*500.00 F photo
108	1		*COOLANT Act -	0	0.00	*20.00 FS ✓
109	1		*RADIATOR FAN COWLING ? cr -	0.00	0.00	*75.00 F photo
110	1		*RADIATOR FAN BLADE ? act -	0.00	0.00	*65.00 F photo
111	1		*RADIATOR FAN MOTOR ? xslc	0.00	0.00	*150.00 FX

F=Franchise part. S=SpcNett.

Total Parts (\$\$)

22,186.00

Sng Ah Tee Motor & Panel Service Pte Ltd/GBE6641K/20/02/2019 11:02. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

SUPPLEMENTAL
- ENGINE ECU \$

total parts \$15021
Suff \$1261
labour \$5207-4870

total \$20488 20796
less 20% = \$4097.60 ~ \$16800 + 4%
16,636.80 \$16,600
limit \$14 Before tax
\$500

repair limit = \$14k
22 days

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO KNOCK,WELD FRT BUMPER,FRT FLOOR PANEL, FRT PANEL, FRT WIPER PANEL, WINDSCREEN PANEL X2, FRT DOOR PILLAR LH, ROOF TOP PANEL, ROCKER PANEL LH, STEP PANEL LH, FRT DOOR X2, REMOVE & FIX ON ABOVE PARTS	New	2000 2,800.00
2	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	1200 1,600
3	TO STRAIGHTEN FRT CHASSIS FRAME	New	400 600.00
4	TO TRANSFER FRT DOOR GLASS X2	New	60 100.00
5	TO REMOVE & REPLACE FRT DASHBOARD	New	150 200.00
6	TO REMOVE & REFIX FRT WINDSCREEN	New	100 100.00
7	TO REMOVE & REFIX FRT CABIN SEAT	New	100 150.00
8	TO REMOVE & REFIX FRT AIRBAG SYSTEM	New	250 350.00
9	TO DIAGNOSE & RESET FAULT CODE	New	80 100.00
10	TO TOP UP AIRCON GAS	New	50 50.00
11	TO REMOVE & REFIX ROOF LINING	New	60 80.00
12	TO LIFT UP CABIN (photo) XAN (no photo)	New	X 250 350.00
13	TO CHECK WIRING	New	20 50.00
14	TO REMOVE & FIX FRT WIRE HARNESS (photo) XAN	New	X 150 180.00 X
Gross Labour Cost (S\$)			5400 7,710.00
			4870

Sng Ah Tee Motor & Panel Service Pte Ltd/GBE6641K/20/02/2019 11:02. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul

Hp 90010018

22 days

4/3

21/02/19 @ 1600

EXCESS: 500

Revert

Resurvey after repair

Limit \$14k

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Feb 2019 Sendback Est	20 Feb 2019 11:02 S\$29,896.00	20 Feb 2019 16:01 Edit Adj Rpt	S\$14,000.00 Edit Estimates	S\$14,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	THE BEST STAR ENGINEERING, Co. Reg. No.: 201507035H		
Vehicle Reg. No.:	GBE6641K	Date of Loss:	13/02/2019 09:00 - :59 [35 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM19D200815C01	Policy/Cover Note No.:	DMCVSN3018511801 (Comprehensive) Coverage: 16/03/2018 - 15/03/2019
		Excess:	S\$500.00
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 01/03/2019]		
Driver/Custodian:	KUPPUSAMY DHANDAYUTHAPANI (37 / Male) , NRIC: G7014094U, Tel: +6586876742 Email: NOEMAIL		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- CHINA_TAIPING (05/03/2019): Alert - Adj Mandate Approved (S\$14000.00) - GBE6641K - Claim Handler: Chong Boon...
- CHINA_TAIPING (26/02/2019): Alert - Adj Mandate Approved (S\$0.00) - GBE6641K - Claim Handler: Chong Boon Sen
- CHINA_TAIPING (25/02/2019): Alert - Adj Mandate Approved (S\$0.00) - GBE6641K - Claim Handler: Chong Boon Sen

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

GBE6641K (SNM19D200815C01)
OD
Feb 13 2019 9:00AM
[THE BEST STAR ENGINEERING]
Sng Ah Tee Motor & Panel Service Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
View [View in Browser](#) ▼

Assessment Reports

No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	1 per page ▼	Thumbnail	Print
1	20/02/19 11:02	Repairer Estimates		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/03/19 10:22	Adjuster Immediate Advice		Load HTM	

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page ▼	Thumbnail	Print
1	04/03/19 10:22	General View		Load JPG	☒
2	04/03/19 10:22	General View		Load JPG	☒
3	04/03/19 10:22	General View		Load JPG	☒
4	04/03/19 10:23	General View		Load JPG	☒
5	04/03/19 10:23	General View		Load JPG	☒
6	04/03/19 10:23	General View		Load JPG	☒
7	04/03/19 10:23	General View		Load JPG	☒
8	04/03/19 10:23	General View		Load JPG	☒
9	04/03/19 10:23	General View		Load JPG	☒
10	04/03/19 10:23	General View		Load JPG	☒
11	04/03/19 10:23	General View		Load JPG	☒
12	04/03/19 10:23	General View		Load JPG	☒
13	04/03/19 10:23	General View		Load JPG	☒
14	04/03/19 10:23	General View		Load JPG	☒
15	04/03/19 10:23	General View		Load JPG	☒
16	04/03/19 10:23	General View		Load JPG	☒
17	04/03/19 10:23	General View		Load JPG	☒
18	04/03/19 10:23	General View		Load JPG	☒
19	04/03/19 10:23	General View		Load JPG	☒
20	04/03/19 10:23	General View		Load JPG	☒
21	04/03/19 10:23	General View		Load JPG	☒
22	04/03/19 10:23	General View		Load JPG	☒
23	04/03/19 10:23	General View		Load JPG	☒
24	04/03/19 10:23	General View		Load JPG	☒
25	04/03/19 10:23	General View		Load JPG	☒
26	04/03/19 10:23	General View		Load JPG	☒
27	04/03/19 10:23	General View		Load JPG	☒
28	04/03/19 10:23	General View		Load JPG	☒
29	04/03/19 10:23	General View		Load JPG	☒
30	04/03/19 10:23	General View		Load JPG	☒
31	04/03/19 10:23	General View		Load JPG	☒
32	04/03/19 10:23	General View		Load JPG	☒

Assessment Reports			1 per page	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail Print
33	04/03/19 10:23	General View	1	Load JPG
34	04/03/19 10:23	General View	1	Load JPG
35	04/03/19 10:23	General View	1	Load JPG
36	04/03/19 10:23	General View	1	Load JPG
37	04/03/19 10:23	General View	1	Load JPG
38	04/03/19 10:23	General View	1	Load JPG
39	04/03/19 10:23	General View	1	Load JPG
40	04/03/19 10:23	General View	1	Load JPG
41	04/03/19 10:23	General View	1	Load JPG
42	04/03/19 10:23	General View	1	Load JPG
43	04/03/19 10:23	General View	1	Load JPG
44	04/03/19 10:23	General View	1	Load JPG
45	04/03/19 10:23	General View	1	Load JPG
46	04/03/19 10:23	General View	1	Load JPG
47	04/03/19 10:23	General View	1	Load JPG
48	04/03/19 10:23	General View	1	Load JPG
49	04/03/19 10:23	General View	1	Load JPG
50	04/03/19 10:23	General View	1	Load JPG
51	04/03/19 10:23	General View	1	Load JPG
52	04/03/19 10:23	General View	1	Load JPG
53	04/03/19 10:23	General View	1	Load JPG
54	04/03/19 10:23	General View	1	Load JPG
55	04/03/19 10:23	General View	1	Load JPG
56	04/03/19 10:23	General View	1	Load JPG
57	04/03/19 10:23	General View	1	Load JPG
58	04/03/19 10:23	General View	1	Load JPG
59	04/03/19 10:23	General View	1	Load JPG
60	04/03/19 10:23	General View	1	Load JPG
61	04/03/19 10:23	General View	1	Load JPG
62	04/03/19 10:23	General View	1	Load JPG
63	04/03/19 10:23	General View	1	Load JPG
64	04/03/19 10:23	General View	1	Load JPG
65	04/03/19 10:23	General View	1	Load JPG
66	04/03/19 10:23	General View	1	Load JPG
67	04/03/19 10:23	General View	1	Load JPG
68	04/03/19 10:23	General View	1	Load JPG
69	04/03/19 10:23	General View	1	Load JPG
70	04/03/19 10:23	General View	1	Load JPG
71	04/03/19 10:23	General View	1	Load JPG
72	04/03/19 10:23	General View	1	Load JPG
73	04/03/19 10:23	General View	1	Load JPG
74	04/03/19 10:23	General View	1	Load JPG
75	04/03/19 10:23	General View	1	Load JPG
76	04/03/19 10:23	General View	1	Load JPG
77	04/03/19 10:23	General View	1	Load JPG
78	04/03/19 10:23	General View	1	Load JPG
79	04/03/19 10:23	General View	1	Load JPG
80	04/03/19 10:23	General View	1	Load JPG

Assessment Reports			1 per page ▼	✓
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
81	04/03/19 10:23	General View	 Load JPG	✓
82	04/03/19 10:23	General View	 Load JPG	✓
83	04/03/19 10:23	General View	 Load JPG	✓
84	04/03/19 10:23	General View	 Load JPG	✓
85	04/03/19 10:23	General View	 Load JPG	✓
86	04/03/19 10:23	General View	 Load JPG	✓
87	04/03/19 10:23	General View	 Load JPG	✓
88	04/03/19 10:23	General View	 Load JPG	✓
89	04/03/19 10:23	General View	 Load JPG	✓
90	04/03/19 10:23	General View	 Load JPG	✓
91	04/03/19 10:23	General View	 Load JPG	✓
92	04/03/19 10:23	General View	 Load JPG	✓
93	04/03/19 10:23	General View	 Load JPG	✓
94	04/03/19 10:23	General View	 Load JPG	✓
95	04/03/19 10:23	General View	 Load JPG	✓
96	04/03/19 10:23	General View	 Load JPG	✓
97	04/03/19 10:23	General View	 Load JPG	✓
98	04/03/19 10:23	General View	 Load JPG	✓
99	04/03/19 10:23	General View	 Load JPG	✓
100	04/03/19 10:23	General View	 Load JPG	✓
101	04/03/19 10:23	General View	 Load JPG	✓
102	04/03/19 10:23	General View	 Load JPG	✓
103	04/03/19 10:23	General View	 Load JPG	✓
104	04/03/19 10:23	General View	 Load JPG	✓
105	04/03/19 10:23	General View	 Load JPG	✓
106	04/03/19 10:23	General View	 Load JPG	✓
107	04/03/19 10:23	General View	 Load JPG	✓
108	28/08/19 11:54	Reinspection Photo	 Load JPG	✓
109	28/08/19 11:54	Reinspection Photo	 Load JPG	✓
110	28/08/19 11:54	Reinspection Photo	 Load JPG	✓
111	28/08/19 11:54	Reinspection Photo	 Load JPG	✓
112	28/08/19 11:54	Reinspection Photo	 Load JPG	✓
113	28/08/19 11:54	Reinspection Photo	 Load JPG	✓
114	28/08/19 11:54	Reinspection Photo	 Load JPG	✓
115	28/08/19 11:54	Reinspection Photo	 Load JPG	✓
116	28/08/19 11:54	Reinspection Photo	 Load JPG	✓
117	28/08/19 11:54	Reinspection Photo	 Load JPG	✓
118	28/08/19 11:54	Reinspection Photo	 Load JPG	✓
119	28/08/19 11:54	Reinspection Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	20/02/19 10:30	E-filed GIA report	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/02/19 14:41	ESTIMATE	 Load PDF	
2	04/03/19 11:09	ESTIMATE	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	1 per page	☒
1	03/09/19 23:36	Accident Statement		Thumbnail Load HTM
Photos/Images				
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	3 per page	☒
1	13/02/19 14:11	Accident Photo		Thumbnail Load JPG
2	13/02/19 14:11	Accident Photo		Load JPG
3	13/02/19 14:11	Accident Photo		Load JPG
4	13/02/19 14:11	Accident Photo		Load JPG
5	13/02/19 14:11	Accident Photo		Load JPG
6	13/02/19 14:11	Accident Photo		Load JPG
7	13/02/19 14:11	Accident Photo		Load JPG
8	13/02/19 14:11	Accident Photo		Load JPG
9	13/02/19 14:11	Accident Photo		Load JPG
10	13/02/19 14:11	Accident Photo		Load JPG
11	13/02/19 14:11	Accident Photo		Load JPG
12	13/02/19 14:11	Accident Photo		Load JPG
13	13/02/19 14:11	Accident Photo		Load JPG
14	13/02/19 14:11	Accident Photo		Load JPG
15	13/02/19 14:11	Accident Photo		Load JPG
16	13/02/19 14:11	Accident Photo		Load JPG
17	13/02/19 14:11	Accident Photo		Load JPG
18	13/02/19 14:11	Accident Photo		Load JPG
19	13/02/19 14:11	Accident Photo		Load JPG
20	13/02/19 14:11	Accident Photo		Load JPG
21	13/02/19 14:11	Accident Photo		Load JPG
22	13/02/19 14:11	Accident Photo		Load JPG
23	13/02/19 14:11	Accident Photo		Load JPG
24	13/02/19 14:11	Accident Photo		Load JPG
25	13/02/19 14:11	Accident Photo		Load JPG
26	13/02/19 14:11	Accident Photo		Load JPG
27	13/02/19 14:11	Accident Photo		Load JPG
28	13/02/19 14:11	Accident Photo		Load JPG
29	13/02/19 14:11	Accident Photo		Load JPG
30	13/02/19 14:11	Accident Photo		Load JPG
31	13/02/19 14:11	Accident Photo		Load JPG
Documentation				
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	1 per page	☒
1	13/02/19 14:12	Sketch Plan		Thumbnail Load TIF
2	13/02/19 14:12	CI,IC,DL		Load TIF

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI19003275/R1TD3S2

Date: 04/09/2019

REFERENCE

Insured/Claimant: THE BEST STAR ENGINEERING

Policy No: DMCVSN3018511801

Date of Loss: 13/02/2019

Nature of Claim: OD

Claim No: SNM19D200815C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE6641K	Engine No:	1KD2565717
Make & Model:	TOYOTA DYNA, 3.0 D TURBO M/T 2WD (M)	Chassis No:	KDY2318022212
Reg. Date:	26/02/2016 (Man. Year: 2015)	Odometer:	0 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	S\$45,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	155 R13C (D)
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 5/5 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,186.00	15,928.00	6,258.00	28.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,710.00	4,870.00	2,840.00	36.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,896.00	20,798.00	9,098.00	30.43
Approved Total (Overridden) (S\$)		14,000.00		
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	29,896.00	13,500.00	16,396.00	54.84
+ GST 7.00/7.00% (S\$)	2,092.72	945.00	1,147.72	54.84
Nett Amount (S\$)	31,988.72	14,445.00	17,543.72	54.84

INSPECTION

Date of Assignment:	20/02/2019 Present Location:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Date Inspected:	21/02/2019 Inspected At:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18 Singapore 628457
Estimated Period of Repair:	22.0 days	

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 04 Sep 2019)

Parts: N/A TOYOTA DYNA 3.0 D TURBO M/T 2WD (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBE6641K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Scratched	20.00 FS	*20.00 FS
2	1		*FRT BUMPER	Cracked	240.00 F	*240.00 F
3	2		*FRT BUMPER BRACKET	Serviceable	180.00 F	*- F
4	1		*FRT GRILLE	Cracked	140.00 F	*140.00 F
5	1		*FRT GRILLE TOP SEAL	Necessary	35.00 F	*35.00 F
6	1		*FRT GRILLE EMBLEM	Necessary	35.00 F	*35.00 F
7	1		*FRT GRILLE CLIP	Necessary	15.00 F	*15.00 F
8	1		*FRT GRILLE INNER SPONGE	Cut	45.00 F	*45.00 F
9	2		*FRT HEADLAMP	Cracked	640.00 F	*640.00 F
10	2		*FRT HEADLAMP CLIP	Necessary	16.00 F	*16.00 F
11	1		*FRT HEADLAMP LOWER SEAL LH	Cut	15.00 F	*15.00 F
12	1		*AIR CON CONDENSER ASSY	Bent	350.00 F	*350.00 F
13	1		*AIR CON HIGH PRESSURE PIPE	Bent	180.00 F	*180.00 F
14	1		*AIR CON LOWER PRESSURE PIPE	Bent	180.00 F	*180.00 F
15	2		*FRT HEATER HOSE	Cut	240.00 F	*240.00 F
16	1		*FRT HORN	Cut	60.00 F	*60.00 F
17	1		*ALARM SIREN	Cracked	60.00 F	*60.00 F
18	1		*FRT CABIN SUPPORT BEAM	Serviceable	75.00 F	*- F
19	2		*FRT CABIN BEAM MOUNTING BUSH	Serviceable	100.00 F	*- F
20	2		*FRT CABIN BEAM MOUNTING BRACKET	Serviceable	70.00 F	*- F
21	1		*FRT PANEL	Buckled	350.00 F	*350.00 F
22	2		*FRT PANEL INNER SUPPORT	Bent	150.00 F	*150.00 F
23	1		*FRT PANEL DYNA STICKER	Necessary	25.00 F	*25.00 F
24	1		*FRT PANEL TOP GARNISH	Deformed	95.00 F	*95.00 F
25	2		*FRT PANEL TOP GARNISH LH/RH	Distorted	70.00 F	*70.00 F
26	1		*FRT FLOOR PANEL	Buckled	900.00 F	*900.00 F
27	2		*FRT CORNER PANEL	Bent	130.00 F	*130.00 F
28	1		*FRT PANEL TOP GARNISH LH BRACKET	Missing	50.00 F	*50.00 F
29	1		*FRT SIDE MIRROR ASSY	Cracked	170.00 F	*170.00 F
30	1		*FRT WIRE HARNESS	Serviceable	1,600.00 F	*- F
31	1		*FRT WIPER PANEL	Bent	350.00 F	*350.00 F
32	1		*FRT WIPER PANEL LH	Missing	70.00 F	*70.00 F
33	2		*CABLE GEAR SHIFT	Serviceable	360.00 F	*- F
34	1		*FRT WIPER PANEL RH	Scratched	70.00 F	*70.00 F
35	1		*FRT WIPER PANEL TOP SEAL	Necessary	35.00 F	*35.00 F
36	1		*FRT WIPER NOZZLE	O/s Cracked / N/s Serviceable	36.00 F	*18.00 F
37	1		*FRT WIPER NOZZLE NUT	Necessary	5.00 F	*5.00 F
38	1		*FRT WIPER MOTOR	Serviceable	120.00 F	*- F
39	1		*FRT WIPER LINKAGE	Bent	120.00 F	*120.00 F
40	1		*FRT WIPER ARM	Missing	55.00 F	*55.00 F
41	2		*FRT WIPER BLADE	Missing	30.00 F	*30.00 F
42	1		*FRT WIPER ARM COVER	Cut	8.00 F	*8.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*FRT WINDSCREEN	Broken	450.00 F	*450.00 F
44	1		*FRT WINDSCREEN RUBBER	Necessary	120.00 F	*120.00 F
45	1		*ERP STICKER	Necessary	26.00 FS	*26.00 FS
46	1		*FRT WINDSCREEN PILLAR LH	Bent	170.00 F	*170.00 F
47	1		*FRT WINDSCREEN PILLAR INNER TRIM LH	Deformed	120.00 F	*120.00 F
48	1		*FRT ROOF TOP PANEL	Bent	380.00 F	*380.00 F
49	1		*FRT CABIN ROOF LINING	Deformed	280.00 F	*280.00 F
50	1		*FRT DOOR PILLAR @ FRT LH	Bent	170.00 F	*170.00 F
51	1		*FRT DOOR INNER MOULDING LH	Deformed	70.00 F	*70.00 F
52	1		*FRT ROCKER PANEL LH	Bent	240.00 F	*240.00 F
53	1		*FRT ROCKER PANEL SEAL LH	Necessary	50.00 F	*50.00 F
54	1		*FRT SCUFF PLATE LH	Deformed	150.00 F	*150.00 F
55	1		*FRT STEP PANEL LH	Cracked	150.00 F	*150.00 F
56	1		*FRT STEP GARNISH LH	Cracked	95.00 F	*95.00 F
57	2		*FRT DOOR	Buckled	1,100.00 F	*1,100.00 F
58	2		*FRT DOOR HINGE	Bent	70.00 F	*70.00 F
59	1		*FRT DOOR CHECKER	Serviceable	65.00 F	*- F
60	1		*FRT DOOR GLASS RUN CHANNEL	Distorted	70.00 F	*70.00 F
61	1		*FRT DOOR GLASS WINDOW GUIDE	Serviceable	70.00 F	*- F
62	1		*FRT DOOR GLASS LH	Broken	180.00 F	*180.00 F
63	1		*FRT DOOR GLASS OUTER MOULDING LH	Necessary	55.00 F	*55.00 F
64	1		*FRT DOOR GLASS INNER MOULDING LH	Necessary	70.00 F	*70.00 F
65	1		*FRT DOOR FRAME OUTER COVER @ FRONT	Scratched	35.00 F	*35.00 F
66	1		*FRT DOOR SEAL @ FRONT	Necessary	70.00 F	*70.00 F
67	1		*FRT DOOR WEATHERSTRIPE LH	Necessary	75.00 F	*75.00 F
68	1		*FRT DOOR LOWER SEAL LH	Necessary	35.00 F	*35.00 F
69	1		*FRT DOOR OUTER HANDLE LH	Serviceable	55.00 F	*- F
70	1		*FRT DOOR INNER HANDLE LH	Serviceable	35.00 F	*- F
71	1		*FRT DOOR WINDOW SWITCH	Cracked	120.00 F	*120.00 F
72	1		*FRT DOOR SPEAKER LH	Serviceable	80.00 FS	*- FS
73	2		*FRT DOOR INNER TRIM BOARD LH	Deformed	560.00 F	*560.00 F
74	1		*FRT DOOR ARM REST LH	Serviceable	120.00 F	*- F
75	1		*FRT DOOR LOCK LH	Bent	120.00 F	*120.00 F
76	1		*FRT DOOR GLASS REGULATOR LH	Serviceable	75.00 F	*- F
77	1		*FRT DOOR GLASS REGULATOR MOTOR LH	Serviceable	180.00 F	*- F
78	2		*FRT DOOR ROC STICKER	Necessary	40.00 FS	*40.00 FS
79	1		*FRT DOOR PILLAR @ REAR	Bent	170.00 F	*170.00 F
80	1		*FRT WIPER TANK	Serviceable	55.00 F	*- F
81	1		*FRT CABIN RR VIEW MIRROR	Serviceable	55.00 F	*- F
82	1		*FRT DASHBOARD	Deformed	380.00 F	*380.00 F
83	1		*FRT DASHBOARD SUPPORT BEAM	Serviceable	280.00 F	*- F
84	1		*BRAKE BOOSTER	Serviceable	450.00 F	*- F
85	1		*BRAKE MASTER PUMP	Serviceable	150.00 F	*- F
86	1		*BRAKE FLUID TANK	Serviceable	55.00 F	*- F
87	1		*BRAKE FLUID	Necessary	20.00 FS	*20.00 FS
88	1		*SPEEDOMETER	Serviceable	550.00 F	*- F
89	1		*SPEEDOMETER OUTER TRIM	Cracked	150.00 F	*150.00 F
90	1		*STEERING COLUMN UPPER COVER	Serviceable	150.00 F	*- F
91	1		*BRAKE PEDAL ASSY	Serviceable	150.00 F	*- F
92	1		*CLUTCH PEDAL ASSY	Serviceable	150.00 F	*- F
93	1		*RADIO	Serviceable	220.00 FS	*- FS
94	1		*RADIO OUTER TRIM	Cracked	120.00 F	*120.00 F
95	1		*AIRCON CONTROL SWITCH ASSY	Serviceable	120.00 F	*- F
96	1		*GEAR SHIFT CONSOLE BOX	Cracked	150.00 F	*150.00 F
97	1		*GLOVE BOX FRONT LH	Serviceable	150.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
98	1		*AIR CON BLOWER ASSY	Cracked	550.00 F	*550.00 F
99	1		*AIR CON BLOWER OUTER COVER	Cracked	185.00 F	*185.00 F
100	1		*AIR CON HEATER COOLING COIL ASSY	Bent	1,700.00 F	*1,700.00 F
101	1		*FRT DASHBOARD CENTRE LOWER COVER	Serviceable	190.00 F	*- F
102	1		*SPEED DEVICE	Serviceable	180.00 FS	*- FS
103	1		*AIRBAG @STEERING	Activated	550.00 F	*550.00 F
104	1		*AIRBAG CLOCK SPRING	Activated	240.00 F	*240.00 F
105	1		*AIRBAG CONTROL UNIT	Activated	450.00 F	*450.00 F
106	2		*FRT SEAT BELT	Activated	560.00 F	*560.00 F
107	1		*RADIATOR	Bent	500.00 F	*500.00 F
108	1		*COOLANT	Necessary	20.00 FS	*20.00 FS
109	1		*RADIATOR FAN COWLING	Cracked	75.00 F	*75.00 F
110	1		*RADIATOR FAN BLADE	Cut	65.00 F	*65.00 F
111	1		*RADIATOR FAN MOTOR	Serviceable	150.00 F	*- F

F=Franchise part. S=SpcNett.

Total Parts (S\$) 22,186.00 15,928.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK,WELD FRT BUMPER,FRT FLOOR PANEL, FRT PANEL, FRT WIPER PANEL, WINDSCREEN PANEL X2, FRT DOOR PILLAR LH, ROOF TOP PANEL, ROCKER PANEL LH, STEP PANEL LH, FRT DOOR X2, REMOVE & FIX ON ABOVE PARTS	New	2,800.00	2,000.00
2	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	2,600.00	1,600.00
3	TO STRAIGHTEN FRT CHASSIS FRAME	New	600.00	400.00
4	TO TRANSFER FRT DOOR GLASS X2	New	100.00	60.00
5	TO REMOVE & REPLACE FRT DASHBOARD	New	200.00	150.00
6	TO REMOVE & REFIX FRT WINDSCREEN	New	100.00	100.00
7	TO REMOVE & REFIX FRT CABIN SEAT	New	150.00	100.00
8	TO REMOVE & REFIX FRT AIRBAG SYSTEM	New	350.00	250.00
9	TO DIAGNOSE & RESET FAULT CODE	New	100.00	80.00
10	TO TOP UP AIRCON GAS	New	50.00	50.00
11	TO REMOVE & REFIX ROOF LINING	New	80.00	60.00
12	TO LIFT UP CABIN	New	350.00	0.00
13	TO CHECK WIRING	New	50.00	20.00
14	TO REMOVE & FIX FRT WIRE HARNESS	New	180.00	0.00
Gross Labour Cost (S\$)			7,710.00	4,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >