



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Our Ref:

Type of Claim : TP
 Vehicle No. : SLQ3978C
 Make & Model : HONDA GRACE HYB 1.5DX
 Year of Manufacture : 2016
 Chassis No. : GM41105537
 Ins Company : AIG / CHINA TAIPING
 Engine No. : _____
 Excess : _____
 Policy No. : _____
 Date of Accident : 14/02/2019
 Time of Accident : _____
 Suggested Days of Repair : _____
 In-house Vehicle Assessor : _____

Repair Estimate

Parts	(a) Cost / List Price Items	\$	10,727.40
	Plus/Less 20%	\$	2,145.48
	Total of Cost / List	\$	8,581.92
	(b) Nett Price Items	\$	-
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	350.00
Total Parts Cost (Appendix A)		\$	8,931.92
Labour (Appendix B)		\$	7,410.00
Total Repair Cost		\$	16,341.92

Case Owner : Andrew
 Signature : _____

Contact No
Frt Counter Operation
 6383 7466 – Patrick Tia
 6383 7730 – Brenda Ng
 6383 7890 – Rohani
braddell_cr@sparkcarcare.com

Workshop Operation
 63837656 - Ngo Toh Wee
 63837362 - Andrew Goh
 63838115 - William Wang
braddell_operation@sparkcarcare.com

The above total will be subjected to 7% G.S.T.

Name of Surveyor : _____
 Company : _____
 Survey conducted on : _____ at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

Spare Parts

Vehicle No : SLQ3978C Case Owner : Andrew

Make & Model : HONDA GRACE HYB 1.5D Year Manufacture : 2016

Chassis No : GM41105537 Engine No : 0

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear number plate with casing	1				\$ 40.00	
2	Rear bumper	1		\$ 937.60			
3	Rear bumper reflector LH	1		\$ 30.80			
4	Rear bumper reflector RH	1		\$ 30.80			
5	Rear bumper side retainer LH	1		\$ 14.00			
6	Rear bumper side retainer RH	1		\$ 14.00			
7	Rear bumper clips	10		\$ 39.00			
8	Bootlid	1		\$ 675.20			
9	Bootlid hinge LH	1		\$ 68.40			
10	Bootlid hinge RH	1		\$ 68.40			
11	Bootlid inner trim	1		\$ 99.70			
12	Bootlid inner trim clips	10		\$ 42.00			
13	Bootlid lock	1		\$ 90.30			
14	Bootlid weatherstrip	1		\$ 91.50			
15	Bootlid lamp LH	1		\$ 306.70			
16	Bootlid lamp RH	1		\$ 306.70			
17	Bootlid emblem logo H	1		\$ 27.40			
18	Bootlid emblem GRACE	1		\$ 45.00			
19	Bootlid emblem HYBRID	1		\$ 58.00			
20	Bootlid chrome moulding	1		\$ 165.00			
21	Bootlid chrome moulding clips	4		\$ 16.80			
22	Taillamp LH	1		\$ 381.70			
23	Taillamp RH	1		\$ 381.70			
24	Taillamp panel LH	1		\$ 98.00			
25	Taillamp panel RH	1		\$ 98.00			
26	Taillamp clips	2		\$ 8.60			
27	Rear end panel	1		\$ 395.30			
28	Rear end panel top garnish	1		\$ 86.40			
29	LH rear fender	1		\$ 1,129.40			
30	RH rear fender	1		\$ 1,129.40			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

Spare Parts

Vehicle No : SLQ3978C Case Owner : Andrew

Make & Model : HONDA GRACE HYB 1.5D Year Manufacture : 2016

Chassis No : GM41105537 Engine No : 0

Sales Order : 0 Supplier : 0

Order By : 0 Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
31	LH rear fender inner trim	1		\$ 265.00			
32	RH rear fender inner trim	1		\$ 265.00			
33	LH rear fender air vent	1		\$ 28.80			
34	RH rear fender air vent	1		\$ 28.80			
35	Rear floor panel	1		\$ 855.00			
36	Rear floor undercover	1		\$ 135.00			
37	Rear cargo tools tray	1		\$ 168.50			
38	Rear cargo top cover	1		\$ 254.30			
39	Rear windscreen glass	1		\$ 1,650.30			
40	Rear windscreen glass moulding upper	1		\$ 38.10			
41	Rear windscreen glass moulding lower	1		\$ 48.80			
42	Rear windscreen glass moulding LH	1		\$ 30.10			
43	Rear windscreen glass moulding RH	1		\$ 38.10			
44	Sealant	1				\$ 40.00	
45	Inner seal	1				\$ 30.00	
46	Rear end panel buzzer	1		\$ 85.80			
47	Reverse sensor	1				\$ 240.00	
48	0	0					
49	0	0					
50	0	0					
51	0	0					
52	0	0					
53	0	0					
54	0	0					
55	0	0					
56	0	0					
57	0	0					
58	0	0					
59	0	0					
60	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Vehicle No.	: <u>SLQ3978C</u>	Case Owner	: <u>Andrew</u>
Make & Model	: <u>ONDA GRACE HYB 1.5DX</u>	Year of Manufacture	: <u>2016</u>

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.