

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE Our Ref: Vehicle No. SLQ3978C Type of Claim : Make & Model HONDA GRACE HYB 1.5DX Year of Manufacture Chassis No. GM41105537 : AIG / CHINA TAIPING Engine No. Excess Policy No. Date of Accident : 14/02/2019 Time of Accident Suggested Days of Repair In-house Vehicle Assessor Case Owner Repair Estimate Andrew Signature Parts (a) Cost / List Price Items Contact No 20%Plus/Less **Frt Counter Operation** 6383 7466 - Patrick Tia Total of Cost / List 6383 7730 - Brenda Ng 6383 7890 - Rohani (b) Nett Price Items braddell er it sparkeareare.com Less Workshop Operation 63837656 - Ngo Toh Wee Total of Nett Item 63837362 - Andrew Goh 63838115 - William Wang (c) Special Nett Items 350.00 braddell operation/a/sparkearcare.com Not Notherral Menny Blepain Total Parts Cost (Appendix A) 350.00 Labour (Appendix B) 7,410.00 **Total Repair Cost** 7,760.00 The above total will be subjected to 7% G.S.T. Name of Surveyor Company Survey conducted on

Survey conducted on : 20/2/19 at

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 2/ day(s)

(c) Resurvey : Required / Not Required

(d) Excess :\$

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62844284,62815767

Spare Parts

Vehicle No	: SLQ3978C	Case Owner	: Andrew
Make & Model	: HONDA GRACE HYB 1.5D	Year Manufacture	: <u>2016</u>
Chassis No	: <u>GM41105537</u>	Engine No	: <u>0</u>
Sales Order	:	Supplier	:
Order By	:	Type of Claim	: TP

		I	Cost	List	Nett		Disposition By
S/No		QTY	Price	Price	Price	S/N	Surveyor
ı	Rear number plate with casing B7 —	1				\$ 40.00	
2	Rear bumper B-1 —	1					
3	Rear bumper reflector LH 7	1					
4	Rear bumper reflector RH CM -	1					
5	Rear bumper side retainer LH CM	1					
6	Rear bumper side retainer RH CM-	1					
7	Rear bumper clips Na —	10					
8	Bootlid Br —	1					
9	Bootlid hinge LH	1					
10	Bootlid hinge RH 31	l					
11	Bootlid inner trim Rofun,	1					
12	Bootlid inner trim clips Na —	10					
13	Bootlid lock By —	1					
14	Bootlid weatherstrip & ~ ~	1					
15	Bootlid lamp LH (PA -	l					
16	Bootlid lamp RH CM —	1					
17	Bootlid emblem logo H na —	ı					
18	Bootlid emblem GRACE	1	7 17 17 17 17 17 17 17 17 17 17 17 17 17				
19	Bootlid emblem HYBRID New —	1					
20	Bootlid chrome moulding CM-]					
21	Bootlid chrome moulding clips 16.	4					
22	Taillamp LH Br —	1	, , , , , , , , , , , , , , , , , , , ,				
23	Taillamp RH Bn	1					
24	Taillamp panel LH 84 —	1					
25	Taillamp panel RH B1	1					
26	Taillamp clips New /	2					
27	Rear end panel By	1					
28	Rear end panel top garnish Pu -	1					
29	LH rear fender Bre —	1					
30	RH rear fender Bur —	1					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62844284,62815767

Spare Parts

Vehicle No : SLQ3978C Case Owner : Andrew Year Manufacture : 2016 Make & Model : HONDA GRACE HYB 1.5D Chassis No : GM41105537 : 0 Engine No Sales Order : 0 Supplier Order By Type of Claim : <u>TP</u>

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
31	LH rear fender inner trim Pehons	1					
32	RH rear fender inner trim	1					
	LH rear fender air vent 7	1					
34	RH rear fender air vent	1					
35	Rear floor panel ?	1					
	Rear floor undercover Dir	1					
37	Rear cargo tools tray	1					
38	Rear cargo top cover	1					
39	Rear windscreen glass for X	1					
	Rear windscreen glass moulding upper Nec-	- 1					
	Rear windscreen glass moulding lower Ac -	_					
	Rear windscreen glass moulding LH 1/2 -						
	Rear windscreen glass moulding RH 16.						
	Sealant Ma	1				\$ 40.00	
45	Inner seal New	1	***************************************			\$ 30.00	
46	Rear end panel buzzer	1					7
	Reverse sensor No	1				\$ 240.00	2001a
	0	0					
49	0	0					
50	0	0					
51	0	0					
52	0	0					
53	0	0					
	0	0					
	0	0					
	0	0					
	0	0					
	0	0					
	0	0					
	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62844284,62815767

Labour

Vehicle No.	:	SLQ3978C	Case Owner	:	Andrew
Make & Model	:	ONDA GRACE HYB 1.5DX	Year of Manufacture	:	2016

S/No	Labour Description	Esimated Price	Adjusted Price
1	To remove and replace rear windscreen glass	\$120.00	~
2	To panel beat, repair, cut and weld to replace rear panels on LH rear fender, RH rear fender, Rear floor panel, Rear end panel	\$3,600.00	28fe1
	and affected areas		
3	To check wiring functions	\$80.00	301
4	To install reverse sensor	\$80.00	
5	To diagnose and reset on electronic systems	\$280.00	2001
6	To apply rust proofing on repair and replace panels	\$500.00	20cl
7	To putty and spray paint Rear floor panel, Rear end panel, Bootlid, LH rear fender, RH rear fender, Rear bumper, LH rear door, RH rear door and affected areas	\$2,500.00	2000h
8	To mount vehicle on black hawk floor bench in order to re-align (Photo) chassis members or body structure.	\$250.00	

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.