

SS. REC. BY:

REF:

es/CTI/9003286/Kvd3ⁿ²

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Chong Guan Sen

of

CTI

Date/Time:

21/2/19 @ 11-09am

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBJ 684A

Insured:

YN 7910H

at Workshop m/s

Cheng Hwe Motor

Tel:

6755 6142

of

Blk 1019 # 01-374 / 382 Yishun Ind. park

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/01/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:09am @ 21/2/19

Person Contacted:

Effreda

Vehicle:

☒ IN ☐ OUT

Date/Time

Action/Instruction

(✓)

Estimate

GBJ 684A - X

YN 7910H - NA / EQI / 7014240 / 4

D.O.A: 21/7/2017

ASS. REC. BY:

REF:

0721

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

1.B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBJ 684A

Yr Regn:

12, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy T-Hau

c.c

2982

Colour:

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

17223

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTFHT 02P 600 246388

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: M / S / Rim / STD A / Rim or

Tyre Size:

F:

195 R15 X8

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

20/1/19

Rear

R/Bal.

9

mm

L/Bal.

9

mm

D.O.I.

21/2/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to

13/5 02535.u Confirm & feed? (Red 200, 710)

RECEIVED 14 MAY 2019

13/5/2019

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2)

14/5- typst

Days Of Repair:

6

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S - RS. SI

Fixturs

Others

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format:

merimen

Lump Sum / I.B.I: (\$

2535/2

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Feb 2019 14:49 Sendback Est	21 Feb 2019 10:50 S\$2,735.00	21 Feb 2019 11:09 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	PIKASA BUILDERS, Co. Reg. No.: 201113963N		
Main Claimant:	MAROOFA TRADINGS PTE LTD		
Vehicle Reg. No.:	GBJ684A	Date of Loss:	20/01/2019 15:00 - :59 [1 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	YN7910H	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/03/2019]		
Driver/Custodian (Insured):	SAHATHEVAN SANKARAN (/ Male), NRIC: G2050278P		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									


> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7925W
Vehicle Details	
Vehicle No.:	GBJ684A
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE VAN TURBO 5DR MT
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	1KD2831996
Chassis No.:	JTFHT02P600246398
Maximum Power Output:	-
Open Market Value:	\$28,136.00
Original Registration Date:	17 Dec 2018
First Registration Date:	17 Dec 2018
Transfer Count:	0
Actual ARF Paid:	\$1,407.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	16 Dec 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$27,009.00
COE Rebate Amount:	\$26,742.00
Total Rebate Amount:	\$26,742.00

The information contained herein is correct as at 21 Jan 2019

OK

**CHENG HOE MOTOR PTE LTD**

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
PIKASA BUILDERS

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP/CHINA
Policy No:		Date of Loss:	20/01/2019
Vehicle Reg. No.:	GBJ684A	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	LIAQUAT ALI MARICAR MUJIPUR RAHMAN	Driver (Insured):	SAHATHEVAN SANKARAN
Make/Model:	TOYOTA HIACE, 3.0 D (M)	Vehicle Reg. Date:	17/12/2018
Vehicle Colour:	WHITE		
Engine No:	1KD2831996	Chassis No:	JTFHT02P600246398
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	REFER TO GIA REPORT ATTACHED		
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)		

Not Notarized
1-B-1
Missing B&P print
6 days

COST OF CLAIMS	Amount
Parts	1,185.00
Miscellaneous Items	0.00
Labour	1,550.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,735.00
+ GST 7.00% (S\$)	191.45
Nett Amount (S\$)	2,926.45

This claim is handled by: EFEEDA BINTE MOHAMED OTHMAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

68J684A

P/China

REPAIR DETAILS**Reference**

Part Source: (Last Synchronised: 21 Feb 2019)

Parts: N/A TOYOTA HIACE 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Hoe Motor Pte Ltd/GBJ684A/21/02/2019 10:50

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*RH TAILLAMP	0.00	0.00	Bn *120.00 F ✓
2	1		*RH TAILLAMP PANEL	0.00	0.00	Bn *190.00 F ✓
3	1		*RH TAILLAMP LOWER PANEL	0.00	0.00	CM *35.00 F ✓
4	1		*REAR RH SIDE PANEL	0.00	0.00	Bn *670.00 F ✓
5	1		*REAR BUMPER	0.00	0.00	*155.00 F ✓
6	1		*REAR BUMPER RH SIDE RETAINER	0.00	0.00	D/H *15.00 F ✓
Total Parts (S\$)						1,185.00

F=Franchise part.

Cheng Hoe Motor Pte Ltd/GBJ684A/21/02/2019 10:50. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	REMOVE AND REFIT REAR BUMPER ASSY, TAILLAMPS. TO CUT, WELD AND RENEW REAR RH SIDE PANEL, RH TAILLAMP PANEL. TO KNOCK AND REPAIR REAR INNER RH SIDE PANEL AND REALIGN THE SAME.	New	900.00
2	PUTTY AND RESPRAY ON REAR BUMPER, REAR RH SIDE PANEL, TAILLAMP PANEL, TOP ROOF PANEL.	New	650.00
Gross Labour Cost (S\$)			1,550.00

Cheng Hoe Motor Pte Ltd/GBJ684A/21/02/2019 10:50. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119003286/KVD3N2

Date: 14/05/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	
Claimant Vehicle No :	GBJ684A	Insured Vehicle No :	YN7910H
Date of Loss:	20/01/2019	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ684A	Engine No:	1KD2831996
Make & Model:	TOYOTA HIACE, 3.0 D (M)	Chassis No:	JTFHT02P600246398
Reg. Date:	17/12/2018 (Man. Year: 2018)	Odometer:	17223 km
Colour:	Metallic Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15X8	Rear Tyre Size:	195R15X8
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,185.00	1,185.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,550.00	1,350.00	200.00	12.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,735.00	2,535.00	200.00	7.31
+ GST 7.00/7.00% (\$\$)	191.45	177.45	14.00	7.31
Nett Amount (\$\$)	2,926.45	2,712.45	214.00	7.31

INSPECTION

Date of Assignment:	21/02/2019	Present Location:	Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected:	21/02/2019	Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 May 2019)	
Parts:	N/A	TOYOTA HIACE 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ684A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH TAILLAMP	Broken	120.00 F	*120.00 FS
2	1		*RH TAILLAMP PANEL	Bent	190.00 F	*190.00 FS
3	1		*RH TAILLAMP LOWER PANEL	Cracked	35.00 F	*35.00 FS
4	1		*REAR RH SIDE PANEL	Bent	670.00 F	*670.00 FS
5	1		*REAR BUMPER	Mtg Cracked	155.00 F	*155.00 FS
6	1		*REAR BUMPER RH SIDE RETAINER	Distorted	15.00 F	*15.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	1,185.00	1,185.00
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND REFIT REAR BUMPER ASSY, TAILLAMPS. TO CUT,WELD AND RENEW REAR RH SIDE PANEL, RH TAILLAMP PANEL. TO KNOCK AND REPAIR REAR INNER RH SIDE PANEL AND REALIGN THE SAME.	New	900.00	800.00
2	PUTTY AND RESPRAY ON REAR BUMPER, REAR RH SIDE PANEL, TAILLAMP PANEL, TOP ROOF PANEL.	New	650.00	550.00
Gross Labour Cost (\$\$)			1,550.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >