

ASS. REC. BY:

REF:

CS/FCI/9003300/Ktd3

Special Instruction:

Surveyor:

CWS

Kenneth

ASSIGNMENT (Office)

From (Person):

Henry Kao

of

FCI

Date/Time: 5.55pm @ 20/2/19

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHF641Z

Insured:

SHC7180G

at Workshop m/s:

Transcub

Tel:

62876666

of

No. 2 AMICST - 63

Policy No:

Claim No:

D19001184MF84

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15/02/2019

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time:

9:17am @ 21/02/19

Person Contacted:

Amender

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SHF641Z-CC4/AXA/6023551/UwgBs2

DOA: 5/12/16

SHC7180G-CC3/FGT/7011489/Mtwa3y2

DOA: 9/6/17

2/2

Revised preli advice via email

L/Ly & 23501 mmms (Red: 24759.90, 91%)

FCI

INSURANCE

Date: 21/2/19

Insured's Name:

OD / PD / WS / TP / RES / OD / RES / EVA / INV / MV

Insured's Vehicle No:

SHF 641Z

at Workshop on:

Trans-cab

of:

NO-2 AMK sf-63

Insured:

Policy No:

Claim No:

Sum Insured:


Excess:

(Client's Record)

Make of Vehicle:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

20

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

(PS)

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Vehicle:

SHF 641Z 06 14

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Lotus

CC

1995

Colour:

Wh. White / Red

AC

Insured / Std / NI / NA

Sp. Reading:

505211

IRadio: Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABC15AUC 278299

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: M / S/Rim / STD A/Rim or

Tyre Size:

Prime Well 215/60R16

R: Falken

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

4

mm

R/Bal:

7

mm

L/Bal:

4

mm

L/Bal:

7

mm

D.O.A.

15/2/19

D.O.A.

21/2/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S / R

The U/C / Chassis frame / Body Structure affected due to collision

RECEIVED 30 MAY 2019

Date/Time: File Pass by:

☐

Pref. Report

30/5 Typist

☒

Final Report

Date/Time: File Return by:

Days Of Repair:

2

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

1. S + PS: \$

1. Hike:

1. Other:

1. Total:

350

Add Fee:

☐

Site Insp: \$

☐

Interview: \$

☐

Tech. Insp: \$

☐

Work-out: \$

Report Format:

Lump Sum / L.B. / L.S.

TP

2350/-



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001137MFSH

Date: 25/2/2019

Our Ref: CS/FCI19003206/Gtd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLB 8881T

Please be informed that we had conducted the inspection of the abovementioned vehicle 21/2/2019 at the premises of M/s MBM Wheelpower have the following to report: -

Workshop Estimate Amount	: S\$ <u>10,802.00</u>
Revised Estimate Amount	: S\$ <u>3,454.00</u>
"Check" Items Amount	: S\$ <u>1,966.00</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:
The vehicle sustained damages at the rear portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully
Guo Qiang
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	18-02-2019	Our Ref No. D19001184MFSH
Accident Date	15-02-2019	Claim Type. Third Party
Insured Vehicle	SHC7180G	Third Party Vehicle. SHF641Z
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	AMANDA TAY	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 25 February 2019 2:43 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'May Chua Hui Chin'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001137MFSH/1
Attachments: PRELI ADVISED SLB 8881T.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLB 8881T**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 20 February 2019 11:08 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001137MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer arrange on 21/02/2019.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 19 February 2019 5:47 PM

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHF641Z
Vehicle to be Exported:	Yes
Intended Deregistration Date:	18 Feb 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001625
Chassis No.:	VF1ABL15AUC278299
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	27 Jun 2014
First Registration Date:	27 Jun 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jun 2022
PARF Rebate Amount:	\$9,373.00

Intended COE Rebate Details

COE Expiry Date:	26 Jun 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$57,338.00
COE Rebate Amount:	\$24,050.00
Total Rebate Amount:	\$33,423.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 18 Feb 2019

OK

Trans-cab Auto Services Pte Ltd

AAD1902-144

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 641Z

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHF 641Z

VF1ABL15AUC278299

RENAULT

LATITUDE

15.2.2019

FCIL

27/6/2014

PART**LIST**

1	BUMPER COVER FRT	\$
1	BUMPER SPOILER FRT	\$
1	BUMPER ABSORBER FRT	\$
1	BUMPER RETAINER FRT LH	\$
1	BUMPER SUPPORT FRT	\$
1	BUMPER RETAINER FRT RH	\$
1	BUMPER SUPPORT FRT	\$
1	BUMPER UNDERTRAY FRT	\$
1	BUMPER GRILLE LOWER FRT	\$
1	BUMPER FOG LAMP GRILLE LH	\$
1	BUMPER BEAM FRT	\$
1	HEADLAMP LH	\$
1	HEADLAMP PANEL FRT LH	\$
1	FENDER PANEL FRT LH	\$
1	WHEELARCH FRT LH	\$
1	FENDER BRACKET LOWER LH	\$
1	FENDER INSULATOR LH	\$
1	DOOR PANEL FRT LH	\$
1	RADIATOR GRILLE	\$
1	RADIATOR GRILLE BADGE 'RENAULT'	\$
1	RADIATOR GRILLE FRAME	\$
1	RADIATOR FAN COWLING	\$
1	RADIATOR FAN MOTOR LH	\$
1	RADIATOR FAN MOTOR RH	\$
1	RADIATOR GRILLE FRAME	\$
1	FRAME FULL SUPPORT PANEL	\$
1	FRAME FULL SUPPORT BRACKET	\$
1	AIR CLEANER BOX	\$
1	AIR CLEANER HOSE	\$

<i>Ben</i>	1,259.42	✓
<i>Sn</i>	181.75	X
<i>Sn</i>	394.68	X
<i>Dis</i>	151.41	✓
<i>Sn</i>	123.88	X
<i>Sn</i>	150.77	X
<i>Sn</i>	123.88	X
<i>Sn</i>	472.83	X
<i>Sn</i>	266.80	X
<i>Sn</i>	207.21	X
<i>R</i>	914.08	X
<i>Sn</i>	184.43	X
<i>R</i>	152.15	X
<i>B</i>	783.83	✓
<i>Sn</i>	278.84	} X
<i>Sn</i>	15.79	
<i>Sn</i>	130.84	
<i>R</i>	2,844.66	
<i>Sn</i>	1,707.78	
<i>Sn</i>	225.36	
<i>Sn</i>	1,353.75	
<i>Sn</i>	820.54	
<i>Sn</i>	967.36	
<i>Sn</i>	1,479.46	
<i>Sn</i>	1,353.75	
<i>Sn</i>	615.90	
<i>R</i>	89.79	
<i>Sn</i>	464.20	
<i>Sn</i>	175.85	

Not Authored
L/Ly @ 2350
Direct Settlement

Trans-cab Auto Services Pte Ltd

AAD1902-144

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 641Z

TOTAL	\$	18,891.00
10%	\$	1,889.10
	\$	17,001.90

Special Nett

1SET	BUMPER CLIP FRT	\$	na	66.00	✓
1	BUMPER BRACKET CLIP FRT LH	\$	na	12.00	}
1	BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	
1SET	BUMPER GRILLE LOWER CLIP	\$	na	69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	}
1SET	WHEELARCH CLIP FRT RH	\$	na	30.50	
1	FRONT LEFT TYRE RIM	\$	sn	380.00	
1	FRONT LEFT TYRE	\$	sn	330.00	
		\$		1,018.00	

TOTAL PARTS	\$	18,019.90
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	3,500.00	400
----	----------	-----

Putty and spray painting of the affected portion.

\$	3,000.00	440
----	----------	-----

To rust-proofing of the affected areas.

\$	170.00	30
----	--------	----

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	na	380.00	X
----	----	--------	---

To check steering geometry and computer wheel alignment

\$	~	220.00	X
----	---	--------	---

To transfer of tire, rim and on wheel balancing.

\$	~	170.00	X
----	---	--------	---

To Check Electrical Lighting Concerned.

\$		170.00	20
----	--	--------	----

Trans-cab Auto Services Pte Ltd**AAD1902-144**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 641Z

To transfer of front fender fittings, attachment and perform water seepage test.	\$	na	380.00	X
To vacuum, replace, refix and recharge air condenser	\$	na	380.00	X
To replace, refix and top up coolant for radiator	\$	na	170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	na	170.00	X
To transfer of front door fittings, attachment and perform water seepage test.	\$	na	380.00	X

TOTAL \$ 9,090.00**Over All Total \$ 27,109.90****LUMP SUM (REPAIR DAY)****10 DAYS****2 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19003300/Ktd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 31-05-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7180G	Veh. Inspected	SHF 641Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	D190011184MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	20/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF1ABL15AUC278299	Colour	METALLIC WHITE / RED	
Odometer	505211	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	PRIMEWELL	4 mm	
L/H Front Tyre	215/60 R16	PRIMEWELL	4 mm	
R/H Rear Tyre	215/60 R16	FALKEN	7 mm	
L/H Rear Tyre	215/60 R16	FALKEN	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/02/2019	Inspection Date	21/02/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 641Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER FRT	BUCKLED	1,259.42	1,259.42
1	BUMPER SPOILER FRT	SERVICEABLE	181.75	-
1	BUMPER ABSORBER FRT	SERVICEABLE	394.68	-
1	BUMPER RETAINER FRT LH	DISTORTED	151.41	151.41
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER RETAINER FRT RH	SERVICEABLE	150.77	-
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER UNDERTRAY FRT	SERVICEABLE	472.83	-
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	266.80	-
1	BUMPER FOG LAMP GRILLE LH	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	914.08	-
1	HEADLAMP LH	SERVICEABLE	1,184.43	-
1	HEADLAMP PANEL FRT LH	TO REPAIR SEE LABOUR	152.15	-
1	FENDER PANEL FRT LH	BENT	783.83	783.83
1	WHEELARCH FRT LH	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER LH	SERVICEABLE	15.79	-
1	FENDER INSULATOR LH	SERVICEABLE	130.84	-
1	DOOR PANEL FRT LH	TO REPAIR SEE LABOUR	2,844.66	-
1	RADIATOR GRILLE	SERVICEABLE	1,707.78	-
1	RADIATOR GRILLE BADGE "RENAULT"	SERVICEABLE	225.36	-
1	RADIATOR GRILLE FRAME	SERVICEABLE	1,353.75	-
1	RADIATOR FAN COWLING	SERVICEABLE	820.54	-
1	RADIATOR FAN MOTOR LH	SERVICEABLE	967.36	-
1	RADIATOR FAN MOTOR RH	SERVICEABLE	1,479.46	-
1	RADIATOR GRILLE FRAME	SERVICEABLE	1,353.75	-
1	FRAME FULL SUPPORT PANEL	SERVICEABLE	615.90	-
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR	89.79	-
1	AIR CLEANER BOX	SERVICEABLE	464.20	-

Report Ref No. CS/FCI19003300/Ktd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIR CLEANER HOSE	SERVICEABLE	175.85	-
	LESS 10% DISCOUNT		-1,889.10	-219.47
			17,001.89	1,975.19
	SPECIAL NETT ITEMS			
1	SET BUMPER CLIP FRT (SN)	NECESSARY	66.00	66.00
1	BUMPER BRACKET CLIP FRT LH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (SN)	NOT NECESSARY	10.50	-
1	SET BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	SET WHEELARCH CLIP FRT RH (SN)	NOT NECESSARY	30.50	-
1	FRONT LEFT TYRE RIM (SN)	SERVICEABLE	380.00	-
1	FRONT LEFT TYRE (SN)	SERVICEABLE	330.00	-
			1,018.00	66.00
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM FRT,HEADLAMP PANEL FRT LH,DOOR PANEL FRT LH AND FRAME FULL SUPPORT BRACKET.		3,500.00	400.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	440.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-

Report Ref No. CS/FCI19003300/Ktd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR CONDENSER.	NOT NECESSARY	380.00	-
	TO REPLACE,REFIX AND TOP UP COOLANT FOR RADIATOR.	NOT NECESSARY	170.00	-
	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR INTERCOOLER.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FRONT DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
			9,090.00	890.00
GRAND TOTAL			27,109.89	2,931.19
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,350.00

Report Ref No. CS/FCI19003300/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.