

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 19.02.2019

Third Party Insurer: AIG

Vehicle No: SLU1473J

Third Party Veh No: SLE5601P

Model: BMW 520 SE AUTO

Date of Accident: 18.02.2019

Chassis: WBAJC32030G867973 - 2017

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER <i>B1</i>	1		✓
2	REAR BUMPER REVERSE SENSOR LH <i>Shan</i>	1		✓
3	REAR BUMPER REVERSE SENSOR RING LH (RUBBER SEAL) <i>na</i>	1		✓
4	REAR BUMPER LOWER GARNISH <i>CTH</i>	1		✓
5	REAR BUMPER LOWER DIFFUSER	1		?
6	REAR BUMPER REINFORCEMENT <i>B1</i>	1		✓
7	REAR BUMPER INNER UPPER RETAINER GUIDE	1		?
8	REAR BUMPER INNER RETAINER GUIDE	1		?
9	REAR BUMPER INNER SIDE RETAINER GUIDE LH <i>D.1</i>	1		✓
10	REAR BUMPER UPPER SIDE FOIL LH	1		?
11	REAR BUMPER CLIPS <i>na</i>	12		✓
12	REAR KICK SENSOR UPPER	1		?
13	REAR KICK SENSOR LOWER	1		?
14	REAR END PANEL	1		?
15	REAR EXHAUST PIPE ASSY	1		?
16	REAR EXHAUST PIPE TAIL LH (CHROME) <i>Rd</i>	1		✓
17	REAR EXHAUST PIPE HEAT SHIELD UPPER	1		?
18	REAR EXHAUST PIPE HEAT SHIELD LOWER <i>B1</i>	1		✓
19	REAR EXHAUST PIPE HEAT SHIELD LH <i>B1</i>	1		✓
20	REAR EXHAUST PIPE HEAT SHIELD RH	1		?
21	REAR EXHAUST PIPE HANGER RUBBER (MOUNTING)	3		?
22	REAR EXHAUST PIPE TAIL RH (CHROME) <i>SL</i>	1		X
23	REAR EXHAUST PIPE HEAT SHIELD NUT (PLASTIC)	8		?
24	REAR BOOT LID	1		REPAIR
25	REAR QUATER PANEL LH	1		REPAIR
SUB TOTAL				
LESS 5%				
PARTS TOTAL				

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR END PANEL JOINT SEALANT	1		\$80.00
S/N TOTAL				\$80.00

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 19.02.2019

Third Party Insurer: AIG

Vehicle No: SLU1473J

Third Party Veh No: SLE5601P

Model: BMW 520 SE AUTO

Date of Accident: 18.02.2019

Chassis: WBAJC32030G867973 – 2017

ESTIMATE

LABOUR CHARGES:

TO REMOVE & REFIX/REPLACE REAR ACCIDENT AREAS & ETC. BACK TO ORIGINAL CONDITION	\$1,000.00	7
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS	6601 \$900.00	
TO TUFF KOTE / ANTI-RUST	\$80.00	7
TO REMOVE & REFIX/REPLACE REAR BUMPER REVERSE SENSOR, REAR KICK SENSOR & ETC	\$150.00	801
TO DISMANTLE & REPLACE REAR EXHAUST PIPE ASSY & ETC	\$220.00	} 7
TO REMOVE & REPLACE REAR EXHAUST PIPE HEAT SHIELD ASSY & ETC	\$120.00	
TO CHECK WIRING & ELETRICAL DIAGNOSTICS	\$150.00	1201
LABOUR TOTAL		\$2,620.00
ONG	TOTAL	\$2,700.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: