

7/20/2007

ASS. REC. BY:

REF:

28/FCI 19603312/K1xd3

Special Instruction:

Surveyor:

Kalm

ASSIGNMENT (Office)

From (Person):

Menina Chia

of

FCI

Date/Time:

12.51pm @ 21/2/19

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 6279 M

Insured:

SHC 7083 D

at Workshop m/s:

Premier Automotive

Tel:

85446689

of

23 Cheryi south Ave 2 #01-02

Policy No:

Claim No:

D19001260MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/2/2019

CA / REV / REP. / REV 24 HRS

DS

H.O.D. Endorsement:

Date/Time:

1.49pm @ 21/2/19

Person Contacted:

Vincent

Vehicle:

☒ IN / ☐ OUT

Date/Time

Action/Instruction ☒ Estimate

SHC 6279 M - (C31A) A 12020485 / H/v/dy

JdtA: 18/10/12

SHC 7083 D - CS3 / FCI 14001373 / Evbdi

JdtA: 20/1/19

22/2/19

Email preli revised to FCI

Surney: Kelvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Insp'd Vehicle No: _____

at Workshop m/s _____

at _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vch: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / .REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No:

SHC 6279M

Yr Regn:

1 Nov, 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KIA optima

c.c.

1600

Colour:

Silver

AJC:

Insured / Std / NI / NA

Sp. Reading

412887

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KNA6M414MF5554568

Gen. Cond: Good / F6 / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

205/65R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hawke

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

20/2/19

D.O.I.

21/2/19

Survey held at

Premier

Des. of Damages: Frl / Rear / O/S / N/S / U/C / Rooftop or

Front / Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2/3/19

Lund 45 \$9950/ 8 Rp. (Red 6668-30, 40M)

FCI

RECEIVED 25 MAR 2019

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 25/3 - typist

Report Format:

CWS

Lump Sum / I.B.I. (\$)

99500

Days Of Repair:

8

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

170+90

Transportation:

50

S + RS \$

50

Photos

74

Others

53/11

TOTAL

434

6x15=90



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19001260MFSH

Our ref: CS/FCI19003312/K1vd3

DATE: 22/2/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 6279M


We thank you for your instruction on 21/2/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 21/2/2019 at the premises of M/s PREMIER AUTOMOTIVE SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$15,318.90
Revised Estimate Amount	: S\$8,795.80
"Check" Items Amount	: S\$1,244.70
Book Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front and rear n/s portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kalvin Ang
Technical Investigator
Technical Investigation & Reconstructionist (SAE-A)

MOTOR SURVEY ASSIGNMENT

Date	20-02-2019	Our Ref No. D19001260MFSH
Accident Date	20-02-2019	Claim Type. Third Party
Insured Vehicle	SHC7083D	Third Party Vehicle. SHC6279M
Survey Location	23 CHANGI SOUTH AVENUE 2 #01-02	
Contact Person.	VINCENT CHUA	
Contact No.	62148880/ 65446689	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MERINA CHIA SAN SAN	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 22 February 2019 5:37 PM
To: 'CWS Motor Claims'
Cc: 'Merina Chia San San'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001260MFSH/1, SHC 6279M
Attachments: SHC 6279M PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHC 6279M
Date of survey: 21/2/2019
Number of days : 8 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 21 February 2019 2:16 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Merina Chia San San' <MerinaChia@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001260MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 21 February 2019 12:51 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Merina Chia San San

<MerinaChia@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19001260MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	11 Nov 2014 / 09:40:10	Receipt No.:	AACCK001-AX239-141111-000007
Asset Type:	Vehicle	Transaction Amount:	\$63,968.00
Asset ID:	SHC6279M	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20141111094010681261		
Vehicle No.:	SHC6279M		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	11 Nov 2014		
Original Registration Date:	11 Nov 2014		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414MF5554568		
Engine No.:	D4FDEH311786		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2014		
Open Market Value:	\$19,991.00		
Minimum PARF Benefit:	\$7,494.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	11 Nov 2014 09:40:10		
COE No.:	2014111101001254N		
COE Expiry Date:	10 Nov 2022		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$51,337.00		
Lifespan Expiry Date:	10 Nov 2022		
Owner ID Type:	Company		

CASH SALE/WORK ORDER

No:AD 4970



PEOPLE'S VEHICLE SERVICE PTE LTD

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717

TEL : 6743 1987 (3 LINES) FAX : 6743 0013

Reg No: 200415052W

Date, 20.2.19

寶號 Premier
Messrs:

車號 S/H C6279M 車型 0 Pto 1 mff
Vehicle No: Model No:

由 Griffith Road Rd
From:

到 Omega
To:

其他 (Kp) (1 len) Left-back tyre punctured,
Remark:

時間 06:09:06:49:07:29 AMOUNT: \$
Time: AMOUNT: \$

注意：本公司對所拖之車輛，在運行中如有任何損失或破壞，一概由車主自行負責。
NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

經手人 [Signature] 收貨人 [Signature]
Authorised by: Received by:

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

21-Feb-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6279 M

1 pc	Bonnet <i>X repair</i>	\$	979.00
1 pc	Bonnet grille <i>✓ con</i>	\$	385.00
1 pc	Support panel <i>X repair</i>	\$	645.00
1 pc	Front bumper <i>✓ con</i>	\$	531.00
1 pc	Front bumper emblem <i>✓ con</i>	\$	44.00
1 pc	Front bumper centre grille <i>✓ con</i>	\$	174.00
1 pc	Front bumper lower stiffer <i>X repair</i>	\$	134.00
1 pc	Front bumper tow hook cover <i>X repair</i>	\$	14.00
1 pc	Front bumper lip <i>X repair</i>	\$	52.00
1 pc	Front bumper inner sponge <i>✓ con</i>	\$	110.00
1 pc	Front bumper reinforcement <i>✓ con</i>	\$	328.00
2 pcs	Front bumper n/s & o/s protector @ \$51.00 <i>X sm</i>	\$	102.00
2 pcs	Front bumper n/s & o/s fog lamp cover @ \$66.00 <i>X sm</i>	\$	132.00
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00 <i>✓ con</i>	\$	32.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00 <i>X sm</i>	\$	32.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00 <i>✓ con</i>	\$	32.00
2 pcs	n/s & o/s headlamp @ \$1028.00 <i>✓ con</i>	\$	2,056.00
1 pc	Rear n/s fender <i>✓ con</i>	\$	1,205.00
1 pc	Rear n/s fender inner shield <i>✓ con</i>	\$	120.00
1 pc	Rear n/s fender inner trim <i>✓ con</i>	\$	179.00
1 pc	Rear n/s tail lamp @ \$421.00 <i>✓ con</i>	\$	421.00
1 pc	Bootlid weatherstrip @ \$96.00 <i>X sm</i>	\$	96.00
1 pc	Bootlid n/s reflector @ \$350.00 <i>X sm</i>	\$	350.00
1 pc	Rear n/s air vent <i>✓ con</i>	\$	30.00
1 pc	Rear bumper <i>✓ con</i>	\$	696.00
1 pc	Rear bumper lower cover <i>✓ con</i>	\$	206.00
2 pcs	Rear bumper n/s & o/s side bracket @ \$29.00 <i>1/s ✓ con o/s X sm</i>	\$	29.00 58
1 pc	Rear bumper n/s reflector @ \$46.00 <i>✓ con</i>	\$	46.00
1 pc	Rear n/s lower arm <i>✓ con</i>	\$	351.00
1 pc	Rear n/s assist arm <i>✓ con</i>	\$	163.00
1 pc	Rear n/s trailing arm <i>✓ con</i>	\$	159.00
1 pc	Rear n/s shock absorber <i>✓ con</i>	\$	313.00
1 pc	Rear n/s knuckle bearing <i>X sm</i>	\$	349.00
1 pc	Rear n/s knuckle arm <i>✓ con</i>	\$	525.00
1 pc	Rear n/s stabilizer link <i>X sm</i>	\$	192.00

1 pc	Rear n/s rim @ \$246.00	Ref	\$ 246.00
1 pc	Rear n/s wheel cover @ \$116.00	crs	\$ 116.00
1 pc	Rear windscreen moulding	nc	\$ 87.00
			\$ 11,661.00
	Less 10%		\$ 1,166.10
			\$ 10,494.90

21-Feb-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6279 M

S/NETT

1 set	Front bumper clips	nc	\$ 48.00
1 pc	Front no. plate with casing	2nd	\$ 50.00 35
1 set	Rear bumper clips	nc	\$ 48.00
1 set	Reverse sensor	shld	\$ 280.00 200
1 pc	Rear bumper top protector	nc	\$ 80.00 50
1 set	Bootlid stickers	X	\$ 100.00
1 pc	Rear n/s fender sticker	nc	\$ 60.00
1 set	Rear n/s fender inner shield clips	nc	\$ 28.00
1 set	Sealant	nc	\$ 50.00
1 pc	Tyre (Hankook) @ \$200.00	patch 100	\$ 200.00 100
	Sundry		\$ 50.00 20 nc
	Towing Fee		\$ 50.00
	To dismantle and refit old windscreen glass onto new moulding		\$ 120.00 100
	To dismantle / refit rear n/s wheel undercarriage		\$ 250.00 100
	To check rear n/s wheel alignment		\$ 80.00 60
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$ 180.00 50
	To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the end panel, rear n/s fender. Including knock-out, straighten, repair, reshape and adjust of the rear n/s tail lamp panel, etc		\$ 1,800.00 1400
	To putty and spray painting on front bumper, rear bumper, end panel, bootlid, n/s tail lamp panel, rear n/s fender, front bumper		\$ 1,200.00 1680
	To apply rustproofing on the repaired and replaced panels.		\$ 150.00 50
			\$ 15,318.90

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
**THE ABOVE ESTIMATED COST OF REPAIR DO NOT
INCLUDE ANY UNFORESEEN DAMAGES.**

Kahin 16,618.30
2/2/19 1700hr
8 Rgs.
45
After Repair ph

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

20-Mar-19

SUPPLEMENTARY ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC6279M

1 pc	Rear upper arm with bush	— <i>Ref</i>	\$	84.00
1 pc	Rear ABS sensor LH	— <i>544</i>	\$	232.00
1 pc	Rear Bumper Inner Sponge	— <i>kn</i>	\$	114.00
1 pc	Rear LH floor side panel	— <i>Ref</i>	\$	65.00
1 pc	Rear Bumper Stay LH	— <i>Ref</i>	\$	54.00
1 pc	Spare Wheel Clamp	— <i>Ref</i>	\$	10.00
1 pc	Rear bumper reinforcement	— <i>Ref</i>	\$	607.00
			\$	1,166.00
			Less 10%	\$ 116.60
			\$	1,049.40

To dismantle / replace rear n/s wheel undercarriage

150
\$ ~~250.00~~

Total \$ 1,299.40

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT
INCLUDE ANY UNFORESEEN DAMAGES.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19003312/K1vd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 02-04-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7083D	Veh. Inspected	SHC 6279M	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19001260MFSH	Excess (\$)	0.00	
Assign From	MERINA CHIA	Assign Date	21/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KNAGM414MF5554568	Colour	SILVER	
Odometer	412887	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	HANKOOK	7 mm	
L/H Front Tyre	205/65 R16	HANKOOK	7 mm	
R/H Rear Tyre	205/65 R16	HANKOOK	7 mm	
L/H Rear Tyre	205/65 R16	HANKOOK	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/02/2019	Inspection Date	21/02/2019	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6279M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET	TO REPAIR SEE LABOUR	979.00	-
1	BONNET GRILLE	CRACKED	385.00	385.00
1	SUPPORT PANEL	TO REPAIR SEE LABOUR	645.00	-
1	FRONT BUMPER	CRACKED	531.00	531.00
1	FRONT BUMPER EMBLEM	NECESSARY	44.00	44.00
1	FRONT BUMPER CENTRE GRILLE	CRACKED	174.00	174.00
1	FRONT BUMPER LOWER STIFFER	TO REPAIR SEE LABOUR	134.00	-
1	FRONT BUMPER TOW HOOK COVER	TO REPAIR SEE LABOUR	14.00	-
1	FRONT BUMPER LIP	TO REPAIR SEE LABOUR	52.00	-
1	FRONT BUMPER INNER SPONGE	TORN	110.00	110.00
1	FRONT BUMPER REINFORCEMENT	BENT	328.00	328.00
2	FRONT BUMPER N/S & O/S PROTECTOR @\$51.00	SERVICEABLE	102.00	-
2	FRONT BUMPER N/S & O/S FOG LAMP COVER @\$66.00	SERVICEABLE	132.00	-
2	FRONT BUMPER O/S & N/S SIDE RETAINER @\$16.00	CRACKED	32.00	32.00
2	FRONT BUMPER O/S & N/S UPPER BRACKET @\$16.00	SERVICEABLE	32.00	-
2	FRONT BUMPER O/S & N/S SUPPORT BRACKET @\$16.00	CRACKED	32.00	32.00
2	N/S & O/S HEADLAMP @\$1028.00	CRACKED	2,056.00	2,056.00
1	REAR N/S FENDER	BUCKLED	1,205.00	1,205.00
1	REAR N/S FENDER INNER SHIELD	TORN	120.00	120.00
1	REAR N/S FENDER INNER TRIM	TORN	179.00	179.00
1	REAR N/S TAIL LAMP	CRACKED	421.00	421.00
1	BOOTLID WEATHERSTRIP	SERVICEABLE	96.00	-
1	BOOTLID N/S REFLECTOR	SERVICEABLE	350.00	-
1	REAR N/S AIR VENT	CRACKED	30.00	30.00
1	REAR BUMPER	DEFORMED	696.00	696.00
1	REAR BUMPER LOWER COVER	CRACKED	206.00	206.00
2	REAR BUMPER N/S & O/S SIDE BRACKET @\$29.00	N/S CRACKED / O/S SERVICEABLE	58.00	29.00

Report Ref No. CS/FCI19003312/K1vd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER N/S REFLECTOR	CRACKED	46.00	46.00
1	REAR N/S LOWER ARM	BENT	351.00	351.00
1	REAR N/S ASSIST ARM	BENT	163.00	163.00
1	REAR N/S TRAILING ARM	BENT	159.00	159.00
1	REAR N/S SHOCK ABSORBER	BENT	313.00	313.00
1	REAR N/S KNUCKLE BEARING	SERVICEABLE	349.00	-
1	REAR N/S KNUCKLE ARM	BENT	525.00	525.00
1	REAR N/S STABILIZER LINK	SERVICEABLE	192.00	-
1	REAR N/S RIM	BENT	246.00	246.00
1	REAR N/S WHEEL COVER	CRACKED	116.00	116.00
1	REAR WINDSCREEN MOULDING	NECESSARY	87.00	87.00
1	REAR UPPER ARM WITH BUSH (ADDITIONAL)	BENT	84.00	84.00
1	REAR ABS SENSOR LH (ADDITIONAL)	SHORTED	232.00	232.00
1	REAR BUMPER INNER SPONGE (ADDITIONAL)	TORN	114.00	114.00
1	REAR LH FLOOR SIDE PANEL (ADDITIONAL)	DENTED	65.00	65.00
1	REAR BUMPER STAY LH (ADDITIONAL)	BENT	54.00	54.00
1	SPARE WHEEL CLAMP (ADDITIONAL)	BROKEN	10.00	10.00
1	REAR BUMPER REINFORCEMENT (ADDITIONAL)	BENT	607.00	607.00
	LESS 10% DISCOUNT		-1,285.60	-975.00
			11,570.40	8,775.00
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	FRONT NO PLATE WITH CASING (SN)	BENT	50.00	35.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR BUMPER TOP PROTECTOR (SN)	NECESSARY	80.00	50.00
1	SET BOOTLID STICKERS (SN)	NOT NECESSARY	100.00	-
1	REAR N/S FENDER STICKER (SN)	NECESSARY	60.00	60.00
1	SET REAR N/S FENDER INNER SHIELD CLIPS (SN)	NECESSARY	28.00	28.00
1	SET SEALANT (SN)	NECESSARY	50.00	50.00
1	TYRE (HANKOOK)(SN)	PUNCTURE	200.00	100.00

Report Ref No. CS/FCI19003312/K1vd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			994.00	639.00
	LABOUR			
	TOWING FEE.		50.00	50.00
	TO DISMANTLE AND REFIT OLD WINDSCREEN GLASS ONTO NEW MOULDING.		120.00	100.00
	TO DISMANTLE/REFIT REAR N/S WHEEL UNDERCARRIAGE.		250.00	100.00
	TO CHECK REAR N/S WHEEL ALIGNMENT.		80.00	60.00
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.		180.00	50.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS TO HEAT/WELD, CUT-OFF THE END PANEL, REAR N/S FENDER, INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE REAR N/S TAIL LAMP PANEL, ETC. INCLUSIVE OF THE REPAIR OF BONNET, SUPPORT PANEL, FRONT BUMPER LOWER STIFFER, FRONT BUMPER TOW HOOK COVER AND FRONT BUMPER LIP.		1,800.00	1,400.00
	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER, REAR BUMPER, END PANEL, BOOTLID, N/S TAIL LAMP PANEL, REAR N/S FENDER, FRONT BONNET.		1,200.00	1,080.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		150.00	50.00
	TO DISMANTLE/REPLACE REAR N/S WHEEL UNDERCARRIAGE (ADDITIONAL).		250.00	150.00
			4,080.00	3,040.00
	GRAND TOTAL		16,644.40	12,454.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			9,950.00

Report Ref No. CS/FCI19003312/K1vd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.