

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG19003315/T1TD3S2**Date:** 08/04/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100396106
Claimant Vehicle No :	GBG530B	Insured Vehicle No :	SKQ6461T
Date of Loss:	16/02/2019	Nature of Claim:	TP
		Claim No:	1923503838SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG530B		
Make & Model:	TOYOTA REGIUS ACE, 3.0 SUPER GL DARK PRIME (A)	Engine No:	1KD2578966
Reg. Date:	22/12/2016 (Man. Year: 2015)	Chassis No:	KDH2010186499
Colour:	Black	Odometer:	58471 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/35ZR20	Rear Tyre Size:	245/35ZR20
Front Left Side:	Falken 7 mm	Rear Left Side:	Falken 7 mm
Front Right Side:	Falken 7 mm	Rear Right Side:	Falken 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,874.10	2,062.25	11,811.85	85.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	1,340.00	960.00	41.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,174.10	3,402.25	12,771.85	78.96
Approved Total (Overridden) (S\$)		2,700.00		
Nett Amount (S\$)	16,174.10	2,700.00	13,474.10	83.31
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	20/02/2019	
Date Inspected:	21/02/2019 Inspected At:	Car Pro Auto (HQ) Blk 6 Yew Tee Industrial Estate 399-J, Woodlands Road Singapore 678008
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

THE REPAIRER IS INFORMED ON THE REVISED AMOUNT BUT NOT AGREED WITH OUR RECOMMENDATION.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER BRACKET LH	Not Necessary	38.00 FL	*- FL
2	1		*REAR FENDER LH	Repair	1,382.00 FL	*- FL
3	1		*REAR BUMPER	Deformed	557.50 FL	*557.50 FL
4	1		*AXLE	Not Necessary	4,355.80 FL	*- FL
5	1		*DRIVESHAFT	Bent	485.50 FL	*485.50 FL
6	1		*LH RIM (JAPAN)	Cut	7,800.00 FS	*1,000.00 FS
7	1		*LH TYRE	Not Necessary	350.00 FS	*- FS
8	1		*SEALANT FOR WHEEL ARCH	Necessary	60.00 FS	*30.00 FS
9	1		*WHEEL ARCH (LH)	Cut	550.00 FS	*250.00 FS
					Sub Total (\$)	15,578.80
					- List Item Discount on L Items 25.00/25.00% (\$)	2,323.00
						1,704.70
					Total Parts (\$)	2,062.25

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS.	New	700.00	500.00
2	TO ANTI-RUST.	New	100.00	30.00
3	TO CHECK WIRING & LIGHTINGS.	New	60.00	30.00
4	TO REMOVE DOOR COMPONENTS.	New	120.00	0.00
5	TO REMOVE & REFIX ROCKER PANEL.	New	120.00	0.00
6	TO REMOVE & REFIX UNDERACRRIAGE.	New	300.00	100.00
7	TO PERFORM 4 WHEEL ALIGNMENT (BEFORE AND AFTER).	New	100.00	80.00
8	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS.	New	800.00	600.00
Gross Labour Cost (\$\$)			2,300.00	1,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >