



Case Details

Case Reference Number : TAX/02/19/2101
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHC4877A

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-5799-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 20/02/2019 06:00 AM
 Vehicle Age(In Months) : 15

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	0	Repair ▾	
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	0.00 120	Replace ▾	NEG
One Time Key In	Main			FILLER, RR BUMPER, LH	1	119.90	119.90	25.00	89.93	Replace	1	0	Repair ▾	
One Time Key In	Main			FENDER RR/LH	1	766.80	766.80	25.00	575.10	Replace	1	0	Repair ▾	
One Time Key In	Main			WHEEL, DISC	1	1,490.20	1,490.20	25.00	1,117.65	Replace	1	0	Repair ▾	
Total Spare Part Cost									2,220.60		Surveyor Total		0.00	
Lump Sum Discount (%)									0		Lump Sum Dis (%)		0	
Final Spare Part Cost									2,220.60		Final Sur Total		0.00	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR LEFT REAR PORTION	507.00	400	
Total:			507.00	400.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
Total:			1,116.00	500.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
2	Main	TO RESPRAY FILLER RR BUMPER LH	180.00	50	
3	Main	TO RESPRAY REAR FENDER LH	378.00	200	
4	Main	TO RESPRAY RIM	180.00	50	
Total:			1,116.00	500.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	
3	Main	TO WASH AND VACUUM	60.00	0	
4	Main	TO REPLACE SUNDRY PARTS	100.00	0	
Total:			360.00	0.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	2,220.60	0.00
Total Labour Cost	507.00	400.00
Total Spray Painting	1,116.00	500.00
Other	360.00	0.00
Overall Total	4,203.60	900.00
Lump Sum Repair Option	☐	☐
Lump Sum Total	0.00	900.00
Surveyor Approved Amount		900.00
No of Repair Days*	4	3
Remarks	-	P/P REPAIR, PHOTO AFTER REPAIR.
Surveyor Name		Hwee jie

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Signature		
Survey Date	21/02/2019	Save Clear

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: