



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 296H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BUMPER FRT (DISC 25%) (CONSISTENT)	BUCKLED	482.00	361.50
10	BUMPER CLIPS @\$1.61 (DISC 25%) (CONSISTENT)	NECESSARY	16.10	12.08
1	HOOD PANEL (DISC 25%) (CONSISTENT)	BUCKLED	748.10	561.08
1	FENDER FRT/LH (DISC 25%) (CONSISTENT)	BUCKLED	723.40	542.55
1	NAME PLATE (HYBRID) (DISC 25%) (CONSISTENT)	NECESSARY	51.90	38.93
1	LENS & BODY ,FR TURN LH (DISC 10%) (CONSISTENT)	SCRATCHED	511.80	460.62
1	HEAD LAMP LH (DISC 10%) (CONSISTENT)	CRACKED	945.20	850.68
1	SOLAR FILM (CONSISTENT)	NOT NECESSARY	125.00	-
1	BUMPER ENERGY ABSORBER FRT (CONSISTENT)	SERVICEABLE	78.80	-
1	BUMPER REINFORCEMENT FRT (CONSISTENT)	SERVICEABLE	498.40	-
1	ARM SUB-ASSY ,FR BUMPER LH (CONSISTENT)	SERVICEABLE	250.40	-
1	BUMPER SUPPORT F/LH (CONSISTENT)	SERVICEABLE	76.40	-
1	BRACKET ,FR TURN CENTER LH (CONSISTENT)	SERVICEABLE	58.20	-
1	BRACKET ,FR TURN LOWER LH (CONSISTENT)	SERVICEABLE	26.00	-
1	BUMPER ,FR TURN UPPER LH (CONSISTENT)	SERVICEABLE	24.40	-
1	BUMPER FRT ABSORBER LOWER (CONSISTENT)	SERVICEABLE	127.70	-
1	WIRE ,ENGINE ROOM,NO.3 (CONSISTENT)	SERVICEABLE	242.00	-
1	HOOD HINGE LH (CONSISTENT)	SERVICEABLE	55.90	-
1	HOOD HINGE RH (CONSISTENT)	SERVICEABLE	55.90	-
1	HOOD LOCK (CONSISTENT)	SERVICEABLE	128.90	-
1	SUPPORT SUB-ASSY (CONSISTENT)	SERVICEABLE	1,460.40	-
1	FENDER LINER FRT/LH (CONSISTENT)	SERVICEABLE	171.70	-
1	FENDER PROTECTOR FRT/LH UPPER (CONSISTENT)	SERVICEABLE	46.10	-
1	FENDER APRON SUB FRT/LH (CONSISTENT)	SERVICEABLE	637.80	-
1	TYRE (CONSISTENT)	SERVICEABLE	126.74	-
1	QUARTER GLASS FRT/LH (CONSISTENT)	SERVICEABLE	234.90	-
1	SEALANT W/SCREEN (CONSISTENT)	SERVICEABLE	37.00	-
1	WHEEL DISC FRONT (CONSISTENT)	TO REPAIR SEE LABOUR	1,484.20	-
			9,425.34	2,827.44

Report Ref No. CC4/ASM19003368/Jpa3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	PANEL BEATING & BODY WORK.INCLUSIVE OF THE REPAIR OF WHEEL DISC FRONT .		1,014.00	600.00
	SPRAY PAINT.		1,674.00	650.00
	TO CHECK WIRING AND SYSTEM FUNCTION .		80.00	20.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	30.00
	TO DO WHEEL ALIGNMENT /TYRE BALANCING .	NOT NECESSARY	120.00	-
	TO TOP UP A/C GAS.	NOT NECESSARY	120.00	-
	TO REMOVE & REFIX FRONT LHS/RHS QUARTER GLASS .	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE).		120.00	30.00
	TO REMOVE AND REFIT WIRE HARDESS.	NOT NECESSARY	200.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM .	NOT NECESSARY	60.00	-
			3,708.00	1,330.00
	<b>GRAND TOTAL</b>		<b>13,133.34</b>	<b>4,157.44</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,600.00</b>

Report Ref No. CC4/ASM19003368/Jpa3q2

ONG HWEE JIE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.