

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 7954J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT WHEEL (CONSISTENT)	NOT NECESSARY	485.00	-
1	HANDLE BAR (CONSISTENT)	BENT	175.00	175.00
1	LEVER (CONSISTENT)	CUT	38.00	38.00
1	LEVER HOLDER (CONSISTENT)	CUT	68.00	68.00
1	SIGNAL LAMP (CONSISTENT)	DISTORTED	110.00	110.00
1	MIRROR (CONSISTENT)	SCRATCHED	98.00	98.00
1	NUMBER PLATE (CONSISTENT)	CUT	12.00	12.00
1	HANDLE END (CONSISTENT)	CUT	30.00	30.00
1	GEAR LEVER (CONSISTENT)	BENT	90.00	90.00
1	FRONT FOOTREST (CONSISTENT)	BROKEN	75.00	75.00
1	REAR FOOTREST (CONSISTENT)	CUT	65.00	65.00
1	TANK COVER (CONSISTENT)	CUT	220.00	220.00
1	LEFT COVER (CONSISTENT)	CUT	150.00	150.00
	LESS 10% DISCOUNT		-161.60	-113.10
			1,454.40	1,017.90
2	FRONT FORK (SN) (CONSISTENT) (LOCAL REPAIR)	BENT	750.00	100.00
	LESS 10% DISCOUNT		-75.00	-
			675.00	100.00
	SPECIAL NETT ITEMS			
1	IU (SN) (CONSISTENT)	сит	155.80	155.80
			155.80	155.80
	<u>LABOUR</u>			
	TOWING FEES.		50.00	50.00
	LABOUR CHARGES.		380.00	150.00
	BODY REPAIR .	NOT NECESSARY	350.00	-
			780.00	200.00
	GRAND TOTAL		3,065.20	1,473.70

Report Ref No. CC4/ASM19003371/Gga3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,150.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM19003371/Gga3q2

XING GUO QIANG

M.MATAI, AMSAE-A

monto

HO LEONG CHUAN

Automotive Assessor

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.