



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:TEE LEE GREEN			Ref: CC4/ASM19003371/Gga3q2 Date: 18/05/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 5851S	Veh. Inspected	FBM 7954J	
Policy No.	P1680520	Coverage (\$)	0.00	
Claim No.	S9M01BGH	Excess (\$)	0.00	
Assign From		Assign Date	22/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CB150R	c.c	149	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	MLHKC2886J5003153	Colour	BLUE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	110/70 R17	DUNLOP	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	160/60 R17	DUNLOP	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/01/2019	Inspection Date	22/02/2019	
Survey held at	BAN HONG GEOK KEE CO BLK 5038 ANG MO KIO IND PK 2 #01-419 SINGAPORE 569541			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	