

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG19003376/JQD3E2

Date: 08/05/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29069766MKF

Claimant Vehicle No : SHB1724H

Insured Vehicle No : SLK1383M

Date of Loss: 15/02/2019

Nature of Claim: TP

Claim No: 585251

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHB1724H**

Make & Model: TOYOTA PRIUS TAXI, 1.8 (A)

Engine No: 2ZR1394000

Reg. Date: 06/08/2014 (Man. Year: 2014)

Chassis No: JTDKN36UX05747419

Colour: Maroon

Odometer: 480243 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Chilles 6 mm

Rear Left Side:

Chilles 6 mm

Front Right Side: Chilles 6 mm

Rear Right Side:

Chilles 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,388.94	120.00	3,268.94	96.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,261.00	480.00	1,781.00	78.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	5,649.94	600.00	5,049.94	89.38

INSPECTION

Date of Assignment: 25/02/2019

Date Inspected: 19/02/2019 Inspected At:

SMRT AUTOMOTIVE SERVICES PTE LTD

60 WOODLANDS INDUSTRIAL PARK E4

SINGAPORE 757705

Estimated Period of Repair: 2.0 days

Adjuster: ONG HWEE JIE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 May 2019)

Parts: 144 TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHB1724H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*PIXEL STICKER	Necessary	120.00 F	*120.00 F
2	1		*BUMPER SIDE RETAINER RR/LH	Not Necessary	94.80 F	*- F
3	1		*TYRE	Not Necessary	126.74 F	*- F
4	1		*BUMPER LIP COVER RR/LH	Not Necessary	72.20 F	*- F
5	1		*FENDER RR/LH	Not Necessary	766.80 F	*- F
6	1		*FENDER LINER RR/LH	Not Necessary	141.30 F	*- F
7	1		*STICKER DECAL 6555 8888	Not Necessary	21.60 F	*- F
8	1		*SMRT LOGO	Not Necessary	7.80 F	*- F
9	1		*BUMPER SEAL, RR LH	Not Necessary	88.90 F	*- F
10	1		*WHEEL, DISC	Repair	1,490.20 F	*- F
11	1		*BUMPER REAR	Repair	458.60 F	*- F
					Total Parts (S\$)	3,388.94 120.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODY WORK	New	845.00	200.00
2	SPRAY PAINT	New	936.00	250.00
3	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	0.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	0.00
5	TO DO WHEEL ALIGNMENT / TYRE BALANCING	New	120.00	0.00
6	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	30.00
7	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (\$\$)			2,261.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >