## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Nor Azian Binte Noordin Date: 11 Apr 2019

# **Preliminary Advice**

Vehicle No : SME9645A **Accident Date** : 16/02/2019 Make : BLUECAR BLUECAR Policy No. : 29112616MCY **Assignment Date** : 20/03/2019 **Excess** : S\$2,000.00 Date of Inspection : 22/02/2019 Est. Duration of Repair : 5 days

Inspection At : Indeco Engineers Pte Ltd (Defu)

No. 39 Defu Lane 12

Singapore 539315

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,858.80 (INCLUSIVE SUPPLEMENTARY)
Revised Amount	:S\$	2,931.20 (INCLUSIVE SUPPLEMENTARY)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,931.20

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :S\$

Pre-Accident Value :S\$ 66,000.00 COE / PARF Rebate :S\$ 38,501.00

Salvage Value :S\$

Margin for Repair :S\$ 27,499.00

### Remarks

( X )	The vehicle is economical for repair. We have received supplementary from repairer. Our surveyor had
	since checked and verified the supplementary parts and is of the view that the supplementary parts are
	consistent to the nature of the accident and is economical to repair. Supplementary amount is \$ 123.20.

The above survey was conducted on a 'without prejudice' basis.