

WGS REC'D BY

REF

es/MSG/19003385/Dsd30

Instruction

Surveyor

Bryen

## ASSIGNMENT (Office)

From (Person)

Eng Huey Ni

of

MSG

Date/Time:

21/2/19 @ 1:33pm

Estimated Cost:

Bill to:

☒ OD / TP / AWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SME 9645A

Insured:

at Workshop m/s

Indeco

Tel:

of

37 Deth June 12

Policy No:

Claim No:

M585367

Sum Insured:

Excess:

\$2000.00

Make of Veh:

(Client's Record)

D.O.A.

16/02/2019

CA / ☒ REV /

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:20am 22/2/19

Person Contacted:

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SME 9645A - X
27/03/19	@ 11:48 a.m. revised IA to Nor Azian Binte Nordin via memo.
27/03/19	@ 11:50 mandate requested authority to Nor Azian Binte Nordin via memo.
28/03/19	@ 15:58 mandate approved by Eng Huey Ni.

Location Date  
Insured/  
OD / TP / WS / TP RES / OD RLS / EVA / INV / MV  
Estimated Vehicle No  
at Workshop No  
of  
Insured  
Policy No  
Claim No  
Sum Insured, Excess  
(Client's Record)  
Make of Veh

(Policy Condition)  
Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value  
IDAC: Accident Report Consistent? : Yes or No  
GIA / PR Seen Consistent? : Yes or No  
Est. Repairs: 5 days Res: Yes or No  
Lump Sum 7/P % 3-Val: Yes or No  
CA / REV / REP: / 24 HRS

Date Person Contacted Vehicle: IN / OUT

Vehicle No **SME 9645A** at Regn **2018 Oct**  
Type: ☒ M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make **Blue Car** Insured / Std / NI / NA  
Colour **White** A/R Insured / Std / NI / NA  
Sp Reading **N.A.** T/Radio Insured / Std / NI / NA  
Eng/No  
ChNo **VL4BCB4RJ5T003362**  
Gen Cond: ☒ Good / Fair / Poor / Burnt  
Steering: Inorder / Jammed / Leaked / Burnt or  
Brake: Inorder / Jammed / Leaked / Burnt or  
Mod: Nil / ☒ R/Rim / STD A/Rim or  
Tyre Size: F: **175/65 R15**  
R: **— 11 —**  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or **Michelin**  
Front Rear  
R/Bal: 7 mm R/Bal: 7 mm  
L/Bal: 7 mm L/Bal: 7 mm  
D.O.A: 16/02/2019 D.O.I: 22/02/2019  
Survey held at **Indero. Raju Lane**  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
**4/3 Front**  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

**MSIG OD**

**MV 66K  
L/A 38.5K  
W/L 27.5K**

28/05/19 @ 16:53 pm. revert authorize repair to Choe Cygnus? via email.  
(P 1,929.60 Red - 40%)

17/07/19 **Final 7/P 2931.20 with 5 days grace**

Date/Time: File Pass to: ☐ Prel. Report

18/07/19 **Ty44** ☒ Final Report

Days Of Repair: **5**

Resurvey No. of Trip: **1**

Survey Fee:

Transportation

Photo

Other

Total

Report Format

Lump Sum / L/S: **2,931.20 P/P**

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech Invz (\$)

☐ Weekend (\$)

**190**

**11**

**161**

RECEIVED 10 JUL 2019

## Nivitha (LKK Auto)

---

**From:** Shiau Chan (LKKAuto) <siewsc@lkkauto.com>  
**Sent:** Thursday, 21 February 2019 4:33 PM  
**To:** assignments  
**Subject:** FW: Yref: New case - Inspection on insured vehicle SME9645A; DOA: 16.2.2019; Our Ref: M585367; To survey on 22.02.2019  
**Attachments:** GIA - SME9645A.pdf

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Eng Huey Ni <HueyNi\_Eng@sg.msig-asia.com>

**Sent:** Thursday, 21 February 2019 4:14 PM

**To:** SUR <sur@lkkauto.com>

**Cc:** Nor Azian Binte Noordin <NorAzian\_Noordin@sg.msig-asia.com>; Chhia Nyuk Pui <NyukPui\_Chhia@sg.msig-asia.com>

**Subject:** Yref: New case - Inspection on insured vehicle SME9645A; DOA: 16.2.2019; Our Ref: M585367; To survey on 22.02.2019

Hi Shiau Chan,

As spoken, please arrange to survey the above insured vehicle at Indeco Engineers located at 37 Defu lane 12.

The insured reported the left tyre was flat and dropped out after the accident.

Please check if the tyre was in efficient conditions before the accident or the damages of the tyre was a result of the accident. Please also check for any other possible breach. (please do not alert the insured on the purpose of the inspection if possible)

If the insured pass you the OD estimate during the inspection, please conduct the OD survey as well.

Excess is \$2000.

Thanks

**Eng Huey Ni**

Senior Executive, Claims Services

D: +65 6643 1314 | F: +65 6225 7402 | [hueyni\\_eng@sg.msig-asia.com](mailto:hueyni_eng@sg.msig-asia.com)



**MSIG**

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	7259H
<b>Vehicle Details</b>	
Vehicle No.:	SME9645A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	27 Mar 2019
Vehicle Make:	BLUECAR
Vehicle Model:	BLUECAR
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	-
Chassis No.:	VL4BCEB4RJT003362
Maximum Power Output:	50.0 kW (67 bhp)
Open Market Value:	\$33,595.00
Original Registration Date:	24 Oct 2018
First Registration Date:	24 Oct 2018
Transfer Count:	0
Actual ARF Paid:	\$19,033.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Oct 2028
PARF Rebate Amount:	\$14,274.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	23 Oct 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
PQP Paid:	\$30,284.00
COE Rebate Amount:	\$24,227.00
<b>Total Rebate Amount:</b>	<b>\$38,501.00</b>

The information contained herein is correct as at 27 Mar 2019

OK

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Thursday, 28 March 2019 4:57 PM  
**To:** bylai@sg.indeco.cwtlimited.com  
**Cc:** SUR  
**Subject:** RE: SME 9645A OD (MSIG)  
**Attachments:** ESTIMATE.pdf

Dear Chloe,

Enclosed estimate marked.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]  
**Sent:** Thursday, 28 March 2019 4:53 PM  
**To:** bylai@sg.indeco.cwtlimited.com  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** SME 9645A OD (MSIG)

Dear Chloe,

As instructed by our client, please proceed to repair the insured vehicle **SME 9645A (Excess \$ 2,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## View Received Message

This mail is associated with :

**\*SME9645A (585367)**

OD

Feb 16 2019 1:00PM

[BLUECAR EAST ASIA PTE LTD]

Indeco Engineers Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** MSIG Insurance (Singapore) Pte. Ltd. (MSIG\_SG), sent on 16/04/2019 08:47 AM.

**To** LKK\_HQ

**Subject** Alert - Adj Mandate Approved (S\$2931.20) - SME9645A - Claim Handler: Nor Azian Binte Noordin

Approved:2931.20.

### DOCUMENTS SUMMARY

There are no documents.

## View Received Message

This mail is associated with :

**\*SME9645A (585367)**

OD

Feb 16 2019 1:00PM

[BLUECAR EAST ASIA PTE LTD]

Indeco Engineers Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** MSIG Insurance (Singapore) Pte. Ltd. (MSIG\_SG), sent on 28/03/2019 15:58 PM.

**To** LKK\_HQ

**Subject** Alert - Adj Mandate Approved (S\$2130.00) - SME9645A - Claim Handler: Nor Azian Binte Noordin

Approved:2130.00:Approved mandate \$2130.00 (subject to excess \$2000). Check items of \$243 to be verified and confirmed

### DOCUMENTS SUMMARY

There are no documents.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Nor Azian Binte Noordin

Date: 11 Apr 2019

**Preliminary Advice**

Vehicle No	: SME9645A	Accident Date	: 16/02/2019
Make	: BLUECAR BLUECAR	Policy No.	: 29112616MCY
Assignment Date	: 20/03/2019	Excess	: S\$2,000.00
Date of Inspection	: 22/02/2019	Est. Duration of Repair	: 5 days
Inspection At	: Indeco Engineers Pte Ltd (Defu) No. 39 Defu Lane 12 Singapore 539315		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,858.80 (INCLUSIVE SUPPLEMENTARY)
Revised Amount	:S\$	2,931.20 (INCLUSIVE SUPPLEMENTARY)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,931.20
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	66,000.00
COE / PARF Rebate	:S\$	38,501.00
Salvage Value	:S\$	
Margin for Repair	:S\$	27,499.00

**Remarks**

- ( X ) The vehicle is economical for repair. We have received supplementary from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair. Supplementary amount is \$ 123.20.
- ( ) The above survey was conducted on a 'without prejudice' basis.



# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Nor Azian Binte Noordin

Date: 27 Mar 2019

## Preliminary Advice

Vehicle No	: SME9645A	Accident Date	: 16/02/2019
Make	: BLUECAR BLUECAR	Policy No.	: 29112616MCY
Assignment Date	: 20/03/2019	Excess	: S\$2,000.00
Date of Inspection	: 22/02/2019	Est. Duration of Repair	: 5 days
Inspection At	: Indeco Engineers Pte Ltd (Defu) No. 39 Defu Lane 12 Singapore 539315		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,735.60
Revised Amount	:S\$	2,130.00
Check Items (Estimated)	:S\$	243.00
Total	:S\$	2,373.00

Lump Sum Repair	:S\$	
-----------------	------	--

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	66,000.00
COE / PARF Rebate	:S\$	38,501.00
Salvage Value	:S\$	
Margin for Repair	:S\$	27,499.00

### Remarks

( X ) The vehicle is economical for repair.

( ) The above survey was conducted on a 'without prejudice' basis.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	18/02/2019 14:41
Date Of Accident	16/02/2019 13:00
Exact Location Of Accident	72 JOO CHIAT PLACE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SME9645A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	BLUECAR EAST ASIA PTE LTD
Co Reg No	201617259H
Email Address	CLAIMS@BLUESG.COM.SG
Mobile Phone No	(LOCAL) +65-97365541
Alternative Phone No	OFFICE-31637900

### Vehicle Particulars

Manufacturer	BLUECAR
Model	BLUECAR-(A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	MSD/VPCP/18-000001
Cover Note Number	

### Driver

Name of Driver	KOH HWEE LIN
NRIC No	S7612300D
Date Of Birth	01/05/1976
Occupation	INDOOR
Date Of Driving Pass	31/03/1998
Driving Experience	20 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-90492477
Fax Number	
Contact Number	
EMail Address	HL_KOH@YAHOO.COM.SG

Address	BLK 166 HOUGANG AVE. 1 #13-1572
Postcode	530166
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	FIRE, EXPLOSION OR LIGHTNING
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

Refer circumstance to sketch plan.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SBA113D
Vehicle Make/Model/Colour	BMW
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

IMPORTANT NOTICE

- [illegible]

Author's address: *University of Cambridge, 477 Charles Street, Cambridge, MA 02139, USA*  
E-mail: *john@cs.cmu.edu*


Driver's Signature \_\_\_\_\_  
Date & Time \_\_\_\_\_ 16/02/19



Signature: \_\_\_\_\_  
Name: \_\_\_\_\_  
Address: \_\_\_\_\_

SKETCH PLAN

(72 Joo Chiat place) (Fei Fei coffee shop)



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along 72 Joo Chiat place at a very slow speed. I heard a loud sound the car swayed and hit a parked car. I got down the car and saw the whole tyre flat and car has come off. The stick which held the front left tyre has dropped out.

DECLARATION

I hereby declare the foregoing particulars are true to the best of my knowledge.

*Hwee Lin*  
Driver's Signature

Date & Time 16/02/19

3pm

Police Officer's Signature  
Sgt. A. Tan

Responsible Person's Signature  
Name  
Date/Time



**ACCIDENT REPAIR ESTIMATES**

Our Ref:

Type of Claim : ODVehicle No. : SME9645AMake & Model : BLUE CARYear of Manufacture : 2018Chassis No. : VL4BCEB4RJT003362Engine No. : 922403A18W122453489Policy No. : Time of Accident : 13:00Ins Company : MSIGExcess : \$2,000.00Date of Accident : 26/2/2019Suggested Days of Repair : **Repair Estimates**Parts (a) Cost / List Price Items \$ 1,696.00Plus/Less 10% \$ 169.60Total of Cost / List \$ 1,865.60(b) Nett Price Items \$ -Less Total of Nett Item (c) Special Nett Items \$ 70.00Total Parts Cost (Appendix A) \$ 1,935.60Labour (Appendix B) \$ 2,800.00Total Repair Cost \$ 4,735.60

The above total will be subjected to 7% G.S.T.

4858.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: Date: Name of Surveyor : P Ryan 9723 7799Company : LKK AutoSurvey conducted on : 22/02/2019 at 1200hrsRemarks By Surveyor(a) The repair of this vehicle is authorized / is not authorized until further notice.(b) Recommended Days of Repair : 5 day(s)(c) Resurvey : Required / Not Required(d) Excess : \$ (e) Signature of surveyor :  Date: 

Part / Part.  
Photo B4 spray  
with damaged  
Part.



VEHICLES &amp; EQUIPMENT DIVISION

No. 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

**ESTIMATED REPAIR COST DETAILS**

Vehicle No : SME9645A Case Owner : 0

Make & Model : BLUE CAR Year Manufacture : 2018

Chassis No : VL4BCEB4RJT003362 Engine No : 922403A18W122453489

Date & Time : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim : OD

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N
1	Front fender LH <i>Dented</i>	1	\$ 520.00	\$ 520.00	✓	
2	Front fender protector LH <i>1st</i>	1	\$ 70.00	\$ 70.00	✓	
3	Front fender inne shield set LH <i>deformed</i>	1	\$ 36.00	\$ 36.00	✓	
4	Front fender inne shield clip <i>new</i>	7	\$ 2.00	\$ 14.00	✓	
5	Tyre <i>Swat cut 70% depreciation</i>	1	\$ 130.00	\$ 130.00	✓	91.00 SH
6	Tyre pressure sensor <i>new</i>	1	\$ 56.00	\$ 56.00	X	
7	Steel rim <i>1st</i>	1	\$ 70.00	\$ 70.00	✓	
8	Rim cover set <i>cut 1st</i>	1	\$ 50.00	\$ 50.00	✓	
9	Front lower arm LH <i>broken</i>	1	\$ 160.00	\$ 160.00	✓	
10	Front shock absorber set LH <i>2 1st</i>	1	\$ 100.00	\$ 100.00	✓	
11	Drive shaft LH <i>Down</i>	1	\$ 180.00	\$ 180.00	✓	
12	Anti roll bar tie rod LH <i>new</i>	1	\$ 20.00	\$ 20.00	X	
13	Front knuckle arm LH <i>2 deformed</i>	1	\$ 170.00	\$ 170.00	✓	
14	Side skirt LH <i>new</i>	1	\$ 120.00	\$ 120.00	X	
15	Door stickers <i>new 1st</i>	1			X	\$ 70.00 ✓
16	0	0				
17	0	0				
18	0	0				
19	0	0				
20	0	0				
21	0	0				
22	0	0				
23	0	1				
24	0	0				
25	0	0		1370 cost.		61.00 SH
26	0	0				
27	0	0	107.	1507.00		161.00 SH
28	0	0				
29	0	0				
30	0	0				

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**TOTAL**

\$ 1,684.00 \$ 1,696.00 \$ - \$ 70.00



Tel: (65) 382 2736 FAX: (65) 6382 2817

Vehicle No. :	<u>SME9645A</u>	Case Owner :	<u>0</u>
Make & Model :	<u>BLUE CAR</u>	Year of Manufacture :	<u>2018</u>

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*



## Supplementary 1

Vehicle No : SME9645A Case Owner : 0

Make & Model : BLUE CAR Year Manufacture : 2018

Chassis No : VL4BCEB4RJT003362 Engine No : 922403A18W122453489

Sales Order : 0 Supplier : 0

Order By : \_\_\_\_\_ Type of Claim : OD

S/No	Part Description	QTY	Unit Price	Cost Price	Nett Item	S/N	Disposition By Surveyor
1	Steering rack end <i>45</i>	1	\$ 100.00	\$ 100.00	✓		
2	Tie rod end <i>151</i>	1	\$ 12.00	\$ 12.00	✓		
3							
4							
5							
6							
7							
8							
9	<i>3 Nya</i>						
10							
11							
12	<i>2 LK And</i>						
13							
14							
15							
16							
17							
18							
19							
20							
21	<i>Subject to approval</i>						
22							
23							
24	<i>Photo 38-43 in</i>						
25	<i>Mr. Liman.</i>						
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Feb 2019		20 Mar 2019 10:52 <a href="#">Edit Adj Rpt</a>	<b>S\$2,931.20</b> <a href="#">Edit Estimates</a>	<b>S\$2,931.20</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>



















































  







































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	BLUECAR EAST ASIA PTE LTD, Co. Reg. No.: 201617259H								
Vehicle Reg. No.:	SME9645A	Date of Loss:	16/02/2019 13:00 - :59 [3 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 585367	Policy/Cover Note No.:	29112616MCY (Comprehensive) Coverage: 01/01/2019 - 31/12/2019						
		Excess:	S\$2,000.00						
Repairer:	Indeco Engineers Pte Ltd (Defu) No. 39 Defu Lane 12, 539315 Defu Lane - Tel: 6382 2738								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pang Xiu Shi - 6594 2586]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 19/04/2019]								
Driver/Custodian:	KOH HWEE LIN (42 / Female) , NRIC: S7612300D, Tel: +6590492477 Email: hl_koh@yahoo.com.sg								
Adj Asg. Remarks:	Please revert and inform us if unable to attend. Car in. Tks.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>MSIG_SG (16/04/2019): Alert - Adj Mandate Approved (S\$2931.20) - SME9645A - Claim Handler: Nor Azian B...</li> <li>MSIG_SG (28/03/2019): Alert - Adj Mandate Approved (S\$2130.00) - SME9645A - Claim Handler: Nor Azian B...</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents


\*SME9645A (585367)  
OD  
Feb 16 2019 1:00PM  
[BLUECAR EAST ASIA PTE LTD]  
Indeco Engineers Pte Ltd

























Upload Documents			Upload Photos		Compose New Letter		View		View in Browser		▼		
Assessment Reports								1 per page		▼		☑	
No	Finalized On	BlueSG Pte Ltd (HQ)							Thumbnail	Print			
1	18/02/19 14:53	Accident Statement						1	Load HTM				
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print			
1	27/03/19 11:48	Adjuster Immediate Advice						1	Load HTM				
2	11/04/19 17:54	Adjuster Immediate Advice						1	Load HTM				
Photos/Images								3 per page		▼		☑	
No	Finalized On	BlueSG Pte Ltd (HQ)							Thumbnail	Print			
1	18/02/19 14:52	Accident Photo [Linked Accident Report Documents]						1	Load JPG	☑			
2	18/02/19 14:52	Accident Photo [Linked Accident Report Documents]						1	Load JPG	☑			
3	18/02/19 14:52	Accident Photo [Linked Accident Report Documents]						1	Load JPG	☑			
4	18/02/19 14:52	Accident Photo [Linked Accident Report Documents]						1	Load JPG	☑			
5	18/02/19 14:52	Accident Photo [Linked Accident Report Documents]						1	Load JPG	☑			
6	18/02/19 14:52	Accident Photo [Linked Accident Report Documents]						1	Load JPG	☑			
7	18/02/19 14:52	Accident Photo [Linked Accident Report Documents]						1	Load JPG	☑			
8	18/02/19 14:52	Accident Photo [Linked Accident Report Documents]						1	Load JPG	☑			
9	18/02/19 14:52	Accident Photo [Linked Accident Report Documents]						1	Load JPG	☑			
10	18/02/19 14:52	Accident Photo [Linked Accident Report Documents]						1	Load JPG	☑			
11	18/02/19 14:52	Accident Photo [Linked Accident Report Documents]						1	Load JPG	☑			
12	18/02/19 14:52	Accident Photo [Linked Accident Report Documents]						1	Load JPG	☑			
13	18/02/19 14:52	Accident Photo [Linked Accident Report Documents]						1	Load JPG	☑			
14	18/02/19 14:52	Accident Photo [Linked Accident Report Documents]						1	Load JPG	☑			
15	18/02/19 14:52	Accident Photo [Linked Accident Report Documents]						1	Load JPG	☑			
16	18/02/19 14:52	Accident Photo [Linked Accident Report Documents]						1	Load JPG	☑			
17	18/02/19 14:52	Driving License [Linked Accident Report Documents]						1	Load JPG	☑			
18	18/02/19 14:52	Driving License [Linked Accident Report Documents]						1	Load JPG	☑			
19	18/02/19 14:52	Identification Card [Linked Accident Report Documents]						1	Load JPG	☑			
20	18/02/19 14:52	Identification Card [Linked Accident Report Documents]						1	Load JPG	☑			
21	18/02/19 14:52	Accident Photo [Linked Accident Report Documents]						1	Load JPG	☑			
22	18/02/19 14:52	Accident Photo [Linked Accident Report Documents]						1	Load JPG	☑			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print			
1	28/03/19 12:55	Front View Right						1	Load JPG	☑			
2	28/03/19 12:55	Front View Left						1	Load JPG	☑			

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	BlueSG Pte Ltd (HQ)	Thumbnail	Print
3	28/03/19 12:58	General View	 Load JPG	<input checked="" type="checkbox"/>
4	28/03/19 12:58	General View	 Load JPG	<input checked="" type="checkbox"/>
5	28/03/19 12:58	General View	 Load JPG	<input checked="" type="checkbox"/>
6	28/03/19 12:58	General View	 Load JPG	<input checked="" type="checkbox"/>
7	28/03/19 12:58	General View	 Load JPG	<input checked="" type="checkbox"/>
8	28/03/19 12:58	General View	 Load JPG	<input checked="" type="checkbox"/>
9	28/03/19 12:58	General View	 Load JPG	<input checked="" type="checkbox"/>
10	28/03/19 12:58	General View	 Load JPG	<input checked="" type="checkbox"/>
11	28/03/19 12:58	General View	 Load JPG	<input checked="" type="checkbox"/>
12	28/03/19 12:58	General View	 Load JPG	<input checked="" type="checkbox"/>
13	28/03/19 12:58	General View	 Load JPG	<input checked="" type="checkbox"/>
14	28/03/19 12:58	General View	 Load JPG	<input checked="" type="checkbox"/>
15	28/03/19 12:58	General View	 Load JPG	<input checked="" type="checkbox"/>
16	28/03/19 12:58	General View	 Load JPG	<input checked="" type="checkbox"/>
17	28/03/19 12:58	General View	 Load JPG	<input checked="" type="checkbox"/>
18	28/03/19 12:58	General View	 Load JPG	<input checked="" type="checkbox"/>
19	28/03/19 12:58	General View	 Load JPG	<input checked="" type="checkbox"/>
20	28/03/19 12:58	General View	 Load JPG	<input checked="" type="checkbox"/>
21	28/03/19 12:58	General View	 Load JPG	<input checked="" type="checkbox"/>
22	28/03/19 12:58	General View	 Load JPG	<input checked="" type="checkbox"/>
23	28/03/19 12:58	General View	 Load JPG	<input checked="" type="checkbox"/>
24	28/03/19 12:58	General View	 Load JPG	<input checked="" type="checkbox"/>
25	28/03/19 12:58	General View	 Load JPG	<input checked="" type="checkbox"/>
26	28/03/19 12:58	General View	 Load JPG	<input checked="" type="checkbox"/>
27	28/03/19 12:58	General View	 Load JPG	<input checked="" type="checkbox"/>
28	28/03/19 12:58	General View	 Load JPG	<input checked="" type="checkbox"/>
29	28/03/19 12:58	General View	 Load JPG	<input checked="" type="checkbox"/>
30	28/03/19 12:58	General View	 Load JPG	<input checked="" type="checkbox"/>
31	28/03/19 12:58	General View	 Load JPG	<input checked="" type="checkbox"/>
32	28/03/19 12:58	General View	 Load JPG	<input checked="" type="checkbox"/>
33	28/03/19 12:58	General View	 Load JPG	<input checked="" type="checkbox"/>
34	28/03/19 12:58	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
35	11/04/19 15:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	11/04/19 15:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	11/04/19 15:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	11/04/19 15:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	11/04/19 15:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	11/04/19 15:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	11/04/19 15:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	11/04/19 15:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	11/04/19 15:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	11/04/19 15:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	11/04/19 15:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	11/04/19 15:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	11/04/19 15:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	11/04/19 15:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	11/04/19 15:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	11/04/19 15:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	11/04/19 15:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	11/04/19 15:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	BlueSG Pte Ltd (HQ)	Thumbnail	Print
53	11/04/19 15:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	11/04/19 15:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	11/04/19 15:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	11/04/19 15:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	11/04/19 15:07	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
58	11/04/19 15:07	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
59	11/04/19 15:07	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
60	11/04/19 15:07	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
61	11/04/19 15:07	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
62	11/04/19 15:07	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
63	11/04/19 15:07	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
64	11/04/19 15:07	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
65	11/04/19 15:07	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
66	11/04/19 15:07	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
67	11/04/19 15:07	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
68	11/04/19 15:07	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
69	11/04/19 15:07	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
70	11/04/19 15:07	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
71	11/04/19 15:07	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
72	11/04/19 15:07	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
73	11/04/19 15:07	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
74	11/04/19 15:07	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
75	11/04/19 15:07	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
76	11/04/19 15:07	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
77	16/07/19 18:25	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
78	16/07/19 18:25	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
79	16/07/19 18:25	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
80	16/07/19 18:25	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
81	16/07/19 18:25	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
82	16/07/19 18:25	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/02/19 19:24	Email to & from LKK	 Load PDF	
2	19/03/19 13:31	Email frm Indeco (to arrange for survey)	 Load PDF	
3	19/03/19 13:31	ESTIMATE	 Load PDF	
4	19/03/19 13:36	COE / PARF Value (details of OIV)	 Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	19/03/19 20:04	email to assign to lkk	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/03/19 11:54	ESTIMATE.pdf	 Load PDF	
2	27/03/19 11:54	SME 9645A GIA.pdf	 Load PDF	
3	11/04/19 17:55	ESTIMATE & SUPPLEMENTARY MARKED.pdf	 Load PDF	

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	BlueSG Pte Ltd (HQ)	Thumbnail	Print
1	18/02/19 14:53	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	BlueSG Pte Ltd (HQ)	Thumbnail	Print

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	BlueSG Pte Ltd (HQ)	Thumbnail	Print
1	18/02/19 14:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	18/02/19 14:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	18/02/19 14:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	18/02/19 14:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	18/02/19 14:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	18/02/19 14:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	18/02/19 14:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	18/02/19 14:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	18/02/19 14:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	18/02/19 14:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	18/02/19 14:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	18/02/19 14:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	18/02/19 14:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	18/02/19 14:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
15	18/02/19 14:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
16	18/02/19 14:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
17	18/02/19 14:52	Driving License	 Load JPG	<input checked="" type="checkbox"/>
18	18/02/19 14:52	Driving License	 Load JPG	<input checked="" type="checkbox"/>
19	18/02/19 14:52	Identification Card	 Load JPG	<input checked="" type="checkbox"/>
20	18/02/19 14:52	Identification Card	 Load JPG	<input checked="" type="checkbox"/>
21	18/02/19 14:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
22	18/02/19 14:52	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	BlueSG Pte Ltd (HQ)	Thumbnail	Print
1	18/02/19 14:51	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>
2	18/02/19 14:51	Sketch Plan #3	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, #21-01 SGX Centre 2  
Singapore 068807

Our File No: CS/MSG19003385/DSD3E2

Date: 02/08/2019

### REFERENCE

Insured/Claimant: BLUECAR EAST ASIA PTE LTD

Policy No: 29112616MCY

Date of Loss: 16/02/2019

Nature of Claim: OD

Claim No: 585367

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SME9645A

Make &amp; Model: BLUECAR BLUECAR, (A)

Engine No: HIDDEN

Reg. Date: 24/10/2018 (Man. Year: 2018)

Chassis No: VL4BCEB4RJT003362

Colour: White

Odometer: 0 km

Engine Capacity: 0 cc

Market Value/New Car Price: S\$66,000.00

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 175/65 R15

Rear Tyre Size: 175/65 R15

Front Left Side: Michelin 7 mm

Rear Left Side: Michelin 7 mm

Front Right Side: Michelin 7 mm

Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,058.80	1,791.20	267.60	13.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,800.00	1,140.00	1,660.00	59.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,858.80</b>	<b>2,931.20</b>	<b>1,927.60</b>	<b>39.67</b>
<b>- Excess (S\$)</b>	<b>2,000.00</b>	<b>2,000.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>2,858.80</b>	<b>931.20</b>	<b>1,927.60</b>	<b>67.43</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>200.12</b>	<b>65.18</b>	<b>134.94</b>	<b>67.43</b>
<b>Nett Amount (S\$)</b>	<b>3,058.92</b>	<b>996.38</b>	<b>2,062.54</b>	<b>67.43</b>

### INSPECTION

Date of Assignment: 20/03/2019

Date Inspected: 22/02/2019 Inspected At:

37 DEFU LANE 12

Repairer : Indeco Engineers Pte Ltd (Defu)

Estimated Period of Repair: 5.0 days

Adjuster: BRYAN TANI

Manager: Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 02 Aug 2019)
<b>Parts:</b>	144	BLUECAR BLUECAR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SME9645A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH (WCP)	Dented	520.00 F	*520.00 F
2	1		*FRONT FENDER PROTECTOR LH (WCP)	Bent	70.00 F	*70.00 F
3	1		*SET FRONT FENDER INNER SHIELD LH (WCP)	Deformed	36.00 F	*36.00 F
4	7		*FRONT FENDER INNER SHIELD CLIP (WCP)	Necessary	14.00 F	*14.00 F
5	1		*TYRE PRESSURE SENSOR (WCP)	Not Necessary	56.00 F	*- F
6	1		*STEEL RIM (WCP)	Bent	70.00 F	*70.00 F
7	1		*SET RIM COVER (WCP)	Cut / Bent	50.00 F	*50.00 F
8	1		*FRONT LOWER ARM LH (WCP)	Broken	160.00 F	*160.00 F
9	1		*SET FRONT SHOCK ABSORBER LH (WCP)	Bent	100.00 F	*100.00 F
10	1		*DRIVE SHAFT LH (WCP)	Damaged	180.00 F	*180.00 F
11	1		*ANTI ROLL BAR TIE ROD LH (WCP)	Not Necessary	20.00 F	*- F
12	1		*FRONT KNUCKLE ARM LH (WCP)	Distorted	170.00 F	*170.00 F
13	1		*SIDE SKIRT LH (WCP)	Not Necessary	120.00 F	*- F
14	1		*TYRE (\$130.00) (70%)	Cut	143.00 FS	*91.00 FS
15	1		*DOOR STICKERS	Necessary	70.00 FS	*70.00 FS
16	1		*STEERING RACK END (WCP)	Bent	100.00 F	*100.00 F
17	1		*TIE ROD END (WCP)	Bent	12.00 F	*12.00 F

F=Franchise part. S=SpcNett.

<b>Sub Total (\$\$)</b>	<b>1,891.00</b>	<b>1,643.00</b>
<b>+ Margin on L,N Items 10.00/10.00% (\$\$)</b>	<b>167.80</b>	<b>148.20</b>
<b>Total Parts (\$\$)</b>	<b>2,058.80</b>	<b>1,791.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPAIR, REPLACE, ON FIRE WALL, LHF FENDER, WHEEL HOUSE, LHF FLOOR PANEL, FRT BUMPER AND AFFECTED AREA	New	1,000.00	500.00
2	TO PUTTY AND RESPRAY ON FIRE WALL, LHF FENDER, WHEEL HOUSE, LHF FLOOR PANEL, FRT BUMPER AND AFFECTED AREA	New	1,000.00	400.00
3	TO REMOVE AND REFIX LHF SEAT, CARPET, UPHOLSTERY TO ASSIST WORK	New	400.00	0.00
4	TO REMOVE AND REFIX LHF UNDERCARRIAGE	New	300.00	180.00
5	TO PERFORM 4 WHEEL ALIGNMENT	New	100.00	60.00
Gross Labour Cost (S\$)			<b>2,800.00</b>	<b>1,140.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >