

20090901

ASS. REC. BY

REF: CS/FCS/19003406/Dtd3n2

Special Instruction

Surveyor: Bryan

ASSIGNMENT (Office)

CWS

From (Team): Joanne Yong

of FCI

Date/Time: 9.22am @ 22/1/19

Estimated Cost

Bill to:

OD / (IP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 1660C

Insured: SHC 8987P

at Workshop n/s: chunni Motor

Tel: 65425119

of Amk Auto Point #01-05 / 06

Policy No:

Claim No: D19001279MFSH

Sum Insured:

Excess:

Make of Veh: (Client's Record)

D.O.A. 19/02/2019

CA / REV / REP. / REV 24 HRS ^{lup}

H.O.D. Endorsement:

Date/Time: 9.18am @ 22/1/19

Person Contacted: Lynn

Vehicle: IN/OUT

Date/Time	Action/Instruction (-) Estimate
	SHD 1660C - CS/FCS/17019301 / Sg be 2 DVA: 17/4/17
	SHC 8987P - CS/FCS/18017835 / d3xx DVA: 28/9/18
27/1/19 @ 5:59pm	revised preli advise via email.
RECEIVED 29 MAR 2019	


998 1844 P

REF:

ASSIGNMENT

COE June 2021

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MY
 To inspect Vehicle No: _____
 at Workshop no: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt. Consistent? Yes or No
 GIA / PR Seen Consistent? Yes or No
 Est. Repairs: 10 ~~X~~ days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT



Veh No: SHD 4660C Yr Reg: 2013 June
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Prime Mover /
 Truck / Trailer or
 Make: Hyundai Sonata Cc: 1991
 Colour: Blue A/C: Insured / Std / Nil / NA
 Sp. Reading: 290870 T/Radio: Insured / Std / Nil / NA
 Eng No: D4BAD312229
 C/No: KMHE141VMDA834667
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Incl / Jammed / Leaked / Burnt or
 Brake: Incl / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/60 R16
 R: ————
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Westlake
 Front: S mm Rear: S mm
 R/Bal: S mm R/Bal: S mm
 L/Bal: S mm L/Bal: S mm
 D.O.A. 19/02/2019 D.O.I. 22/02/2019
 Survey held at Chunnik AMK
 Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or
 O/S Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: _____ Action / Instruction: _____
 First Capital SHC 8987P
 29/03/19 given 2/5 to 501 - with 10 days 2 m
 (Red: 3529.66 / 33%)

Date/Time: File Pass to? Preli. Report
 29/3 Typist Final Report
 Date/Time: File Return by?

Days Of Repair: 10
 Resurvey No. of Trip: 1

Add Fee: Site Insp (\$) Interview (\$) Tech Inv. (\$) Weekend (\$)

Survey Fee	170
Transportation	50
5+RS 3	50+50
Photos	98
Other	BSD
29/3/19	
TOTAL	418

Report Format: TP
 Lump Sum LBE (\$) 70500



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001279MFSH

Date: 27/2/2019

Our Ref: CS/FCI19003406/Dtd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 4660C

Please be informed that we had conducted the inspection of the abovementioned vehicle 22/2/2019 at the premises of M/s Chun Ni have the following to report: -

Workshop Estimate Amount	: S\$ <u>10,579.16</u>
Revised Estimate Amount	: S\$ <u>8,843.08</u>
"Check" Items Amount	: S\$ <u>0.00</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the o/s rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Bryan

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	21-02-2019	Our Ref No. D19001279MFSH
Accident Date	19-02-2019	Claim Type. Third Party
Insured Vehicle	SHC8987P	Third Party Vehicle. SHD4660C
Survey Location	AMK AUTOPOINT, SOON HOCK MOTOR,#01-05/06	
Contact Person.	LYNN OR IRENE - 65421726	
Contact No.	65427162/ 65425119	Fax No. 65426039
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 27 February 2019 5:59 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'Joanne Yong Lai fong'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001279MFSH/1
Attachments: PRELI ADVISED SHD 4660C.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHD 4660C**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 22 February 2019 12:05 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <Joaneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001279MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 22 February 2019 9:22 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <Joaneyong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19001279MFSH/1

Dear Sir/Mdm,

(LKK)

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 4660C

DATE : 20.02.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI SONATA

FAX : 6542 6039

FCI

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>Cut</i>			S 578.40 ✓
	Rear Bumper Clip <i>hll</i>			S 22.00 ✓
	Rear Bumper Bracket <i>hll</i>			S 49.00 X
	Rear Bumper Protector (RH) <i>reg</i>			S 38.00 X
	Rear Fender (RH) <i>Dental</i>			S 2,171.40 ✓
	Rear Fender Inner Lining (RH) <i>hll</i>			S 169.30 X
	Rear Fender Mudflap (RH) <i>Cut</i>			S 15.80 ✓
	Rear Windscreen Moulding <i>hll</i>			S 60.00 ✓
	Rear Door (RH) <i>hll</i>			S 2,201.10 X ✓
	Rear Tyre Rim (RH) <i>2 distorted</i>			S 325.30 ✓
	Rear Wheel Hup-Cap (RH) <i>Cut</i>			S 145.00 ✓
	Rear Wheelbearing ING & Hub <i>2 Down</i>			S 384.60 ✓
	Rear Trailing Arm (RH) <i>2 distorted</i>			S 192.00 ✓
	Rear Assist (RH) <i>2 distorted</i>			S 145.70 ✓
	Rear Shock Absorber (RH) <i>2 distorted</i>			S 276.30 ✓
	Rear Shock Absorber Mounting (RH) <i>hll</i>			S 81.30 X
	Rear Crossmember <i>2 distorted</i>			S 1,140.40 ✓
	Stabilizer Bar <i>2 distorted</i>			S 199.60 ✓
	Stabilizer Link <i>2 distorted</i>			S 85.90 ✓
	Rear Upper Arm (RH) <i>2 distorted</i>			S 335.75 ✓
	Rear Lower Arm (RH) <i>2 distorted</i>			S 353.80 ✓
	Rear Knuckle Arm (RH) <i>2 distorted</i>			S 550.80 ✓
			9183.85	
			7347.08	
			SUB TOTAL	S 9,521.45
			LESS 20%	S 1,904.29
			DISCOUNTED TOTAL	S 7,617.16
	Rear Windscreen Sealant <i>hll</i>			S 46.00 Nett ✓
	Rear Door Tel No. Sticker (RH) <i>hll</i>			S 10.00 Nett X
	Rear Tyre (RH) <i>SVL</i>		46.00	S 216.00 Nett X
				S 272.00

SHD 4660C

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			S 1,000.00 500/-
	Spray Painting Charge			S 750.00 500/-
	Wiring Charge			S 50.00 44
	Tuff Kote			S 50.00 40/-
	Towing Charge			S 50.00 44
	Remove/Refix Cushion & Upholstery Rear			S 150.00 80/-
	Remove/Refix Rear Windscreen Glass			S 120.00 80/-
	Remove/Refix Reverse Sensor			S 120.00 40/-
	Transfer of Door		1450.00	S 80.00 44
	Remove/Refix Undercarriage (RR)			S 200.00 150/-
	Rear Wheel Alignment			S 120.00 60/-
	TOTAL LABOUR			S 2,690.00
	ESTIMATE TOTAL			S 10,579.16
	<p>02/02/2019 @ 0930 hrs</p> <p>167 Antmal</p> <p>L/Sun 10 days</p> <p>Ryan</p> <p>LKK Auto</p> 		<p>8843.08</p> <p>457050/-</p>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAME
ADDRESS

Home Tel.:
VIN:
Registration: SHD 4660 C
Technician:
Mileage: 290870
Time Printed 22.2.19 12:36 PM

Hyundai : Sonata : 2005-

Front : Left

Actual	BEFORE	Specified Range
-0°43'		-0°30' 0°30'
3°35'		3°50' 5°50'
-0°45'		-0°05' 0°05'
16°10'		
15°27'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-0°08'		-0°30' 0°30'
3°41'		3°50' 5°50'
0°07'		-0°05' 0°05'
6°56'		
6°48'		

Front

	Actual	BEFORE	Specified Range
Cross Camber	-0°35'		
Cross Caster	-0°06'		
Cross SAI	9°14'		
Total Toe	-0°38'		-0°09' 0°09'
Cross Turn Diff.			

Rear : Left

Actual	BEFORE	Specified Range
-2°45'		-1°00' 0°00'
-0°23'		0°00' 0°09'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-6°22'		-1°00' 0°00'
-2°41'		0°00' 0°09'

Rear

	Actual	BEFORE	Specified Range
Cross Camber	3°37'		
Total Toe	-3°04'		0°00' 0°19'
Thrust Angle	1°09'		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19003406/Dtd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 01-04-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 8987P	Veh. Inspected	SHD 4660C
Policy No.		Coverage (\$)	0.00
Claim No.	D19001279MFSH	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	22/02/2019
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI SONATA	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	KMHET41VMDA834667	Colour	BLUE
Odometer	290870	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	WEST LAKE	5 mm
L/H Front Tyre	215/60 R16	WEST LAKE	5 mm
R/H Rear Tyre	215/60 R16	WEST LAKE	5 mm
L/H Rear Tyre	215/60 R16	WEST LAKE	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	19/02/2019	Inspection Date	22/02/2019
Survey held at	CHUNNI MOTOR REPAIRS PTE LTD BLK 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTOPOINT #03-19 SINGAPORE 568047		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4660C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	CUT	578.40	578.40
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
1	REAR BUMPER BRACKET	NOT NECESSARY	49.00	-
1	REAR BUMPER PROTECTOR (RH)	TO REPAIR SEE LABOUR	38.00	-
1	REAR FENDER (RH)	DENTED	2,171.40	2,171.40
1	REAR FENDER INNER LINING (RH)	NOT NECESSARY	169.30	-
1	REAR FENDER MUDFLAP (RH)	CUT	15.80	15.80
1	REAR WINDSCREEN MOULDING	NECESSARY	60.00	60.00
1	REAR DOOR (RH)	BENT	2,201.10	2,201.10
1	REAR TYRE RIM (RH)	DISTORTED	325.30	325.30
1	REAR WHEEL HUP-CAP (RH)	CUT	145.00	145.00
1	REAR WHEELBEARING ING & HUB	DAMAGED	384.60	384.60
1	REAR TRAILING ARM (RH)	DISTORTED	192.00	192.00
1	REAR ASSIST (RH)	DISTORTED	145.70	145.70
1	REAR SHOCK ABSORBER (RH)	DISTORTED	276.30	276.30
1	REAR SHOCK ABSORBER MOUNTING (RH)	NOT NECESSARY	81.30	-
1	REAR CROSSMEMBER	DISTORTED	1,140.40	1,140.40
1	STABILIZER BAR	DISTORTED	199.60	199.60
1	STABILIZER LINK	DISTORTED	85.90	85.90
1	REAR UPPER ARM (RH)	DISTORTED	335.75	335.75
1	REAR LOWER ARM (RH)	DISTORTED	353.80	353.80
1	REAR KNUCKLE ARM (RH)	DISTORTED	550.80	550.80
	LESS 20% DISCOUNT		-1,904.29	-1,836.77
			7,617.16	7,347.08
SPECIAL NETT ITEMS				
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR DOOR TEL NO STICKER (RH)(SN)	NOT NECESSARY	10.00	-
1	REAR TYRE (RH)(SN)	SERVICEABLE	216.00	-
			272.00	46.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER PROTECTOR (RH).		1,000.00	500.00
	SPRAY PAINTING CHARGE.		750.00	500.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	TUFF KOTE.		50.00	40.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.		120.00	80.00
	REMOVE/REFIX REVERSE SENSOR.		120.00	40.00
	TRANSFER OF DOOR.	NOT NECESSARY	80.00	-
	REMOVE/REFIX UNDERCARRIAGE (RR).		200.00	150.00
	REAR WHEEL ALIGNMENT.		120.00	60.00
			2,690.00	1,450.00
	GRAND TOTAL		10,579.16	8,843.08
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,050.00

Report Ref No. CS/FC119003406/Dtd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.