



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

LKK 63660255

Customer	: AXA INSURANCE S'PORE PTE LTD 8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811	Document No.	: SQT19000788	Page	1
Registration No	: SLK5080K	Date	: 19. Feb 2019	Customer No.	: WZA006
Chassis No	: JHMRU1810GX201693	Svc Advisor	: ARY CHUA WAI NGEE	Engine No	: L15B4531693
Model	: HRV DX-SIN CVT YM 2016	Date Time	: 19. Feb 2019 12:53:45 PM	Surveyor Name	: DID : +65 6846 5673
Owner's Name	: TONG WAI PING	Survey Date	: HP : +65 8100 6306	Authorisation Date	: Email : arychua@honda.com.sg
Ins Policy No.	: 10800712				
Date of Accident	: 18/2/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 72200) OWNER: TONG WAI PING OWNER INSURER: AVIVA LTD ACC DATE: 18/02/2019@18.00PM ACC: CTE SLIP RD LOR CHUAN (L/P81) ~ BRADDELL RD SURVEYED BY: REF NO: TP INSURER: AXA INSURANCE S'PORE PTE LTD TP VEH: GBE5043T - TOYOTA/VAN/WHITE						
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>/ MLC</i>	1	60.00		60.00	4.20	64.20
33502-T7A-J01	LAMP UNITR. <i>?</i>	1	441.50	25	331.12	23.18	354.30
34150-T7A-J01	LIGHT ASSY,R.LID <i>?</i>	1	269.90	25	202.42	14.17	216.59
34155-T7A-J01	LIGHT ASSYL.LID <i>/ YCA</i>	1	269.90	25	202.42	14.17	216.59
33552-T7A-J01	LAMP UNITL. <i>/ MLC</i>	1	441.50	25	331.12	23.18	354.30
75701-T5A-000	EMBLEMH <i>/ MLC</i>	1	10.70	25	8.02	0.56	8.58
90301-ST0-003	NUTPUSH 3MM <i>/ MLC</i>	2	2.10	25	3.15	0.22	3.37
74890-T7A-J12ZC	GARNISH ASSYRR.LICENSE <i>/ ee</i>	1	193.60	25	145.20	10.16	155.36
75722-T7W-A01	EMBLEMRR. <i>/ MLC</i>	1	13.30	25	9.97	0.70	10.67
75725-T8N-T00	EMBLEM,RR. I-VTEC <i>/ MLC</i>	1	14.50	25	10.87	0.76	11.63
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER <i>/ MLC</i>	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5 <i>/ MLC</i>	1	8.50	25	6.37	0.45	6.82
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER <i>/ MLC</i>	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT <i>/ MLC</i>	1	4.80	25	3.60	0.25	3.85
91501-S70-003	FASTENER BW/SHIELD <i>/ MLC</i>	4	5.30	25	15.90	1.11	17.01
91502-S70-003	FASTENER B <i>/ MLC</i>	2	5.30	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD <i>/ MLC</i>	2	3.80	25	5.70	0.40	6.10
71501-T7B-000	FACE RR.BUMPER <i>/ ee</i>	1	777.90	25	583.42	40.84	624.26
71593-T7A-J00	SPACER R,RR.BPR S <i>/ MLC</i>	1	16.90	25	12.67	0.89	13.56
71598-T7A-J00	SPACER,L,RR.BPR S <i>/ MLC</i>	1	16.90	25	12.67	0.89	13.56
04717-T7A-000ZZ	FACER,RR.BUMPER CORNER <i>?</i>	1	94.10	25	70.57	4.94	75.51



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE S'PORE PTE LTD 8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811	Document No.	: SQT19000788	Page	2
Registration No	: SLK5080K	Date	: 19. Feb 2019	Customer No.	: WZA006
Chassis No	: JHMRU1810GX201693	Customer No.	: WZA006	Svc Advisor	: ARY CHUA WAI NGEE
Model	: HRV DX-SIN CVT YM 2016	Engine No	: L15B4531693	Date Time	: 19. Feb 2019 12:53:45 PM
Owner's Name	: TONG WAI PING	Surveyor Name	:	Survey Date	:
Ins Policy No.	: 10800712	Authorisation Date	:		
Date of Accident	: 18/2/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
04718-T7A-000ZZ	FACEL.RR.BUMPER CORNER ?	1	94.10	25	70.57	4.94	75.51
91505-TM8-003	CLIP,BUMPER <i>16c</i>	8	2.30	25	13.80	0.97	14.77
38387-TZ5-A01	ANTENNA ASSYL.F. ?	1	59.30	25	44.47	3.11	47.58
74940-TZ5-A01	BUZZER ASSYSMART ?	1	60.40	25	45.30	3.17	48.47
33505-T7A-J01	REFLECTOR ASSYR.RR. <i>X NN</i>	1	156.30	25	117.22	8.21	125.43
33555-T7A-J01	REFLECTOR ASSYL.RR. <i>X NN</i>	1	156.30	25	117.22	8.21	125.43
66100-T7A-300ZZ	PANEL COMPRR. <i>Repair X</i>	1	373.10	25	279.82	19.59	299.41
74800-T7A-J02	LOCK ASSYTAILGATE <i>/ JM</i>	1	78.90	25	59.17	4.14	63.31
74440-T7A-003	WEATHERSTRIPTAILGATE ?	1	98.70	25	74.02	5.18	79.20
68100-T7A-J20ZZ	TAIL GATE COMP <i>/ BMC</i>	1	855.70	25	641.77	44.92	686.69
Sum Item					3515.44	246.09	3,761.53
BOSUN	SUNDRIES	1	60.00 <i>20</i>		60.00	4.20	64.20
BOBC	BODY UNDERSIDE COATING (N)	1	100.00 <i>X NN</i>		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	100.00 <i>X NN</i>		100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	140.00 <i>100</i>		140.00	9.80	149.80
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00 <i>160</i>		180.00	12.60	192.60
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00 <i>X NN</i>		250.00	17.50	267.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	350.00 <i>300</i>		350.00	24.50	374.50
BOMISC1	RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM (N)	1	350.00 <i>300</i>		350.00	24.50	374.50
BOMISC1	REMOVE & INSTALL REVERSE CAMERA & CALIBRATION (N)	1	350.00 <i>300</i>		350.00	24.50	374.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	450.00 <i>350</i>		450.00	31.50	481.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	550.00 <i>450</i>		550.00	38.50	588.50
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2800.00 <i>1800</i>		2800.00	196.00	2996.00
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN	1	4800.00 <i>1120 (over)</i>		4800.00	336.00	5136.00
Sum Labor					10480.00	733.60	11,213.60

Survey By _____

Printed on 22/2/2019 9:07:47 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE S'PORE PTE LTD 8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811	Document No.	: SQT19000788	Page	3
Registration No	: SLK5080K	Date	: 19. Feb 2019	Customer No.	: WZA006
Chassis No	: JHMRU1810GX201693	Svc Advisor	: ARY CHUA WAI NGEE	Engine No	: L15B4531693
Model	: HRV DX-SIN CVT YM 2016	Date Time	: 19. Feb 2019 12:53:45 PM	Surveyor Name	:
Owner's Name	: TONG WAI PING	Survey Date	:	Authorisation Date	:
Ins Policy No.	: 10800712				
Date of Accident	: 18/2/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Date & Time	18/2/19 26/2/19				Total Amount	13,995.44	979.69
Excess					Total (Inclusive of GST)		14,975.13
Status							
Signature	_____ _____						

_____ 82880282
6 days.
before part photos.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Printed on 22/2/2019 9:07:47 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)