

Surveyor

From (Person)

RASHI

Junice Goh

ASSIGNMENT (Office)

JCS

Date/Time 25/2/19 @ 10:17am

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKS1537G

Insured:

at Workshop m/s

progressive Car

Tel:

67415336

of

BLK 3022A ubi Rd L# 01-45/46

Policy No: MPC18A00086700

Claim No:

DMPC19000504/5G

Sum Insured:

Excess:

JBA \$0/-

Make of Veh:

D.O.A 22/2/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 11:46pm @ 25/2/19 Person Contacted:

pei wen

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKS1537G-X
25/02/19 @ 16:55 p.m.	revised IA to Junice Goh via merimer.
25/02/19 @ 13:54 p.m.	mandate requested revert authorize repair to Junice Goh via merimer.
26/02/19 @ 14:56 p.m.	mandate approved by Junice Goh.
27/02/19 @ 10:56 am.	revert authorize repair to PEI WEN Cyprian


Form

REF:

7739E

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 (C) TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **SKS 1537G**
 at Workshop nbs: **PROGRESSIVE**
 of: **3022A WBI RD 1 #01-44/4C**
 Insured: **ECICS**
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: **TBA f.o/**
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: **91K**
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: days Res: Yes or No
 Lum Sum: % 3 Val: Yes or No
 CA / (REV) / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SKS 1537G** Yr Regn: **2015 MAR**
 Type: **(C) M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /**
 Truck / Trailer or

Make: **TOYOTA HARRIER 2.0 EC** G.S. **1986**
 Colour: **BLACK** A/C: Insured / Std / NI / NA
 Sp. Reading: **82535** T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: **254 6 00030206**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: **(C)** In order / Jammed / Leaked / Burnt or

Brake: **(C)** In order / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size: F: **235/60R18**
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **CONTINENTAL**

Front		Rear
R/Bal. 6 mm		R/Bal. 6 mm
L/Bal. 6 mm		L/Bal. 6 mm
D.O.A. 22/02/19		D.O.I. 25/02/19

Survey held at **PROGRESSIVE**

Des. of Damages: **(C) Fr** / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

05/04/19 Confirmed **RP/P** \$ **4,287.95** @ **5 days** with **Resul**
 (\$ **2,955.20** red - **38%**)

[Signature]
5/4/2019

RECEIVED 05 APR 2019

Date/Time: For Pass to?

05/04/19

Date/Time: To Return to?

Typo

☐ : Preli. Report
☒ : Final Report

Days Of Repair: **5**

Resurvey No. of Trip: **1**

Survey Fee:

Transportation:

3 + RS St

2 Photos

1 Other

1014

Add Fee: ☐ Site Insp. (\$)
☐ Interview (\$)
☐ Tech Insp. (\$)
☐ Workshop (\$)

Report Format:

Lump Sum / L.B.F. (\$)

250
10

...CLAIM SUBFOLDER...(New Assignment)

Midnight Accident

CLAIM SUBFOLDER TRACKING

Case	Notified	Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Feb 2019 15:31 Sendback Est S\$7,452.55	23 Feb 2019 15:40 Assign	25 Feb 2019 10:17			New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS				
Insured: WONG FOONG SUN, ID: S7277739E, Tel: +6588183895, Email: FOONGSUN_WONG@HOTMAIL.COM				
Vehicle Reg. No.: SKS1537G		Date of Loss: 22/02/2019 06:00 - :59 [46 Months and 26 Days From LTA Reg Date (Man Yr)]		
Claim Type: OD / DMPC1900050H/JG		Policy/Cover Note No.: MPC18A00086700 (Comprehensive)		
		Excess: S\$0.00		
Repairer: Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46, 408716 Ubi - Tel: 67415336				
Handling Insurer: ECICS Limited (HQ) - Tel: 63374779 / 6303 0178 ... [Handled by Janice Goh - 6303 0182]				
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/03/2019]				
Driver/Custodian: WONG FOONG SUN (46 / Female), NRIC: S7277739E, Tel: +6588183895 Email: FOONGSUN_WONG@HOTMAIL.COM				
ASSOCIATED MAIL RECEIVED				
There are no mail for this case.				View All Compose Case Mail
ALL ASSOCIATED TASKS				
View All Search Tasks Create New Task Complete				
Due Date	Type	Task Group	Subject	Handler
		Assigned By	Completed On	Created On
No results.				

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 5 April 2019 4:09 PM
To: 'Ray'
Cc: Rasul (LKKAuto)
Subject: RE: SKS1537G - TO FINALIZE

Dear Ray,

Confirmed final fig \$4,887.85 @ 5 days of repairs before excess \$0/- & GST.

Final invoice and all supporting documents sent over to ECICS LTD.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ray [mailto:ray@procarcare.com.sg]
Sent: Thursday, 4 April 2019 9:55 AM
To: Rasul@lkkauto.com; Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: FW: SKS1537G - TO FINALIZE

Hi Rasul/ Veron,

Please refer to finalize

Supp	\$165.00
Parts	\$3567.85
Sn	\$35.00
Lab	\$1120.00
Total	\$4887.85

Regards,

Ray LIN

Damage Assessment

Progressive Automotive Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

T: +65 6741 5336 | F: +65 6741 7208

E: claims@procarcare.com.sg

W: www.procarcare.com.sg

With effect from 1 Sep 2018, **Progressive Automotive Pte Ltd will be rebranded as **Progressive Car Care Pte Ltd**. You may now reach us at our new email addresses (@procarcare.com.sg) and our old email addresses (@progauto.com.sg) shall cease to function with effect from 1 Sep 2018. We look forward to your continued support.*

Shirley Hiew (LKK Auto)

Subject: FW: SKS1537G - TO FINALIZE
Attachments: INVOICE .pdf; REPORT .pdf

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ray [mailto:ray@procarcare.com.sg]
Sent: Friday, 15 March 2019 10:41 AM
To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>
Cc: Wayne <wayne@procarcare.com.sg>; Peiwen <peiwen@procarcare.com.sg>; Chermaine <chermaine@procarcare.com.sg>
Subject: SKS1537G - TO FINALIZE

Hi Adrian,

Please refer to finalize

Supp	\$165.00
Parts	\$3567.85
Sn	\$35.00
Lab	\$1120.00
Total	\$4887.85

Regards,

Ray LIN

Damage Assessment

Progressive Automotive Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

T: +65 6741 5336 | F: +65 6741 7208

E: claims@procarcare.com.sg

W: www.procarcare.com.sg

With effect from 1 Sep 2018, **Progressive Automotive Pte Ltd will be rebranded as **Progressive Car Care Pte Ltd**. You may now reach us at our new email addresses (@procarcare.com.sg) and our old email addresses (@progauto.com.sg) shall cease to function with effect from 1 Sep 2018. We look forward to your continued support.*

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 27 February 2019 10:56 AM
To: peiwen@progauto.com.sg
Cc: SUR
Subject: SKS 1537G OD (ECICS) DOA 22/02/2019

Dear Pei Wen,

As instructed by our client, please proceed to repair the insured vehicle **SKS 1537G (Excess \$ 0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SKS1537G (DMPC1900050H/JG)

OD

Feb 22 2019 6:00AM

[WONG FOONG SUN]

Progressive Car Care Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From ECICS Limited (HQ) (ECICS), sent on 05/04/2019 15:18 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$4887.85) - SKS1537G - Claim Handler: Janice Goh

Approved:4887.85.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

SKS1537G (DMPC1900050H/JG)

OD

Feb 22 2019 6:00AM

[WONG FOONG SUN]

Progressive Car Care Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From ECICS Limited (HQ) (ECICS), sent on 26/02/2019 14:56 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (\$5135.35) - SKS1537G - Claim Handler: Janice Goh

Approved:5135.35.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Janice Goh

Date: 05 Apr 2019

Preliminary Advice

Vehicle No	: SKS1537G	Accident Date	: 22/02/2019
Make	: TOYOTA HARRIER	Policy No.	: MPC18A00086700
Assignment Date	: 25/02/2019	Excess	: S\$0.00
Date of Inspection	: 25/02/2019	Est. Duration of Repair	: 5 days
Inspection At	: Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46 Singapore 408716		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,843.05 (INCLUSIVE SUPPLEMENTARY)
Revised Amount	:S\$	4,887.85 (INCLUSIVE SUPPLEMENATRY)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,887.85

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	91,000.00
COE / PARF Rebate	:S\$	58,009.00
Salvage Value	:S\$	
Margin for Repair	:S\$	32,991.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have received supplementary from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair. Supplementary amount is \$ 110.00.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Janice Goh

Date: 25 Feb 2019

Preliminary Advice

Vehicle No	: SKS1537G	Accident Date	: 22/02/2019
Make	: TOYOTA HARRIER	Policy No.	: MPC18A00086700
Assignment Date	: 25/02/2019	Excess	: S\$0.00
Date of Inspection	: 25/02/2019	Est. Duration of Repair	: 5 days
Inspection At	: Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46 Singapore 408716		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,452.55
Revised Amount	:S\$	2,660.35
Check Items (Estimated)	:S\$	2,475.00
Total	:S\$	5,135.35

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	91,000.00
COE / PARF Rebate	:S\$	58,009.00
Salvage Value	:S\$	
Margin for Repair	:S\$	32,991.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/02/2019 10:35
Date Of Accident	22/02/2019 06:50
Exact Location Of Accident	JURONG WEST CENTRAL 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKS1537G
Insured/Policyholder	
Name Of Registered Owner	WONG FOONG SUN
NRIC No	S7277739E
Email Address	FOONGSUN_WONG@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-88183895
Alternative Phone No	OTHERS-88183895

Vehicle Particulars

Manufacturer	TOYOTA
Model	HARRIER-2.0 ELEGANCE (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MPC18A00086700
Cover Note Number	

Driver

Name of Driver	WONG FOONG SUN
NRIC No	S7277739E
Date Of Birth	22/12/1972
Occupation	INDOOR
Date Of Driving Pass	02/01/2003
Driving Experience	16 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-88183895
Fax Number	
Contact Number	OTHERS-88183895
Email Address	FOONGSUN_WONG@HOTMAIL.COM

Address	BLK 630 JURONG WEST STREET 65 #04-414 SINGAPORE
Postcode	640630
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN- PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLF8463X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident [all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"], the Insurers' lawyer/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyer/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

23/2/19
10:30AM


Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRC/PIN No.:

PRANAN

Vehicle
A - SKS 15376
B - SLF 8463

Legend
 Vehicle
 Motorcycle

Accident happened @ Juvang West Central 1 near traffic light.
Sudden brake by front car and I unable to stop in
time AS such, hit into front car and his car damage
at back.

1/We declare the foregoing particulars are true in every respect.
Please be advised that your insurer may have a fourteen (14) days clause whereby the claim against your policy must be made within the stipulated timeframe from the day of occurrence. Daily check your policy for more details.

Date & Time: 10:30 AM
23/2/19

Driver's Signature

Reporting Centre Personnel's S

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7739E
Vehicle Details	
Vehicle No.:	SKS1537G
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER 2.0 ELEGANCE AT ABS D/AIRBAG 2WD
Primary Colour:	Black
Manufacturing Year:	2014
Engine No.:	3ZRB472786
Chassis No.:	ZSU600030206
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$26,436.00
Original Registration Date:	27 Mar 2015
First Registration Date:	27 Mar 2015
Transfer Count:	0
Actual ARF Paid:	\$19,011.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Mar 2025
PARF Rebate Amount:	\$14,258.00
Intended COE Rebate Details	
COE Expiry Date:	26 Mar 2025
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$72,100.00
COE Rebate Amount:	\$43,751.00
Total Rebate Amount:	\$58,009.00

The information contained herein is correct as at 25 Feb 2019

OK



PROGRESSIVE
CAR CARE PTE LTD

Progressive Car Care Pte Ltd

(Co. Reg. No. 201006949C)

Blk 3022A Ubi Road 1 #01-45/ 46 S408716

T: +65 6741 5336 | F: +65 6741 7208

E: claims@procarcare.com.sg

W: www.procarcare.com.sg

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD 0219-6897
Policy No:	MPC18A00086700	Date of Loss:	22/02/2019
Vehicle Reg. No.:	SKS1537G	Driveable?	
Driver Age/Info:	46 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	WONG FOONG SUN	Contact No:	+6588183895
Driver:	WONG FOONG SUN		

Make/Model:	TOYOTA HARRIER, 2.0 ELEGANCE (A)	Vehicle Reg. Date:	27/03/2015
Vehicle Colour:	BLACK		
Engine No:	3ZRB472786	Chassis No:	ZSU600030206
Odometer:	82535 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	6

Description of Accident/Loss: REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN- PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336

Remarks: VEHICLE IS IN WORKSHOP

Present Location: PROGRESSIVE CAR CARE PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	5,577.55
Miscellaneous Items	55.00
Labour	920.00
Paintwork Labour	900.00
Towing	0.00
Gross Total (S\$)	7,452.55
+ GST 7.00% (S\$)	521.68
Nett Amount (S\$)	7,974.23

This claim is handled by: NG PEI WEN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Feb 2019)

Parts: M1-SUV TOYOTA HARRIER 2.0 Elegance (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Progressive Car Care Pte Ltd/SKS1537G/23/02/2019 15:40

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*BONNET <i>PA</i>			
2	1	NA	*BONNET RUBBER - LH - NO PRICE <i>X AN</i>	0.00	0.00	*530.00 F ✓
3	1	NA	*BONNET RUBBER - RH - NO PRICE <i>X AN</i>	0.00	0.00	*- F
4	9	NA	*BONNET INSULATOR CLIPS <i>m -</i>	0.00	0.00	*- F
5	1	NA	*BONNET OUTER CHROME MOULDING <i>CRS -</i>	0.00	0.00	*13.50 F ✓
6	1	NA	*GRILLE ASSY <i>CRS -</i>	0.00	0.00	*95.00 F ✓
7	1	NA	*GRILLE LOGO <i>AC X AN</i>	0.00	0.00	*200.00 F ✓
8	1	NA	*FRONT BUMPER <i>CRS -</i>	0.00	0.00	*35.00 F X
9	10	NA	*FRONT BUMPER CLIPS <i>m -</i>	0.00	0.00	*300.00 F ✓
10	1	NA	*FRONT BUMPER SIDE HOLDER - LH <i>? CRX X SUC</i>	0.00	0.00	*15.00 F ✓
11	1	NA	*FRONT BUMPER SIDE HOLDER - RH <i>? CRX X SUC</i>	0.00	0.00	*50.00 F X
12	1	NA	*FRONT BUMPER REINFORCEMENT <i>? CRX X SUC</i>	0.00	0.00	*50.00 F X
13	1	NA	*FRONT BUMPER FOAM - CENTER <i>? CRX X SUC</i>	0.00	0.00	*130.00 F X
14	1	NA	*FRONT BUMPER FOG LAMP - RH <i>? CRX X SUC</i>	0.00	0.00	*50.00 F ✓
15	1	NA	*FRONT BUMPER FOG LAMP COVER - RH <i>X SUC</i>	0.00	0.00	*110.00 F X
16	1	NA	*FRONT BUMPER FOAM - LH <i>? CRX</i>	0.00	0.00	*40.00 F X
17	1	NA	*FRONT BUMPER FOAM - RH <i>? CRX</i>	0.00	0.00	*30.00 F ✓
18	1	NA	*FRONT BUMPER GRILLE TOP RUBBER <i>X SUC</i>	0.00	0.00	*30.00 F ✓
19	1	NA	*FRONT BUMPER CENTRE LOWER GRILLE <i>CRS -</i>	0.00	0.00	*45.00 F X
20	1	NA	*FRONT BUMPER TOWING COVER - RH <i>repair</i>	0.00	0.00	*90.00 F ✓
21	1	NA	*FRONT BUMPER TOWING COVER - LH <i>X SUC</i>	0.00	0.00	*18.00 F X
22	1	NA	*FRONT BUMPER LOWER GARNISH <i>CRS -</i>	0.00	0.00	*18.00 F X
23	1	NA	*BRACE PANEL <i>? X SUC</i>	0.00	0.00	*90.00 F ✓
24	1	NA	*SUPPORT PANEL ASSY <i>X SUC</i>	0.00	0.00	*110.00 F X
25	13	NA	*SUPPORT PANEL TOP GARNISH CLIP <i>X AN</i>	0.00	0.00	*350.00 F X
26	1	NA	*HEAD LAMP PANEL - LH <i>X SUC</i>	0.00	0.00	*26.00 F X
27	1	NA	*HEAD LAMP PANEL - RH <i>X SUC</i>	0.00	0.00	*50.00 F X
28	1	NA	*HEAD LAMP - LH <i>? CRX</i>	0.00	0.00	*50.00 F ✓
29	1	NA	*HEAD LAMP - RH <i>? CRX</i>	0.00	0.00	*900.00 F ✓
30	1	NA	*HEAD LAMP LOWER RETAINER - LH <i>X SUC</i>	0.00	0.00	*900.00 F ✓
31	1	NA	*HEAD LAMP LOWER RETAINER - RH <i>X SUC</i>	0.00	0.00	*45.00 F ✓
32	1	NA	*WIPER TANK <i>X AN</i>	0.00	0.00	*45.00 F X
33	1	NA	*WIPER TANK MOTOR <i>X AN</i>	0.00	0.00	*60.00 F X
34	1	NA	*WIPER TANK NECK <i>X AN</i>	0.00	0.00	*80.00 F X
35	1	NA	*FRONT FENDER - RH <i>repair</i>	0.00	0.00	*30.00 F X
36	10	NA	*FRONT FENDER COWLING CLIPS - RH <i>X SUC</i>	0.00	0.00	*270.00 F X
37	1	NA	*HEAD LAMP PANEL LOWER - LH <i>X</i>	0.00	0.00	*15.00 F X
38	1	NA	*HEAD LAMP PANEL LOWER - RH <i>X</i>	0.00	0.00	*100.00 F X
				0.00	0.00	*100.00 F X

F=Franchise part.

Sub Total (\$\$) 5,070.50

+ Margin on L,N Items 10.00% (\$\$) 507.05

Total Parts (\$\$) 5,577.55

Progressive Car Care Pte Ltd/SKS1537G/23/02/2019 15:40. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	COOLANT <i>X nn</i>	20.00
2	1	FRONT NUMBER PLATE WITH CASING <i>SN</i>	35.00 ✓
Sub Total (S\$)			55.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New <i>600</i>	900.00
<u>Labour Items</u>			
2	TO KNOCK OUT DENTS; SUPPORT PANEL; REMOVE; REPLACE ACCIDENT PARTS	New <i>500</i>	800.00
3	TO CHECK WIRING	New	20.00
4	TO REMOVE; REFILL CONDENSER AND REFILL GAS	New <i>nn X</i>	100.00 ✓
Gross Labour Cost (S\$)			1,820.00

Progressive Car Care Pte Ltd/SKS1537G/23/02/2019 15:40. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate alignment and speedy repairs.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Resue *28/2/19*
Hp 900/10068

5 days

P/P

25/02/19 @ 1220

EXCESS: TBA

REVEAT

Reey 64 paint



PROGRESSIVE CAR CARE PTE LTD

Progressive Car Care Pte Ltd

(Co. Reg. No. 201006949C)

Blk 3022A Ubi Road 1 #01-45/ 46 S408716

T: +65 6741 5336 | F: +65 6741 7208

E: claims@procarcare.com.sg

W: www.procarcare.com.sg

(SUPPLEMENTARY)

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	OD 0219-6897
Policy No:	MPC18A00086700	Date of Loss:	22/02/2019
Vehicle Reg. No.:	SKS1537G	Driveable?	
Driver Age/Info:	46 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	WONG FOONG SUN	Contact No:	+6588183895
Driver:	WONG FOONG SUN		
Make/Model:	TOYOTA HARRIER, 2.0 Elegance (A)	Vehicle Reg. Date:	27/03/2015
Vehicle Colour:	Black	Chassis No:	ZSU600030206
Engine No:	3ZRB472786		
Odometer:	82535 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Description of Accident/Loss	REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN- PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336		
Present Location:	PROGRESSIVE CAR CARE PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	390.50
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	390.50
+ GST 7.00% (\$\$)	27.34
Nett Amount (\$\$)	417.84
+ Previous Estimates (\$\$)	7,974.23
Claim Total (\$\$)	8,392.07

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Feb 2019)
 Parts: M1-SUV TOYOTA HARRIER 2.0 Elegance (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Progressive Car Care Pte Ltd/SKS1537G/27/02/2019 16:24
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*R/F FENDER COWLING <i>part X SUC</i>	0.00	0.00	*190.00 F
2	10		*R/F FENDER COWLING CLIP <i>part X am</i>	0.00	0.00	*15.00 F
3	1		*FRT BUMPER UNDER LOWER COVER <i>part</i>	0.00	0.00	*90.00 F
4	1		*RADIATOR LOWER AIR GUIDE <i>DE</i>	0.00	0.00	*60.00 F
Sub Total (S\$)						355.00
+ Margin on L,N Items 10.00% (S\$)						35.50
Total Parts (S\$)						390.50

F=Franchise part.

Progressive Car Care Pte Ltd/SKS1537G/27/02/2019 16:24. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- * To resurvey before/after spray painting
- * To resurvey damaged part(s) during resurvey
- * These prices are subject to confirmation
- * The survey is on a "Without Prejudice" basis
- * Any modification(s) is allowed
- * Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Progressive Car Care Pte Ltd/SKS1537G/27/02/2019 16:24. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-D-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.

Repairer Estimates

Version: 1.0 (Last Synchronised: 23 Feb 2019)

TOYOTA HARRIER 2.0 Elegance (A) (Catalogue Merimen Singapore 1.0)

(Price-denominated Standard List)

Car Care Pte Ltd/SKS1537G/23/02/2019 15:40

Notes are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker

estimate page

is not in reference catalogue are prefixed with an asterisk *.

Parts

Particulars	%Disc	%Depr	Amount
*BONNET <i>HA</i>	0.00	0.00	*530.00 F
*BONNET RUBBER - LH - NO PRICE <i>HA</i>	0.00	0.00	-. F
*BONNET RUBBER - RH - NO PRICE <i>HA</i>	0.00	0.00	-. F
*BONNET INSULATOR CLIPS <i>HA</i>	0.00	0.00	*13.50 F
*BONNET OUTER CHROME MOULDING <i>CA</i>	0.00	0.00	*95.00 F
*GRILLE ASSY <i>CA</i>	0.00	0.00	*200.00 F
*GRILLE LOGO <i>HA</i>	0.00	0.00	*35.00 F
*FRONT BUMPER <i>CA</i>	0.00	0.00	*300.00 F
*FRONT BUMPER CLIPS <i>HA</i>	0.00	0.00	*15.00 F
*FRONT BUMPER SIDE HOLDER - LH <i>?</i>	0.00	0.00	*50.00 F
*FRONT BUMPER SIDE HOLDER - RH <i>?</i>	0.00	0.00	*50.00 F
*FRONT BUMPER REINFORCEMENT <i>?</i>	0.00	0.00	*130.00 F
*FRONT BUMPER FOAM - CENTER <i>?</i>	0.00	0.00	*50.00 F
*FRONT BUMPER FOG LAMP - RH <i>HA</i>	0.00	0.00	*110.00 F
*FRONT BUMPER FOG LAMP COVER - RH <i>X</i>	0.00	0.00	*40.00 F
*FRONT BUMPER FOAM - LH <i>?</i>	0.00	0.00	*30.00 F
*FRONT BUMPER FOAM - RH <i>?</i>	0.00	0.00	*30.00 F
*FRONT BUMPER GRILLE TOP RUBBER <i>X</i>	0.00	0.00	*45.00 F
*FRONT BUMPER CENTRE LOWER GRILLE <i>CA</i>	0.00	0.00	*90.00 F
*FRONT BUMPER TOWING COVER - RH <i>repair</i>	0.00	0.00	*18.00 F
*FRONT BUMPER TOWING COVER - LH <i>X</i>	0.00	0.00	*18.00 F
*FRONT BUMPER LOWER GARNISH <i>CA</i>	0.00	0.00	*90.00 F
*BRACE PANEL <i>?</i>	0.00	0.00	*110.00 F
*SUPPORT PANEL ASSY <i>X</i>	0.00	0.00	*350.00 F
*SUPPORT PANEL TOP GARNISH CLIP <i>X</i>	0.00	0.00	*26.00 F
*HEAD LAMP PANEL - LH <i>X</i>	0.00	0.00	*50.00 F
*HEAD LAMP PANEL - RH <i>X</i>	0.00	0.00	*50.00 F
*HEAD LAMP - LH <i>?</i>	0.00	0.00	*900.00 F
*HEAD LAMP - RH <i>?</i>	0.00	0.00	*900.00 F
*HEAD LAMP LOWER RETAINER - LH <i>X</i>	0.00	0.00	*45.00 F
*HEAD LAMP LOWER RETAINER - RH <i>X</i>	0.00	0.00	*45.00 F
*WIPER TANK <i>X</i>	0.00	0.00	*60.00 F
*WIPER TANK MOTOR <i>X</i>	0.00	0.00	*80.00 F
*WIPER TANK NECK <i>X</i>	0.00	0.00	*30.00 F
*FRONT FENDER - RH <i>repair</i>	0.00	0.00	*270.00 F
*FRONT FENDER COWLING CLIPS - RH <i>X</i>	0.00	0.00	*15.00 F
*HEAD LAMP PANEL LOWER - LH <i>?</i>	0.00	0.00	*100.00 F
*HEAD LAMP PANEL LOWER - RH <i>X</i>	0.00	0.00	*100.00 F

Sub Total (\$\$) 5,070.50

+ Margin on L,N Items 10.00% (\$\$)

507.05

Total Parts (\$\$)

5,577.55

777E
 2015 MAR

9KS1537G

Repair Estimates

ates on Miscellaneous Items

Particulars	Amount
Miscellaneous Items	
COOLANT X	20.00
FRONT NUMBER PLATE WITH CASING <i>SEA</i>	35.00
Sub Total (\$)	55.00

Estimates on Labour

Particulars	Lab. Type	Amount
Paintwork Labour:		
TO RESPRAY PAINT ON ACCIDENT PORTIONS	Now 600	900.00
Miscellaneous Labour:		
TO KNOCK OUT DENTS; SUPPORT PANEL; REMOVE; REPLACE ACCIDENT PARTS	Now 500	900.00
TO CHECK WIRING	Now	20.00
TO REMOVE, REFILL CONDENSER AND REFILL GAS	Now X	100.00
Gross Labour Cost (\$)		1,820.00

Progressive Car Care Pte Ltd 9KS1537G/2162/2819 15:49 Not valid without Reference section.
 Generated using: Workmen & Claims IEAS
 - END OF ESTIMATES -

For equipment to add the labor and vehicle CAP-Q, PER HOUR 1 hour session, then align and the subject daily session to provide accurate and speedy repairs.

Paul
 Hp 900/10068
 5 days
 P/P
 25/02/19 @ 1220
 EXCESS: TBA
 REVEAT
 Reeng 64 paint

KK Auto Consultants hence notify
 The Reparer of the following:

- To receive before/after spray painting
- To display damaged parts during survey
- Parts prices are subject to confirmation
- This survey is on a "Without Prejudice" basis
- If any modification is allowed
- Any additional items must be reviewed and subject to final approval from Insurance Company

Acknowledged by Reparer
 Signature: _____
 Date: _____



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9781 / 6745 9920



Dept Direct: 6505 5510

Dept Direct: 6505 5511

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9792

Dept Direct: 6417 9790

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE CAR CARE PTE LTD

BLOCK 3022A #01-45/46

UBI ROAD 1

BUTTON 92712711

SINGAPORE 408716

TEL: 67415336 FAX: 67417208 LILY / 68444802 WENDY

ATTN: WENDY / PEI WEN / LEONG KEAT

006897

TAX INVOICE : AR201902-10661

DATE : 27/02/2019

CUSTOMER ID : PRO005

VEH REG. NO. : SKS1537G

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	T81110-48440 ZSU60 AVU65	HEAD LAMP RH ASSY	CC CC12-F-04E	1	900.00	900.00 ✓
2	T81150-48890 ZSU60 AVU65	HEAD LAMP LH ASSY	CC CC12-B-04C	1	900.00	900.00 ✓
3	T52618-48010 ZSU60 AVU65	FRT BUMPER LWR GARNISH	CC CC12-M-09B	1	90.00	90.00 ✓
4	T52614-48040/1 ZSU60 AVU65	FRT BUMPER SPONGE	CC CC12-O-06B	1	50.00	50.00 ✓
5	T52611-48170 ZSU60 AVU65	FRT BUMPER SPONGE RH	CC CC12-N-07B	1	30.00	30.00 ✓
6	T52612-48030 ZSU60 AVU65	FRT BUMPER SPONGE LH	CC CC12-N-07B	1	30.00	30.00 ✓

3393.50

SUB-TOTAL : 2,000.00
ADD GST 7.00 % 140.00

E. & O.E

TOTAL AMOUNT SGD : 2,140.00

[P] 27/02/2019 2:18:17PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 27/02/2019 2:12:05PM

JAE Auto Pte. Ltd.

Sales Executive: HAO

This is computer generated document.

No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WIPERBLADE CLASS
Dept Direct: 6417 9701 / 6745 3023

Arrange by

Driver

STOKY



Dept Direct: 8505 5616

Dept Direct: 6505 6311

Dept Direct: 6417 9752



Dept Direct: 6417 9751

Dept Direct: 6417 9752

Dept Direct: 6417 9753

Dept Direct: 6417 9753

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

PROGRESSIVE CAR CARE PTE LTD

BLOCK 3022A #01-45/46

UBI ROAD 1

BUTTON 92712711

SINGAPORE 408716

TEL: 67415336 FAX: 67417208 LILY / 68444802 WENDY

ATTN: WENDY / PEI WEN / LEONG KEAT

TAX INVOICE : AR201902-10664

DATE : 27/02/2019

CUSTOMER ID : PRO005

VEH REG. NO. : SKS1537G

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR : SGD

SO STOCKID	DESCRIPTION	Stk Loc	QTY	UPRICE	AMOUNT
1. T16683-36020 ZSU60 AVU65	RAD LOWER AIR GUIDE	PA PL2-K1-04S	1	60.00	60.00

SUB-TOTAL : 60.00

ADD GST 7.00 % 4.20

E. & O E

TOTAL AMOUNT SGD: 64.20

[P] 27/02/2019 2:16:49PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 27/02/2019 2:13:36PM

JAE Auto Pte. Ltd.

Sales Executive: HAO

This is computer generated document.

No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6412 9791 / 6745 9532

Arrange By

Driver



Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

ROGRESSIVE CAR CARE PTE LTD

LOCK 3022A #01-45/46

BI ROAD 1

UTTON 92712711

SINGAPORE 408716

EL: 67415336 FAX: 67417208 LILY / 68444802 WENDY

TTN: WENDY / PEI WEN / LEONG KEAT

TAX INVOICE : AR201902-10564

DATE : 27/02/2019

CUSTOMER ID : PRO005

VEH REG. NO. : SKS1537G

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : SGD

Q STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. T53301-48170 ZSU60 AVU65	FRT BONET	CC CC12-G-08B	1	530.00	530.00 ✓
2. T90467-T0014/09050 ZSU60 ZRE171	FRT BONET INSULATOR CLIP	CC CC12-N-03B4	9	1.50	13.50 ✓
3. T75770-48030 ZSU60 AVU65	FRT BONET MLDG	CC CC12-O-04C1	1	95.00	95.00 ✓
4. T53101-48722/B30 ZSU60	RAD GRILLE (PREMIUM)	CC CC12-N-01E	1	200.00	200.00 ✓
5. T53112-48150 ZSU60 AVU65	FRT BUMPER LWR GRILLE	CC CC12-O-03C1	1	90.00	90.00 ✓
6. T52411-48020 ZSU60 AVU65	FRT BUMPER LWR GUARD	CC CC12-I-02D	1	90.00	90.00 ✓

SUB-TOTAL : 1,018.50

ADD GST 7.00 % 71.30

E & O E

TOTAL AMOUNT SGD : 1,089.80

14/03/2019 12:46:21

[E] 27/02/2019 12:54:57PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: HAO

This is computer generated document.

Signature is required.



* AR 201902-10564 *

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9701 / 6745 0923

Arrange By

Driver



Dept Direct: 6305 0010

Dept Direct: 6305 0511

Dept Direct: 6417 0752



Dept Direct: 6417 9754

Dept Direct: 6417 9752

Dept Direct: 6417 9756

Dept Direct: 6417 9753

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

ROGRESSIVE CAR CARE PTE LTD

LOCK 3022A #01-45/46

BI ROAD 1

UTTON 92712711

NGAPORE 408716

EL: 67415336 FAX: 67417208 LILY / 68444802 WENDY

TIN: WENDY / PEI WEN / LEONG KEAT

006897

TAX INVOICE : AR201902-10565

DATE : 27/02/2019

CUSTOMER ID : PRO005

VEH REG. NO. : SKS1537G

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : SGD

Q STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. T52119-4A914 ZSU60	FRT BUMPER	PA PL4-E1-07	1	300.00	300.00
2. T52161-16010 ROC ALL MODEL	BUMPER CLIP	PA PL2-N1-04A	10	1.50	15.00

SUB-TOTAL : 315.00
ADD GST 7.00 % 22.05

E. & O.E TOTAL AMOUNT SGD : 337.05

14/03/2019 12:46:27

[E] 27/02/2019 12:56:57PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : HAO

This is computer generated document.

No signature is required.



* AR 201902 - 10565 *

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date

...CLAIM SUBFOLDER...(Pending for Survey Report)

Midnight Accident

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Feb 2019 15:31 Sendback Est	23 Feb 2019 15:40 S\$7,452.55	25 Feb 2019 10:17 Edit Adj Rpt	S\$4,887.85 Edit Estimates	S\$4,887.85 View Rpt		Pending for Survey Report Cancel Case
Supp #1	27 Feb 2019 13:03	27 Feb 2019 15:53 S\$390.50	27 Feb 2019 15:12				Closed(Cancelled)
Supp #2	27 Feb 2019 16:23	27 Feb 2019 16:24 S\$390.50	27 Feb 2019 16:24			(Combined)	Combined with Main Uncombine Suppl.

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	WONG FOONG SUN , ID: S7277739E, Tel: +6588183895, Email: FOONGSUN_WONG@HOTMAIL.COM		
Vehicle Reg. No.:	SKS1537G	Date of Loss:	22/02/2019 06:00 - :59 [46 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / DMPC1900050H/JG	Policy/Cover Note No.:	MPC18A00086700 (Comprehensive)
		Excess:	S\$0.00
Repairer:	Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46, 408716 Ubi - Tel: 67415336		
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Janice Goh - 6303 0182]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 06/03/2019]		
Driver/Custodian:	WONG FOONG SUN (46 / Female) , NRIC: S7277739E, Tel: +6588183895 Email: FOONGSUN_WONG@HOTMAIL.COM		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- ECICS (05/04/2019): **Alert - Adj Mandate Approved (S\$4887.85) - SKS1537G - Claim Handler: Janice Goh**
- ECICS (26/02/2019): **Alert - Adj Mandate Approved (S\$5135.35) - SKS1537G - Claim Handler: Janice Goh**

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKS1537G (DMPC1900050H/JG)

OD

Feb 22 2019 6:00AM

[WONG FOONG SUN]

Progressive Car Care Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports

1 per page ▼ ☒

No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	23/02/19 15:40	Repairer Estimates	 Load HTM	☐
2	27/02/19 15:53	Repairer Estimates Suppl. #1	 Load HTM	☐
3	27/02/19 16:24	Repairer Estimates Suppl. #2	 Load HTM	☐
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/02/19 16:55	Adjuster Immediate Advice	 Load HTM	☐
2	05/04/19 11:32	Adjuster Immediate Advice	 Load HTM	☐

Photos/Images

3 per page ▼ ☒

No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	23/02/19 15:40	1	 Load JPG ☒	☒
2	23/02/19 15:40	2	 Load JPG ☒	☒
3	23/02/19 15:40	3	 Load JPG ☒	☒
4	23/02/19 15:40	4	 Load JPG ☒	☒
5	23/02/19 15:40	5	 Load JPG ☒	☒
6	23/02/19 15:40	6	 Load JPG ☒	☒
7	23/02/19 15:40	7	 Load JPG ☒	☒
8	23/02/19 15:40	8	 Load JPG ☒	☒
9	23/02/19 15:40	9	 Load JPG ☒	☒
10	23/02/19 15:40	10	 Load JPG ☒	☒
11	23/02/19 15:40	11	 Load JPG ☒	☒
12	23/02/19 15:40	12	 Load JPG ☒	☒
13	23/02/19 15:40	13	 Load JPG ☒	☒
14	23/02/19 15:40	14	 Load JPG ☒	☒
15	23/02/19 15:40	15	 Load JPG ☒	☒
16	23/02/19 15:40	16	 Load JPG ☒	☒
17	23/02/19 15:40	17	 Load JPG ☒	☒
18	23/02/19 15:40	18	 Load JPG ☒	☒
19	23/02/19 15:40	19	 Load JPG ☒	☒
20	23/02/19 15:40	20	 Load JPG ☒	☒
21	23/02/19 15:40	21	 Load JPG ☒	☒
22	23/02/19 15:40	22	 Load JPG ☒	☒
23	23/02/19 15:40	23	 Load JPG ☒	☒
24	23/02/19 15:40	24	 Load JPG ☒	☒
25	23/02/19 15:40	25	 Load JPG ☒	☒
26	23/02/19 15:40	26	 Load JPG ☒	☒
27	23/02/19 15:40	27	 Load JPG ☒	☒
28	23/02/19 15:40	28	 Load JPG ☒	☒
29	23/02/19 15:40	29	 Load JPG ☒	☒

Assessment Reports			1 per page ▼	✓
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
30	23/02/19 15:40	30	 Load JPG	✓
31	23/02/19 15:40	31	 Load JPG	✓
32	23/02/19 15:40	32	 Load JPG	✓
33	23/02/19 15:40	33	 Load JPG	✓
34	23/02/19 15:40	34	 Load JPG	✓
35	23/02/19 15:40	35	 Load JPG	✓
36	23/02/19 15:40	36	 Load JPG	✓
37	23/02/19 15:40	37	 Load JPG	✓
38	23/02/19 15:40	38	 Load JPG	✓
39	23/02/19 15:40	39	 Load JPG	✓
40	23/02/19 15:40	40	 Load JPG	✓
41	23/02/19 15:40	41	 Load JPG	✓
42	23/02/19 15:40	42	 Load JPG	✓
43	23/02/19 15:40	43	 Load JPG	✓
44	23/02/19 15:40	44	 Load JPG	✓
45	23/02/19 15:40	45	 Load JPG	✓
46	23/02/19 15:40	46	 Load JPG	✓
47	23/02/19 15:40	47	 Load JPG	✓
48	23/02/19 15:40	48	 Load JPG	✓
49	23/02/19 15:40	49	 Load JPG	✓
50	23/02/19 15:40	50	 Load JPG	✓
51	23/02/19 15:40	51	 Load JPG	✓
52	23/02/19 15:40	52	 Load JPG	✓
53	23/02/19 15:40	53	 Load JPG	✓
54	23/02/19 15:40	54	 Load JPG	✓
55	23/02/19 15:40	55	 Load JPG	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/02/19 13:56	Odometer Reading	 Load JPG	✓
2	26/02/19 13:56	Chassis Number	 Load JPG	✓
3	26/02/19 13:56	General View	 Load JPG	✓
4	26/02/19 13:56	General View	 Load JPG	✓
5	26/02/19 13:56	General View	 Load JPG	✓
6	26/02/19 13:56	General View	 Load JPG	✓
7	26/02/19 13:56	General View	 Load JPG	✓
8	26/02/19 13:56	General View	 Load JPG	✓
9	26/02/19 13:56	General View	 Load JPG	✓
10	26/02/19 13:56	General View	 Load JPG	✓
11	26/02/19 13:56	General View	 Load JPG	✓
12	26/02/19 13:56	General View	 Load JPG	✓
13	26/02/19 13:56	General View	 Load JPG	✓
14	26/02/19 13:56	General View	 Load JPG	✓
15	26/02/19 13:56	General View	 Load JPG	✓
16	26/02/19 13:56	General View	 Load JPG	✓
17	26/02/19 13:56	General View	 Load JPG	✓
18	26/02/19 13:56	General View	 Load JPG	✓
19	26/02/19 13:56	General View	 Load JPG	✓
20	26/02/19 13:56	General View	 Load JPG	✓
21	26/02/19 13:56	General View	 Load JPG	✓

Assessment Reports			1 per page ▾	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
22	26/02/19 13:56	General View	 Load JPG	☒
23	26/02/19 13:56	General View	 Load JPG	☒
24	26/02/19 13:56	General View	 Load JPG	☒
25	26/02/19 13:56	General View	 Load JPG	☒
26	26/02/19 13:56	General View	 Load JPG	☒
27	26/02/19 13:56	General View	 Load JPG	☒
28	26/02/19 13:56	General View	 Load JPG	☒
29	26/02/19 13:56	General View	 Load JPG	☒
30	26/02/19 13:56	General View	 Load JPG	☒
31	26/02/19 13:56	General View	 Load JPG	☒
32	26/02/19 13:56	General View	 Load JPG	☒
33	26/02/19 13:56	General View	 Load JPG	☒
34	26/02/19 13:56	General View	 Load JPG	☒
35	26/02/19 13:56	General View	 Load JPG	☒
36	26/02/19 13:56	General View	 Load JPG	☒
37	26/02/19 13:56	General View	 Load JPG	☒
38	26/02/19 13:56	General View	 Load JPG	☒
39	26/02/19 13:56	General View	 Load JPG	☒
40	26/02/19 13:56	General View	 Load JPG	☒
41	26/02/19 13:56	General View	 Load JPG	☒
42	26/02/19 13:56	General View	 Load JPG	☒
43	26/02/19 13:56	General View	 Load JPG	☒
44	26/02/19 13:56	General View	 Load JPG	☒
45	26/02/19 13:56	General View	 Load JPG	☒
46	26/02/19 13:56	General View	 Load JPG	☒
47	26/02/19 13:56	General View	 Load JPG	☒
48	26/02/19 13:56	General View	 Load JPG	☒
49	26/02/19 13:56	General View	 Load JPG	☒
50	26/02/19 13:56	General View	 Load JPG	☒
51	26/02/19 13:56	General View	 Load JPG	☒
52	26/02/19 13:56	General View	 Load JPG	☒
53	26/02/19 13:56	General View	 Load JPG	☒
54	26/02/19 13:56	General View	 Load JPG	☒
55	26/02/19 13:56	General View	 Load JPG	☒
56	26/02/19 13:56	General View	 Load JPG	☒
57	26/02/19 13:56	General View	 Load JPG	☒
58	26/02/19 13:56	General View	 Load JPG	☒
59	26/02/19 13:56	General View	 Load JPG	☒
60	26/02/19 13:56	General View	 Load JPG	☒
61	26/02/19 13:56	General View	 Load JPG	☒
62	26/02/19 13:56	General View	 Load JPG	☒
63	26/02/19 13:56	General View	 Load JPG	☒
64	26/02/19 13:56	General View	 Load JPG	☒
65	05/03/19 17:20	Reinspection Photo	 Load JPG	☒
66	05/03/19 17:20	Reinspection Photo	 Load JPG	☒
67	05/03/19 17:20	Reinspection Photo	 Load JPG	☒
68	05/03/19 17:20	Reinspection Photo	 Load JPG	☒
69	05/03/19 17:20	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
70	05/03/19 17:20	Reinspection Photo		☒
71	05/03/19 17:20	Reinspection Photo		☒
72	05/03/19 17:20	Reinspection Photo		☒
73	05/03/19 17:20	Reinspection Photo		☒
74	05/03/19 17:20	Reinspection Photo		☒
75	05/03/19 17:20	Reinspection Photo		☒
76	05/03/19 17:20	Reinspection Photo		☒
77	05/03/19 17:20	Reinspection Photo		☒
78	05/03/19 17:20	Reinspection Photo		☒
79	05/03/19 17:20	Reinspection Photo		☒
80	05/03/19 17:20	Reinspection Photo		☒
81	05/03/19 17:20	Reinspection Photo		☒
82	05/03/19 17:20	Reinspection Photo		☒
83	05/03/19 17:20	Reinspection Photo		☒
84	05/03/19 17:20	Reinspection Photo		☒
85	05/03/19 17:20	Reinspection Photo		☒
86	05/03/19 17:20	Reinspection Photo		☒
87	05/03/19 17:20	Reinspection Photo		☒
88	05/03/19 17:20	Reinspection Photo		☒
89	05/03/19 17:20	Reinspection Photo		☒
90	05/03/19 17:20	Reinspection Photo		☒
91	05/03/19 17:20	Reinspection Photo		☒
92	05/03/19 17:20	Reinspection Photo		☒

Documentation			1 per page	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	23/02/19 15:38	E-filed GIA report		
2	23/02/19 15:38	Certificate of Insurance		
3	23/02/19 15:38	Claimant's NRIC & LICENSE		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/02/19 16:55	ESTIMATE.pdf		
2	05/04/19 11:34	ESTIMATE & SUPPLEMENTARY MARKED.pdf		
3	24/04/19 10:23	PARTS INVOICE		

Linked Accident Report Documents

Assessment Reports			View	View in Browser	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print	
1	23/02/19 11:09	Accident Statement		Load HTM	

Photos/Images			3 per page	☒
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	23/02/19 11:09	Accident Photo		☒
2	23/02/19 11:09	Accident Photo		☒
3	23/02/19 11:09	Accident Photo		☒
4	23/02/19 11:09	Accident Photo		☒
5	23/02/19 11:09	Accident Photo		☒
6	23/02/19 11:09	Accident Photo		☒
7	23/02/19 11:09	Accident Photo		☒

Assessment Reports			1 per page ▼	✓
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
8	23/02/19 11:09	Accident Photo	 Load JPG	✓
9	23/02/19 11:09	Accident Photo	 Load JPG	✓
10	23/02/19 11:09	Accident Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	23/02/19 10:39	Sketch Plan	 Load JPG	✓
2	23/02/19 10:39	Sketch Plan #2	 Load JPG	✓
3	23/02/19 10:39	CI	 Load TIF	
4	23/02/19 10:39	DRIVER NRIC & LICENSE	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS19003446/R1SD3S2

Date: 24/04/2019

REFERENCE

Insured/Claimant: WONG FOONG SUN Policy No: MPC18A00086700
Date of Loss: 22/02/2019 Nature of Claim: OD Claim No: DMPC1900050H/JG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKS1537G**
Make & Model: TOYOTA HARRIER, 2.0 Elegance (A) Engine No: 3ZRB472786
Reg. Date: 27/03/2015 (Man. Year: 2014) Chassis No: ZSU600030206
Colour: Black Odometer: 82535 km
Engine Capacity: 1986 cc
Market Value/New Car Price: S\$91,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/60R18 Rear Tyre Size: 235/60R18
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,968.05	3,732.85	2,235.20	37.45
Miscellaneous Items	55.00	35.00	20.00	36.36
Labour	920.00	520.00	400.00	43.48
Paintwork Labour	900.00	600.00	300.00	33.33
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,843.05	4,887.85	2,955.20	37.68
+ GST 7.00/7.00% (S\$)	549.02	342.15	206.87	37.68
Nett Amount (S\$)	8,392.07	5,230.00	3,162.07	37.68

INSPECTION

Date of Assignment: 25/02/2019 Present Location: Progressive Car Care Pte Ltd (HQ)
Date Inspected: 25/02/2019 Inspected At: Progressive Car Care Pte Ltd (HQ)
Estimated Period of Repair: 5.0 days Blk 3022A Ubi Road 1, #01-45/46
Singapore 408716

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Apr 2019)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 Elegance (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKS1537G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*BONNET (WCP)	Bent	530.00 F	*530.00 F
2	1	NA	*BONNET RUBBER - LH - NO PRICE (NPA)(WCP)	Not Necessary	0.00 F	*- F
3	1	NA	*BONNET RUBBER - RH - NO PRICE (NPA) (WCP)	Not Necessary	0.00 F	*- F
4	9	NA	*BONNET INSULATOR CLIPS (WCP)	Necessary	13.50 F	*13.50 F
5	1	NA	*BONNET OUTER CHROME MOULDING (WCP)	Cracked	95.00 F	*95.00 F
6	1	NA	*GRILLE ASSY (WCP)	Cracked	200.00 F	*200.00 F
7	1	NA	*GRILLE LOGO (WCP)	Not Necessary	35.00 F	*- F
8	1	NA	*FRONT BUMPER (WCP)	Cracked	300.00 F	*300.00 F
9	10	NA	*FRONT BUMPER CLIPS (WCP)	Necessary	15.00 F	*15.00 F
10	1	NA	*FRONT BUMPER SIDE HOLDER - LH (WCP)	Serviceable	50.00 F	*- F
11	1	NA	*FRONT BUMPER SIDE HOLDER - RH (WCP)	Serviceable	50.00 F	*- F
12	1	NA	*FRONT BUMPER REINFORCEMENT (WCP)	Serviceable	130.00 F	*- F
13	1	NA	*FRONT BUMPER FOAM - CENTER (WCP)	Cracked	50.00 F	*50.00 F
14	1	NA	*FRONT BUMPER FOG LAMP - RH (WCP)	Serviceable	110.00 F	*- F
15	1	NA	*FRONT BUMPER FOG LAMP COVER - RH (WCP)	Serviceable	40.00 F	*- F
16	1	NA	*FRONT BUMPER FOAM - LH (WCP)	Cracked	30.00 F	*30.00 F
17	1	NA	*FRONT BUMPER FOAM - RH (WCP)	Cracked	30.00 F	*30.00 F
18	1	NA	*FRONT BUMPER GRILLE TOP RUBBER (WCP)	Serviceable	45.00 F	*- F
19	1	NA	*FRONT BUMPER CENTRE LOWER GRILLE (WCP)	Cracked	90.00 F	*90.00 F
20	1	NA	*FRONT BUMPER TOWING COVER - RH (WCP)	Repair	18.00 F	*- F
21	1	NA	*FRONT BUMPER TOWING COVER - LH (WCP)	Serviceable	18.00 F	*- F
22	1	NA	*FRONT BUMPER LOWER GARNISH (WCP)	Cracked	90.00 F	*90.00 F
23	1	NA	*BRACE PANEL (WCP)	Serviceable	110.00 F	*- F
24	1	NA	*SUPPORT PANEL ASSY (WCP)	Serviceable	350.00 F	*- F
25	13	NA	*SUPPORT PANEL TOP GARNISH CLIP (WCP)	Not Necessary	26.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1	NA	*HEAD LAMP PANEL - LH (WCP)	Serviceable	50.00 F	*- F
27	1	NA	*HEAD LAMP PANEL - RH (WCP)	Serviceable	50.00 F	*- F
28	1	NA	*HEAD LAMP - LH (WCP)	Cracked	900.00 F	*900.00 F
29	1	NA	*HEAD LAMP - RH (WCP)	Cracked	900.00 F	*900.00 F
30	1	NA	*HEAD LAMP LOWER RETAINER - LH (WCP)	Serviceable	45.00 F	*- F
31	1	NA	*HEAD LAMP LOWER RETAINER - RH (WCP)	Serviceable	45.00 F	*- F
32	1	NA	*WIPER TANK (WCP)	Serviceable	60.00 F	*- F
33	1	NA	*WIPER TANK MOTOR (WCP)	Not Necessary	80.00 F	*- F
34	1	NA	*WIPER TANK NECK (WCP)	Serviceable	30.00 F	*- F
35	1	NA	*FRONT FENDER - RH (WCP)	Repair	270.00 F	*- F
36	10	NA	*FRONT FENDER COWLING CLIPS - RH (WCP)	Serviceable	15.00 F	*- F
37	1	NA	*HEAD LAMP PANEL LOWER - LH (WCP)	Serviceable	100.00 F	*- F
38	1	NA	*HEAD LAMP PANEL LOWER - RH (WCP)	Serviceable	100.00 F	*- F
Supplementary #2						
39	1		*R/F FENDER COWLING (WCP)	Serviceable	190.00 F	*- F
40	10		*R/F FENDER COWLING CLIP (WCP)	Not Necessary	15.00 F	*- F
41	1		*FRT BUMPER UNDER LOWER COVER (WCP)	Cracked	90.00 F	*90.00 F
42	1		*RADIATOR LOWER AIR GUIDE (WCP)	Deformed	60.00 F	*60.00 F

F=Franchise part.

Sub Total (\$\$)	5,425.50	3,393.50
+ Margin on L,N Items 10.00/10.00% (\$\$)	542.55	339.35
Total Parts (\$\$)	5,968.05	3,732.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	COOLANT (NOT NECESSARY)	20.00	0.00
2	1	FRONT NUMBER PLATE WITH CASING (SCRATCHED)	35.00	35.00
Sub Total (\$\$)			55.00	35.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	900.00	600.00
<u>Labour Items</u>				
2	TO KNOCK OUT DENTS; SUPPORT PANEL; REMOVE; REPLACE ACCIDENT PARTS	New	800.00	500.00
3	TO CHECK WIRING	New	20.00	20.00
4	TO REMOVE; REFIX CONDENSER AND REFILL GAS	New	100.00	0.00
Gross Labour Cost (\$\$)			1,820.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >