

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19003447/BKA3Q2

**Date:** 28/04/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800017518

**Claimant**  
**Vehicle No :** SKC385T **Insured Vehicle No :** EH3200T

Date of Loss: 21/02/2019 Nature of Claim: TP Claim No: 0304768983SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKC385T</b>		
Make & Model:	TOYOTA VIOS, 1.5 (A)	Engine No:	1NZX894719
Reg. Date:	23/04/2019 (Man. Year: 2019)	Chassis No:	MR053HY9305109847
Colour:	Beige	Odometer:	120764 km
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,506.16	1,376.48	129.68	8.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,170.00	500.00	670.00	57.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,676.16</b>	<b>1,876.48</b>	<b>799.68</b>	<b>29.88</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,350.00</b>		
<b>Nett Amount (S\$)</b>	<b>2,676.16</b>	<b>1,350.00</b>	<b>1,326.16</b>	<b>49.55</b>
<b>+ Loss of Use (6.0 x S\$60.00/day) (S\$)</b>		360.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>1,717.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>1,700.00</b>		

### INSPECTION

Date of Assignment: 25/02/2019

Date Inspected: 25/02/2019 Inspected At:

Team Autopro Pte Ltd (HQ)  
8 KAKI BUKIT AVE 4, #01-07  
PREMIER @ KAKI BUKIT  
Singapore 415875

Estimated Period of Repair: 3.0 days

**Adjuster:** Lim Teow Guan

**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	527.70 FL	*527.70 FL
2	1		*REAR BUMPER BRACKET	Bent	133.80 FL	*133.80 FL
3	1		*REAR BUMPER RETAINER	Necessary	78.40 FL	*78.40 FL
4	1		*REAR BUMPER REFLECTOR	Not Necessary	87.10 FL	*- FL
5	1		*SUNDRIES	Not Necessary	60.00 FS	*- FS
6	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
7	1		*EXHAUST MUFFLER	Bent	682.00 FL	*682.00 FL
8	1		*EXHAUST MOUNTING	Cut	62.00 FL	*62.00 FL
9	2		*REAR BUMPER REFLECTOR	Broken	174.20 FL	*174.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>1,855.20</b>	<b>1,708.10</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	349.04	331.62
<b>Total Parts (S\$)</b>	<b>1,506.16</b>	<b>1,376.48</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	R&R REVERSE SENSOR	New	100.00	100.00
2	PANEL BEAT	New	400.00	0.00
3	RUST PROOFING	New	60.00	0.00
4	SPRAY PAINTING	New	400.00	200.00
5	CHECK WIRING	New	60.00	50.00
6	R&R EXHAUST PIPE	New	150.00	150.00
<b>Gross Labour Cost (S\$)</b>			<b>1,170.00</b>	<b>500.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >