

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG19003456/KEA3Q2**Date:** 04/05/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800071481
Claimant
Vehicle No : SMG9604H **Insured Vehicle No :** SMA7615X
Date of Loss: 19/02/2019 Nature of Claim: TP Claim No: 7197890659SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMG9604H**
Make & Model: HYUNDAI AVANTE, 1.6 (A) Engine No: G4FGJU040288
Reg. Date: 05/01/2019 (Man. Year: 2018) Chassis No: KMHD841CMKU809712
Colour: Metallic Silver Odometer: 1822 km
Engine Capacity: 1591 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Kumho 9 mm Rear Left Side: Kumho 9 mm
Front Right Side: Kumho 9 mm Rear Right Side: Kumho 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	629.76	408.32	221.44	35.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,560.00	440.00	1,120.00	71.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,189.76	848.32	1,341.44	61.26
+ GST 7.00/7.00% (S\$)	153.28	59.38	93.90	61.26
Nett Amount (S\$)	2,343.04	907.70	1,435.34	61.26
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 22/02/2019
Date Inspected: 26/02/2019 Inspected At: BH Auto Services Pte Ltd (Sin Ming)
Blk 1 Sin Ming Industrial Estate Sector
C, #01/111/113/115/117
Singapore 575636
Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled / Cut	474.40 FL	*474.40 FL
2	1		*FRONT BUMPER SIDE RETAINER LH (NPA)	Not Necessary	0.00 FL	*- FL
3	1		*FRONT BUMPER SIDE RETAINER RH (NPA)	Not Necessary	0.00 FL	*- FL
4	12		*FRONT BUMPER CLIPS	Necessary	36.00 FL	*36.00 FL
5	1		*FRONT BUMPER FOG LAMP RH	*Check	164.80 FL	*- FL
6	1		*FRONT BUMPER FOG LAMP SIDE GARNISH RH (NPA)	Scratched	0.00 FL	*- FL
7	1		*HEADLAMP ASSY RH (NPA)	Cracked	0.00 FL	*- FL
8	1		*HEADLAMP LOWER BRACKET RH (RH)	*Check	12.00 FL	*- FL
9	1		*ANTI-RUST COATING	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	767.20	510.40
- List Item Discount on L Items 20.00/20.00% (S\$)	137.44	102.08
Total Parts (S\$)	629.76	408.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PROVIDE SKILL LABOUR TO RMEOVE ALL DAMAGED PARTS, PANEL BEAT ,CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS	New	750.00	200.00
2	PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITATES	New	750.00	220.00
3	PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING	New	60.00	20.00
			Gross Labour Cost (\$\$)	440.00
			1,560.00	1,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >