

15/5/2019

INS. CASE OWNER:

CC 6/CTI1900

LKK:

IDAC:

Surveyor:

Kenneth

DOI:

ASSIGNMENT

W/1/1/1

Date / Time:

11/1/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBB 8663A

Name of Insured:

NTH CONSTRUCTION P/L

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

18/1/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO. Driver Name / Age:

RAVICHANORAN JAYA MURRAY

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

MLSHR

PIE B4 BANESTIER EXIT

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLM 6103L

INSRS:
WSP:
Tel:
Liability:
RMKS:WAE
BrackenINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
15/1/19 04:30pm	Non-Reporting ltr (1st):	
15/1/19 04:30pm	Non-Reporting ltr (2nd):	
15/1/19 04:30pm	Non-Reporting ltr (Final):	
15/1/19 04:30pm	Notification ltr (if non-pickup):	
15/1/19 04:30pm	Call OI:	
15/1/19 04:30pm	After call ltr to OI:	
15/1/19 04:30pm	Documentation Check List: Handler	Typist
15/1/19 04:30pm	Notification ltr (if non-pickup)	
15/1/19 04:30pm	After call ltr to OI:	
15/1/19 04:30pm	Authorisation To Act:	
15/1/19 04:30pm	Release Voucher:	
15/1/19 04:30pm	Final Repair Bill:	
15/1/19 04:30pm	Car Rental Invoice:	
15/1/19 04:30pm	Towing Invoice:	
15/1/19 04:30pm	LTA / GIA:	
15/1/19 04:30pm	Medical Bill:	
15/1/19 04:30pm	PIR:	
15/1/19 04:30pm	Mandate/Reject Instruction:	
15/1/19 04:30pm	LOD	
15/1/19 04:30pm	Payment Breakdown Form:	
15/1/19 04:30pm	Post-Repair Photos:	
15/1/19 04:30pm	Others:	

PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost:	SS 3,329.53	(5 days) Reduction: 66 %
FINAL SETTLEMENT	Date/Time: 02-01-20	Confirm with: GLO/PH
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.: 27
Repair Cost:	SS 3,562.59	
Loss of Rental (LOR):	SS -	(days)
Loss of Use (LOU):	SS 510.00	(# 60 x 95 days)
Loss of Income (LOI):	SS -	(S x days)
LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LO ☐		[Tick only one]
GLA / LTA Search	SS 2.00	
Medical:	SS -	
Disbursement:	SS -	(e.g. Tow/ Independent)
Legal Cost	SS -	
Total:	SS 4,134.59	Global Sum SS: 4,100
FINAL PAYMENT	Date/Time: 02-01-20	Confirm with: CLO/PH
Payee 1:	SS 4,100.00	Name 1: COMPOTRUGED ENGINEERING PTE LTD
Payee 2: (Strike if N.A.)	SS -	Name 2:
Payee 3: (Strike if N.A.)	SS -	Name 3:

ASS. REC. BY:

REF:

C721

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4-5 days

Res.: Yes or No

Lum Sum:

1A.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

File pass to

P/P: +3,329.52 (RES: +6,363.40 66%)

Veh No:

SUM 61036

Yr Regn:

04, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Honda Grace

c.c

1496

Colour:

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

144225

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GM 4 1105449

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

DUNLOP

Front

R/Bal.

S

mm

Rear

R/Bal.

S

mm

L/Bal.

P

mm

L/Bal.

P

mm

D.O.A.

18/12/19

D.O.L.

22/2/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fixtures

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Kp

Spark Car Care
 ComfortDelgro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax: 62815767

Finalization Form

Bill To : CHINA TAIPING Vehicle Number : SLM6103L
 Attn to : LKK - KENNETH Type Of Claim : TP

A. Spare parts	\$ 1,811.90	F. Total Parts	\$ 1,649.52
B. Supplementary	\$ -	G. Total Labour	\$ 1,680.00
C. Nett Price	\$ -	H. Total Repair	\$ 3,329.52
D. Supp Nett Price	\$ -	I. Excess	_____
E. S/Nett	\$ 200.00	P/P Total	3,329.52 ✓

Total Spare Parts Price	\$ 1,811.90
Cost plus / List Down	20% 362.38
Total	1,449.52

Total Nett Price	\$ -
Nett Price Less	\$ -
Total	-

Lump Sum Less _____ \$ -

Lump Sum Rounding _____

Total Finalized \$ 3,329.52

N.B. If we DO NOT receive your reply within 2 weeks, we shall treat the above finalized amount as confirmed & correct.

Remarks : Please confirm and revert by Fax or Email

Date In : _____	Total Repair Day _____
Date Survey : _____	LOU/ Day _____
Date Out : _____	Total LOU _____
Sat/Sun/Ph. : _____	Rental/Day _____
Authorized Repair Day <u>5</u>	Total Rental _____

Submitted By / Date :
 WILLIAM WANG
 11.04.2019

Confirmed By / Date :

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SLM6103L Case Owner : 0

Make & Model : GRACE HYBRID 1.5DX AU Year Manufacture : 2016

Chassis No : GM41105449 Engine No : LEB5255464

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear number number plate with casing	1					
2	Rear number number plate lamp LH	1					
3	Rear number number plate lamp RH	1					
4	Rear bumper	1		\$ 937.50			
5	Rear bumper reflector LH	1					
6	Rear bumper reflector RH	1					
7	Rear bumper retainer LH	1					
8	Rear bumper retainer RH	1		\$ 13.90			
9	Rear bumper clips	10		\$ 39.00			
10	Reverse sensor set	1				\$ 200.00	
11	Taillamp LH	1					
12	Taillamp RH	1					
13	Bootlid	1		\$ 675.20			
14	Bootlid badge logo	1		\$ 24.70			
15	Bootlid emblem - GRACE	1		\$ 45.00			
16	Bootlid emblem - HYBRID	1		\$ 58.60			
17	Bootlid spoiler	1					
18	Bootlid lamp LH	1					
19	Bootlid lamp RH	1					
20	Bootlid chrome moulding	1					
21	Bootlid inner trim	1					
22	Bootlid inner trim clips	10					
23	Bootlid upper lock	1					
24	Bootlid striker	1					
25	Bootlid weatherstrip	1					
26	Bootlid hinge LH	1					
27	Bootlid hinge RH	1					
28	Bootlid opening switch	1					
29	Rear end panel	1					
30	Rear end panel inner garnish	1					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SLM6103L Case Owner : 0

Make & Model : GRACE HYBRID 1.5DX AU Year Manufacture : 2016

Chassis No : GM41105449 Engine No : LEB5255464

Sales Order : 0 Supplier : 0

Order By : 0 Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
31	Taillamp panel LH	1					
32	Taillamp panel RH	1					
33	Rear tool tray	1					
34	Rear hybrid battery air duct	1					
35	Rear floorboard cover	1					
36	Rear floorboard under cover	1					
37	Rear antenna control	1					
38	Rear end buzzer	1					
39	Bootlid chrome moulding clips	4		\$ 18.00			
40	0	0					
41	0	0					
42	0	0					
43	0	0					
44	0	0					
45	0	0					
46	0	0					
47	0	0					
48	0	0					
49	0	0					
50	0	0					
51	0	0					
52	0	0					
53	0	0					
54	0	0					
55	0	0					
56	0	0					
57	0	0					
58	0	0					
59	0	0					
60	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Labour

Vehicle No. : **SLM6103L** Case Owner : **0**
 Make & Model : **RACE HYBRID 1.5DX AUTO** Year of Manufacture : **2016**

S/No	Labour Description	Estimated Price	Adjusted Price
1	To mount vehicle on black hawk floor bench in order to re-align chassis members or body structure.	\$250.00	
2			
2	To remove/refit hybrid to facilitate repairs.	\$250.00	
3	To remove/refit boot compartment trims and garnish to facilitate repairs.	\$180.00	\$ 100.00
4	Labour charges to repair and panel beat the RH rear fender, LH rear fender, rear chassis members, rear floorboard panel, cutting/welding & replacing damaged parts.	\$1,200.00	\$ 480.00
5	To check wiring functions.	\$40.00	\$ 20.00
6	To replace reverse sensor set.	\$120.00	\$ 80.00
7	To putty, apply primer & spray-paint the rear bumper, bootlid, bootlid spoiler, bootlid hinges, RH rear fender, LH rear fender, rear end panel, taillamp panel LH, taillamp RH, rear chassis members, spare tyre panel and affected areas.	\$1,750.00	\$ 1,000.00
8	To apply rust-proofing on repaired/replaced panels.	\$200.00	
9	To diagnose and re-set hybrid battery system	\$500.00	

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC6/CTI19003476/Kpb3

Date: 25.02.2019

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLM6103L


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 22.02.2019 at the premises of M/s Comfortdelgro Engineering Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	9,892.92
Revised Estimate Amount	: S\$	3,454.96
"Check" Items Amount	: S\$	2,531.84
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4-5 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Our Ref:

Type of Claim : TPVehicle No. : SLM6103LMake & Model : GRACE HYBRID 1.5DX AUTOYear of Manufacture : 2016Chassis No. : GM41105449Ins Company : AIG VS CHINA TAIPINGEngine No. : LEB5255464Excess : -Policy No. : -Date of Accident : 18.02.2019Time of Accident : 07:30

Suggested Days of Repair : _____

In-house Vehicle Assessor

Repair Estimate

Case Owner : _____

Signature : _____

Parts (a) Cost / List Price Items \$ 6,447.40Plus/Less 20% \$ 1,289.48Total of Cost / List \$ 5,157.92(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ 245.00Total Parts Cost (Appendix A) \$ 5,402.92Labour (Appendix B) \$ 4,490.00Total Repair Cost \$ 9,892.92

Contact No

Frt Counter Operation

63837103 - Patrick Tia

63837730 - Brenda Ng

63837466 - Rohani

braddell_cr@sparkcarcare.com

Workshop Operation

63837656 - Ngo Toh Wee

63837362 -

63838115 - William Wang

63838115 - Andrew Goh

braddell_operation@sparkcarcare.com

The above total will be subjected to 7% G.S.T.

Not Authorized
Resurvey B4 point

Name of Surveyor : Kenneth
 Company : LKK
 Survey conducted on : 22/2/19 at _____

Remarks By Surveyor(a) The repair of this vehicle is not authorized / is not authorized until further notice.(b) Recommended Days of Repair : 4-5 day(s)(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Lc Date: 22/2/19

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SLM6103L Case Owner : 0

Make & Model : GRACE HYBRID 1.5DX AU Year Manufacture : 2016

Chassis No : GM41105449 Engine No : LEB5255464

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear number number plate with casing	1			<i>Sn</i>	\$ 45.00	X
2	Rear number-number plate lamp LH	1	<i>Sn</i>	\$ 36.10			✓
3	Rear number-number plate lamp RH	1	<i>Sn</i>	\$ 36.10			X
4	Rear bumper	1	<i>Bu</i>	\$ 937.50	✓		✓
5	Rear bumper reflector LH	1	<i>Sn</i>	\$ 30.00			X
6	Rear bumper reflector RH	1	<i>Sn</i>	\$ 30.00			X
7	Rear bumper retainer LH	1	<i>Sn</i>	\$ 13.90			X
8	Rear bumper retainer RH	1	<i>Dis</i>	\$ 13.90	✓		✓
9	Rear bumper clips	10	<i>Sn</i>	\$ 39.00	✓		✓
10	Reverse sensor set	1			<i>Res</i>	\$ 200.00	✓
11	Taillamp LH	1	<i>Sn</i>	\$ 381.70			X
12	Taillamp RH	1	<i>Sn</i>	\$ 381.70			X
13	Bootlid	1	<i>Bu</i>	\$ 675.20	✓		✓
14	Bootlid badge logo	1	<i>Sn</i>	\$ 24.70	✓		✓
15	Bootlid emblem - GRACE	1	<i>Sn</i>	\$ 45.00	✓		✓
16	Bootlid emblem - HYBRID	1	<i>Sn</i>	\$ 58.60	✓		✓
17	Bootlid spoiler	1	<i>MM X</i>	\$ 461.00			?
18	Bootlid lamp LH	1	<i>Sn</i>	\$ 306.70			X
19	Bootlid lamp RH	1	<i>Sn</i>	\$ 306.70			X
20	Bootlid chrome moulding	1	<i>MM X</i>	\$ 165.80			?
21	Bootlid inner trim	1	<i>Sn</i>	\$ 119.60			X
22	Bootlid inner trim clips	10	<i>Sn</i>	\$ 42.00			X
23	Bootlid upper lock	1	<i>MM X</i>	\$ 90.30			?
24	Bootlid striker	1	<i>R</i>	\$ 28.90			X
25	Bootlid weatherstrip	1	<i>MM X</i>	\$ 91.60			?
26	Bootlid hinge LH	1	<i>R</i>	\$ 68.40			✓
27	Bootlid hinge RH	1	<i>R</i>	\$ 68.40			X
28	Bootlid opening switch	1	<i>X</i>	\$ 210.60			?
29	Rear end panel	1	<i>MM X</i>	\$ 395.00			?
30	Rear end panel inner garnish	1	<i>X</i>	\$ 86.40			?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SLM6103L Case Owner : 0

Make & Model : GRACE HYBRID 1.5DX AU Year Manufacture : 2016

Chassis No : GM41105449 Engine No : LEB5255464

Sales Order : 0 Supplier : 0

Order By : 0 Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
31	Taillamp panel LH	1	<i>✓</i>	\$ 98.00			<i>✓</i>
32	Taillamp panel RH	1	<i>✓</i>	\$ 98.00			<i>✓</i>
33	Rear tool tray	1	<i>✓</i>	\$ 168.50			<i>✓</i>
34	Rear hybrid battery air duct	1	<i>✓</i>	\$ 197.20			<i>✓</i>
35	Rear floorboard cover	1	<i>✓</i>	\$ 254.30			<i>✓</i>
36	Rear floorboard under cover	1	<i>✓</i>	\$ 135.00			<i>✓</i>
37	Rear antenna control	1	<i>not x</i>	\$ 318.00			<i>?</i>
38	Rear end buzzer	1		\$ 33.60			<i>?</i>
39	Bootlid chrome moulding clips	4	<i>✓</i>	\$ 18.00			<i>✓</i>
40	0	0					
41	0	0					
42	0	0					
43	0	0					
44	0	0					
45	0	0					
46	0	0					
47	0	0					
48	0	0					
49	0	0					
50	0	0					
51	0	0					
52	0	0					
53	0	0					
54	0	0					
55	0	0					
56	0	0					
57	0	0					
58	0	0					
59	0	0					
60	0	0					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a Without Prejudice basis
- Physical modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Labour

Vehicle No. : **SLM6103L** Case Owner : **0**
 Make & Model : **RACE HYBRID 1.5DX AUTO** Year of Manufacture : **2016**

S/No	Labour Description	Estimated Price	Adjusted Price
1	To mount vehicle on black hawk floor bench in order to re-align chassis members or body structure.	\$250.00	~ ~ X
2			
2	To remove/refit hybrid to facilitate repairs.	\$250.00	X
3	To remove/refit boot compartment trims and garnish to facilitate repairs.	\$180.00	100% ✓
4	Labour charges to repair and panel beat the RH rear fender, LH rear fender, rear chassis members, rear floorboard panel, cutting/welding & replacing damaged parts.	\$1,200.00	480% ✓ 720%
5	To check wiring functions.	\$40.00	20% ✓
6	To replace reverse sensor set.	\$120.00	80% ✓
7	To putty, apply primer & spray-paint the rear bumper, bootlid, bootlid spoiler, bootlid hinges, RH rear fender, LH rear fender, rear end panel, taillamp panel LH, taillamp RH, rear chassis members, spare tyre panel and affected areas.	\$1,750.00	100% ✓
8	To apply rust-proofing on repaired/replaced panels.	\$200.00	X
9	To diagnose and re-set hybrid battery system	\$500.00	X
		4907.32%	

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.



ComfortDelGro Engineering

Date: 09/03/2020

Our Ref: PTE/SLM6103L/20190218/DS-CL

Your Ref: **SNM19D201104**

M/s LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933
Attn: Asher Sng

Without Prejudice

Dear Sir/Madam

**ACCIDENT ON 18/02/2019 INVOLVING SLM6103L & GBB8663A
ALONG PIE**

Strictly without admission of any liability and solely for quick amicable settlement, we confirm settlement at **\$4,100.00** for property damage only. Please note that this acceptance is purely for quick settlement and it shall not be cited or relied on as precedent in any proceeding. Please note that the contents of this document apply to vehicle damages only. It is condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/driver/claimant.

The duly completed document is enclosed for your attention. Please arrange to let us have your payment made in favor of ComfortDelGro Engineering Pte Ltd within the next seven (7) days.

Yours sincerely

Cecilia Lee
CDGE Claims Department
DID: 6214 8354 FAX: 6214 1843
Email: cecilialee@sparkcarcare.com

ComfortDelGro Engineering Pte Ltd

Corporate Office
205 Braddell Road Singapore 579701
Mainline +65 6383 6280
Facsimile +65 6280 9755

Company Registration No: 199506048W

Car Care Centres

Braddell
205 Braddell Road
Singapore 579701
Tel 6383 8110

Loyang
59 Loyang Drive
Singapore 508969
Tel 6214 8300

Pandan
45 Pandan Road
Singapore 605286
Tel 6338 8778

Sin Ming
383 Sin Ming Drive
Singapore 575717
Tel 6553 0400

Sungei Kadut
7 Sungei Kadut Way
Singapore 728781
Tel 6389 7369

Ubi
320 Ubi Road 3
Singapore 408649
Tel 6846 5721

www.SPARKcarcare.com

A member of

COMFORTDELGRO

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI19003476/Kea3s2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 25-03-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBB 8663A	Veh. Inspected	SLM 6103L
Policy No.	DMCVSN3033071803	Coverage (\$)	0.00
Claim No.	SNM19D201104/C02/3/ock	Excess (\$)	0.00
Assign From		Assign Date	22/02/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA GRACE (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	GM41105449	Colour	METALLIC SILVER
Odometer	144225	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	DAVANTI	8 mm
L/H Front Tyre	185/60 R15	DAVANTI	8 mm
R/H Rear Tyre	185/60 R15	DAVANTI	8 mm
L/H Rear Tyre	185/60 R15	DAVANTI	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	18/02/2019	Inspection Date	22/02/2019
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 205 BRADDELL ROAD BLK C, 3RD FLOOR SINGAPORE 579701.		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 6103L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR NUMBER PLATE LAMP LH	SERVICEABLE	36.10	-
1	REAR NUMBER PLATE LAMP RH	SERVICEABLE	36.10	-
1	REAR BUMPER	BUCKLED	937.50	937.50
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	30.00	-
1	REAR BUMPER REFLECTOR RH	SERVICEABLE	30.00	-
1	REAR BUMPER RETAINER LH	SERVICEABLE	13.90	-
1	REAR BUMPER RETAINER RH	DISTORTED	13.90	13.90
10	REAR BUMPER CLIPS	NECESSARY	39.00	39.00
1	TAILLAMP LH	SERVICEABLE	381.70	-
1	TAILLAMP RH	SERVICEABLE	381.70	-
1	BOOTLID	BENT	675.20	675.20
1	BOOTLID BADGE LOGO	NECESSARY	24.70	24.70
1	BOOTLID EMBLEM - GRACE	NECESSARY	45.00	45.00
1	BOOTLID EMBLEM - HYBRID	NECESSARY	58.60	58.60
1	BOOTLID SPOILER	NOT NECESSARY	461.00	-
1	BOOTLID LAMP LH	SERVICEABLE	306.70	-
1	BOOTLID LAMP RH	SERVICEABLE	306.70	-
1	BOOTLID CHROME MOULDING	NOT NECESSARY	165.80	-
1	BOOTLID INNER TRIM	SERVICEABLE	119.60	-
10	BOOTLID INNER TRIM CLIPS	NOT NECESSARY	42.00	-
1	BOOTLID UPPER LOCK	NOT NECESSARY	90.30	-
1	BOOTLID STRIKER	TO REPAIR SEE LABOUR	28.90	-
1	BOOTLID WEATHERSTRIP	NOT NECESSARY	91.60	-
1	BOOTLID HINGE LH	TO REPAIR SEE LABOUR	68.40	-
1	BOOTLID HINGE RH	TO REPAIR SEE LABOUR	68.40	-
1	BOOTLID OPENING SWITCH	NOT NECESSARY	210.60	-
1	REAR END PANEL	NOT NECESSARY	395.00	-
1	REAR END PANEL INNER GARNISH	NOT NECESSARY	86.40	-

Report Ref No. CC6/CTI19003476/Kea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	98.00	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	98.00	-
1	REAR TOOL TRAY	SERVICEABLE	168.50	-
1	REAR HYBRID BATTERY AIR DUCT	SERVICEABLE	197.20	-
1	REAR FLOORBOARD COVER	SERVICEABLE	254.30	-
1	REAR FLOORBOARD UNDER COVER	SERVICEABLE	135.00	-
1	REAR ANTENNA CONTROL	NOT NECESSARY	318.00	-
1	REAR END BUZZER	NOT NECESSARY	33.60	-
4	BOOTLID CHROME MOULDING CLIPS	NECESSARY	18.00	18.00
	LESS 20% DISCOUNT		-1,293.08	-362.38
			5,172.32	1,449.52
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE WITH CASING (SN)	SERVICEABLE	45.00	-
1	SET REVERSE SENSOR (SN)	DENTED	200.00	200.00
			245.00	200.00
	LABOUR			
	TO MOUNT VEHICLE ON BLACK HAWK FLOOR BENCH IN ORDER TO RE-ALIGN CHASSIS MEMBERS OR BODY STRUCTURE.	NOT NECESSARY	250.00	-
	TO REMOVE / REFIT HYBRID TO FACILITATE REPAIRS.	NOT NECESSARY	250.00	-
	TO REMOVE / REFIT BOOT COMPARTMENT TRIMS AND GARNISH TO FACILITATE REPAIRS.		180.00	100.00
	LABOUR CHARGES TO REPAIR AND PANEL BEAT THE RH REAR FENDER, LH REAR FENDER, REAR CHASSIS MEMBERS, REAR FLOORBOARD PANEL, CUTTING / WELDING & REPLACING DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF BOOTLID STRIKER, BOOTLID HINGE LH, BOOTLID HINGE RH, TAILLAMP PANEL LH AND TAILLAMP PANEL RH.		1,200.00	480.00
	TO CHECK WIRING FUNCTIONS.		40.00	20.00
	TO REPLACE REVERSE SENSOR SET.		120.00	80.00

Report Ref No. CC6/CTI19003476/Kea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY, APPLY PRIMER & SPRAY-PAINT THE REAR BUMPER, BOOTLID, BOOTLID SPOILER, BOOTLID HINGES, RH REAR FENDER, LH REAR FENDER, REAR END PANEL, TAILLAMP PANEL LH, TAILLAMP RH, REAR CHASSIS MEMBERS, SPARE TYRE PANEL AND AFFECTED AREAS.		1,750.00	1,000.00
	TO APPLY RUST-PROOFING ON REPAIRED / REPLACED PANELS.	NOT NECESSARY	200.00	-
	TO DIAGNOSE AND RE-SET HYBRID BATTERY SYSTEM.	NOT NECESSARY	500.00	-
			4,490.00	1,680.00
GRAND TOTAL			9,907.32	3,329.52
RECOMMENDED COST OF REPAIRS				3,329.52

Report Ref No. CC6/CTI19003476/Kea3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.