

ASS. REC. BY:

REF:

C721

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

File pass to

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

Photos

Others

TOTAL

Veh No:

SIM 6103L

Yr Regn:

04, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Honda Grace

c.c

1486

Colour:

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

144225

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GM 4

1105449

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NII / S/Rlm / STD A/Rlm or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Daveni

Front

R/Bal.

P

mm

Rear

R/Bal.

P

mm

L/Bal.

P

mm

L/Bal.

P

mm

D.O.A.

18/2/19

D.O.I.

22/2/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Our Ref:

Type of Claim : TPVehicle No. : SLM6103LMake & Model : GRACE HYBRID 1.5DX AUTOYear of Manufacture : 2016Chassis No. : GM41105449Ins Company : AIG VS CHINA TAIPINGEngine No. : LEB5255464Excess : -Policy No. : -Date of Accident : 18.02.2019Time of Accident : 07:30

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimate**

Case Owner : _____

Signature : _____

Parts (a) Cost / List Price Items \$ 6,447.40Plus/Less 20% \$ 1,289.48Total of Cost / List \$ 5,157.92(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ 245.00Total Parts Cost (Appendix A) \$ 5,402.92Labour (Appendix B) \$ 4,490.00Total Repair Cost \$ 9,892.92

Contact No

Frt Counter Operation

63837103 - Patrick Tia

63837730 - Brenda Ng

63837466 - Rohani

braddell_cr@sparkcarcare.com

Workshop Operation

63837656 - Ngo Toh Wee

63837362 -

63838115 - William Wang

63838115 - Andrew Goh

braddell_operation@sparkcarcare.com

The above total will be subjected to 7% G.S.T.

Not Authorized
Resurvey By point

Name of Surveyor : Kenneth
 Company : LKK
 Survey conducted on : 22/2/19 at _____

Remarks By Surveyor(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.(b) Recommended Days of Repair : 4-5 day(s)(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : Le Date: 22/2/19

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SLM6103L Case Owner : 0

Make & Model : GRACE HYBRID 1.5DX AU Year Manufacture : 2016

Chassis No : GM41105449 Engine No : LEB5255464

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear number number plate with casing	1			<i>Sn</i>	\$ 45.00	X
2	Rear number number plate lamp LH	1	<i>Sn</i>	\$ 36.10			✓
3	Rear number number plate lamp RH	1	<i>Sn</i>	\$ 36.10			X
4	Rear bumper	1	<i>Bu</i>	\$ 937.50			✓
5	Rear bumper reflector LH	1	<i>Sn</i>	\$ 30.00			X
6	Rear bumper reflector RH	1	<i>Sn</i>	\$ 30.00			X
7	Rear bumper retainer LH	1	<i>Sn</i>	\$ 13.90			X
8	Rear bumper retainer RH	1	<i>Dis</i>	\$ 13.90			✓
9	Rear bumper clips	10	<i>Sn</i>	\$ 39.00			✓
10	Reverse sensor set	1			<i>Net</i>	\$ 200.00	✓
11	Taillamp LH	1	<i>Sn</i>	\$ 381.70			X
12	Taillamp RH	1	<i>Sn</i>	\$ 381.70			X
13	Bootlid	1	<i>Bu</i>	\$ 675.20			✓
14	Bootlid badge logo	1	<i>Sn</i>	\$ 24.70			✓
15	Bootlid emblem - GRACE	1	<i>Sn</i>	\$ 45.00			✓
16	Bootlid emblem - HYBRID	1	<i>Sn</i>	\$ 58.60			✓
17	Bootlid spoiler	1		\$ 461.00			?
18	Bootlid lamp LH	1	<i>Sn</i>	\$ 306.70			X
19	Bootlid lamp RH	1	<i>Sn</i>	\$ 306.70			X
20	Bootlid chrome moulding	1		\$ 165.80			?
21	Bootlid inner trim	1	<i>Sn</i>	\$ 119.60			X
22	Bootlid inner trim clips	10	<i>Sn</i>	\$ 42.00			X
23	Bootlid upper lock	1		\$ 90.30			?
24	Bootlid striker	1	<i>R</i>	\$ 28.90			X
25	Bootlid weatherstrip	1		\$ 91.60			?
26	Bootlid hinge LH	1	<i>R</i>	\$ 68.40			✓
27	Bootlid hinge RH	1	<i>R</i>	\$ 68.40			X
28	Bootlid opening switch	1		\$ 210.60			?
29	Rear end panel	1		\$ 395.00			?
30	Rear end panel inner garnish	1		\$ 86.40			?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SLM6103L Case Owner : 0

Make & Model : GRACE HYBRID 1.5DX AU Year Manufacture : 2016

Chassis No : GM41105449 Engine No : LEB5255464

Sales Order : 0 Supplier : 0

Order By : 0 Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
31	Taillamp panel LH	1	<i>AK</i>	\$ 98.00			<i>X</i>
32	Taillamp panel RH	1	<i>AK</i>	\$ 98.00			<i>X</i>
33	Rear tool tray	1	<i>fm</i>	\$ 168.50			<i>X</i>
34	Rear hybrid battery air duct	1	<i>fm</i>	\$ 197.20			<i>X</i>
35	Rear floorboard cover	1	<i>fm</i>	\$ 254.30			<i>X</i>
36	Rear floorboard under cover	1	<i>fm</i>	\$ 135.00			<i>X</i>
37	Rear antenna control	1		\$ 318.00			<i>?</i>
38	Rear end buzzer	1		\$ 33.60			<i>?</i>
39	Bootlid chrome moulding clips	4	<i>fm</i>				<i>✓</i>
40	0	0					
41	0	0					
42	0	0					
43	0	0					
44	0	0					
45	0	0					
46	0	0					
47	0	0					
48	0	0					
49	0	0					
50	0	0					
51	0	0					
52	0	0					
53	0	0					
54	0	0					
55	0	0					
56	0	0					
57	0	0					
58	0	0					
59	0	0					
60	0	0					

I KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a Without Prejudice basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Labour

Vehicle No. : **SLM6103L** Case Owner : **0**
 Make & Model : **RACE HYBRID 1.5DX AUTO** Year of Manufacture : **2016**

S/No	Labour Description	Estimated Price	Adjusted Price
1	To mount vehicle on black hawk floor bench in order to re-align chassis members or body structure.	\$250.00	~ X
2			
2	To remove/refit hybrid to facilitate repairs.	\$250.00	?
3	To remove/refit boot compartment trims and garnish to facilitate repairs.	\$180.00	100% ?
4	Labour charges to repair and panel beat the RH rear fender, LH rear fender, rear chassis members, rear floorboard panel, cutting/welding & replacing damaged parts.	\$1,200.00	480% - 720%
5	To check wiring functions.	\$40.00	20%
6	To replace reverse sensor set.	\$120.00	80%
7	To putty, apply primer & spray-paint the rear bumper, bootlid, bootlid spoiler, bootlid hinges, RH rear fender, LH rear fender, rear end panel, taillamp panel LH, taillamp RH, rear chassis members, spare tyre panel and affected areas.	\$1,750.00	1000%
8	To apply rust-proofing on repaired/replaced panels.	\$200.00	?
9	To diagnose and re-set hybrid battery system	\$500.00	?

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.