

23/03/2003

/ SS. REC. BY:

REF:

cs/FCI19003485/Kqd3ⁿ²

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

CWS

From (Person):

May chun

of

FCI

Date/Time:

5:09pm @ 22/2/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SKW 3542G

Insured:

SH 9660T

at Workshop m/s

Esteem performance

Tel:

64841221

of

Blk 5033 Amic, Ind park 2 #01-251

Policy No:

Claim No:

D19001302MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/02/2019

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

10:47am @ 25/2/19

Person Contacted:

jenny

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKW 3542G - NBA / ZIP 17006278/Y DVA: 27/3/17
	SH 9660T - CC3 / 2CR / 8011496 / Klug 3y 2 DVA: 20/6/18
26/7/19 @ 4:11pm	revised to May Chun by email.
14/3	1/1 Lmp @ 1950L email & confirmed Cred \$1831.80, 49%

ASS. REC. BY:

REF:

F021

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 860k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: Skw 3542G Yr Regn: 10, 15Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Honda Vezel c.c. 1496Colour: M. P. White A/C: Insured / Std / NI / NASp. Reading: 27333 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: Ry 1 1103064Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rim / STD A/Rim orTyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen

Front

R/Bal. 9 mm

Rear

R/Bal. 9 mmL/Bal. 9 mmL/Bal. 9 mmD.O.A. 18/2/19D.O.I. 25/2/19

Survey held at _____

Des. of Damages: Frt Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to

RECEIVED 14 MAR 2019

Date/Time, File Pass to?

☐ : Prell. Report1) 14/3 Final☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 4Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S. R.S. SI

Fees

Others

TOTAL

Report Format: 71Lump Sum / I.B.I. (\$) 1950

130

50

50

12

242



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003485MFSH

Date: 26 February 2019

Our Ref: CS/FCI19003485/Kqd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKW 3542G

Please be informed that we had conducted the inspection of the abovementioned vehicle on 25/02/2019 at the premises of M/s ESTEEM PERFORMANCE, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,801.80</u>
Revised Estimate Amount	: S\$ <u>2,430.56</u>
"Check" Items Amount	: S\$ <u>350.00</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:
The vehicle sustained damages
at the rear portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	21-02-2019	Our Ref No. D19001302MFSH
Accident Date	18-02-2019	Claim Type. Third Party
Insured Vehicle	SH9660T	Third Party Vehicle. SKW3542G
Survey Location	BLK 5033 ANG MO KIO, IND PARK 2 #01-251/259	
Contact Person.	JENNY CHONG	
Contact No.	64841221/ 0	Fax No. 64847829
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ESTEEM PERFORMANCE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 26 February 2019 4:11 PM
To: 'CWS Motor Claims'; assignments
Cc: 'May Chua Hui Chin'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001302MFSH/1
Attachments: CSFCI19003485Kqd3.pdf

Dear May,

Enclosed herewith preliminary advice of SKW 3542G.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 25 February 2019 10:49 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001302MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 22 February 2019 5:09 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19001302MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

SUMP - LKK



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SKW 3542 G

Parts (a) Cost / List Price Items	\$	1,846.00
Plus/Less 20%	\$	369.20
Total of Cost / List	\$	1,476.80
(b) Nett Price Items		
Less		
Total of Nett Item		
(c) Special Nett Items	\$	295.00
Total Parts Cost	\$	1,771.80
Labour	\$	2,030.00
Total	\$	3,801.80

The above total will be subjected to 7% G.S.T.

Not Withheld
11 Sep @ 1950h
Returning After Repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be recovered and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 25/2/19 at _____

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : Lc

Date: 25/2/19



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SKW 3542 G**
Make & Model : **HONDA VAZEL**
Chassis No : **RU11103064**

Submit By : **Carmen Lim**
Year Manufacture : **2015**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear windscreen moulding	1	\$120.00		✓
2	Rear windscreen sealant	1	\$50.00	S.N	405m
3	Reverse sensor	1	\$200.00	S.N	X
4	Rear number plate	1	\$45.00	S.N	X
5	Rear bumper	1	\$463.70		✓
6	Rear bumper clip	10	\$39.00		✓
7	Rear bumper side retainer LH	1	\$17.50		X
8	Rear bumper side retainer RH	1	\$17.50		X
9	Rear bumper reinforcement	1	N/A		X
10	Tail door	1	\$972.50		✓
11	Tail door lock	1	\$157.10		X
12	Tail door emblem	1	\$15.70		X
13	Wording "Vazael"	1	\$43.00		✓
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SKW 3542 G** Submit By : **Carmen Lim**
Make & Model : **HONDA VAZEL** Year of Manufacture : **2015**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAIL DOOR)	\$600.00	400
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAIL DOOR)	\$600.00	400
3	To check wiring	\$50.00	20
4	To remove & refit reverse sensor	\$120.00	50
5	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	X
6	To remove & refix windscreen glass	\$120.00	✓
7	To tuff coat.	\$150.00	30
8	To transfer boot mechanism to new boot	\$120.00	60
9	To conduct water leakage tests to ensure proper air and sealing	\$120.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19003485/Kqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 15-03-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 9660T	Veh. Inspected	SKW 3542G	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19001302MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	22/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	RU11103064	Colour	METALLIC PEARL WHITE	
Odometer	27333	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	NEXEN	9 mm	
L/H Front Tyre	215/60 R16	NEXEN	9 mm	
R/H Rear Tyre	215/60 R16	NEXEN	9 mm	
L/H Rear Tyre	215/60 R16	NEXEN	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/02/2019	Inspection Date	25/02/2019	
Survey held at	ESTEEM PERFORMANCE PTE LTD BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 3542G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR WINDSCREEN MOULDING	NECESSARY	120.00	120.00
1	REAR BUMPER	BUCKLED / DENTED	463.70	463.70
10	REAR BUMPER CLIP	NECESSARY	39.00	39.00
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	17.50	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	17.50	-
1	REAR BUMPER REINFORCEMENT (NPA)	NO SUCH PARTS	-	-
1	TAIL DOOR	BENT	972.50	972.50
1	TAIL DOOR LOCK	TO REPAIR SEE LABOUR	157.10	-
1	TAIL DOOR EMBLEM	NOT NECESSARY	15.70	-
1	"WORDING" VEZEL	NECESSARY	43.00	43.00
	LESS 20% DISCOUNT		-369.20	-327.64
			1,476.80	1,310.56
SPECIAL NETT ITEMS				
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REVERSE SENSOR (SN)	SERVICEABLE	200.00	-
1	REAR NUMBER PLATE (SN)	SERVICEABLE	45.00	-
			295.00	40.00
LABOUR				
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(REAR BUMPER,TAIL DOOR).INCLUSIVE OF THE REPAIR OF TAIL DOOR LOCK.		600.00	400.00
	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(REAR BUMPER,TAIL DOOR).		600.00	400.00
	TO CHECK WIIRNG.		50.00	20.00
	TO REMOVE & REFIT REVERSE SENSOR.		120.00	50.00
	TO REMOVE & REFIT SPARE TYRE,SPARE TYRE BOARD,CARPET TRIM TO ASSIST WORK LOAD.	NOT NECESSARY	150.00	-
	TO REMOVE & REFIX WINSCREEN GLASS.		120.00	120.00
	TO TUFF COAT.		150.00	30.00
	TO TRANSFER BOOT MECHANISM TO NEW BOOT.		120.00	60.00

Report Ref No. CS/FCI19003485/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING.	NOT NECESSARY	120.00	-
			2,030.00	1,080.00
	GRAND TOTAL		3,801.80	2,430.56
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,950.00

Report Ref No. CS/FCI19003485/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.